

RQ09-002

FORD

8-27-2009

ATTACHMENT

c39371 grease over corrosion

From: SSSC [sssc@renkim.com]
Sent: Friday, September 07, 2007 8:26 AM
To: Centa, John (J.R.)
Cc: Burroughs, Mary (M.M.); Collins, Melissa; Harris, Ursula; Ursum, Deb (D.L.)
Subject: FW: 2001 escape fire at abs control module pig tail / 1FMYU03141K [REDACTED]
Attachments: 000_2968.JPG; 000_2968.JPG; 000_2967.JPG; 000_2966.JPG

John:

This one to me appears that they installed grease in a corroded pigtail. I am basing that on the fact that it got hot, but there are no pins left in the module at all. I can see some green corrosion on the smaller pins that did not get any grease on the extreme left of the picture.

Call to discuss.

Deb

From: Murphy, Gregory [mailto:MurphyG1@autonation.com]
Sent: Thursday, September 06, 2007 8:21 PM
To: sssc@renkim.com
Subject: 2001 escape fire at abs control module pig tail

Mary & Deb,

Hear are the photos of the area of concern. The Vin # is 1FMYU03141K [REDACTED]. P&A code [REDACTED]

Thanks <<000_2968.JPG>> <<000_2968.JPG>> <<000_2967.JPG>> <<000_2966.JPG>>

Greg Murphy

Fixed Operations Director
Power Ford Torrance
3311 Pacific Coast Hwy
Torrance, CA 90505
Office (310) 784-4720
Fax (310) 784-4756
murphyg1@autonation.com





EC38 43 780
YL84 2C286 FA

4X2

02220204087517112093

25.0X0



EC38 43 780
YL84 2C286 FA

4X2

02220204087517112093

25.0X0


RQ09-002


FORD

8-27-2009

ATTACHMENT

Contamination_corrosion _no
grease







RQ09-002

FORD

8-27-2009

ATTACHMENT

factory tie-wrap in place







RQ09-002

FORD

8-27-2009

ATTACHMENT

incorrect grease





RQ09-002

FORD

8-27-2009

ATTACHMENT

insufficient grease



YLBP-2

YLBP EAT1 1282 0722



EC30 43 780
VL04 20200 FA

4X2



YL8P-25

YL8P EAT1 1262 0702

4X2

EC300 4X2 780
VL804 EC3000 P/A

4X2

1262 0702



RQ09-002

FORD

8-27-2009

ATTACHMENT

no grease2

