



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 10-019
Date Opened: 05/28/2010
Principal Investigator: Steve Mchenry
Subject: Accelerator pedal entrapment.

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: FORD MOTOR COMPANY
Products: 2010 Ford Fusion and Mercury Milan
Population: 249,301 (Estimated)
Problem Description: An accessory floor mat may entrap the accelerator pedal.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	3	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD

ACTION / SUMMARY INFORMATION

Action: A Preliminary Investigation has been opened.

Summary:

ODI has received three complaints of accelerator pedals being trapped by unsecured "all weather" floor mats in current production Model Year 2010 Ford Fusion vehicles.

A Preliminary Evaluation has been opened to assess the scope, frequency, and potential safety-related consequences of the alleged defect.