

U.S. Department of Transportation

National Highway Traffic Safety Administration

ODI RESUME

Investigation: PE 10-032Date Opened: 08/23/2010Investigator: Michael Lee

Approver: Richard Boyd

Subject: Fuel Spill During Refueling

Reviewer: Scott Yon

MANUFACTURER & PRODUCT INFORMATION

Manufacturer:CHRYSLER GROUP LLCProducts:2007-2008 Jeep WranglerPopulation:223,000 (Estimated)

Problem Description: Fuel spills out of the filler port during refueling.

FAILURE REPORT SUMMARY

TAILORE REPORT SOMMARY			
	ODI	Manufacturer	Total
Complaints:	217	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD

ACTION / SUMMARY INFORMATION

Action: Open a Preliminary Evaluation (PE).

Summary:

ODI has received 217 consumer complaints alleging that fuel spills out of the filler port during the refueling process. This condition generally occurs when the fuel tank is filled to the full or nearly full level and the gas pump automatically shuts or clicks off. Consumers report that the spilled fuel can splash on the person fueling the vehicle, or on the side of the vehicle and the ground.

Investigation: PE 10-032 Open Resume Page 1 of 1