

# **ODI RESUME**

U.S. Department of Transportation National Highway Traffic Safety Administration

Investigation:PE 10-033Date Opened:08/23/2010Investigator:Steve MchenryApprover:Richard BoydSubject:Engine stalling

Reviewer:

Steve Mchenry

### MANUFACTURER & PRODUCT INFORMATION

Manufacturer:	FORD MOTOR COMPANY		
Products:	2004 through 2007 Ford Freestar and Mercury Monterey		
Population:	280,489 (Estimated)		
Broblem Description:	The orgine may stall due to water entering the newertrain control module		

**Problem Description:** The engine may stall due to water entering the powertrain control module.

## FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total	
Complaints:	27	144	162**	
Crashes/Fires:	1	0	1	
Injury Incidents:	1	0	1	
Fatality Incidents:	0	0	0	
Other*:	0	176	176	

\*Description of Other: MY 2004 warranty claims for stalling due to water intrustion into the PCM

\*\* Count indicates duplicate reports received by ODI and manufacturer.

### **ACTION / SUMMARY INFORMATION**

Action: A Preliminary Evaluation has been opened.

#### Summary:

This Preliminary Evaluation (PE) is being opened based on information obtained during the investigation DP09-004, which was specifically related to Model Year (MY) 2004 Ford Freestar vehicles. The manufacturer's numbers presented on the Failure Report of the opening of this PE are for MY 2004 Ford Freestar vehicles only, the ODI number represents 15 MY 2004 complaints and 12 MY 2005 complaints; the scope of this PE investigation for MY 2004 to 2007 Freestars and Montereys is based on complaints received to ODI and on Ford's Technical Service Bulletin TSB 06-14-10.

The one crash noted is for a MY Freestar, VOQ #10311522.

This PE has been opened to assess the scope, frequency, and potential safety-related consequences of the alleged defect.