



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 10-037
Date Opened: 09/16/2010
Investigator: John Abbott
Approver: Richard Boyd
Subject: Low Beam Headlights
Reviewer: Scott Yon

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: HONDA (AMERICAN HONDA MOTOR CO.)
Products: 2007 and 2008 Honda Fit
Population: 133,000 (Estimated)

Problem Description: Low beam headlights stop working

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	8	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD

ACTION / SUMMARY INFORMATION

Action: Open a Preliminary Evaluation

Summary:

The Office of Defects Investigation has received eight reports from consumers alleging the low beam headlights stopped working. Several of the complainants report having a wiring harness connector and headlight switch replaced as the repair.