



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 10-047
Date Opened: 11/22/2010
Investigator: John Abbott **Reviewer:** Scott Yon
Approver: Richard Boyd
Subject: Driver's Master Power Window Switch

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: HONDA (AMERICAN HONDA MOTOR CO.)
Products: 2006 Honda CR-V
Population: 150,000 (Estimated)
Problem Description: Melting or burning of the master power window switch and related electrical system wiring components

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	3	TBD	TBD
Crashes/Fires:	3	TBD	TBD
Injury Incidents:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD
Other*:	0	TBD	TBD

*Description of Other:

ACTION / SUMMARY INFORMATION

Action: Open Preliminary Evaluation

Summary:

The Office of Defects Investigation has opened this investigation based on three Vehicle Owner's Questionnaire reports alleging a fire occurred in the driver's door related to the driver's master power window switch.