

Toyota Motor Engineering &
Manufacturing North America, Inc.

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

October 29, 2014

Jennifer T. Timian, Chief
Recall Management Division
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

Re: NVS-215jt; AQ10-001

Dear Ms. Timian:

On behalf of Toyota Motor Corporation, we are providing responses to your October 14, 2014 Information Request (IR) regarding AQ10-001. Responses follow each question below. The information for all responses was obtained from Toyota Technical Information System and Quality Compliance Department records as of October 24, 2014.

1. Identify, by the recall's NHTSA-assigned identification number, each recall conducted by you since January 1, 2000.

Response 1

Information responsive to this request is contained in the enclosed file:
AQ10-001_Toyota_Recall_final.xlsx.

2. Provide the total number of vehicles covered by all recalls identified in response to Question No. 1.

Response 2

Information responsive to this request is contained in the enclosed file:
AQ10-001_Toyota_Recall_final.xlsx

3. Identify, by the recall's NHTSA-assigned identification number, each recall conducted by you since January 1, 2000 for which the notification required by 49 U.S.C. §§ 30118(b) or 30118(c) contained precautionary advice to refrain from driving the vehicle until the remedy specified by the recall was completed.

Response 3

Information responsive to this request is contained in the enclosed file:

AQ10-001_Toyota_Recall_final.xlsx

4. For each recall identified in Question No.3, provide the total number of vehicles covered by the recall.

Response 4

Information responsive to this request is contained in the enclosed:

AQ10-001_Toyota_Recall_final.xlsx

5. Provide the total number of vehicles covered by all recalls identified in response to Question No.3.

Response 5

Information responsive to this request is contained in the enclosed file:

AQ10-001_Toyota_Recall_final.xlsx

Should you have any questions about this response, please contact me directly.

Sincerely,



Matthew D. Collins
Manager, Vehicle Safety and Compliance Liaison
Office
Toyota Motor Engineering & Manufacturing
North America, Inc.

Enclosure

Toyota has no recalls with specific advice to refrain from driving until the remedy is completed. One recall, 14V-655, contains conditional language directing drivers to refrain from using their vehicle if the remedy is not performed. Also note that, in some instances, precautionary advice was provided to certain conditions were present (e.g., the presence of a warning lamp). These have been included in response to this request in the column Mitigation Instructions.

NHTSA_RECALL_NO	NHTSA_RECALL_DT	TMS_RECALL_NO	RECALL_TITLE	TOTAL_VINS	COMP_VINS	%age	Do Not Drive	Mitigation Instructions
00V103	4/7/2000	Y01	2000 MY Tundra Stop Lamp	16,782	13,689	81.57 N		
00V154	6/5/2000	Y02	2000 MY Avalon, Camry, and Camry Solara Rear Axle Hub Assembly	541	469	86.69 N		
00V211	8/9/2000	YE1	1998-2000 MY RAV4 EV Parking Lock Rod Replacement	755	712	94.30 N		
00V212	8/9/2000	YE2	1998-2000 MY RAV4 EV Front Rotor and Steel Wheel Replacement	779	673	86.39 N		
00V256	9/7/2000	Y04	2000 MY Echo Vacuum Brake Tube - Cold States Only	22,997	11,543	50.19 N		Customers advised to allow the vehicle to warm up before being driven.
00V285	9/21/2000	Y05	2001 MY Prius Power Steering Gear	1,772	1,735	97.91 N		
01E041	8/1/2001	10H	2000 MY Tundra and 1999 - 2000 MY Tacoma Trailer Wire Harness	441,106	133,265	30.21 N		
01V012	1/16/2001	10A	1998-2001 MY TMMK Camry V6 Cruise Control Acceleration Cable	54,265	46,601	85.88 N		
01V072	3/5/2001	10E	2001 MY Camry, Avalon, Sienna Front Sub-Frame Assembly	552	476	86.23 N		
01V228	7/5/2001	10G	2001 MY Highlander Brake Master Cylinder Reservoir Cap	41,172	38,226	92.84 N		
01V306	9/25/2001	1S1	2002 MY Camry - Front Passenger-Side Air Bag	2	2	100.00 N		
01V326	10/10/2001	10L	2000 MY Echo Brake Booster and Front Brake Pad Replacement - Equipped with Automatic Transmission	42,128	33,994	80.69 N		
01V371	12/11/2001	1LF	2002 MY ES300 Front Brake Tube (Left Hand)	3,505	3,403	97.09 N		
01V372	12/11/2001	1LG	2002 MY ES300 Driver's Side Front Airbag	8,340	8,057	96.61 N		
02V021	1/18/2002	20A	Safety Recall 20A - 1996 to early 1998 MY 4Runner Rear Suspension	273,919	212,012	77.40 N		
02V074	3/11/2002	20B	Safety Recall 20B - 2003 MY Corolla torque on rear hub bolts	8,483	7,651	90.19 N		
02V208	7/30/2002	20D	Safety Recall 20D - 2001 to 2002 MY Toyota Highlander ORVR Valve Breather Hose Clamp	154,386	139,249	90.20 N		
02V268	10/1/2002	20E	Safety Recall 20E - 2001 and 2002 MY Toyota Echo Rear Brake Tube	59,394	42,053	70.80 N		
03V031	2/11/2003	3LA	Safety Recall 3LA - 2003 MY Lexus GX 470 Certification Label Replacement	5,878	4,157	70.72 N		
03V074	3/5/2003	30B	Safety Recall 30B - Late 2002 to early 2003 MY Toyota Celica Fuel Tank Check Valve	16,305	12,527	76.83 N		
03V088	3/10/2003	3LB	Safety Recall 3LB - 2003 Model Year GX 470 Middle Row Seat Lock	3,666	3,223	87.92 N		
03V146	4/14/2003	30C	Safety Recall 30C - Early 2003 Model Year Toyota 4Runner V6 Fuel Pulsation Damper	29,487	27,180	92.18 N		
03V189	5/19/2003	30H	Safety Recall 30H - 2001 Through Mid-2003 MY Toyota Tacoma Double Cab Fuel Hose Protector	123,360	100,996	81.87 N		
03V291	8/12/2003	30K	Safety Recall 30K - Early To Mid-2004 Model Year Sienna Fuel Tank Replacement	38,973	34,386	88.23 N		
03V366	10/6/2003	30L	Safety Recall 30L - 2004 Model Year Toyota Nummi Built Corolla Factory Aluminum Alloy Wheel	573	512	89.35 N		
04V181	4/15/2004	40B	Safety Recall 40B - 2001 to Early 2004 Model Year Toyota Highlander Child Protection Lock System	366,560	298,211	81.35 N		
04V295	6/25/2004	4LB	Safety Recall 4LB - 2004 Model Year LS 430 Fuel Pump Replacement	14,259	13,993	98.13 N		
04V317	7/1/2004	4LC	Safety Recall 4LC - 2004 Model Year LS 430 Transmission Replacement	13,109	12,952	98.80 N		
04V346	7/13/2004	40F	Safety Recall 40F - 2002 to Early 2004 Model Year North American Produced Toyota Camry Curtain Side Airbag	128,315	115,269	89.83 N		
04V455	9/17/2004	40K	Safety Recall 40K - 2000 Model Year Toyota Celica And Echo Brake Master Cylinder Inspection	108,804	71,741	65.94 N		
04V558	11/22/2004	40L,4LH	Safety Recall 40L - 2004 Model Year Prius Brake Light Switch; Safety Recall 4LH - 2004 Model Year RX 330 Brake Light Switch	183,145	177,202	96.76 N		
04V566	11/29/2004	50D	Safety (Non-Compliance) Recall 50D - 2000 Through 2001 Model Year Celica Daytime Running Lights (Drl)	92,579	53,879	58.20 N		
04V595	12/15/2004	40M,4LI	Safety Recall 40M - 2004 Through Early 2005 Model Year Toyota Camry Right Front Power Seat, Seat Belt Buckle Status Switch Replacement; Safety Recall 4LI - 2004 Through Early 2005 Model Year Lexus ES 330 Right Front Seat, Seat Belt Buckle Status Switch Replacement	155,172	130,788	84.29 N		Never install a rear-facing child restraint in the front passenger seat, even if the passenger Airbag OFF lamp is illuminated.
05V050	2/11/2005	50C	Safety Recall 50C - 2005 Model Year Tacoma Parking Brake Pedal Cable Lock Nut	22,124	19,016	85.95 N		
05V123	3/30/2005	50E	Safety Recall 50E - 2004 Through Early 2005 Model Year Tundra With Bot VSC and TRD Dual Exhaust System	5,726	3,392	59.24 N		
05V225	5/17/2005	50J	Safety Recall 50J - Toyota Front Suspension Lower Ball Joint	790,338	677,573	85.73 N		
05V227	5/16/2005	50F	Safety Recall 50F - Early 2005 Model Year Toyota Avalon Steering Column Assembly Inspection	4,855	4,693	96.66 N		
05V254	6/2/2005	70A,70C	Safety (Non-Compliance) Recall 70C - 2003 through Mid-2005 Model Year Tundra Access Cab Child Restraint Anchorage System Installation; Safety Recall 70A - 2003 Through Mid-2005 Tundra Access Cab Child Restraint Anchorage System Caution Label Installation	157,441	18,466	11.73 N		Use passenger seat belt and turn airbag off using switch for child seat.
05V302	6/28/2005	50I	Safety Recall 50I - 2005 MY Tacoma Regular Cab Bench Seat Wire Harness	11,592	8,212	70.84 N		
05V327	7/20/2005	50L	Safety Recall 50L - 2004 Through Mid-2005 MY Sienna Middle Row Seatbelt Bezel	345,305	302,500	87.60 N		
05V328	7/20/2005	50K	Safety Recall 50K - Mid-2005 Model Year Tundra Access Cab With Front Captains Chairs Front Passenger Occupant Classification System Indicator Light Lens	2,527	1,925	76.18 N		
05V389	9/6/2005	50N	Safety Recall 50N - Certain 1989 - 1995 Truck 4WD, 1990 - 1995 4Runner 2WD And 4WD, And 1993 - 1998 T100 (4WD Vehicles Equipped With Power Steering) Steering Relay Rod Replacement	977,838	447,176	45.73 N		
05V483	10/18/2005	50S	Safety Recall 50S - 2005 And Early 2006 Model Year Scion TC Moonroof Wind Deflector Laminate Installation	71,392	55,694	78.01 N		
05V539	11/22/2005	50T	Safety (Non-Compliance) Recall 50T - Early 2006 Model Year North American Produced Camry Tire Information Label	4,503	651	14.46 N		
05V565	12/19/2005	5LB,5LC	Safety (Non-Compliance) Recall 5LB - 1998 To Early 2005 Model Year Lexus LX 470 Daytime Running Lights; Safety Recall 5LC - Early 2006 Model Year Lexus IS 250 Awd Accelerator Pedal Assembly	79,475	55,175	69.42 N		
06V023	1/27/2006	6LA	Safety Recall 6LA - Early 2004 Model Year RX 330 - Rear, Left-Hand Side Seat Belt Buckle Anchor Bolt	3,851	3,476	90.26 N		
06V061	3/2/2006	60A	Safety Recall 60A - Early 2006 Model Year Tacoma 2WD Equipped With Firestone 97S Destination LE P215/70R15 Tires	12,020	8,909	74.12 N		

06V096	4/3/2006 60B,6LB	Safety Recall 60B - Supplemental Restraint System (SRS) Airbag Replacement;Safety Recall 6LB - Supplemental Restraint System (SRS) Airbag Replacement	134	122	91.04 N	
06V121	4/13/2006 6LC	Safety Recall 6LC - Early 2006 Model Year Lexus IS And GS - Front Seatbelt Assemblies	28,947	28,074	96.98 N	
06V188	5/31/2006 60C	Safety Recall 60C - 2004 Through Early 2006 Model Year Prius Steering Intermediate Shaft Replacement	170,856	166,671	97.55 N	
06V235	6/26/2006 60D,6AD	Early 2007 Model Year FJ Cruiser Vehicles Equipped With Bridgestone Dueler H/T P265/70R17 113S Or Dunlop Grandtrek AT20 P265/70R17 113S Tires;Safety Recall 6AD - Early 2007 Model Year FJ Cruiser Vehicles Equipped With Bridgestone Dueler H/T P265/70R17 113S Or Dunlop Grandtrek AT20 P265/70R17 113S Tires	18,868	9,896	52.45 N	
06V253	7/13/2006 60F,6LD	2004 Through 2005 Highlander And Early 2006 Highlander HV Center Console (Floor Carpet Cover) Retaining Clips;2004 Through 2005 Japan Produced RX 330 And Early 2006 RX 400H Center Console (Floor Carpet Cover) Retaining Clips	367,503	289,232	78.70 N	
06V266	7/19/2006 60G	Safety Recall 60G - 2001 Through Early 2002 Echo And Prius Crankshaft Position Sensor	34,771	25,750	74.06 N	
06V408	10/26/2006 60H	Safety Recall 60H - 2005 Through Late 2006 Scion TC Side Impact Airbag Sensors	29,542	22,067	74.70 N	
06V488	12/21/2006 60J	Safety Recall 60J - 2007 Model Year Camry Solara Curtain Side Airbags Front Tether Routing	160	127	79.38 N	
07E082	9/26/2007 70F,7LB	Lexus ES 350 All Weather Floor Mat Accessory For 2007 And Early 2008 Model Year Vehicles;Toyota Camry All Weather Floor Mat Accessory For 2007 And Early 2008 Model Year Vehicles	852,070	182,659	21.44 N	Properly Secure Floor mat using retaining clips
07V013	1/19/2007 70B	Safety Recall 70B - 2004 through Early 2007 Model Year Sequoia and 2004 through Late 2006 Model Year Tundra Front Suspension Lower Ball Joints	533,102	492,084	92.31 N	
07V324	7/26/2007 70D	Safety Recall 70D - 2007 Model Year Tacoma 4WD Rear Propeller Shaft	108	94	87.04 N	
07V545	11/28/2007 7LC	Safety Recall 7LC - 2006 MY Lexus IS 250/350 And GS 300 Fuel Pipe Replacement	34,344	32,496	94.62	
07V579	12/18/2007 70G	Safety Recall 70G - 2007 Model Year Tundra 4WD Rear Propeller Shaft	15,815	14,267	90.21 N	
08V162	4/10/2008 80A	Safety Recall 80A - 2003 Through 2004 Model Corolla and Corolla Matrix Front Door Glass Bolts	547,058	369,618	67.56 N	
08V181	4/18/2008 80D	Safety Recall 80D - 2008 Highlander And Highlander HV Equipped With Third Row Seat	87,151	78,306	89.85 N	
08V244	6/3/2008 80C	Safety Recall 80C - Certain 2004 - 2006 Sienna Vehicles Equipped W/ Power Back Door (Power Rear Liftgate)	196,396	165,013	84.02 N	
09E022	4/27/2009 90E	Safety Recall 90E - Toyota Stainless Steel Exhaust Tip Accessory Clamp - For 2008 Model Year Highlander and Highlander HV Vehicles	120,260	70,723	58.81 N	
09V020	1/16/2009 9LA	Safety Recall 9LA - Certain 2006 - 2007 GS, 2006 - 2008 IS And 2007 - 2008 LS Vehicles, Replacement Of Fuel Delivery Pipes (Fuel Rails)	214,570	203,232	94.72 N	
09V023	1/16/2009 90B	Safety Recall 90B - Early 2004 Sienna - Floor Carpet Cover And Retaining Clip	26,877	16,249	60.46 N	
09V031	1/29/2009 90C	Safety Recall 90C - 2006 Through 2007 Model Year Yaris - Center Pillar Sound Insulator Removal	149,003	104,757	70.31 N	
09V223	6/15/2009 90I	Special Service Campaign (Non-Compliance Recall) 90I - Update to Vehicle Capacity Weight and Gross Vehicles Weight Rating	27,080	27,080	100.00 N	
09V234	6/25/2009 90J,9LF	Safety (Non-Compliance) Recall 90J - Update to Vehicle Capacity Weight and Gross Vehicles Weight Rating;Safety (Non-Compliance) Recall 9LF - Update to Vehicle Capacity Weight and Gross Vehicles Weight Rating	2,204	749	33.98 N	
09V332	8/19/2009 90G	Safety (Non-Compliance) Recall 90G - 2010 Model Year Corolla Vehicles - Airbag Caution Label on Driver's Sun-Visor	1,309	998	76.24 N	
09V338	8/27/2009 90H	Safety Recall 90H - Certain 2009-2010 Toyota Corolla, Corolla Matrix and 2008-2009 Scion xD Vehicles Equipped with 2ZR-FE (1.8 liter) Engines Brake System Vacuum Port	496,145	402,422	81.11 N	
09V388	10/5/2009 90L,9LG	Safety Recall 90L - Potential Floor Mat Interference with Accelerator Pedal;Safety Recall 9LG - Potential Floor Mat Interference with Accelerator Pedal	4,450,695	3,873,978	87.04 N	Properly Secure Floor mat using retaining clips or remove from vehicle
09V444	11/18/2009 90M,B0D,BXD,BZD	Safety Recall 90M - Certain 2000 through 2003 Tundra Vehicles Severe Corrosion of the Rear Cross-Member;Safety Recall B0D (Safety Recall 90M CRC Application Phase 2) 2000 - 2003 MY Tundra Frame Corrosion-Resistant Compound;Safety Recall BXD (Safety Recall 90M CRC Application Phase 2) 2000 - 2003 MY Tundra Frame Corrosion-Resistant Compound;Safety Recall BZD - SUPPLEMENTAL INFORMATION for Campaign BXD - Only for Dealerships Located Outside of the 20 Cold Climate States Servicing Vehicles Covered by BXD	326,165	129,927	39.83 N	
10V017	1/21/2010 A0A	Safety Recall A0A - Accelerator Pedal Reinforcement Bar Installation	2,241,984	2,072,546	92.44 N	
10V023	1/27/2010 90L	Safety Recall 90L - Potential Floor Mat Interference with Accelerator Pedal	1,131,462	995,125	87.95 N	
10V039	2/9/2010 A0B,ALA	Safety Recall A0B - Certain 2010 Model Year Prius Vehicles - ABS Actuator ECU Update;Safety Recall ALA - Certain 2010 Model Year HS 250 Vehicles - ABS Actuator ECU Update	148,238	146,753	99.00 N	
10V040	2/9/2010 A0C	Safety Recall A0C - Certain Early Production 2010 Model Year Camry Vehicles Equipped with 4 Cylinder (2AR-FE) - Brake Tube Inspection and/c Repositioning	7,314	6,598	90.21 N	
10V042	2/18/2010 A0D	Safety Recall A0D - Certain 2010 Model Year Tacoma 4WD Vehicles Vehicles Front Propeller Shaft Inspection	7,519	7,093	94.33 N	
10V159	4/20/2010 ALB	Safety Recall ALB - Certain 2010 Model Year GX 460 Vehicles - VSC ECU Update	9,411	8,924	94.83 N	
10V160	4/20/2010 A8E	Safety Recall A8E Phase 1, 2, & 3 (Remedy Notice) - Certain 1998 through 2010 Toyota Sienna Vehicles Equipped with a Spare Tire - Severe Corrosion of the Spare Tire Carrier Cable	573,427	360,263	62.83 N	
10V176	4/30/2010 A0G	Safety Recall A0G - Certain 2003 Model Year Toyota Sequoia Vehicles - Vehicle Stability Control System, Skid Control ECU Update	48,542	38,063	78.41 N	

10V218	5/21/2010 ALC	Safety Recall ALC - Specific Late 2009 and Certain 2010 Model Year Lexus LS Vehicles Equipped with the Variable Gear Ratio Steering (VGRS) Steering Wheel Temporarily Off-Center	3,826	3,733	97.57 N	
10V285	6/25/2010 ALD	Safety Recall ALD - Certain 2010 Model Year Lexus HS250h Vehicles - FMVSS 301	17,801	17,335	97.38 N	
10V309	7/6/2010 ALE	Safety Recall ALE - Certain Lexus GS 350, GS 450h, GS 460, IS 350, LS 460, LS 460 L, and LS 600h L Vehicles - Valve Spring	138,878	128,084	92.23 N	
10V345	7/29/2010 AOH	Safety Recall AOH - Certain 2000 through 2004 Toyota Avalon Vehicles Steering Column Upper Bracket	372,607	285,636	76.66 N	
10V346	7/29/2010 ALF	Safety Recall ALF - Certain 2003 through 2007 Model Year Lexus LX 470 Vehicles Steering Shaft	39,159	24,233	61.88 N	
10V384	8/26/2010 AOJ	Safety Recall AOJ - Engine Control Module (ECM) for Certain 2005 through 2008 Toyota Corolla and Corolla Matrix Models Equipped with a 1ZZ-FE Engine and Two Wheel Drive	1,146,531	919,395	80.19 N	
10V499	10/21/2010 AOM,ALG	Safety Recall AOM - Certain 2005 through 2006 Model Year Toyota Avalon Vehicles & Certain 2004 through 2006 Model Year Highlander (Non Hybrid) Vehicles Brake Master Cylinder Cup Replacement; Safety Recall ALG - Certain 2006 Model Year Lexus IS and GS Vehicles & Certain 2004 through 2006 Model Year RX Vehicles Brake Master Cylinder Cup Replacement	728,578	591,212	81.15 N	If brake warning light is on or the pedal feel changes, check brake fluid level
10V620	12/13/2010 AOP	Safety Recall AOP Remedy Notice - Certain 2011 Model Year Toyota Sierr Vehicles - Brake Light (Stop Lamp) Switch Bracket	99,098	90,098	90.92 N	Warning on the proximity of the Stop Lamp Switch Bracket
11V029	1/26/2011 BLA	Safety Recall BLA Certain 2006 - 2007 GS, 2006 - early 2009 IS 250 and 2006 - early 2008 IS 350 vehicles Insufficient Tightening of the Fuel Pressure Sensor	244,800	219,702	89.75 N	
11V112	2/24/2011 B0A,BLC	Safety Recall B0A - Certain 2004 2006 model year Highlander/Highlander HV Driver's Side Floor Carpet Cover and Retention Clip; Safety Recall BLC - Certain 2004 2006 model year RX 330, RX 350 and RX 400h Vehicles Driver's Side Floor Carpet Cover and Retention Clip	769,435	565,069	73.44 N	
11V113	2/24/2011 90L,9LG	Safety Recall 90L - Potential Floor Mat Interference with Accelerator Pedal; Safety Recall 9LG - Potential Floor Mat Interference with Accelerator Pedal	1,381,097	1,045,294	75.69 N	Properly Secure Floor mat using retaining clips or remove from vehicle
11V115	2/24/2011 BLB	Safety Recall BLB - 2006 - Early 2007 Model Year GS 300 and GS 350 AWD Vehicles Plastic Pad Embedded into the Floor Carpet	19,656	16,044	81.62 N	
11V148	3/4/2011 B0B	Safety (Non-Compliance) Recall B0B - Certain 2008 through 2011 Model Year Land Cruiser, Sequoia, Tacoma and Tundra Vehicles Equipped with Toyota-Recommended Light Truck tires and TRD Accessory Wheel	921,936	645,410	70.01 N	
11V245	4/21/2011 B0E	Safety Recall B0E - Certain 2007-2008 Model Year RAV4 Vehicles Certain 2008 Model Year Highlander/Highlander HV Vehicles Curtain Shield Airbag (CSA) Sensor - Remedy Parts Available	332,371	264,258	79.51 N	
11V254	4/26/2011 B0F	Safety Recall B0F - Certain 2011 model year Tundra Vehicles - Inspection and Possible Replacement of Rear Propeller Shaft Q&A	50,736	46,647	91.94 N	
11V304	6/1/2011 B0G	Safety Recall B0G - 2001 to 2003 model year Prius Vehicles - Electric Power Steering (EPS) Pinion Shaft Nuts	52,378	41,685	79.58 N	
11V306	6/1/2011 B0H	Safety Recall B0H - Certain 2011 Model Year Sienna AWD and Venza AWD Vehicles Right-Hand Front Drive Shaft	50	47	94.00 N	
11V342	6/29/2011 B0J,BLD,BSD,BSJ	Safety Recall B0J - Certain 2006 through 2007 Model Year Highlander HV Vehicles Intelligent Power Module (IPM) Replacement - Remedy Available; Safety Recall BLD - Certain 2006 through 2007 Model Year RX 400h Vehicles Intelligent Power Module (IPM) Replacement - Remedy Available; Safety Recall BSD (Supplement to BLD) - Certain 2006 through 2007 Model Year RX 400h Vehicles Intelligent Power Module (IPM) Replacement - Remedy Available; Safety Recall BSJ (Supplement to B0J) - Certain 2006 through 2007 Model Year Highlander HV Vehicles Intelligent Power Module (IPM) Replacement - Remedy Available	77,801	76,489	98.31 N	
11V377	7/26/2011 BLF	Safety Recall BLF (Remedy) - Thirty Two RX 350 (2011 Model Year) Vehicles Brake Actuator Assembly	32	28	87.50 N	
11V539	1/9/2011 B0M,BLG	Safety Recall B0M - Certain 2004 and 2005 Model Year Camry, Camry Solara, Highlander, Sienna, Solara, certain 2004 Model Year Avalon and certain 2005 and 2006 Model Year Highlander HV Vehicles - 1MZ-FE/3MZ-FE V6 Engine Cranks; Safety Recall BLG - Certain 2004 and 2005 Model Year ES 330 and RX 330 and Certain 2006 Model Year RX 400h Vehicles - 1MZ-FE/3MZ-FE V6 Engine Crankshaft Pulley - Remedy Available	424,327	313,807	73.95 N	Pay attention to any abnormal noise from the engine compartment
11V560	11/30/2011 B0N,BSN	Safety (Non-Compliance) Recall B0N - Customer Notification Phase 2011 and Certain early 2012 Model Year Sienna Vehicles - Tire and Loading Info Placard and Owner's Manual update sent to owners. Assist customer if requested; Safety (Non-Compliance) Recall BSN - Supplemental Phase for Vehicles with Specific Accessories 2011 and certain early 2012 Model Year Sienna Vehicles Tire and Loading Information Placard	210,491	45,192	21.47 N	
12E046	10/17/2012 C0R	Safety Recall C0R Remedy Notice - TRD High Performance Brake Kit Accessory Equipment Recall Designed to fit 2007 to 2012 Model Year FJ Cruiser Vehicles	206,730	70,212	33.96 N	
12V029	2/1/2012 C0A	Safety Recall C0A - Specific 2011 Model Year RAV4 Vehicles - Supplemental Restrain System (SRS), Side Curtain Airbag Replacement	451	414	91.80 N	
12V091	3/7/2012 C0E	Safety Recall C0E - Remedy Notice - Certain 2009 Model Year Toyota Camry & 2009 to Certain 2011 Model Year Venza - Stop Lamp Switch Replacement	187,960	152,620	81.20 N	
12V092	3/7/2012 C0B	Safety Recall C0B - Certain 2005 to 2009 Model Year Tacoma Vehicles - Spiral Cable Assembly Replacement	494,000	310,973	62.95 N	
12V221	5/16/2012 CLD	Safety Recall CLD - Certain 2013 Model Year GS350 F-Sport RWD Vehicles Variable Gear Ratio Steering (VGRS) Off-Center	651	625	96.01 N	Center steering wheel after parking and before turning off

12V255	6/5/2012 COH	Safety (Non-Compliance) Recall COH - Remedy Notice - Early 2013 Model Year Scion FR-S Vehicles Owner's Manual Update	1,060	220	20.75	N	
12V305	6/29/2012 90L,9LG	Safety Recall 90L - Potential Floor Mat Interference with Accelerator Pedal; Safety Recall 9LG - Potential Floor Mat Interference with Accelerator Pedal	164,601	133,768	81.27	N	Properly Secure Floor mat using retaining clips or remove from vehicle
12V373	8/2/2012 C0J,C3E,CLE,CSE	Safety Recall COJ Remedy Notice - Certain 2006 through 2011 Model Year Toyota RAV4 Vehicles Rear Lower Suspension Arm No.1; Safety Recall CLE Remedy Notice - Certain 2010 Model Year HS 250h Vehicles Rear Lower Suspension Arm No.1; Safety Recall CSE (C3E) Interim Notice - Certain 2010 Model Year HS 250h Vehicles REINSPECTION REQUIRED - Rear Lower Suspension Arm No. 1; Safety Recall CSE Remedy Notice - 2010 Model HS 250h Vehicles RE-INSPECTION REQUIRED for Rear Lower Suspension Arm No. 1	860,858	548,811	63.75	N	
12V491	10/10/2012 C0M	Safety Recall C0M Remedy Notice - Multiple Models and Model Years - Power Window Master Switch (PWMS)	2,541,191	1,653,284	65.06	N	Do not attempt to clean notchy or sticking switch.
12V528	11/8/2012 C0S	Safety Recall C0S - 2012 to early 2013 Model Scion iQ Vehicles Occupant Classification System (OCS)	11,101	9,615	86.61	N	
12V536	11/14/2012 C0U	Safety Recall C0U Remedy Notice - 2004 to certain 2009 Model Year Prius Vehicles Hybrid Electric Water Pump	345,202	275,624	79.84	N	
12V537	11/14/2012 C0T	Safety Recall C0T - 2004 to certain 2009 Model Year Prius Vehicles Steering Intermediate Extension Shaft	669,705	548,123	81.85	N	
12V542	11/23/2012 C0V	Safety Recall C0V Remedy - Certain 2001 - 2004 MY Tacoma Originally Sold In and/or Currently Registered in the Cold Climate States - Excessive Corrosion of the Spare Tire Carrier Lift Plate	168,303	56,827	33.76	N	
13V029	1/30/2013 D0B	Safety Recall D0B Remedy Notice - 2003 through 2004 Model Year Corolla and Corolla Matrix Vehicles - Supplemental Restraint System (SRS) Electronic Control Module (ECM)	760,179	313,019	41.18	N	
13V030	1/30/2013 DLA	Safety Recall DLA - Remedy Notice - 2006 Through Early 2012 Model Year IS 250 and IS 350, 2010 Through Early 2012 Model Year IS250C and IS 350C, and 2008 Through 2011 Model Year IS-F Front Wiper Arm Nut	267,720	190,055	70.99	N	Clear off any heavy snow and ensure the wipers are not frozen to windshield before turning on. If condition occurs while driving safety move the vehicle off the road.
13V098	3/15/2013 D0C	Safety Recall D0C - 2007 through 2013 Model Year FJ Cruiser Vehicles Access Door Inner Panel	215,259	110,040	51.12	N	
13V133	4/11/2013 D0F,DLC	Safety Recall D0F Remedy Notice - 2003 - 2004 MY Corolla, Corolla Matrix, and Tundra and 2002 - Early 2004 MY Sequoia Vehicles - Front Passenger Airbag Inflator Module; Safety Recall DLC - Remedy Notice - 2002 through certain 2003 Model Year and One 2004 Model Year SC 430 Vehicles - Front Passenger Air Bag Inflator	223,005	221,669	99.40	N	
13V163	4/25/2013 D0G	Safety (Non-Compliance) Recall D0G Remedy Notice - Genuine Toyota Auxiliary Light Kit Accessory Designed to fit 2007 to 2013 Model Year FJ Cruiser Vehicles	207,840	65,435	31.48	N	Inspect to see if vehicle has covered part
13V235	6/5/2013 D0H,DLD	Safety Recall D0H Remedy Notice - Certain 2010 Model Year Prius - Brake Booster Pump Assembly (Accumulator); Safety Recall DLD Remedy Notice - Certain 2010 Model Year HS 250h - Brake Booster Pump Assembly (Accumulator)	87,060	75,884	87.16	N	
13V292	7/3/2013 D0K	Safety Recall D0K Remedy Notice - Certain 2012 Model Year Yaris Lift Back Vehicles - Power Steering Control Module	74	51	68.92	N	
13V337	8/7/2013 D0L	Safety Recall D0L - Remedy Available - 2005 through 2011 Model Year Tacoma Access Cab Vehicles - Driver and Front Passenger Seat Belt Assemblies	342,451	123,839	36.16	N	
13V383	8/28/2013 CSJ	Safety Recall CSJ Remedy Notice - Certain 2006 through 2011 Model Year Toyota RAV4 Vehicles RE-INSPECTION REQUIRED for Rear Lower Suspension Arm No. 1	762,508	367,399	48.18	N	
13V395	9/4/2013 DLG	Safety Recall DLG Remedy Notice - Certain 2006 to 2011 Model Year IS350, Certain 2010 to 2011 Model Year IS350C and Certain 2007 to 2011 Model Year GS350 Vehicles - 2GR-FSE Intake VVT Actuator Gear	101,583	78,286	77.07	N	
13V396	9/4/2013 D0M,DLF	Safety Recall D0M Remedy Notice - Certain 2006 through 2010 Model Year Highlander HV Vehicles Intelligent Power Module (IPM) Replacement; Safety Recall DLF - Certain 2006 through 2008 Model Year RX 400H Vehicles Intelligent Power Module (IPM) Replacement	133,033	96,584	72.60	N	Until the remedy is performed, we recommend you take the following steps to help minimize the occurrence of this condition: (1) When parking the vehicle, always apply the parking brake. (2) After starting the engine, always step on the brake pedal before shifting from the P position. (3) Do not attempt to force the shift lever out of the P position. (4) Be careful not to damage the shift lever if you are moving between the front driver and passenger seats or let unattended children play in the vehicle.
13V429	9/26/2013 D0R	Safety Recall D0R Remedy Notice - Certain 2004 to 2005 and Certain 2007 to 2009 MY Sienna Vehicles - Shift Lock Solenoid	637,442	241,567	37.90	N	
13V442	10/17/2013 D0T	Safety Recall D0T Remedy Notice - Certain 2012 - 2013 MY Avalon, Camry, Camry Hybrid, Venza, and Certain 2013 MY Avalon Hybrid vehicles HVAC Assembly	813,366	633,772	77.92	N	Pay attention to the airbag and electrical power steering warning lights
13V505	10/17/2013 D0S	Safety (Non-Compliance) Recall D0S (D1S) Remedy Notice - Certain 2013 MY Avalon, Avalon Hybrid, Certain 2013 - 2014 MY Camry, Camry Hybrid, and Certain 2014 MY Corolla Vehicles - Windshield Wiper Switch	9,795	8,517	86.95	N	Do not use the mist setting on your windshield
13V557	11/7/2013 D0U	Safety Recall D0U Remedy Notice - Certain 2013 - 2014 MY Tacoma Vehicles Equipped with a 4 Cylinder Engine (2TR-FE) - Valve Spring Replacement (Toyota de Mexico - Certain 2013 MY Hiace)	4,640	3,222	69.44	N	
14V024	1/29/2014 E0B	STOP SALE - Pre-Delivery Activity Required for New Dealer Stock Noncompliance E0B - Remedy Notification - Multiple 2013 and 2014 MY Models	43,004	38,653	89.88	N	
14V051	2/7/2014 E0C	Safety (Non-Compliance) Recall E0C Remedy Notice - Certain 2014 MY Highlander Vehicles - 3rd Row Center Seat Belt	7,367	6,008	81.55	N	Don't sit occupants in the center seat on the 3rd row
14V053	2/12/2014 E0E	STOP SALE - Safety Recall E0E - Remedy Available - Certain 2010 - 2014 MY Prius Vehicles - Software Update for Motor Generator ECU and Power Management ECU	698,627	571,378	81.79	N	Avoid High Loads on the Hybrid System. Avoid full throttle application-Do not tow
14V054	2/12/2014 E0F,ELA	Safety Recall E0F - Remedy Notice - Certain 2012 and 2013 Model Year Tacoma Vehicles - Certain 2012 Model Year RAV4 Vehicles - Brake Actuator Reprogramming; Safety Recall ELA - Remedy Notice - Certain 2012 and 2013 Model Year RX350 Vehicles - Brake Actuator Reprogramming	269,303	200,550	74.47	N	Until the remedy is completed on your vehicle, please pay close attention to the Slip Indicator Light, ABS Warning Light, and/or the Brake System Warning Light (located in the instrument panel).

14V147	3/27/2014 E0G	Safety Recall E0G (Remedy) - 2003 and 2004 Model Year Avalon Vehicles Supplemental Restraint System (SRS) Electronic Control Module (ECU)	119,140	6,048	5.08 N	"Until the remedy is performed, please pay close attention to the SRS (airbag) Warning Light"
14V148	3/27/2014 E0H	Safety (Non-Compliance) Recall E0H - Remedy Notice Certain 2013 Model Year Highlander Vehicles 2nd Row Left Hand Seat Inboard Seat Track	47,217	29,685	62.87 N	Don't Lock the seat track in the first or second adjusting positions
14V168	4/9/2014 E0M	Safety Recall E0M - Remedy Notice Various Models - Spiral Cable Safety Recall E0L Remedy Certain 2006-10 MY Yaris Hatchback, Certain 2007-10 MY Yaris Sedan, Certain 2008-10 MY Scion xD - Driver Side Seat Track Assembly & Passenger Seat Track Assembly (3 Door) Yaris Hatchback)	1,512,824	31,977	2.11 N	"Until the remedy is performed, please pay close attention to the SRS (airbag) Warning Light"
14V169	6/12/2014 E0L	Safety Recall ELB - Remedy Notice - Certain 2013 Model Year GS350 Vehicles - Brake Pedal Load Sensing Switch	520,728	81,428	15.64 N	minimize frequent forward and rearward adjustment of the seat assembly Until the remedy is completed on your vehicle, please be aware there are no warnings or indicators of this condition. However, if the condition occurs, the Brake System Warning Light (located in the instrument panel) will illuminate.
14V270	5/22/2014 ELB	Safety (Noncompliance) Recall E0T - Remedy Notice Certain 2014 Model Year Highlander and Highlander Hybrid Vehicles Passenger Seatbelt Selectable Force Limiter - Software Update	10,462	6,055	57.88 N	
14V272	5/22/2014 E0T	Safety Recall EOS (E1S) Interim Notice - 2004 through Certain 2011 MY Toyota Sienna (2WD) Vehicles REVISED REMEDY UNDER DEVELOPMENT Excessive Corrosion of the Spare Tire Carrier Cable	50,751	36,522	71.96 N	
14V273	5/22/2014 E1S	Safety (Noncompliance) Recall E0R Remedy Notice - Certain 2014 MY Highlander Vehicles - 2nd Row Passenger-Side Inboard Seat Track for 60/40 Split Seat	419,519	18,149	4.33 N	Toyota dealer will relocate spare tire and provide roadside assistance
14V274	5/22/2014 E0R	Safety Recall DSC (D3C) (Supplement to DLC) - Interim Notice - 2002 through certain 2003 Model Year and One 2004 Model Year SC 430 Vehicles Front Passenger Airbag Inflator Module; Safety Recall DSC (Supplement to DLC) ♦ Remedy (Phase 1) - 2002 through certain 2003 Model Year and One 2004 Model Year SC 430 Vehicles - Front Passenger Air Bag Inflator Module; Safety Recall DSF (D3F) (Supplement to D0F) - Interim Notification 2003 - Certain 2004 MY Corolla, Corolla Matrix, and Tundra Vehicles & 2002 - Early 2004 MY Sequoia Vehicles Front Passenger Airbag Inflator Module; Safety Recall DSF (Supplement to D0F) ♦ Remedy (Phase 1) 2003-2004 Model Year Corolla, Corolla Matrix, and Tundra Vehicles 2002 - Early 2004 Model Year Sequoia Vehicles - Front Passenger Airbag Inflator Module	231	149	64.50 N	Don't Lock the Seat Track in the First - Third forward adjusting positions
14V312	6/10/2014 D3C,D3F,DSC,DSF	Special Service Campaign E0V (E1V) Prelim Product Investigation & Limited Regional Recall - Certain 2003 - 2005 MY Corolla, Corolla Matrix, Sequoia & Tundra Vehicles - Front Passenger Airbag Inflator Module; Special Service Campaign ELC (E2C) Prelim Product Investigation & Limited Regional Recall - Certain 2003 - 2005 MY SC430 Vehicles - Front Passenger Airbag Inflator Module	609,891	9,202	1.51 N	
14V350	6/20/2014 E1V,E2C	Safety (Non-Compliance) Recall E0W - Remedy Notice - Certain 2014 Model Year Sienna Vehicles - Transmission Shift Control Cable	78,854	0	0.00 N	
14V414	7/8/2014 E0W	Safety (Noncompliance) Recall E0X - Remedy Notice - Certain 2008 through 2014 Model Year Tacoma and FJ Cruiser Vehicles - Tire and Loading Info. Label - TRD Accessory Wheels and Toyota-recommended Light Truck Tires	263	188	71.48 N	
14V475	8/4/2014 E0X	Safety Recall E0Y - Remedy Notice - Certain 2014 Model Year FJ Cruiser Vehicles - Trail Teams Ultimate Edition Package ♦ Lower Ball Joint Bolts	445,598	31,554	7.08 N	"Until the remedy is completed on your vehicle, please be aware that, if a front lower ball joint bolt or front suspension lower arm bolt becomes loose or is missing, an abnormal steering vibration or pulling may be noticed and the tire could appear to be tilted out of alignment. If you experience abnormal steering vibration or pulling, or otherwise do not believe the steering or suspension systems are operating properly, please contact your local authorized Toyota dealer for diagnosis and repair"
14V539	8/28/2014 E0Y	Safety Recall E0Z - Remedy Notice - Certain 2014 Model Year Tundra Double and CrewMax Vehicles - Curtain Shield Airbag	2,501	471	18.83 N	
AWAITING#	9/11/2014 E0Z	Safety Recall E01 (E11) - Preliminary Notice - Certain 2014 Model Year Avalon, Camry, Highlander, and Sienna Vehicles Equipped with 2GR-FE Engine Potential Fuel Delivery Pipe Leak	132,664	30,947	23.33 N	
AWAITING#	9/18/2014 E11	Safety Recall ELD (E2D) - Preliminary Notice - Certain 2015 Model Year R 350 Vehicles Equipped with 2GR-FE Engine - Potential Fuel Delivery Pipe Leak	14,182	2,181	15.38 N	If you smell fuel while driving or immediately after driving contact your dealer.
AWAITING#	9/18/2014 E2D	Safety Recall E02 (E12) Preliminary Notification - Certain 2005-2011 Model Year Tacoma Pre-Runner and 4x4 Vehicles Rear Leaf Spring	3,650	920	25.21 N	If you smell fuel while driving or immediately after driving contact your dealer.
AWAITING#	9/29/2014 E12	Safety Recall ELF (E2F) - Preliminary Notice - Various Models - Potential Fuel Pressure Sensor Leak	732,948		0.00 N	
AWAITING#	10/15/2014 E2F	Safety Recall E04 - Remedy Notice - 2003-2005 Model Year Corolla, Corolla Matrix, and Tundra Vehicles - 2002-2005 Model Year Sequoia Vehicles - Front Passenger Air Bag Inflator Module	422,728		0.00 N	If you smell fuel while driving or immediately after driving contact your dealer.
AWAITING#	10/20/2014 E04	Safety Recall ELG - Remedy Notice - 2002 through 2005 Model Year SC 430 Vehicles - Front Passenger Air Bag Inflator Module	239,789		0.00 C	Do not use passenger seat until remedy completed. If you do not follow the instructions in this letter, you should not drive your vehicle
AWAITING#	10/20/2014 ELG	Total	6,804	26,431,558	0.00 N	Lexus recommends that you locate passengers into the rear seating positions