

U.S. Department of Transportation

National Highway Traffic Safety Administration

ODI RESUME

Investigation: PE 12-003

Date Opened:02/09/2012Date Closed:06/11/2012Investigator:Emily ReichardReviewer:Scott Yon

Approver: Frank Borris

Subject: Driver's Master Power Window Switch

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: GENERAL MOTORS LLC

Products: MY 2006-2007 Chevrolet Trailblazers

Population: 341,786

Problem Description: Melting and/or burning of the driver's master power window switch and related electrical

components.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	83	167	242**
Crashes/Fires:	11	21	28**
Injury Incidents:	0	0	0
Fatality Incidents:	0	0	0
Other*:	0	698	677**

^{*}Description of Other: Warranty claims describing melting and/or burning of driver side power window switch.

ACTION / SUMMARY INFORMATION

Action: This Preliminary Investigation has been upgraded to an Engineering Analysis (EA12-004).

Summary:

The Office of Defects Investigation (ODI) opened this investigation on February 9, 2012 in response to complaints alleging driver door module melting and/or burning in MY 2006-2007 Chevrolet Trailblazers. In response to ODI's Information Request letter, General Motors presented 167 reports and 698 warranty claims that related to the alleged problem. ODI has received a total of 83 complaints, 66 alleging the door module had melted or burned, and the remaining 17 stating that the window switches acted erratically or were inoperative. Twenty-eight of the reports received have led to driver door fires, some of which allege the vehicle was keyed off and unattended.

Based on the agency's current analysis, ODI has upgraded its investigation to an Engineering Analysis (EA12-004) to determine whether the subject vehicles contain a defect that presents an unreasonable risk to safety. The vehicle models and production dates of affected vehicles will be evaluated, particularly other GMT360 vehicles.

The ODI reports cited above can be reviewed online at www-odi.nhtsa.dot.gov/complaints under the following identification (ODI) numbers: 10247838, 10260600, 10274337, 10275626, 10284010, 10396958, 10406203, 10409023, 10414691, 10417938, 10423865, 10426281, 10434446, 10445657, 10447754, 10447757, 10447770, 10447788, 10447813, 10447831, 10447865, 10447880, 10447892, 10447938, 10447994, 10447996, 10447997, 10448028, 10448086, 10448138, 10448176, 10448201, 10448337, 10448455, 10448464, 10448478, 10448540, 10448900, 10448941, 10449150, 10449166, 10449169, 10449236, 10449722, 10450055, 10450202, 10450284, 10451584, 10451878, 10451918, 10452197, 10452301, 10452586, 10452743, 10452895, 10453161, 10453227, 10453261, 10453578, 10453746, 10453951, 10454196, 10457644, 10457811, 10458224, 10458485, 10458599, 10455279, 10455469, 10456285, 10456529, 10457116, 10457644, 10457811, 10458224, 10458485, 10458599,

Investigation: PE 12-003 Close Resume Page 1 of 2

^{**} Total eliminates duplicates received by ODI and manufacturer.

10458743, 10458846, 10460062, 10460141, 10460732, 10460843

Investigation: PE 12-003 Close Resume Page 2 of 2