



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 12-002
Date Opened: 02/06/2012
Investigator: Michael Lee
Approver: Frank Borris
Subject: Driver Door Fire
Reviewer: Scott Yon

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: TOYOTA MOTOR CORPORATION
Products: 2007 Toyota RAV4 and Camry
Population: 830,000 (Estimated)
Problem Description: Electrical fire originating in the driver's side door.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	6	TBD	TBD
Crashes/Fires:	6	TBD	TBD
Injury Incidents:	0	TBD	TBD
Fatality Incidents:	0	TBD	TBD
Other*:	0	TBD	TBD

*Description of Other:

ACTION / SUMMARY INFORMATION

Action: Open a Preliminary Evaluation.

Summary:

ODI has received 6 consumer complaints, and other manufacturer reports supplied through Early Warning Reporting data submissions, alleging a fire in the driver's side door on model year 2007 Toyota RAV4 and Camry vehicles. Based on the available information, it appears the fires are originating from the power window master switch located on the driver's door.

An investigation has been opened to evaluate the alleged defect in the subject vehicles.

The ODI reports cited above can be viewed at www-odi.nhtsa.dot.gov/complaints under the following identification (ODI) numbers: 10446699, 10436663 10429983 10411328 10394453 10323848