

U.S. Department of Transportation

National Highway Traffic Safety Administration

# **ODI RESUME**

Investigation: PE 12-012 Date Opened: 05/10/2012

Investigator: Michael Lee Reviewer: Scott Yon

**Approver:** Frank Borris

**Subject:** Side Curtain Air Bag Improper Deployment

### MANUFACTURER & PRODUCT INFORMATION

Manufacturer: HYUNDAI MOTOR COMPANY

**Products:** 2012 Hyundai Elantra **Population:** 123,000 (Estimated)

**Problem Description:** The improper deployment of the driver-side curtain air bag resulted in a laceration to the

driver's ear/face.

## FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	1	TBD	TBD
Crashes/Fires:	0	TBD	TBD
Injury Incidents:	1	TBD	TBD
Number of Injuries:	1	TBD	TBD
Fatality Incidents:	0	TBD	TBD
Number of Fatalities:	0	TBD	TBD

### **ACTION / SUMMARY INFORMATION**

**Action:** Open a Preliminary Evaluation.

#### **Summary:**

ODI has received a complaint of an improper deployment of the driver-side curtain air bag that deployed as a result of a crash. The photographs of the model year 2012 Hyundai Elantra provided by the vehicle owner show a metal component protruding from the left edge of the headliner above the driver's seat. It appears that the metal component caused a laceration to the driver's ear/face.

An investigation has been opened to evaluate the alleged defect in the subject vehicles.

The ODI report cited above can be viewed at www-odi.nhtsa.dot.gov/complaints under the following identification (ODI) number: 10457696

Investigation: PE 12-012 Open Resume Page 1 of 1