

INFORMATION Redacted PURSUANT TO THE FREEDOM OF  
INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup



1699

Jeep







Jeep  
4x4

Jeep  
LIBERTY

3.7L

[Redacted license plate]





LIBERTY

MFD BY DAIMLERCHRYSLER  
CORPORATION

DATE OF MFR  
5-02

GWR  
2541 KG(05600 LB)

GAWR FRONT	WITH TIRES	RIMS AT	COLD
1248 KG(2750 LB)	235/70R16	16X7	227 KPA(33
GAWR REAR	WITH TIRES	RIMS AT	COLD
1429 KG(3150 LB)	235/70R16	16X7	227 KPA(33

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY AND THE PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VIN: 1J4GL58KX2W [REDACTED] TYPE: MPV SINGLE X DUAL



MOI:

051412 779AA PNT:PX8

VEHICLE MADE IN U.S.A. TRM:DLD2 4648503







Jeep  
LIBERTY

3.7L

A close-up photograph of a grey metal component, likely a part of a mechanical assembly. The component features a row of six yellow pins or contacts along its length. The background is dark and out of focus. A green wire is visible on the left side. The text "left 'D' ring" is overlaid in yellow on the image.

left "D" ring

left belt latch

10089



left belt latch

**TRW**

H01-07

left frt belt label

174023R

MEETS FMVSS 209  
ASSEMBLED IN MEXICO

# **! WARNING**



## **DEATH OR SERIOUS INJURY CAN OCCUR**

- CHILDREN 12 AND UNDER CAN BE KILLED BY THE AIR BAG.
- THE **BACK SEAT** IS THE **SAFEST PLACE** FOR CHILDREN.
- **NEVER** PUT A REAR-FACING CHILD SEAT IN THE FRONT.
- SIT AS FAR BACK AS POSSIBLE FROM THE AIR BAG.
- **ALWAYS USE SEAT BELTS AND CHILD RESTRAINTS.**



E  
GE  
FULLY!





right belt latch

A close-up photograph of a grey plastic seatbelt buckle. A dark-colored fabric strap is inserted into the buckle. The buckle has a D-shaped opening. A person's finger is visible on the left side, holding the buckle. The background is blurred, showing some green and blue colors.

right belt "D" ring

**TRW**

H01-06

176029R

MEETS FMVSS 209  
ASSEMBLED IN MEXICO

right belt label



right fit belt latch

10085

ORC DTCs 1 of 5

INTERNAL 1

MINUTES: 339 IGN CNTS: 0

--- DTC 2 of 5 ---

PASSENGER SOUTB 1

SHORT TO GROUND

MINUTES: 1 IGN CNTS: 35

DTC TYPE

1. Active
2. Stored

— ORC DTCs 1 of 1

INTERNAL 1

Reading Stored DICs



AIRBAG Module Information

2002 Body Style: KJ

Part#: 56010501AG

S/W Version: 05.05

TRW Gen V

Front Dr and Pass/PCI Bus SAB  
and Lamp Dr w/On/Off Sw or AOSIM



DRIVEN

-- ORC DTCs 3 of 5 --

STORED ENERGY  
FIRING 1

MINUTES: 39 IGN CNTS: 29

--- DTC 4 of 5 ---

DRIVER SQUIB 2  
SHORT TO GROUND

MINUTES: 1 IGN CNTS: 35

-- ORC DTCs 5 of 5 --

PASSENGER SQUIB 2  
SHORT TO GROUND

MINUTES: 1 IGN CNTS: 35

-- DTC 1 of 5 --

INTERNAL 1

MINUTES: 342 IGN CNTS: 0

-- ORC DTCs 5 of 5 --

PASSENGER SQUIB 2  
SHORT TO GROUND

MINUTES: 1 IGN CNTS: 35

--- DTC 1 of 5 ---

1

MINUTES: 342 IGN CNTS: 0







Date:9/4, 2004

FAX TO: Mr. Porterfield

Fax # 248-512-8748

Subject: Cair # 12601751 -slaughter , copy of damage report 10/23/2003

From: Lyle Beckman, EAA -913-825-3670

# of pages with cover: 5



CAIR #  
12601751  
Slaughter

SCHULER / COLLISION DAMAGE APPRAISAL SERVICE  
P.O. BOX 85  
GRANDVIEW, MO 64030  
PHONE: (816) 331-3785 FAX: (816) 331-3785

CD LOG NO 398

-1  
SUPPLEMENT

DATE 10-23-03

CLAIM INFORMATION

CLAIM #  
COMPANY  
INSURED  
CLAIMANT



POLICY #  
CLAIM REP  
LOSS DATE 08-14-03  
LOSS TYPE COLLISION



INSPECTION

TYPE INDEPENDENT FIELD  
PRIMARY POI FRONT END RIGHT  
APPRAISER NAME TERRY SCHULER  
WORK PHONE (816) 331-3785  
ADDRESS P O BOX 85  
CITY STATE GRANDVIEW MO  
ZIP 64030-

SECOND POI  
FAX (816) 331-3785  
INSP DATE 08-18-03  
LOCATION OP JEEP  
CITY STATE OP

KS

OWNER



WORK#  
HOME#



REPAIR

ATTN TERRY  
OVERLAND PARK JEEP  
8775 METCALF  
OVERLAND PARK KS 66212-  
SHOP PHONE (913) 381-8100

SHOP LIC#  
CAR IN  
CAR OUT  
REPAIR DAYS  
REG. ID 48-0794879  
FAX (913) 381-7523

VEHICLE

2002 JEEP LIBERTY LIMITED 4 DR WAGON  
6CYL GASOLINE 3.7

OPTIONS

TWO-STAGE - EXTERIOR SURFACES  
POWER DOOR LOCKS  
LUGGAGE RACK  
AIR CONDITIONING  
CRUISE CONTROL

4-WHEEL DRIVE  
POWER WINDOWS  
TILT STEERING WHEEL  
AUTOMATIC TRANS

BODY COLOR BLK  
CONDITION GOOD  
LICENSE # 547CPB  
LICENSE STATE MO

MILEAGE  
VIN 1J4GL58KX2W339030  
CODE J725  
VEH INSP #

2002 JEEP LIBERTY LIMITED 4 DR WAGON  
 CLAIM # [REDACTED]

DATE 10-23-03  
 LOG 398 -1

L	0073	PANEL ASSEMBLY, RAD SU	REFINISH			1.3 4
			1.3 Surface			
E	0072	CRSMBR, RAD PANEL UPR	55176763AC	32.00		INC 1
L	0072	CRSMBR, RAD PANEL UPR	REFINISH			0.5 4
			0.5 Surface			
E	0024 07	CRSMBR, RAD PNL LOWER	55360190AD	71.00		1.9 1
E	0755	RADIATOR	52080118AB	212.00		0.2 1
E	0102 01	TRAY, BATTERY	LT 55360084AD	25.85	S1	0.3 1
N	0987	A/C EVAC RECHRG & RCV	ADDITIONAL LABOR			1.9 2
E	0731	CONDENSER, A/C	55037465AB	380.00		0.2 2
I	0106 07	PANEL, INNER FENDER	RT REPAIR		S1	4.0*1
I	0142 07	WHLHS, FRT FENDER IN	RT REPAIR			6.0*1
L	0142	WHLHS, FRT FENDER IN	RT REFINISH			0.3 4
			0.3 Surface			
I	0572	CRADLE, ENGINE	REPAIR		S1	4.0*1*
E	0104	FENDER, FRONT	RT 55177100AC	132.00		0.3 1
L	0104	FENDER, FRONT	RT REFINISH			2.1 4
			1.3 Surface			
			0.5 Edge			
			0.3 Two-stage			
RI	0132	MAST, ANTENNA	RT R&I ASSEMBLY			0.1 1
RI	0382	GUARD, FENDER MUD	RT R&I ASSEMBLY			INC 1
E	0124	BRKT, FLARE MOUNTING	RT 55155988AB	8.60	S1	INC 1
I	0265	FLARE, WHEEL OPENING	LT REPAIR		S1	1.0*1
L	0265	FLARE, WHEEL OPENING	LT REFINISH		S1	1.4 4
			1.2 Surface			
			0.2 Two-stage			
E	0266 01	FLARE, WHEEL OPENING	RT 5GH00TZZAE	220.00		INC 1
L	0266	FLARE, WHEEL OPENING	RT REFINISH		S1	1.4 4
			1.2 Surface			
			0.2 Two-stage			
E	0112	SHIELD, FRONT SPLASH	RT 55360144AG	26.35		INC 1
E	0822	AIR CLEANER ASSEMBLY	53013108AA	122.00		INC 2
E	1060	PUMP, WASHER	5066880AA	93.85	S1	INC 1
E	0149	RESERVOIR, W/S WASHER	5066867AA	84.25		0.7 1
RI	0577	PAD, SIDE STEP PANEL	RT R&I ASSEMBLY			0.6 1
I	M18	SET-UP AND MEASURE	REPAIR			1.5*1*
EC	M20	ANTI-FREEZE-COOLANT	REPLACE ECONOMY	24.50*	S1	1
I		ALIGNMENT	SUBLET	59.95*	S1	1
E		LUBRICANT	REPLACE OEM	28.50*	S1	1
E		HEATER HOSE	REPLACE OEM	94.86*	S1	1.0*2*
I		WIRING	REPAIR		S1	2.0*1*

55 ITEMS

MC MESSAGE

01 CALL DEALER FOR EXACT PART # / PRICE  
 07 STRUCTURAL PART AS IDENTIFIED BY I-CAR

FROM : LJB

10/23/03 11:01am P 007

2002 JEEP LIBERTY LIMITED 4 DR WAGON  
CLAIM # [REDACTED]

DATE 10-23-03  
LOG 398 -1

REMARKS:  
PLEASE MAIL SUPPLEMENT PAYMENT DIRECTLY TO SHOP  
DRV-NO  
PHOTOS ON SCENE GENESIS  
PROD DATE 5/02  
LICENSE EXPIRATION DATE MAY04

OP CODES:

* = USER-ENTERED VALUE	E = REPLACE OEM	NG = REPLACE NAGS
EC = REPLACE ECONOMY	UC = RECONDITIONED PRT	UM = REMAN/REBUILT PRT
EU = LIKE KIND & QUAL. PRT	EP = REPLACE PXN	PC = PXN RECONDITIONED
PM = PXN REMAN/REBUILT	TE = PARTL REPL PRICE	ET = PARTL REPL LABOR
IT = PARTIAL REPAIR	I = REPAIR	L = REFINISH
BR = BLEND REFINISH	TT = TWO-TONE	CG = CHIPGUARD
SB = SUBLET	N = ADDITIONAL LABOR	RI = R&I ASSEMBLY
P = CHECK	AA = APPEAR ALLOWANCE	RP = RELATED PRIOR
UP = UNRELATED PRIOR		

OP	GDE	MC	DESCRIPTION	MFR. PART NO.	PRICE	AJ%	B%	HOURS	R
J			UNIBODY-FRAME INCL SET REPAIR					5.0*3*	
E	0025	01	COVER, FRONT BUMPER	5066606AB	400.00			0.7	1
L	0025		COVER, FRONT BUMPER	REFINISH				3.5	4
			2.4 Surface						
			0.6 Two-stage setup						
			0.5 Two-stage						
E	0048		BRACKET, LICENSE MTG	5288487	39.20		S1	0.2	1
E	0069		ABSORBER, FRONT BUMPER	55156042AD	65.10			INC	1
E	0028		GRILLE ASSEMBLY	55156608AA	180.00			0.2	1
L	0028		GRILLE ASSEMBLY	REFINISH				2.5	4
			2.1 Surface						
			0.4 Two-stage						
E	0047		SENSOR, TEMPERATURE	56042395	33.75		S1	INC	1
E	0041		HEADLAMP ASSEMBLY	LT 5101821AA	234.00		S1	INC	1
E	0042		HEADLAMP ASSEMBLY	RT 55155808AA	234.00		S1	INC	1
N	0973		HEADLAMPS AIM	ADDITIONAL LABOR				0.5	1
E	0033		PANEL, HEADLAMP MTG	55155800AC	179.00			0.4	1
E	0014		PARKLAMP ASSEMBLY	RT 55155910AB	32.00			INC	1
E	0056		LAMP ASSEMBLY, FOG	RT 5083896AA	115.00			INC	1
I	0083		PANEL, HOOD	REPAIR				4.0*1	
L	0083		PANEL, HOOD	REFINISH				3.1	4
			2.6 Surface						
			0.5 Two-stage						
E	0062		N/PLATE, HOOD PANEL	55156554AB	20.75				
E	0088		LATCH, HOOD PANEL	55156554AB					

10/23/03 11:01am P. 004

2002 JEEP LIBERTY LIMITED 4 DR WAGON

DATE 10 23 03



DATE 10-23-03  
LOG 398 -1

FINAL CALCULATIONS & ENTRIES  
PARTS

GROSS PARTS \$ 3,183.41  
OTHER PARTS \$ 24.50  
PAINT MATERIAL \$ 402.50

ADJUSTMENTS DISCOUNT MARKUP  
PARTS TOTAL \$ 3,610.41  
TAX ON PARTS & MATERIAL @ 7.525% \$ 271.68

LABOR	RATE	REPLACE HRS	REPAIR HRS		
1-SHEET METAL	\$ 42.00	17.0	25.0	\$	1,764.00
2-MECH/ELEC	\$ 86.00	1.2	1.9	\$	266.60
3-FRAME	\$ 55.00		5.0	\$	275.00
4-REFINISH	\$ 42.00	16.1		\$	676.20
5-PAINT	\$ 25.00				

LABOR TOTAL \$ 2,981.80  
TAX ON LABOR @ 7.525% \$ 224.38  
TAX ON SUBLET @ 7.525% \$ 4.51  
SUBLET REPAIRS \$ 59.95  
TOWING \$ 375.00  
STORAGE

GROSS TOTAL \$ 7,527.73  
LESS: DEDUCTIBLE \$ 250.00-

NET TOTAL \$ 7,277.73

LESS: PREVIOUS NET TOTAL \$ 5,441.47-

NET SUPPLEMENT TOTAL \$ 1,836.26

PXN Y/00/00/00/00/00 CUM 00/00/00/00/00 Geocode: 66204 OVERLAND PARK KANSAS  
ADP PENPRO W0405 S1 LOG398 -1 10-23-03 10:30:54 REL 4.05 SW09/03 DT10/03  
(C) 1993 - 2003 ADP CLAIMS SOLUTIONS GROUP, INC.

2.7 HRS WERE ADDED TO THIS EST. BASED ON ADP'S TWO-STAGE REFINISH FORMULA.  
"THIS IS NOT AN AUTHORIZATION TO REPAIR."

"REPAIRS MUST BE AUTHORIZED BY VEHICLE OWNER. REPAIRER AGREES TO COMPLETE LISTED REPAIRS IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS FOR TOTAL COST OF REPAIRS AND TO CONTACT APPRAISER FOR VERIFICATION OF ANY LOSS RELATED DAMAGE THAT MAY BE DISCOVERED BEFORE OR DURING REPAIRS."

"THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF ONE OR MORE CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE PARTS

WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE PARTS

913 492 2564

PAGE.04

SEP 04 2004 15:04

**CONFIDENTIAL - Prior Approval Required Before Duplicating****Preliminary Vehicle Investigation Report(PVIR)**

CAIR# 12601751

YEAR	BRAND	VEHICLE IDENTIFICATION NUMBER		MO/DY-HR	ODOMETER	IN-SERVICE
2002	JEEP LIBERTY LTD EDITION 4X4 SPORT UTILITY 4-DR	1J4GL58KX2W [REDACTED]		05-14 12	28664	06/13/2002
NAME OF OWNER		ADDRESS/LOCATION		CITY	STATE	COUNTRY
[REDACTED]		[REDACTED]		KANSAS CITY	MO	USA
ZIP	COLOR	MODEL	HOME PHONE		BUSINESS PHONE	
[REDACTED]	Black Clear Coat	KJJ	[REDACTED]		[REDACTED]	
SELLING DEALER NAME		BUSINESS CENTER	DLR. CODE	CITY	STATE	COUNTRY
OVERLAND PARK JEEP INC		74	23633	OVERLAND PARK	KS	USA
INSPECTOR - NAME FIRST, LAST, MIDDLE		INSPECTOR'S COMPANY		INSPECTOR'S PHONE NO.		
Lyle Beckman J		EAA`		913-825-3670		
DAMAGE ESTIMATE				REPAIR ESTIMATE		
<input type="radio"/> MINOR <input checked="" type="radio"/> MODERATE <input type="radio"/> TOTAL LOSS				\$ .00		

**INTERVIEW**

INTERVIEW WITH:

 DRIVER  OWNER  OTHER  DRIVER/OWNER

NAME: LAST, FIRST, MIDDLE

[REDACTED]

INTERVIEW DATE:

DATE OF INCIDENT:

TIME OF INCIDENT

INSPECTION DATE:

**09/04/2004****08/30/2004****03:30**  AM  PM**09/03/2004**

1. DRIVER'S

DESCRIPTION OF EVENT:

**Owner stated that she was just leaving work and noticed her air bag light was on, when she stopped at a stop light the air bags deployed. Owner stated that she had an accident about 1 year ago and had frontal damage but the bags did not deploy at that time. Owner states that the air bag light did not come on at any other time except when she turned the ignition switch on and then it always went off after a few seconds.**

Insurance

Company

Name:

Personal Injury:

Were there

 Yes  No

Personal

If Yes, complete section "B"

Injuries?

Any Indicator/

Warning Lights

 Yes  No

on Prior?

If Yes, What light: **air bag light**

**IMPORTANT: SHOW THIS REPORT TO NO ONE & ONLY STATE FACTS (DRAW NO CONCLUSIONS)**

Help Key

**PART A- GENERAL**

**REQUIRED PHOTOGRAPHS:** ALL FOUR SIDE VIEWS**IF CRASH DAMAGED:**

PERSPECTIVE FROM EVERY  
CORNER OF VEHICLE DOWN  
BOTH ORIGINAL LATERAL  
SIGHT LINES(8 TOTAL)

- ANY RECENT VEHICLE  
SERVICE

YES  NO

UNKNOWN

IF YES, ENCLOSE COPIES OF  
REPAIR ORDERS

**INFORMATION:** POLICE/AGENCY REPORT #:

ALL REPORTS/PHOTOS BY  
OTHERS

- ADDRESS OF INSPECTION

Address **Overland Park Jeep**

1

Address **8775 Metcalf**

2

City **Overland Park**

State **KS**

Zip **66210**

Phone **913-381-8100**

- EVIDENCE OF TAMPERING OR PRIOR  
DISASSEMBLY

YES  NO

- IF YES, DESCRIBE AND PHOTOGRAPH

---



---

### PART B - EXTERIOR/INTERIOR VEHICLE DAMAGE

---

**REQUIRED PHOTOGRAPHS:** The vehicle exhibits no damage except the drivers side and passenger side air bag deployment. no injuries reported

 WINDSHIELD

ALL AREAS OF DAMAGE  
MARKINGS ON INTERIOR  
AND EXTERIOR

CLOSE UPS OF STAINS,  
SKIN, HAIR, CLOTH

EXTERIOR AND INTERIOR  
DAMAGE INCLUDING  
UNDERCARRIAGE

**INFORMATION:**

DESCRIBE ANY INJURIES  
TO DRIVER AND/OR OTHER  
OCCUPANTS

SEE SEAT BELT/SEATS  
SECTION IF APPLICABLE

---



---

Next

**PART C - AIRBAG(S)**

**REQUIRED PHOTOGRAPHS**

- STEERING WHEEL
- AIRBAG(S)
- KNEE BLOCKERS
- ALL POSSIBLE LOCATIONS OF CONTACT

**AECM INFORMATION**

- SOFTWARE VERSION:

**05.05**

- SERIAL NUMBER :

- PART NUMBER :

**5601050**

- DOES AIRBAG WARNING LIGHT CYCLE ON?

YES  NO  N/A

- ARE WARNING LABELS PRESENT (PHOTO)

YES  NO  N/A

- RECORD LABEL PART NUMBER

**na**

**COMPLETE PART D**

- PHOTOGRAPH REQUIRED FOR DRB SCREENS & RECORD FAULTS

- WERE THERE DRB READINGS TAKEN?

YES  NO IF NO, EXPLAIN

- RECORD ACTIVE DTC'S EXACTLY AS APPEAR :	MIN	COUNT
<b>internal 1</b>		
- RECORD STORED DTC'S (MINUTES/COUNTS) :	MIN	COUNT
<b>internal 1</b>	<b>340</b>	<b>1</b>
<b>Passenger squib 1 short to grd</b>	<b>1</b>	<b>35</b>
<b>stored energy firing 1</b>	<b>39</b>	<b>29</b>
<b>Driver Squib 2 short to grd</b>	<b>1</b>	<b>35</b>
<b>Passenger Squib 2 short to grd</b>	<b>1</b>	<b>35</b>

- WAS AIRBAG DEPLOYED?

DRIVER  YES  NO

IF NO, EXPLAIN

PASSENGER  YES  NO

IF NO, EXPLAIN

SIDE AIRBAG  YES  NO  N/A

IF NO, EXPLAIN

- WHICH SIDE DEPLOYED?

LEFT  RIGHT  N/A

BOTH

- TYPE OF SIDE AIRBAG

SEAT  CURTAIN  N/A

- TYPE OF STEERING WHEEL

TILT  STANDARD

- ANY DAMAGE TO STEERING WHEEL

YES  NO

IF YES, EXPLAIN

**DO NOT ERASE DRB READINGS**

IS VEHICLE EQUIPPED WITH PASSENGER AIRBAG DEFAULT SWITCH?

YES  NO

IF YES,

NOTE POSITION OF PASSENGER A/B SWITCH

ON  OFF  N/A

- EVIDENCE OF TAMPERING OR DISASSEMBLY?

YES  NO  N/A

IF YES, EXPLAIN

CHECK ENTIRE UNDERBODY FOR HIDDEN DAMAGE INCLUDING FRONT AND REAR SUSPENSION COMPONENTS

- UNDERBODY DAMAGED?

YES  NO

IF YES, EXPLAIN

PHOTOGRAPH REQUIRED

**PART D - SEATS/SHOULDER BELTS**

**REQUIRED**

**PHOTOGRAPHS:**

- OVERALL SEAT BELTS I/B & O/B
- CLOSE UP OF ANY IRREGULARITIES
- LATCHPLATE WEAR
- CLOSE UP D-RING TO SHOW LOADING
- OVERALL OF SEAT
- CLOSE UP OF DAMAGE
- RECORD DTC'S:

**INFORMATION:**

- LOCATE SEAT BELT LABELS AND RECORD ALL INFORMATION (SOME LABELS ARE SEWN TO WEBBING, OTHER LABELS ARE ON THE RETRACTOR FRAME: INBOARD SEAT BELT LABELS ARE NEAR THE FLOOR): **Rt-TRW H01-06,176029R Left TRW H01-07, 174023R**
- RECORD ALL INFORMATION STAMPED ON LATCHPLATE **Rt side-- TD085 Left side-TD086**
- PRETENSION DEPLOYED?  YES  NO  UNKNOWN
- EXISTING LOCATION OF RECLINER - DESCRIBE THE LOCATION AND PICTURE OF SEAT BACK WITH B PILLOR AS REFERENCE AND INCLINOMETER READING **65 degree angle**
- EXISTING LOCATION OF HEAD RESTRAINT (MEASURE GAP UNDER HEAD RESTRAINT):

IF ALLOWED. FUNCTION BELTS TO INSURE THEY FUNCTION PROPERLY

NOTE RESULTS

- DOES THE BUCKLE LATCH?

YES  NO

IF NO, EXPLAIN

- DO THEY RELEASE?

YES  NO

IF NO, EXPLAIN

- DO THEY RETRACT?

YES  NO

IF NO, EXPLAIN

- ANY LOOSENESS OR BROKEN PARTS

YES  NO

IF YES, EXPLAIN?

- CHECK FOR SEAT RETAINING BOLTS

NORMAL

BROKEN

LOOSE

MISSING

- NOTE AND RECORD APPROX. SEAT TRACK



OVERLAP  
**0-overlap**

---

---

**PART - E TRANSMISSION NOT APPLICABLE**

---

---

Previous

Next

---

**PART - F UNINTENDED ACCELERATION NOT APPLICABLE**

---

**PART - G BRAKES NOT APPLICABLE**

---

**PART - H STEERING/SUSPENSION/TIRES NOT APPLICABLE**

---

**PART - I AXLE/DIFFERENTIAL NOT APPLICABLE**

---

 **PART J - ADDITIONAL COMMENTS (DO NOT DRAW ANY CONCLUSIONS)**

---

The vehicle does not show any damage to the exterior, interior or undercarriage. Both left and right passenger airbags are deployed. A copy of the repairs to the vehicle on 10/23/03 (collision damage) shows front end damage and repair for a total of \$7,527.73. The air bags did not deploy or were not listed in repairs.

---

[Previous](#)[Form Approved](#)[Returned for corrections](#)

EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup

From: [REDACTED]  
To: customerassist@daimlerchrysler.com  
Date: Fri Sep 10 18:16:00 EDT 2004  
Subject: Reply to DaimlerChrysler (KMM1890167C0KM)  
Reply Comments:

-----  
Reference Number: 12609837

Your response indicated that I talked to someone at DaimlerChrysler by phone. I've only spoken to the service department at Overland Park Jeep. As of today, I haven't heard the status of my Jeep Liberty. However, I've been informed that a report has been sent in and that I will be contacted by Chrysler.

[REDACTED]

From: customerassist@daimlerchrysler.com  
To: [REDACTED]  
Date: Fri Sep 10 09:30:20 EDT 2004  
Subject: Re: DaimlerChrysler Customer Assistance  
Dear [REDACTED]

Thank you for your email to DaimlerChrysler Motors Corporation regarding the  
airbag concern you stated you had with your Jeep Liberty.

Our records show that you have contacted us by telephone and we have addressed  
your concern. We have updated your file to reflect the latest information you  
provided in the email message.

If your concerns have not been addressed, or you have other concerns, please  
email or contact the DaimlerChrysler Customer Assistance Center by telephone at  
1-800-992-1997, 8:00 a.m. to 5:00 p.m., Monday through Friday.

Thank you again for your email.

NOTE: Please do not use the 'Reply' function of your email system. If you have a  
need to respond to this message, please visit us at our reply form (link  
provided below). Our system is NOT able to accept any emails at this address.

For any future communications related to this email, please refer to the  
following information:

REFERENCE NUMBER: 12609837

REPLY LINK:

[http://www.chrysler.com/wccsapp/wccs/brand\\_forms/us/reply.jsp?trk\\_ID=KMM1890167C  
0KM&](http://www.chrysler.com/wccsapp/wccs/brand_forms/us/reply.jsp?trk_ID=KMM1890167C0KM&)

Sincerely,

Kristen  
Senior Staff Representative  
DaimlerChrysler Customer Assistance Center

Original Message Follows:

-----  
Form Selected:  
-----

Category: Recall Information

Brief Description:  
-----

The airbags on my 2002 Jeep Liberty deployed.

Comments:  
-----

My Jeep Liberty had not been hit nor did I hit anything. I had just left  
work. Drove about one block and a half when I noticed the airbag indicator  
light on. By the time I reached the stop sign the airbags deployed. This  
happened on Monday, August 30, 2004. Have you had this problem with other  
2002 Jeep Liberties?

Sender Information:  
-----

Title: Mrs.  
First Name: [REDACTED]

Middle Initial: D

Last Name: [REDACTED]

From: [REDACTED]  
To: customerassistre@daimlerchrysler.com  
Date: Mon Sep 06 16:02:42 EDT 2004  
Subject: DaimlerChrysler Customer Assistance  
Form Selected:

-----  
Category: Recall Information  
Brief Description:

-----  
The airbags on my 2002 Jeep Liberty deployed.

Comments:

-----  
My Jeep Liberty had not been hit nor did I hit anything. I had just left work. Drove about one block and a half when I noticed the airbag indicator light on. By the time I reached the stop sign the airbags deployed. This happened on Monday, August 30, 2004. Have you had this problem with other 2002 Jeep Liberties?

Sender Information:

-----  
Title: Mrs.  
First Name: [REDACTED]  
Middle Initial: [REDACTED]  
Last Name: [REDACTED]

EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup



From: customerassist@daimlerchrysler.com  
To: [REDACTED]  
Date: Tue Oct 05 13:50:48 EDT 2004  
Subject: Re: DaimlerChrysler Customer Assistance  
Dear [REDACTED]

Thank you for your recent email to DaimlerChrysler Motors regarding your 2002 Jeep Liberty.

Our records show that you have contacted us by telephone and we have addressed your concern. We have updated your file to reflect the latest information you provided in the email message.

If your concerns have not been addressed, or you have other concerns, please email or contact the DaimlerChrysler Customer Assistance Center by telephone at 1-800-992-1997, 8:00 a.m. to 5:00 p.m., Monday through Friday.

Thank you again for your email.

NOTE: Please do not use the 'Reply' function of your email system. If you have a need to respond to this message, please visit us at our reply form (link provided below). Our system is NOT able to accept any emails at this address.

For any future communications related to this email, please refer to the following information:

REFERENCE NUMBER: 12687901

REPLY LINK:

[http://www.chrysler.com/wccsapp/wccs/brand\\_forms/us/reply.jsp?trk\\_ID=KMM1950026C0KM&](http://www.chrysler.com/wccsapp/wccs/brand_forms/us/reply.jsp?trk_ID=KMM1950026C0KM&)

Sincerely,

Cody Tucker  
Senior Staff Representative  
DaimlerChrysler Customer Assistance Center

Original Message Follows:

-----  
Form Selected:  
-----

Category: US Customer Service

Brief Description:  
-----

Airbags deployed because of malfunction in the computer.

Comments:  
-----

Sender Information:  
-----

Title: Mrs.

First Name: [REDACTED]

Middle Initial: [REDACTED]

Last Name: [REDACTED]

From: [REDACTED]  
To: customerassist@daimlerchrysler.com  
Date: Fri Oct 01 00:38:57 EDT 2004  
Subject: DaimlerChrysler Customer Assistance  
Form Selected:

-----  
Category: US Customer Service  
Brief Description:

-----  
Airbags deployed because of malfunction in the computer.

Comments:

-----  
Sender Information:

-----  
Title: Mrs.  
First Name: [REDACTED]  
Middle Initial: [REDACTED]  
Last Name: [REDACTED]

EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup

From: customerassist@daimlerchrysler.com  
To: [REDACTED]  
Date: Mon Feb 21 15:15:32 EST 2005  
Subject: Re: DaimlerChrysler Customer Assistance  
Dear [REDACTED]

Thank you for your email regarding your 2002 Jeep Liberty.

I have reviewed the information regarding the unfortunate deployment of your airbags back in 2004. After carefully considering the situation we will have to decline providing any assistance in additional repairs.

Although a more favorable reply could not be provided, sharing your concern with us is appreciated.

Thank you again for your email.

NOTE: Please do not use the 'Reply' function of your email system. If you have a need to respond to this message, please visit us at our reply form (link provided below). Our system is NOT able to accept any emails at this address.

For any future communications related to this email, please refer to the following information:

REFERENCE NUMBER: 13193069

REPLY LINK:

[http://www.chrysler.com/wccsapp/wccs/brand\\_forms/us/reply.jsp?trk\\_ID=KMM2378534C0KM&](http://www.chrysler.com/wccsapp/wccs/brand_forms/us/reply.jsp?trk_ID=KMM2378534C0KM&)

Sincerely,

Jeremy  
Senior Staff Representative  
DaimlerChrysler Customer Assistance Center

Original Message Follows:

-----  
Form Selected:  
-----

Category: US Customer Service

Brief Description:  
-----

Airbag deployment / steering column looseness

Comments:  
-----

The airbags in my vehicle activated inadvertently last January. (chrysler sent an engineer to investigate). Chrysler replaced the airbags at no cost to me.

I noticed looseness in the steering whell after I picked up the vehicle. The looseness continued to get more pronounced. I asked my dealer service man about the looseness and he said it was not related to the airbag deployment.

However since then I have been told by 2 sources that it is standard practice to replace the steering column whenever an

airbag deployment occurs. I would like Chrysler to repair my steering column for me.

Sender Information:

-----

Title: Dr.

First Name:

Middle Initial:

Last Name:



From: [REDACTED]  
To: customerassist@daimlerchrysler.com  
Date: Thu Feb 17 12:42:48 EST 2005  
Subject: DaimlerChrysler Customer Assistance  
Form Selected:

-----  
Category: US Customer Service  
Brief Description:

-----  
Airbag deployment / steering column looseness

Comments:

-----  
The airbags in my vehicle activated inadvertently last January. (chrysler sent an engineer to investigate). Chrysler replaced the airbags at no cost to me.

I noticed looseness in the steering whell after I picked up the vehicle. The looseness continued to get more pronounced. I asked my dealer service man about the looseness and he said it was not related to the airbag deployment.

However since then I have been told by 2 sources that it is standard practice to replace the steering column whenever an airbag deployment occurs. I would like Chrysler to repair my steering column for me.

Sender Information:

-----  
Title: Dr.  
First Name: [REDACTED]  
Middle Initial: [REDACTED]  
Last Name: [REDACTED]

From: [REDACTED]  
To: customerassist@daimlerchrysler.com  
Date: Tue Feb 22 10:23:20 EST 2005  
Subject: Reply to DaimlerChrysler (KMM2378534C0KM)  
Reply Comments:

-----  
In regards to 13193069.  
Your response provided no particulars or details.  
Is it not common practice to replace a steering column in this type of  
vehicle following an airbag deployment?

Has there been any service  
advisories issued addressing this point (or other advisories dealing with  
the steering column)?

I would appreciate actual answers to these  
questions - not auto or canned boilerplate responses.

Thank you  
[REDACTED]

From: customerassist@daimlerchrysler.com  
To: [REDACTED]  
Date: Tue Feb 22 11:13:40 EST 2005  
Subject: Re: Reply to DaimlerChrysler (KMM2378534C0KM)  
Dear [REDACTED]

Thank you for your email regarding your 2002 Jeep Liberty Sport.

The information you are requesting is not available from the DaimlerChrysler Customer Assistance Center. Questions regarding what parts need to be replaced are best directed to your local dealership. I am unable to provide any sort of diagnosis via email.

There have been no service advisories regarding the steering column on your vehicle.

Thank you again for your email.

NOTE: Please do not use the 'Reply' function of your email system. If you have a need to respond to this message, please visit us at our reply form (link provided below). Our system is NOT able to accept any emails at this address.

For any future communications related to this email, please refer to the following information:

REFERENCE NUMBER: 13193069

REPLY LINK:

[http://www.chrysler.com/wccsapp/wccs/brand\\_forms/us/reply.jsp?trk\\_ID=KMM2385130C0KM&](http://www.chrysler.com/wccsapp/wccs/brand_forms/us/reply.jsp?trk_ID=KMM2385130C0KM&)

Sincerely,

Jeremy  
Senior Staff Representative  
DaimlerChrysler Customer Assistance Center

Original Message Follows:

-----  
Reply Comments:  
-----

In regards to 13193069.

Your response provided no particulars or details.

Is it not common practice to replace a steering column in this type of vehicle following an airbag deployment?

Has there been any service advisories issued addressing this point (or other advisories dealing with the steering column)?

I would appreciate actual answers to these questions - not auto or canned boilerplate responses.

Thank you  
[REDACTED]



EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup

MFD BY DAIMLERCHRYSLER  
CORPORATION

DATE OF MFR  
8-02

GVWR  
2427 KG(05350 LB)

GVWR FRONT WITH TIRES  
1248 KG(2750 LB) P215/75R16

RIMS AT  
16X7

COLD  
227 KPA(33 PSI)

GVWR REAR WITH TIRES  
1429 KG(3150 LB) R215/75R16

RIMS AT  
16X7

COLD  
227 KPA(33 PSI)

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY AND THEFT  
PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VIN: 1J4GK48KX3W

TYPE:

MPV

SINGLE X DUAL



MDH: 081506 776AB PNT:PS2

VEHICLE MADE IN U.S.A. TRM:M5L5 4648503

08220  
210220

200

MPH km/h

120

046449

5212 8776AB


**DaimlerChrysler Corporation**  
**IMPORTANT VEHICLE INFORMATION**

THIS VEHICLE CONFORMS TO BIN 9 OF THE U.S. EPA INTERIM NON-TIER 2 REGULATIONS APPLICABLE TO 2003 MODEL YEAR NEW LIGHT-DUTY TRUCKS AND QUALIFIES AS LEV UNDER NLEV REGULATIONS AND ULEV 1 UNDER CALIFORNIA CLEANEST VEHICLE REGULATIONS. VEHICLE CONFORMS TO U.S. EPA REGULATIONS APPLICABLE TO 2003 MODEL YEAR NEW LEV LIGHT-DUTY TRUCKS, CLEAN FUEL FLEET VEHICLE REGULATIONS. CERTIFICATION GASOLINE FUEL PER 86.113-94(a). SFTP COMPLIANT.

- \* BASIC IGNITION TIMING AND IDLE FUEL/AIR MIXTURE HAVE BEEN PRESET AT THE FACTORY. SEE THE SERVICE MANUAL FOR PROPER PROCEDURES AND OTHER ADDITIONAL INFORMATION.
  - ADJUSTMENTS MADE BY OTHER THAN APPROVED SERVICE MANUAL PROCEDURES MAY VIOLATE FEDERAL AND STATE LAWS.
- CAUTION: APPLY PARKING BRAKE WHEN SERVICING VEHICLE.

2HO2S(2), OBDII CERTIFIED, SFI, TWC, 2WUOC		SPARK PLUGS ZFR6F-11G 0.040 in. GAP	
3.7 LITER	NO ADJUSTMENTS NEEDED	3CRXT03.7220 3CRXR0155GCH	<b>CATALYST</b>

PK22G37E





**MOPAR®**

**THANK YOU FOR  
YOUR BUSINESS**

---

**NEXT SERVICE DUE:**

**DATE: 10/19/11**

**MILES: 96,286**

**Dayton Andrews C-J**

**727-799-4539**

12VA



6272

LIBERTY

STAY CLEAR



6272

Jeep



TOPSIDE CREEPER

STOP



6272

LIBERTY

Jeep





DSP600

Jeep  
Suncoast Jeep  
SEMIHOLE • FL

3.7L

HUNTER

HUNTER




SUNCOAST  
SEMINOLE, FL.  
Jeep

3.7L

Jeep

Suncoast Jeep  
SEMINOLE • FL






DSP600

SUNCOAST  
SEMINOLE FL  
Jeep

Jeep  
Suncoast Jeep  
SEMINOLE FL



CHRYSLER

CAUTION  
HOT

Need a Battery?  
Call 800-AAA-HELP  
AAA.com  
Warranty and Recycling Information Call 888-912-6678  
Dist. by Club Assist, LLC, Altamonte Springs, FL 32701

**CAUTION: DANGER/POISON**

SHIELD EYES  
EXPLOSIVE GASES  
CAN CAUSE BLINDNESS  
NO SPARKS  
NO FLAMES  
NO SMOKING  
SULFURIC ACID  
CAN CAUSE BLINDNESS OR SEVERE IRRITATION  
FLUSH EYES IMMEDIATELY WITH WATER.  
GET MEDICAL HELP FAST

WASH HANDS AFTER HANDLING  
Avoid contact with skin and eyes  
Avoid breathing dust, fumes, mist, vapors, or mists  
Avoid contact with clothing and other materials  
Avoid contact with food, drink, and tobacco products  
Avoid contact with children and pets

CAUTION: BATTERY ACID  
PROPOSITION 65 WARNING  
BATTERY ACID CONTAINS LEAD AND OTHER HEAVY METALS  
AND OTHER TOXIC SUBSTANCES  
WHICH CAN CAUSE REPRODUCTIVE HARM  
OR OTHER SERIOUS PHYSICAL HARM

PART NO. 34-H  
CCA @ 0°F 700  
RC 100  
83996108144  
MADE IN U.S.A. 2401








CAUTION  
REPLACE WITH  
FRESH LIQUID  
FRESH LIQUID  
FRESH LIQUID

WARRANTY  
WARRANTY  
WARRANTY

34-H  
700  
DANGER/POISON  
Need a Battery?  
Call 800-AAA-HELP  
AAA.com

WIPER FLUID





423322



BLOWER MOTOR 1 40A	RADIATOR FAN 2 40A	JB POWER 3 50A	
FUEL PUMP 4 40A	EATX 5 30A	ABD 6 30A	JB POWER 7 50A
IGNITION/START 8 40A	JB POWER 9 50A	TRAILER TOW 10 30A	11
LIGHT BARR 12 30A	IGNITION/WINDOWS 13 40A	IGNITION/SWITCH 14 40A	JB POWER 15 50A

ABS FEED 16	15A	17	18
-------------------	-----	----	----

HBL 19	30A	20
-----------	-----	----

A/C CLUTCH 21	30A	22
---------------------	-----	----

23	FUEL PUMP 24	20A
----	-----------------	-----

ABS VALVES 25	20A	26	15A
------------------	-----	----	-----

27	STARTER RELAY 28	15A
----	---------------------	-----

FUEL PUMP  
29

STARTER  
30

WIPER ON/OFF  
31

WIPER HI/LO  
32

BLOWER MOTOR  
33

ABD  
34

A/C CLUTCH  
35

REAR O2 SENSOR  
36

EATX/CLUTCH INTERLOCK  
37

38

39

40

WASST NEVA



ALUMINA 50/50 23V

1127 001 001 001  
001 001 001 001  
001 001 001 001  
001 001 001 001

Serial Number  
TRZME2112A6436



TRZME2112A6436



DaimlerChrysler Part Number  
P56010319AB

Supplier Code  
39754C

















100  
110  
120



PUSH ON VOL. SEEK AM FM SET

BASS TREB L BAL F R

DISC1 2 3 RND DISC2 TIME EJECT MODE

1 2 3 4

CLIMATE CONTROLS

APPLY BRAKE

P  
R  
N  
D  
2  
1

PARTICIPATING  
RETURN TO MAILING  
PLEASE RECYCLE  
STORE!

extra






















140366  
OPEN CASE

TORIG 10446

P235



096449





ABS

E F

3 4 5 6 7

RPM x1000

40 50 60 70 80 90 100 110 120

60 80 100 120 140 160 180 200

MPH km/h

C H







**TRW**

H01-06

312023R

**MEETS FMVSS 209**

**ASSEMBLED IN MEXICO**





311021

DAIMLER CHRYSLER



P5HG361L8AH



TR5211222939

CHRYSLER

DA

P5HG341L8AF

T02212249308

DAIMLER CHRYSLER



P5HG371L8AH



TR4218229447



**! WARNING: HIGHER ROLLOVER RISK**



AVOID ABRUPT MANEUVERS  
AND EXCESSIVE SPEED.

ALWAYS BUCKLE UP.

SEE OWNER'S MANUAL  
FOR FURTHER INFORMATION.





ASSEMBLED  
IN MEXICO

ACCEL  
CANCEL  
COAST











ASSEMBLED  
IN MEXICO

0  
90  
100

ACCEL  
CANCEL  
COAST

TRW 33014254-D (23)

TRW 33014254-D(21)

**RW**

H01-07

313021R

MEETS FITNESS 209

ASSEMBLED IN MEXICO

D  
FR  
CHRYSLER  
P5HG331L8AH  
TP121  
2251408

311021





Key



# **! WARNING**



## **DEATH OR SERIOUS INJURY CAN OCCUR**

- CHILDREN 12 AND UNDER CAN BE KILLED BY THE AIR BAG.
- THE **BACK SEAT** IS THE **SAFEST** PLACE FOR CHILDREN.
- **NEVER** PUT A REAR-FACING CHILD SEAT IN THE FRONT.
- SIT AS FAR BACK AS POSSIBLE FROM THE AIR BAG.
- **ALWAYS** USE **SEAT BELTS** AND **CHILD RESTRAINTS**.



6272

Key Tag



WARNING This could be dangerous if not used properly. To help avoid personal injury, please read the instructions carefully before use.



\*TC0



1218272353\*



\*P55



5020AJ\*



\*HER

STELLUNGSJAHR:

2002\*



A  
D  
M  
H  
W  
H  
E  
E  
D  
K  
T  
B



\*TCO



1218272353\*



\*P55



15020AJ\*

\*HER

HERSTELLUNGSJAHR: 2002\*



Airbag -  
 Druckgasspeicher  
 MP-P6-HGI  
 Hersteller: TRW VSSI  
 Washington, MI, USA  
 Herstellungsstätte: TRWP-5  
 Einführer: z.B. Chrysler  
 Deutschland GmbH,  
 Kerpen  
 Telefonnr.: 02273/957211  
 BAM-PT1-0639

Umgang nur durch geschultes Personal erlaubt. Verwendung nur in Insassen-Rückhaltssystemen mit Luftsackbeuge erlaubt. Bei Auslösung kann die nicht montierte Airbag-Einheit zum gefährlichen Wurfstück werden.

Supplemental Restraint System (SRS) Module  
 Use only a specified Supplemental Restraint System. See DaimlerChrysler Corp. dealer to verify part number for this vehicle.

**WARNING** You could be injured due to unwanted inflation. To help avoid personal injury:  
 1. Do not take apart, crush or puncture.  
 2. Carefully follow instructions in the DaimlerChrysler Corp. Service Manual when performing any type of service or when disposing of this module.











ON • OFF

CRUISE

SET

RES • ACCEL

CANCEL

COAST

5GG241X9AD  
54629

BREED

03

RPM x1000

E F

50 60 70

30 40 50 60 70 80 90 100 110 120

2

3

4

5

6

7

PULL

MIST

ON

DEL

OFF

OFF

\*T1VF219P10294\*



30317088K





OFF

H01 06  
023R  
MEETS FMVSS 209

7198982  
1 9026-53

**Quick Oil Change**  
 Park Blvd. N. • Pinellas Park, FL 33781  
 (727) 545-9747

Mrs. 7-265-4-20 • Sat. 8:00-4:00  
 This receipt should be retained. It will  
 provide proof of date, mileage, and  
 service performed for warranty  
 purposes. Up to 90 days or 1,000  
 miles. See us for more details.

DATE: 11/4/09  
 MILEAGE: 78300  
 NAME: JAMES J. [unclear]  
 ADDRESS: [unclear]  
 CITY: Pinellas Park, FL


PHONE # \_\_\_\_\_  
 STATE: FL

**SERVICE REPORT / INVOICE**

BRAND	VISCOSITY	SERVICE CHARGE
		OIL FILTER
		SPECIAL COOLANT

7138ABF  
1902-33

52772H B-1





\*TN6DT2182K1113\*



\*P5GG30DX9AE\*

5GG30TRMAE

\*HERSTELLUNGSJHAR: 2002\*

528970




HERSTELLUNGSJAHR: 2002  
#P00380494E  
#1116 DT 21824 1113  
#50039149E  
50039149E  
50039149E














CHRYSLER P/N P56010501AH



WARNING. REFER TO SERVICE MANUAL BEFORE SERVICING.  
IMPROPER SERVICING CAN RESULT IN AIR BAG SYSTEM  
FAILURE AND POSSIBLE DRIVER AND/OR PASSENGER INJURY.

CHRYSLER S/N TSFME2182E0543



SUPPLIER CODE

39754C




CHRYSLER P/N P56010501AH



WARNING. REFER TO SERVICE MANUAL BEFORE SERVICING.  
IMPROPER SERVICING CAN RESULT IN AIR BAG SYSTEM  
FAILURE AND POSSIBLE DRIVER AND/OR PASSENGER INJURY.

CHRYSLER S/N TSFME2182E0543





SUPPLIER CODE


39754C











## Main Menu

1. DRB III Standalone
2. Connect to TechTOOLS
3. Generic Scan Tool
4. PEP Module Tools
5. Run Memory Card Program
6. DRB Utilities
7. Vehicle Flash
8. Legacy MDS1 Support



# DRB III Emulator

File Help

Display

```
DRB III CDRB Application
  Chrysler Corp.
  Copyright © 1993-2011
  All Rights Reserved
  RELEASE 64.2 01
Released: 12:03:24 May 27 2011
  Bios Version: N/A
Database: 10:52:06 4/23/2011
Cable in use: J1962 (CH7000A)
```

HELP

Keypad

F1

Enter

DVOM

Read Ho

STAND-ALONE MAIN MENU

- 1. 1998 - 2007 Diagnostics
- 2. 1983 - 1997 Diagnostics
- 3. Vehicle Module Scan
- 4. Customer Preference
- 5. Junction Port Tool
- 6. TechTOOLS DataRecorder



1998 - 2007 DIAGNOSTICS

1. ALL ( Except Below )

- 2. 01 - 05 Stratus/Sebring Coupe
- 3. 98 - 00 Avenger/Sebring Coupe
- 4. 1998 Talon
- 5. 2004 - 2007 (RoW) Crossfire
- 6. 2002 - 2006 Sprinter



# SELECT SYSTEM

1. Engine
2. Transmission & T-Case
3. Body Interior
4. Chassis & Body Exterior
5. Anti-lock Brakes
- 6. Passive Restraints**
7. Theft Alarm
8. System Monitors

Page 1 of 1

HELP

SYS

MAIN



# SELECT RESTRAINT SYSTEM

- 1. Airbag
- 2. Side Airbags
- 3. Airbag On/Off Switch System
- 4. Occupant Classification Sys



NO RESPONSE from ORC  
Please make certain of the  
following items:

- 1) Ignition is turned on.
- 2) DRB III is properly  
connected to the Data  
connector.

HELP

SYS

MAIN

Unable to ID Module for  
ORC

press any key to continue

Unable to ID Module for  
PCM


press any key to continue

Transmission Menu

- 1. Transmission Module
- 2. Transfer Case Module
- 3. Shift Lever Assembly Module
- 4. Final Drive Control Module

Page 1 of 1

HELP      SYS      MAIN



Enter

DVOM

Read Hold

# Transmission Module Information

Version: 18

EATX IV - 45RFE

Perm Non-Autostick

Vehicle Model Year: 2003

Controller Model Year: 2003

TCM PART# 56044573AA

VIN: 1J4GK48KX3W530199

HELP

F2

F3  
MAIN

F1

Ent


DVO

Read H

# EXP800

JACKSONVILLE CJD

904-493-5545



2/06/2012

10:08 AM

## BATTERY TEST

RESULTS	
<b>GOOD - RECHARGE</b>	
VOLTAGE:	12.24V
MEASURED:	427 CCA
RATED:	700 CCA
TEMPERATURE:	81°F



BATTERY IS GOOD, BUT  
LOW ON CHARGE, FULLY  
CHARGE BATTERY,

AVERAGE BATTERY LIFE  
IN THIS AREA 45 MO

CHECK FOR CAUSES OF LOW  
CHARGE:

- CHARGING SYSTEM
- ALTERNATOR BELT
- CABLES AND CONNECTIONS

USING THE BATTERY WHILE  
LOW IN CHARGE WILL  
SHORTEN BATTERY LIFE



STATE OF FLORIDA REGISTRATION # MV-52549

CUSTOMER NO. <b>80389</b>	ADVISOR <b>ALEX</b>	TAG NO. <b>1426 6272</b>	INVOICE DATE <b>02/06/12</b>	INVOICE NO. <b>CHCS273257</b>
[REDACTED] PONTE VEDRA, FL [REDACTED]	LABOR RATE	LICENSE NO.	MILEAGE <b>96,448</b>	COLOR
	YEAR / MAKE / MODEL <b>03/JEEP/LIBERTY/2WD SPORT</b>			DELIVERY DATE
	VEHICLE I.D. NO. <b>1 J 4 G K 4 8 K X 3 W [REDACTED]</b>			DELIVERY MILES
	F.T.E. NO.			SELLING DEALER NO.
BUSINESS PHONE	COMMENTS	P.O. NO.	R.O. DATE <b>02/01/12</b>	PRODUCTION DATE
				<b>MO: 96448</b>

<b>JOB# 1 CHARGES</b>			
LABOR		TECH(S):1400	INTERNAL
J# 1 70CHZRENT	RENTAL SUBLET		
	RENTAL SUBLET		
	RENTAL SUBLET		
	RENTAL SUBLET		
SUBLET	PO#	VEND INV#-INV.DATE-DESCRIPTION	INTERNAL
	80650	02/06/12 RENTAL D425998	
TOTAL - SUBLET			0.00
<b>JOB# 1 TOTALS</b>			
JOB# 1 JOURNAL PREFIX CHCS JOB# 1 TOTAL			0.00
<b>JOB# 2 CHARGES</b>			
LABOR		TECH(S):524	105.43
J# 2+51CHZ	BODY ELECTRICAL		
	C/S BOTH AIRBAGS DEPLOYED IN STOP AND GO TRAFFIC. NO IMPACTS		
	CHRYSLER HERE TO INVESTINGATE		
	INSPECTED FOR E.A.A.		
LABOR			105.43
JOB# 2 JOURNAL PREFIX CHCS JOB# 2 TOTAL			105.43
MISC	CODE	DESCRIPTION	CONTROL NO
JOB # A	SS	SHOP SUPPLY/HAZARD WASTE FEE	
TOTAL - MISC			11.86
COMMENTS			
RENTAL			

**DISCLAIMER OF WARRANTIES**  
Any warranties on the products sold hereby are those made by the manufacturer. The Seller, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products, Parts and Labor are guaranteed for 12 months or 12,000 miles, whichever comes first. Seller does not guarantee that the work performed in accordance with this estimate will correct any problem specified on the description of the complaint.

CUSTOMER SIGNATURE \_\_\_\_\_ CUSTOMER ACKNOWLEDGES RECEIPT OF COPY \_\_\_\_\_

**Shop Supplies and Waste Disposal**  
\* This charge represents costs and profits to the motor repair facility for miscellaneous shop supplies or disposal [s. 559.904(4)].

**Tire and Battery Disposal Fee**  
\* The State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s. 403.718], and a \$1.50 fee to be collected for each new or remanufactured battery sold in the state [s. 403.7185].

**ALL PARTS NEW UNLESS OTHERWISE INDICATED.**





STATE OF FLORIDA REGISTRATION # MV-52549

CUSTOMER NO. <b>80389</b>	ADVISOR <b>ALEX</b>	TAG NO. <b>1426 6272</b>	INVOICE DATE <b>02/06/12</b>	INVOICE NO. <b>CHCS273257</b>
[REDACTED] PONTE VEDRA, FL [REDACTED]	LABOR RATE	LICENSE NO.	MILEAGE <b>96,448</b>	COLOR
	YEAR / MAKE / MODEL <b>03/JEEP/LIBERTY/2WD SPORT</b>			DELIVERY DATE
	VEHICLE I.D. NO. <b>1 J 4 G K 4 8 K X 3 W [REDACTED]</b>			DELIVERY MILES
	F.T.E. NO.	P.O. NO.	SELLING DEALER NO.	PRODUCTION DATE
			R.O. DATE <b>02/01/12</b>	
RE [REDACTED]	BUSINESS PHONE	COMMENTS		

MO: 96448

TOTALS-----

***** METHOD OF PAYMENT *****	TOTAL LABOR....	105.43
* CASH.....	TOTAL PARTS....	0.00
* CREDIT CARD.....	TOTAL SUBLET...	0.00
* CUSTOMER CHECK # .....	TOTAL G.O.G....	0.00
	TOTAL MISC CHG.	11.86
	TOTAL MISC DISC	0.00
	TOTAL TAX.....	8.22

**TOTAL INVOICE \$ 125.51**

I AGREE THAT THE ACTIONS TAKEN TO ADDRESS MY CONCERNS HAVE BEEN ADEQUATELY EXPLAINED TO ME.

**DISCLAIMER OF WARRANTIES**  
Any warranties on the products sold hereby are those made by the manufacturer. The Seller, hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Parts and Labor are guaranteed for 12 months or 12,000 miles, whichever comes first. Seller does not guarantee that the work performed in accordance with this estimate will correct any problem specified on the description of the complaint.

CUSTOMER SIGNATURE CUSTOMER ACKNOWLEDGES RECEIPT OF COPY

**Shop Supplies and Waste Disposal**  
\* This charge represents costs and profits to the motor repair facility for miscellaneous shop supplies or disposal [s. 559.904(4)].

**Tire and Battery Disposal Fee**  
\* The State of Florida requires a \$1.00 fee to be collected for each new tire sold in the state [s. 403.718], and a \$1.50 fee to be collected for each new or remanufactured battery sold in the state [s. 403.7185].

**ALL PARTS NEW UNLESS OTHERWISE INDICATED.**

CUSTOMER SIGNATURE

**JACKSONVILLE CHRYSLE**  
11101 NURSERY FIELD  
JACKSONVILLE, FL 322  
904-493-0000

BATCH: 091  
S-A-L-E-S D-R-A-F-T  
79910021  
330017565039

REF: 0014  
CD TYPE: DISCOVER  
TR TYPE: PURCHASE  
INU: 273257  
DATE: FEB 06, 12 11:34:40

**TOTAL \$125.51**

ACCT: \*\*\*\*\*6033 EXP: \*\*/\*\*  
AP: 006778  
NAME: [REDACTED]  
TRAN. [REDACTED]

CARDMEMBER ACKNOWLEDGES RECEIPT OF GOODS AND/OR SERVICES IN THE AMOUNT OF THE TOTAL SHOWN HEREON AND AGREES TO PERFORM THE OBLIGATIONS SET FORTH BY THE CARDMEMBER'S AGREEMENT WITH THE ISSUER

CUSTOMER COPY

EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup

1J4GL48K23W

MFD BY	DAIMLERCHRYSLER CORPORATION	DATE OF MFR	9-02	GWR	2541 KG(05600 LB)
GAWR FRONT	WITH TIRES	RIMS AT	COLD		
1248 KG(2750 LB)	P215/75R16	16X7	227 KPA(33 PSI)		
GAWR REAR	WITH TIRES	RIMS AT	COLD		
1429 KG(3150 LB)	R215/75R16	16X7	227 KPA(33 PSI)		

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VIN: 1J4GL48K23W [REDACTED] TYPE: MPV SINGLE X DUAL



MDH: 092100 776AB PNT:PS2 VEHICLE MADE IN U.S.A. TRM:MSL5 4648503

DISCO



109905





AIR  
BAG



DAIMLER CHRYSLER

---

DRB III - BIOS Version 4.02  
Copyright 2001, All Rights Reserved  
Serial Number: 1964010459

---

Launching application...

699

KEY TAG

LIC.#

Main Menu

1. **INELT Standard Tools**
2. Connect to TechTOOLS
3. Generic Scan Tool
4. PEP Module Tools
5. Run Memory Card Program
6. DRB Utilities
7. Vehicle Flash
8. Legacy MDSD Support

Page 1 of 1

HELP

64.1



DRB EII CDRB Application

Chrysler Corp.

Copyright © 1993-2006

All Rights Reserved


RELEASE 64.1 01

Released: 15:51:24 10/11/2007

Bios Version: 4.02

Database: 8:18:38 7/19/2007

Cable in use: J1962 (CH7000H)



64.1

STAND-ALONE MAIN MENU

1. 1998 - 2007 Diagnostics
2. 1983 - 1997 Diagnostics
3. Vehicle Module Scan
4. Customer Preference
5. Junction Port Tool
6. TechTOOLS DataRecorder

Page 1 of 1

HELP

64.1

MAIN

1998 - 2007 DIAGNOSTICS


- 1. ALL ( Except Below )
- 2. 01 - 05 Stratus/Sebring Coupe
- 3. 98 - 00 Avenger/Sebring Coupe
- 4. 1998 Talon
- 5. 2004 - 2007 (RoW) Crossfire
- 6. 2002 - 2006 Sprinter

F1  
HELP

F2  
SYS

F3  
MAIN

64.1



SELECT SYSTEM

1. Engine
2. Transmission & T-Case
3. Body Interior
4. Chassis & Body Exterior
5. Anti-lock Brakes
6. Passive Restraints
7. Theft Alarm
8. System Monitors

Page 1 of 1

F1  
HELP

F2  
SYS

F3  
MAIN

64.1

F1

F2

F3

F4

2mi

4mi

7

SELECT RESTRAINT SYSTEM

1. Airbag
2. Side Airbags
3. Airbag On/Off Switch System
4. Occupant Classification Sys

Page 1 of 1

F1  
HELP

F2  
SYS

64.1

F0  
MAIN

----- AIRBAG DIAGNOSTICS -----

Determining Controller  
Type

Please Wait...

F1  
HELP

F2  
SYS  
64.1

F3  
MAIN

This Diagnostic Control  
Module is not supported by  
this software. Please use the  
DRB III with the Supercard  
software to diagnose this  
vehicle.

F1  
HELP

F2  
SYS

64.1

F0  
MAIN



CHRYSLER

**DRB III**™

**SuperCard**  
1994-1997

CH8361

**SPX** **OTC**



This side up



WP→





SELECT FUNCTION

1. System Tests
2. Read DTCs
3. Module Display
4. Sensor Display
5. Input/Output Display
6. Monitor Display
7. Custom Display
8. Actuator Tests
9. Miscellaneous

Page 1 of 1

OCM

F1  
HELP

F2  
SYS

F0  
MAIN

64.1

DTC TYPE

- 1. Active
- 2. Stored

Page 1 of 1

DCM

F1  
HELP

F2  
SYS

F3  
MAIN

64.1

NO RESPONSE from OCM  
Please make certain of the  
following items:

- 1) Ignition is turned on.
- 2) DRB III is properly  
connected to the Data  
connector.

DTC TYPE

- 1. Active
- 2. Stored

F1  
HELP

F2  
SYS

64.1

F3  
MAIN

OK

NO RESPONSE from UCM  
Please make certain of the  
following items:

- 1) Ignition is turned on.
- 2) DRB III is properly  
connected to the Data  
connector.

# AUTOCRAFT

Reliable starting power  
for all seasons

Potencia confiable de arranque  
para todas las estaciones del año

## SILVER

04	04	05	15	
04	04	05		
04	0E	0E	0E	0E
04	30	30	05	05
04	05	0E		
0E	04	04	05	

72472M
4671168E
4671168E
72472M
72472M
4671168E
4671168E
72472M

56006709
56006709
50732
56006709

72472M
4671168E
4671168E
72472M
72472M
4671168E



BLOWER MOTOR 1 40A	RADIATOR FAN 2 40A	JB POWER 3 50A	
ABS PUMP 4 40A	EATX 5 30A	ASD 6 30A	JB POWER 7 50A
IGNITION/ START 8 40A	JB POWER 9 50A	TRAILER TOW 10 30A	11
LIGHT BAR 12 30A	IGNITION/ WINDOWS 13 40A	IGNITION/ SWITCH 14 40A	JB POWER 15 50A

ASD FEED 16	15A	17	18
----------------	-----	----	----

HBL 19	30A	20
-----------	-----	----

A/C CLUTCH 21	20A	22
------------------	-----	----

23	FUEL PUMP 24	20A
----	-----------------	-----

ABS VALVES 25	20A	INJECTORS 26	15A
------------------	-----	-----------------	-----

27	STARTER RELAY 28	15A
----	---------------------	-----

FUEL PUMP  
29

STARTER  
30

WIPER ON/OFF  
31

WIPER HI/LO  
32

BLOWER MOTOR  
33

ASD  
34

A/C CLUTCH  
35

REAR O2 SENSOR  
36

EATX/CLUTCH INTERLOCK  
37

38

39

40

90957 REV A

SEE OWNER'S MANUAL FOR DETAILS

HIGH  
BEAM

DAYTIME  
RUNNING  
LIGHTS

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8

- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23

- 9
- 10
- 11
- 12
- 13

- 34
- 35

- 36
- 37

- 14
- 15
- 24
- 25
- 38
- 39




4671168E  
72472M  
tyco

-02-	-20-	-10-
-10-	-15-	-10-
-15-	-20-	
-10-	-20-	-15-
-10-	-20-	-10-
-20-		-20-
	-10-	-10-
	-10-	-10-
-10-		
-15-		
-15-		
-10-		
-10-		
-10-		
-10-		





CHRYSLER P/N P56010501AH



WARNING. REFER TO SERVICE MANUAL BEFORE SERVICING.  
IMPROPER SERVICING CAN RESULT IN AIR BAG SYSTEM  
FAILURE AND POSSIBLE DRIVER AND/OR PASSENGER INJURY.

CHRYSLER S/N TSFME2552E0271




SUPPLIER CODE

39754C




















ION FQNI

PLEASE LATER  
FOR ACCESS TO  
FUSES AND RELAYS

POWER  
FRAME

AUTOCRAFT  
SILVER  
34-1  
680  
825  
115

6/11



**RENT  
ME**  
TOM AHL CHRYSLER  
228-3497



Jeep

POWER TECH  
2.7L V6



CAUTION

ATTENTION  
WARNING

5212 8776AB



POWERTECH  
2.7 V6

CAUTION  
FUEL  
CAUTION

RELEASE LATCH  
FOR ACCESS TO  
FUSES AND RELAYS

5212 877648

**DaimlerChrysler Corporation**  
**IMPORTANT VEHICLE INFORMATION**

THIS VEHICLE CONTAINS THE 2.7L V6 ENGINE WITH A RECALL FROM APPLICABLE TO ALL 2004 CHRYSLER CRYPTER TRUCKS AND BATTERIES OF 2004 CHRYSLER CRYPTER TRUCKS AND BATTERIES APPLICABLE TO 2004 CHRYSLER CRYPTER TRUCKS AND BATTERIES TO U.S. EPA REGULATION. CERTIFICATION NUMBER: PCH 0404 113-0002 0719 COMPLIANT.

• BASIC ENGINE TUNING AND FUEL AND MIXTURE HAVE BEEN PERFORMED AT THE FACTORY. USE THE SERVICE MANUAL FOR PROPER PROCEDURES AND OTHER ADJUSTMENTS. VARIATIONS MADE BY OTHER THAN APPROVED SERVICE MANUAL PROCEDURES MAY VIOLATE FEDERAL AND STATE LAWS.  
CAUTION: APPLY PARKING BRAKE WHEN SERVICING VEHICLE.

ENGINE OIL CERTIFIED, 5W, 15W, 30W	SPARK PLUGS (P/N) 110 0.900 IN. GAP
3.7 LITER NO ADJUSTMENTS NEEDED	SCARFED TIRE SCARF/TURCH

**CATALYST**



**BELT ROUTING**

**BELT REMOVAL**

960 32038









MBUS



COOPER

DISCOVER L5X



DISCOVERER LSX



305



DISCOVERER LSX

GOODYEAR





DISCOVERER LST

Jeep

GOODYEAR



















LOCATE  
FRAME BEF  
WHEN RAIS

Rotax

BETWEEN  
RAISED

















N

LOCATE THE BARS







8  
869

Jeep



669







Jeep  
LIBERTY

Jeep  
4x4



CHD

Jeep  
LIBERTY

Jeep  
4x4











2VE BKCK

AA0214303

ASSEMBLED  
IN MEXICO

← #D  
☀  
OFF

PULL  
MUS









RES • ACCEL

CANCEL

COAST









SRS AIRBAG

Jeep

# **! WARNING**



## **DEATH OR SERIOUS INJURY CAN OCCUR**

- CHILDREN 12 AND UNDER CAN BE KILLED BY THE AIR BAG.
- THE **BACK SEAT** IS THE **SAFEST** PLACE FOR CHILDREN.
- **NEVER** PUT A REAR-FACING CHILD SEAT IN THE FRONT.
- SIT AS FAR BACK AS POSSIBLE FROM THE AIR BAG.
- **ALWAYS** USE **SEAT BELTS** AND **CHILD RESTRAINTS**.

# **! WARNING: HIGHER ROLLOVER RISK**



AVOID ABRUPT MANEUVERS  
AND EXCESSIVE SPEED.

ALWAYS BUCKLE UP.

SEE OWNER'S MANUAL  
FOR FURTHER INFORMATION.





# **WARNING**



## **DEATH OR SERIOUS INJURY CAN OCCUR**

- CHILDREN 12 AND UNDER CAN BE KILLED BY THE AIR BAG.
- THE **BACK SEAT** IS THE **SAFEST** PLACE FOR CHILDREN.
- **NEVER** PUT A REAR-FACING CHILD SEAT IN THE FRONT.
- SIT AS FAR BACK AS POSSIBLE FROM THE AIR BAG.
- **ALWAYS** USE **SEAT BELTS** AND **CHILD RESTRAINTS**.











MEETS FMVSS 208  
ASSEMBLED IN MEXICO


T

MEETS FMVSS 209  
ASSEMBLED IN MEXICO





181040



P5HG331






F5HG331284H









FRH

374023R

H01-06

MEETS FMVSS 209  
ASSEMBLED IN

DAIMLER  
P5HG347184F  
170256271540





TRW 33014254-D (22)





10 125





H01 06  
4023R  
FMVSS 209





PRESS

PRESS









JOHNSON  
MAGNETIC  
Locata  
ANGLE  
NO. 700  
MADE IN USA

DEGREES

DEGREES





cm  
11  
10  
9  
8  
7  
6  
5  
4  
3  
2







WESTCOTT



12VA



12VA











EA12-001

CHRYSLER

10-4-2012

ENCLOSURE 4

FIELD DATA SUBJECT

CAIRs Backup

















— ORC DTCs 1 of 2 —

INTERNAL 1

— DTC 2 of 2 —

— STORED ENERGY—  
FIRING 1

DTC TYPE

- 1. Active
- 2. Stored

-- ORC DTCs 1 of 2 --

INTERNAL 1

MINUTES: 4785 IGN CNTS: 0

--- DTC 2 of 2 ---

STORED ENERGY

FIRING 1

MINUTES: 4713 IGN CNTS: 0



TYPE 35

10338

TRIP

MFD BY DAIMLERCHRYSLER CORPORATION

DATE OF MFR 8-02

GWR 2427 KG(05350 LB)

GAWR FRONT WITH TIRES 1248 KG(2750 LB) P215/75R16

RIMS AT 16X7 COLD 227 KPA(33 PSI)

GAWR REAR WITH TIRES 1429 KG(3150 LB) R215/75R16

RIMS AT 16X7 COLD 227 KPA(33 PSI)

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.

VIN: 1J4GK48K33 [REDACTED] TYPE: MPV SINGLE X DUAL



MDH: 082612 776AB PNT:PFM VEHICLE MADE IN U.S.A. TRM:MSDU 4648503

AIRBAG Module Information

2002 Body Style: KJ

Part#: 56010501AH

S/W Version: 05.05

TRW Gen V

Front Dr and Pass/PCI Bus SA  
and Lamp Dr w/On/Off Sw or AOS

DTC TYPE

1. Active
2. Stored

Page 1 of 1

DRC

F1  
HELP

F2  
SYS

F9  
MAIN

64.1

--- ORC DTGs 1 of 2 ---  
INTERNAL 1

--- DTG 2 of 2 ---

STORED ENERGY  
FIRING 1

--- ORC DTGs 1 of 2 ---

INTERNAL 1

--- DTG 2 of 2 ---

STORED ENERGY  
FIRING 1

-- ORC DTCs 1 of 2 --

INTERNAL 1

MINUTES: 4806 IGN CNTS: 0

---- DTC 2 of 2 ----

STORED ENERGY  
FIRING 1

MINUTES: 4734 IGN CNTS: 0



Stick in

Jeep



P	R	R	R
←	→	↶	↷
1	2	3	4
5	6	7	8
9	0	*	#























Jeep

3.7L

WRANGLER SR-A  
GOODYEAR



LIBERTY sport

GOODYEAR TRACKER 2




4597

12-12

1 3

Jeep





**FIELD PHOTOGRAPHIC NOTES**

<u>Customer's Name:</u> [REDACTED]	<u>Inspection Date:</u> 03/22/2012
<u>Vehicle Brand:</u> CHRYSLER	<u>Model:</u> 2003 JEEP LIBERTY SPORT 4X2 SUV 4 DR
<u>File #:</u> CAIR 21990396	<u>VIN:</u> 1J4GK48K33W [REDACTED]

Inspector W.R. Bippert, E.A.A. Date: 03/22/2012

Number of Rolls \_\_\_\_\_

Roll Number

- | <u>Neg.#</u> | <u>Description</u>   |
|--------------|--|
| 0            |  |
| 1.           | <u>Front air deflector and front cross member no impact damage observed.</u>               |
| 2.           | <u>Right front suspension and under carriage no impact damage observed.</u>                |
| 3.           | <u>Left front suspension no damage observed.</u>   |
| 4.           | <u>Engine oil pan and cross member no damage observed.</u>                                 |
| 5.           | <u>Transmission and cross member no damage observed.</u>                                   |
| 6.           | <u>Close up of cross member no damage observed. Under carriage components rusted.</u>      |
| 7.           | <u>Differential and fuel tank area no damage observed.</u>                                 |
| 8.           | <u>DRB Screen indicating 2 codes stored and also active in system.</u>                     |
| 9.           | <u>DRB screen with codes present.</u>  |
| 10.          | <u>DRB code counts.</u>  |
| 11.          | <u>Vehicle current mileage.</u>  |
| 12.          | <u>Vehicle VIN. Sticker located on left front door.</u>                                    |
| 13.          | <u>DRB information screen.</u>   |
| 14.          | <u>DRB DTC screen</u>  |
| 15.          | <u>DRB screen with 2 DTC present.</u>  |
| 16.          | <u>DRB screen showing 2 codes in system.</u>   |
| 17.          | <u>Clearer picture of DRB screen.</u>  |
| 18.          | <u>Steering wheel with Air-Bag deployed but cut out and removed prior to inspection.</u>   |
| 19.          | <u>Close up of removed air-bag.</u>  |
| 20.          | <u>Passenger side air-bag deployed and removed prior to inspection.</u>                    |
| 21.          | <u>Cut out and removed air bag on floor on right side of vehicle.</u>                      |
| 22.          | <u>Close up of passenger side air bag compartment air bag removed prior to inspection.</u> |
| 23.          | <u>Cut out air bag on floor of vehicle.</u>  |
| 24.          | <u>Left front seat belt no damage observed.</u>  |
| 25.          | <u>Right front seat belt no damage observed.</u>   |
| 26.          | <u>Front seat backs upright and no damage observed.</u>                                    |
| 27.          | <u>Spare tire on vehicle blown out but no damage observed on wheel.</u>                    |
| 28.          | <u>Rear of vehicle no damage observed.</u>   |
| 29.          | <u>Right side no damage observed.</u>  |
| 30.          | <u>Front no damage observed.</u>   |
| 31.          | <u>Left side no damage observed.</u>   |
| 32.          | <u>Photo description log.</u>  |
| 33.          | _____  |
| 34.          | _____  |
| 35.          | _____  |
| 36.          | _____  |
| 37.          | _____  |