INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

EA12-005 CHRYSLER 2/18/2013 **ENCLOSURE 3 CLAIMS-LAWSUITS** PEER VEHICLES - 1997 -2006 WRANGLER (TJ) CONSUMER COMPLAINTS

Customer .	Assistanc	e Inquiry F	Record (CAIR)#				6571572
VIN	1J4FY49SX	XP	Open Date	12/15/1999	Built Date	06/02/1999	
Model Year	1999	Body	TJJL77	JEEP WRAN	IGLER 4X	4 SPORT UTILITY	2-DR
In Service Dt	07/03/1999	Mileage	4,291	Dealer Zone			
Plant	P	TOLEDO ASS (STICKNEY)	SEMBLY PLANT II	Market	U	us	
Color	PX8	BLACK CLEA	AR COAT				
Engine	ERH	4.0L 16 POWE	ER TECH ENGINE				
Transmission	DGG	3-SPD. AUTO	DMATIC 32RH TRANSM	IISSION			
Owner						Contact Type	TELEPHONE
Address	F					Home Phone	
	BLUE JAY C	A				Country	UNITED STATES

Gas tank leaked, caused vehicle to slide

**** Begin of Str Nar: SI POLICY FIRE OR ACCIDENT ****

Product - Unknown - Unknown - Accident - Default

Owner Alleges:

Gas tanked leaked in driveway, gas got on tires caused vehicle to slide

down steep driveway.

Description of the incident (what, when, where, injuries, etc) Vehicle slid and hit steps by driveway. 12-14-99. At customer's

residence No injuries

Has the owners insurance company been contacted?

Yes

If yes provide name/policy number and phone number Ron Young insurance (818)840-0246.

Where is the vehicle currently located (provide name/address/phone #)

Viking Motors in Rim Forest, CA.

Is there property damage or other vehicles involved in the accident?

Property damage to owners yard.

Has a Police or Fire report been filed (what municipality & report #)

Fire department did go to scene. No other info.

**** End of Str Nar: SI POLICY FIRE OR ACCIDENT ****

Original owner seeking assistance with repairs from accident. Customer states that gas leaked from tank all over driveway and tires. Customer states his wife lost control of vehicle while backing out of steep driveway. Writer advised customer that file would be forwarded to special investigations for further review.

FILE RETURNED BY S/I. WE ARE UNABLE TO SCHEDULE INSPECTION WITHOUT COMPLETE ADDRESS (STREET & #, CITY, STATE, ZIP, PHONE) FOR PHYSICAL LOCATION OF VEHICLE. PLEASE OBTAIN THIS INFO AND RETURN FILE TO S/I. THANKS. JSS15/DRM8.

Viking Auto 26343 Apache Trail Rim Forest CA 92378 (909)337-8534

(909)337-8534

PLEASE CONTACT AND ARRANGE INSPECTION TO DETERMINE CAUSE OF LOSS. PLEASE PROVIDE FULL PVIR REPORT, PHOTOS, POLICE DEPT REPORT (if available), AND ANY OTHER PERTINENT INFORMATION. THANKS. JSS15/DRM8.

CAIR NUMBER 06571572 REQUEST EAA INSPECTION 12-15-1999 14:56 CAIR NUMBER 06571572 FAX SENT TO EAA 12-15-1999 15:00 12/15/99 owner inquires if husband has provided current vehicle location. Verified above address with owner.

12/21/99-Received imaged report....non manufacturing responsibility... will refer owner to ins co.....fuel leak at tank was only at punchure area, damaged and impacted area..... no other leak detected, no sign of dampness areas....unable to pressurize

tank.....drm 12/21/99-Letter sent....drm PHOTOGRAPHIC IMAGES POSTED TO THIS CAIR ON 12/24/99 AT 00:00 06571572 PHOTOGRAPHIC IMAGES POSTED TO THIS CAIR ON 12/24/99 AT 00:00 06571572



































EA ASSOCIATES

W 101



ENGINEERING ANALYSIS ASSOCIATES, INC.

307 de martinach feurt - Suite 4366 Bingham (1949), rink higan 46025-4328 Phone: 248-842/3232 Fax: 2348-842-4558

there the process rain 11/1/95/12/17/97 you may receive an inormal in vehicle inspection well and further distances due to certain SA's worsday a heavier school to a process a process a process to you.


Facelmile Cover Sheet DelinberChrysler Vehicle Investigation Report (VIR)

EAA No: 1960 (1953)	It transitions the complete pleas
	call the above phase number
CAIR No. 200 1890	
To:	The state of the s
Phone Nor	From Time Martin
The state of the s	Date Faxed:
Pax No: Man Gran Cold	Due Dute: 13.
	alexander of the second
Total Control of the	
Please actining the promptly by SEX or phe	one.
Receipt of CATE and Accepting case for inve	estigation V YES NO DETE 12/16/9
	7
	The second secon
Fire Coverations for DelimiterChr	yslar (Service Associate Sas Only)
(also hav to t	EAA for closure)
Date: /Alango	Fax Number: 248-512-6748
Number of pages that Covery	
TO:	
□ Bentine (248) 944-7039	☐ Martell (248) 844 7038
□ Bott (248) 944-7956	Mucci 12487 44 7039
□ GHANE 3248) 944-7637	D Porterfield (245)844-7134
Communication NOTE:	S OF PICH WERE USED!
AND DROES AT	and of report
	* · ·
	The state of the s
A STATE OF THE STA	Notice that we have the second

Exterior Damage Diagram and Measurements

CHAPTER COUNTRY OF CONTROL OF

16199476134



NO EXTERIOR DAMAGE TO VEHICLE

Sketch damage on all views include dimensions to describe and locate each damaged area and maximum depth of penetration for each impact. Annotate observations which might be useful in reconstructing the accident (e.g., direction of scrapes, markings on tires and wheels, etc.). Take photographs.

PRECIMENARY PAR INSPECTION

Division		EIEUDPHOTOGRAPHIC N	
Caimar	THE COLUMN TO ASSESS THE O	" CALL #571572 VIN 15	CHFYMASSXR
-	The state of the s		
	**中华	Organization	EA, A
Phone:		Inspection Date 12 /le 90	and a manufacture of the part of the comments
1		141-41	Milesgeletempectics 0042
(RUINE	unism (1)		
	- who said the		*
Neg.#	Licentellos	X.	
so 10	The second second	when you are all well have you	
2	J. Contraction	THIS KIRM (THOMANI	CARROTT
3,	Alent As	THE HEAD IN	- Y STATE EXTEN
4	THE PROPERTY OF THE PARTY OF TH	CI WORLD	1 DA 24 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
5	VIII METE	W WYW	7 70004 -
. 8		for The No.	
7	Total Control	to TANK & SHICLD INSTALLS	in .
- 8		CARRY TO	and the same of th
ġ,	PHY WEN	FAS BANK + SHOP TO	UT CLPR
10	CONTRACTOR OF THE PARTY OF THE	DEADER (VERTILA)	OF AUSBURGE FROM 12 SCREET
1/1.	Jak Van OF K	EMOUND FOR TANK FROM	9 AUSDUBOR FAVOR IS SCREET
	TOP OF THE PARTY OF	SEMEMBER ETTE	IDE _ OFF
13	PROBLEM BY	Aust Pier Samue	\$104
**4		AUST CHARLES CHARLES COLLE	416
15			
16.	THE PARTY OF THE PARTY OF THE PARTY.	TALLER SHOW IN CO. I AND ALL AND A	BALL MAN
17	A Part of the Part	The state of the s	TRAINSC
18.	THE PROPERTY OF	F CALCUMENT COOK	
19.	A CHARLES TE S	P DEC 181 Product de Dortes -	THE APPROPRIES
21	A CONTRACT OF THE PARTY OF THE	TO THE PART OF COURSE IN	
-	MARKET STATE OF THE STATE OF TH	CIDAL DICHARGON L	13
23	THE VIEW OF THE PROPERTY OF TH	ICLE MACKING BUTO - IMPACT	P STAIRS
24	THE MENT STATE OF MANY	PART BULLITY AND	A STATE OF THE STA
25	C. C	10 old of Delivery	howays party gran show fee
28	-		
27.			
28	CU		
29.			
30,	44214 14 36		······································
31,			
32;			
33.		- 11 45	the same of the sa
34	The said the many the said of the said		
35	in with restriction	- my	management and a warman spile agails alone a real and a second
36 37		The state of the s	The standard are the st
	THE RESERVE OF THE PARTY OF THE		The state of the s
07a.poc		The state of the s	

16199476134

PRELIMINARY PAR INSPECTION MELD PHOTOGRAPHIC NOTES

Black a free	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MAN THE PARTICION	
. IT	Mislon Waller	PRELIMINARY PAR INSPECTION PIECE PHOTOGRAPHIC NOTES	longe to
a L	Mision	Refl	3 200 1 3
C	Mimarit's New Towns of the	ROW CALL & SYIET: VIII AT WE X X 9 5 XXX	
		ADWEYY95XX	
fr. m	special by		-
3 PI	one: [740] President	- Didentification	
1		The particular that the same of the same o	
(R	Il Numarate 1	WHER HE STATES	Secret 004.3
			-
Ne	g.# freetungen		
	a# firetuning	and the second s	
9	done with the way it		
		LEOPHER UP DRIVER OF DRIVE ON	
3	- AND A POLY	CLOOPING UP DRIVE WAY	***
4	The second secon		
5	THE PROPERTY OF	W. N. DAKE DE DE VENIE WAY	
6		A MIDAL OF PRINCIPLE OF STOREWAY I TO DESCRIPT OF PRINCIPLE OF PRINCIPLE OF THE PRINCIPLE	PLINT AT US
7	THE TOTAL LESS	AT THE ON DRIVEWAY MENT TO STATEWAY	
54			
. 3			-
1.1).	THE STATE OF THE S	to standard of secondard	
11	The second second	TI STEELING TO BE ALBERT	
	A STATE OF THE PARTY OF THE PAR	A THE TORREST OF THE TORREST OF THE TENED OF	
77		THE CHARLEST DE - LANGE TO BE THE THE THE THE THE THE THE THE THE TH	the MATER
- 72.		PHOTOM CONTACT POINT STORE SHOW COME SHOW THE	
72. 13.			
13.	A STATE OF THE STATE OF	SPOUND PHOTO FROM FURTHER DOWN DOWN	
14		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Board
14.		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Board
14. 15.		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Board
14. 15. 16.		SPOUND PHOTO FROM FURTHER DOWN DOWN	den at Banch
14. 15. 16. 17.		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16, 17 18		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14. 15. 17. 18. 18. 20.		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14. 15. 17. 18. 19. 20. 21.		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16, 17 18 18 20 21 -23		SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24 25	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 18 20 21 22 23 24 26 26	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14. 15. 16. 17. 18. 18. 20. 21. 22. 24. 26. 27. 27.	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24 26 27 28	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 24 25 26 27 28 29	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24 26 27 28 29 30	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14. 15. 16. 17. 18. 10. 21. 22. 23. 24. 26. 27. 28. 29. 30. 31.	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14. 15. 16. 17. 18. 10. 21. 22. 25. 26. 27. 28. 29. 30. 31. 32.	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24 26 27 28 29 30 32 32 32 32 33	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24 25 27 28 29 30 31 32 33 34	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 20 21 22 23 24 25 27 28 29 30 31 32 33 34	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14 15 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch
14. 15. 17. 18. 120. 27. 23. 24. 26. 27. 28. 29. 30. 32. 33. 35. 56. 35. 35. 35. 35. 35. 35. 35. 35. 35. 35	Electrical of the control of the con	SPOINTAGES ON RIGHT FOR PORT DE DELLA DELLA	den at Banch

CALIFICATION

BALL UTHER

ARPORT SUMDIARY

Bir sedictorial despected at Engal a Vileing Auto, 26343 Apache Trait film Purest U.V., peror of the stop present of the stop of a flat bed track. The gas tanknown pipe anisid was been back and under the gas tanknown with the stop of the

The behind of a streamly been replaced point to my inspection. The original give scale has been replaced for my inspection. Open inspection it was binarilistic characteristic descriptions and maked for my inspection. Open inspection it was binarilistic contributed and the first was impact distings to the lank. The invertigation side of the rank was problem independent of the park was from independent of the park side of the rank was problem independent of the park side of the vehicle. (See phone analyses 1) for inspect of the park side of the vehicle. (See phone analyses 1) for inspect of the park side of the vehicle of impact of section and the park side of the rank park side of the rank park side of the park side of the section and the section of the section of the section was confident in the section of the park side was park side of the par

After respecting the gas bunk I had athresconcerved talen of what I would see at the active of cappened of the evidence of generalize profitage only at the point of impact where the habe was not use the pass large. Instead, the following is what I observed. Black the impact schooling published the grant of the strength of the strength of the way down to the black of the officers. The field marks our to this field and so of the edge of the driveway at the strength of the strength of the first school of the driveway. Impact marks were observed on the brack-school of the strength who shall be specially and the brack school of the strength of the str

There was a fine place in the middle of the throway stering at the top and continuing out the way about the transfer of the was NOT prodominate at the point of implication in the contract of the standard of the contract of the contract of the standard of the contract of the standard of the contract of the standard of

List we have the top of the driveway, or the teveled-off perking area, begin 77 inches from a please typicing list inches to a relief of the list inches from the wall on the left are mark. The well is on the drive the front of the vehicle. This indicates that the are marks are from the front area in the drive the front of the vehicle front area in the drive the front of the front area in the front of the vehicle front and the first the first meeting and the front the vehicle front and the first marks also inches that the vehicle started is the drive area of the first started perking also inches that the vehicle started is the chown the driveway right order the first parking aport. In view of all the orderes at the

comes, a final design more questions are set the classicant. I also decided to go back to the outo surp-

When the best to the auth shap! retaispected the gas lank discontibly over averagement out of the sufficient management of I had missed excing a defect in the sound or around the lasts. Comparison of the surface for couchs or pix holes or anything. No other detects could let the surface of the surface was these. I could not determine what courses the dark countries the dark the countries the dark shaped in the countries of the very top the very top the service of the surface started to the surface of the countries of the very top.

BESORIPTION OF SCENE

The manager placed on top of a full with an asphalt diageway going from a local packing are in the district way, drowed very steep grade to the steet. There is another wal packing the district way, drowed very steep grade to the steet. There is another wal packing of a district way to ensure the steep with each stop investig a rise of secondid con-half steels a steel with a district was for another foliage. Land a grase. The district was the another foliage is the steep, to the bonder of the brick steep. The "drop" in the diversary in the district was the steep, to the bonder of the brick steep. The "drop" in the diversary in the district was remarked by the rise of the steep. It is approximately another in the steep is a problem of the steep. This willings of the maphalit is very smooth dist to a slarry man which is been supplied over the asphalt. It depends have the popular surface normally sould are appeared to paging any part of the steep to the diversely on the left side, then the grade and the diversely on the left side, then the surface of the diversely on the left side, then the surface of the diversely on the left side, then the left side, then the left side, then the left side of the diversely on the left side, then the left side of the diversely on the left side of the diversely on the side of the diversely of the side of the diversely that the source of the diversely on the left side.

CONTINUATION OF INTERVIEW WITH CLAIMANT

Because of the flattings at the incident score companed to the findings at the vertical respection.

The property of the flattings at the incident score companed to the findings at the vertical respection.

The property of the flattings at the incident score companed to the findings at the vertical respection.

- O There a von tirst nonce granding an the drawing?
- A. The programy thing in the bigenesy before I stored the Jeup."
- O Manthag wood saything the whatshire specific
- was a latter anything.
- Continue managers was in the gas back?"
- A. The properties it up a day or service to. I would say it was about fall fall or a little more
- The "The property of their problems grating up or direct the driveway buffore?"
- 13 the lent loss to man the 1-school make to feet the mentals of shi.
- A This abbeing the 4-wheel deliver buckey husband can drive fun Armico up in 2-wheel drive

是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以 第一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以是一个人,也可以

- the stury put (thinke three way? Was it applied over rough asphale?)
- The way have been on going down the driveway."


 The second to hank the the teep began to stide I pressed on the business as hard as I
- se was show 40 decrees that is west't damp."
- partial fewer then hit the stage in the per off the steps, but then the Jean week.
- The property of the leep part of the driveway."

 When I have to the bostons and think up over, I regained to y composes. They first error of the cross I delige know? was looking gas at that time. I you should be be a supply that the condition in what our of gas. Then I saw the trail of gas I tell in the trace.
- Constitute of black stame in the middle of the driveway. Were they there before the de the description of the state are from the gas spaling on the driveway.
- C. "Many standard any gas leading aroung other mus before the incident?"
- the property of the state of th we monume! We find the these in three moinths "
- which are do come on, does the water spray on the didveway"
- the design the design and the design of the The language direct the weather the engine hence If it is going to be below freening during the night a seek at the bottom of the driveway material of the top. It want's the count
- The limbourd thinks the case limber on the tires and made the driveway simpley, so ! and the any inaction. He breaks stated tope of the driveresty on the right at the securior

DATO PRINTERVIEW

Red Line PAA

.



DAIMLERCHRYSLER

DaimlerChrysler Motors Corporation

December 22, 1999

Blue Jay, CA

Reference No.: 6571572 V.I.N.: 1J4FY49SXXP

Dear Mr

This will further acknowledge contact to DaimlerChrysler Motors Corporation, regarding your 1999 Jeep Wrangler.

naturally, we were sorry to learn of the incident described to us during the initial contact. However, we have had the opportunity to review the inspection report and must inform you that we are not led to believe that the incident was due to a manufacturing responsibility. Therefore, we must respectfully decline any assistance associated with this incident.

Based on this information, we can only suggest that you refer this matter to your insurance carrier. Should they feel a manufacturing responsibility exists, they have full subrogation rights under the terms of your policy.

Thank you for allowing us the opportunity in reviewing this matter with you.

Sincerely,

D. R. Mucci Special Investigations (248) 944-7039

DRM/lg

THERE IS ONLY ONE PAGE TO THIS

ATTACHMENT

FAX TRANSMITTAL

4571572

FROM: EARL LIND , E.A.A

TO: DENNIS MUCCI

MESSAGE: RE: CAIR 6571572

THE FOLLOWING 5 PAGES, ARE THE ONES YOU COULDN'T READ. PLEASE LET ME KNOW IF THESE ARE BETTER.

P.S- sording it again for machine.
Re-sording at again for machine.
From a different for

TOTAL PAGES, INCLUDING THIS COVER PAGE

DEC 22 '99 15:22

762244770EA12-005 Peer - Chrysler A0689. 001

CAIR 6571572

REPORT SUMMARY

The vehicle was inspected at Dave's Viking Auto, 26343 Apache Trail, Rim F. 'est, CA, prior to visiting the incident scene. An interview with David Nelson, owner of the shop, revealed the following: The Jeep Wrangler was brought into the shop on a flat-bed truck. I te gas tank was completely empty. The gas tank/exhaust pipe shield was bent back and under the gas tank. Welds were broken from this shield and it was torn loose from the main shield.

The vehicle had already been repaired prior to my inspection. The original gas ank had been removed from the vehicle and saved for my inspection. Upon inspection, it was immediately obvious that there was impact damage to the tank. The lower right-hand comer was scraped and a hole was torn in the plastic tank. The metal shield on the right side of the tank was broken loose from the main shield and bent. (see photos # 13 & 14). There was a reddish cold red scrape mark on the exhaust pipe next to the shield on the right side of the vehicle. (See photon number 7). The underbody of the Jeep was inspected for any more evidence of impact—a scrape mark with paint removed was noted on the right side of the rear axle directly in line with the scrape mark on the exhaust pipe. (see photo # 10). No other damage was found on the vehicle. The gas tank was photographed on top and bottom. (See photos # 11, 12,15,16, & 17). When the inspection was completed, a short phone interview was conducted with the driver, at her place of business. She gave me directions to her home, which is the scene of the incident. However, she was not able to be present at the scene, therefore I inspected the incident scene in thout the benefit of her presence to ask questions as I proceeded. (See description of incident see in.)

After inspecting the gas tank. I had a pre-conceived idea of what I would see at the scene I expected to see evidence of gasoline spillage only at the point of impact where the hole was torn in the gas tank. Instead, the following is what I observed: Black tire marks showing a skidding pattern start at the top of the steep driveway and continue all the way down to tree bottom of the driveway. The skid marks turn to the left and go off the edge of the driveway at the stairway at approximately the mid-point of the driveway. Impact marks were observed on the brick stairway and the corner of one of the brick steps had chips and scrapes and black marks the same color as the gas tank. There was also a tire mark on top of the steps at this point. The skid marks on the asphalt then change direction and pattern at this point, showing a pattern consist at with wheels spinning as though the vehicle med to pull away from the impact area. Then the marks continue down to the bottom of the driveway, again, in a sliding pattern.

There was a dark stain in the middle of the driveway starting at the top and conn. uing all the way down to the bottom and out into the street. It was NOT predominate at the point of impact at the stairway, however the stain became larger and more evident of a fluid spill in the middle of the driveway and as it continued down to the bottom. The stain goes out into the street, then branches off down the right-hand side of the street and continues in a dripping partern (heavy drip) down the street.

The tire marks at the top of the driveway, in the leveled-off parking area, begin? I inches from a block wall on the right tire mark and 120 inches from the wall on the left tire mark. The wall is at an angle from the front of the vehicle. This indicates that the fire marks are from the front tires at this point because the vehicle is much longer than 77 inches long and the rear tire; could not have been that close to the wall. The vehicle tread width from right to left tires was mi asured at 65 inches at the outside edges of the tire marks. These marks also indicate that the vi hicle started to slide down the driveway right from the unitial parking spot. In view of all the evi tence at the

scene, I had many more questions to ask the claimant. I also decided to go bac to the auto shop, to re-examine the gas tank to see if I had missed anything on my first inspection

When I got back to the auto shop I re-inspected the gas tank thoroughly over every square inch of the surface to determine if I had missed seeing a defect in the seam or around the hose connections or anywhere else on the surface for cracks or pin holes or anything. No other defects could be found. Only the impact damage was there. I could not determine what caused the dark stains in the claimant's driveway starting above the impact point, nor why the vehicle started to slide down the driveway all the way from it's parking location at the very top.

DESCRIPTION OF SCENE

The residence is situated on top of a hill with an asphalt driveway going from a evel parking area at the top of the driveway, down a very steep grade to the street. There is anoth r level parking area adjacent to the driveway at street level. On the left side of the driveway, to oking up from the street, is a brick stairway consisting of 33 steps with each step having a rise of seven and one-half inches. The right side is dirt with some foliage, but no grass. The dirt was dry and the foliage is sparse. The driveway is 13 feet wide and approximately 59 feet long from the cest where it levels off at the top, to the bottom of the brick steps. The "drop" in the driveway in that distance is approximately 21 feet as measured by the rise of the steps. It is approximately another 30 more feet to the edge of the street. The surface of the asphalt is very smooth due to a Jurry coat which has been applied over the asphalt. It does not have the porous surface normally seen on asphalt. There is a 2-inch diameter water drainage pipe at the top of the driveway on the eft side, next to the stairway, with a shallow gutter running down along the side of the driveway text to the stairway. Off to the right of the driveway, in the dirt area, are "mini-sprayer" sp inklers, starting at the top of the hill and spaced several feet apart along the hill going towards th: street.

CONTINUATION OF INTERVIEW WITH CLAIMAN T

Because of the findings at the incident scene compared to the findings at the vel. clc inspection, many questions arose in my mind. I telephoned the claimant, Mrs. again. The following is the question and answer session:

- Q. "When did you first notice gasoline in the driveway?"
- A. "I didn't see anything in the driveway before I started the Jeep."
- Q. "Did you smell anything like a gasoline smell?"
- A. "No, I didn't smell anything."
- Q. "How much gas was in the gas tank?"
- A. "I had just filled it up a day or so ago I would say it was about half full or a little more."
- Q. "Have you ever had problems getting up or down the driveway before?"
- A. "No."
- Q "Do you need to use the 4-wheel drive to get up the driveway?"
- A. "Yes, I always use 4-wheel drive, but my husband can drive his Branco up : 2-wheel drive."

- Q. "When was the slurry put on the driveway? Was it applied over rough asp talt?"
- R. "It was already there when we purchased the house 4 or 5 months ago."
- Q. "How did this incident begin to happen?"
- A. "As soon as I started to back up, the Jeep began to slide. I pressed on the L akes as hard as I could, but it just kept on going down the driveway."
- Q. "What was the weather like?"
- A. "It was cold about 40 degrees, but it wasn't damp."
- Q. "There were a lot of tire marks, in a strange pattern. How did that happen?
- A "I just slid down, then hit the steps. I tried to get off the steps, but then the cop went sideways. I thought I was going to tip over It slid sideways all the way do un to the bottom."
- "How did you get the Jeep out of the driveway?"
- A "When I got to the bottom and didn't tip over, I regained my composure. hen I just drove away down the street. I didn't know I was leaking gas at that time. I got al out 2 blocks away and the car died. It was out of gas. Then I saw the trail of gas I left is the street.
- Q. "I saw a lot of black stains in the middle of the driveway. Were they there efore the incident?"
- A. "No, they weren't there. The stains are from the gas spilling on the driveway."
- Q. "Did you notice any gas leakage at any other time before the incident?"
- A. "No, never."
- Q. "I noticed sprinklers alongside the driveway. Are they on timers?"
- A. "No. They are manual. We haven't used them in three months."
- Q. "When they do come on, does the water spray on the driveway?"
- A. "No."
- Q. "Could there have been any frost on your driveway that day?"
- A. "No. I always check the weather the night before. If it is going to be below feezing during the night, I park at the bottom of the driveway instead of the top. It wasn't that cold."
- Q. "Can you think of any other reason that your Jeep could have slid down the till?"
- A. "No. My husband thinks the gas leaked on the tires and made the driveway slippery, so I didn't have any traction. He made a video tape of the driveway on the night of the accident."

END OF INTERVIEW

Garl Land

Earl Lind, EAA

DEC 22 '99 15:82

Mile, ge at Inspection, 004291

(page 1 of 1)

PRELIMINARY PAR INSPECTION EIELD PHOTOGRAPHIC NOTES

Division: DAIMLER- CHRYSLER	Ref# PAIR 157	C71 VIN 1 THEY WAS	
Claimant's Name (LAST, Fi	rst)	1572 VIN 154FY49.3X	
Inspected By: <u>EARL</u> Phone: (760) 947-780	X reneation	Organization: E.A.A	it Inspection. CO429

Roll Number /

Neg.#	Description	
1.	LEFT FRONT 3/4 VIEW (SHOWING CAID	
2.	RIGHT FRONT 3/4 VIEW (SHOWING CAIR	
3.	RIGHT REAR 3/4 VION) SIND EXTER
4.	LEFT REAR 3/4 VIEW	DAMAGE TO
5.	VIN PLATE	BODY
6.		
7	SCRAPE MAN TANK + SHIELD INSTALLED	
8.	THE ON EVALUET PINE	
9.	-CLUSE UP OF STRADE MADE	
10.		
11.	- LIFER ON KT VEAD AVEC 11	OR PAINT IS THE
12.		OFF
	OF KEMOVED AND THE	
13.	- EXTRAST PIPE STIELD	
14.	DISTORIED EXHAUST PIDE SHIPLD SHOULD	
15.	THE TENTOUS GALLE	DAMAGE
16.	CORNER OF GAS TANK SHOWING IMPAUT DAMAGE	
17.	CLOSE UP OF IMPACT DAMAGE	
18	OVERALL VIOW OF INCIDENT SCENE	
19.	VIEW OF CHER SCENE	
20.	VIEW OF STEEP DRIVEWAY + RESIDENCE ADVI	ESS ON TREE
21.	THE THE OF UPINE IA	
22.	VIEW LOOKING DOWN DRIVEWAY	
23.	CLOSEUD OF WEALT DIE IMPACTED STAIR	
24.	DE IMPIECI POLIT AL PA	
25.	VIEW FROM MIDDLE OF DRIVEWAY (SHOWING DE	PL STAND FROM FL
_		TO LOOK
6 _		
27		
8		
9.	The second of th	
0.		
1.		
2.		
3.		
4.		
5. —		
-		
-		

PRELIMINARY PAR INSPECTION FIELD PHOTOGRAPHIC NOTES

(page 1 of 1)

la manage	CHRYSLER Ref# CAIR 6 It's Name (LAST, First)			P
inspecte	BY EARL LIND	August 1		
Phone:	7/01 6/17	Organization:		
	mber 2	Tate 12 16, 99	Mile. ge at	Inspection: 0042
0	Description			
1.	GAS STAIN IN STREET GAS STAIN (LOOKING	AND AT FIRE		
3.	GAS STAIN (600 KING	UP DRIVE WAY)	DRIVECTAY	
	TIRE MARKS AT BOTT	M OF THE		
4.	TIRE MARKS IN MIDDLE OF	DOUTENA	9	
5.	TIRE MARKS IN MIDDLE OF GAS STAINS (?) IN DRIVER DRAINAGE PIPE AT TOP OF I	IAU DALL PATAC	ENT TO MAP	ACT POINT AT IF
6.	ENTINAGE PIPE ATTOR	Carlo de la carlo	THE PLINT	
7.	SPRINKLERS IN VARA TO A	CUL- NEXI TO	STAIRWAY	
0.	SPRINKLERS AT TO	THE OF DRIV	EWAY	
9.	CLOSE-UP SHOWAIL = 0	aveury		
10.	DP OF DRIVENCES SILLING	OF SPHUNKLERS		
11.	STOW/NG ?	TRE MARKS AND "DA	OK SPOT BE	TWEEL TO ACE
Aller Area	MIDDLE DE DRIVERTE			
12.	MIDDLE OF DRIVEWING SHOWING THE DRIVEWING COME	ACT POINT, OTHER SI	E. COR IGH	AS SOSTAN AS DO
	TADITER VIEW OF ARIUM	11 - 10	COR JAIL	OF STERS AF DOLL
13.	PROXIMITY OF SPRINKED	HOTO FROM FURTHE	COR JAIL	OF STERS AF DOLL
13. 14.	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS	HOTO FROM FURTHE	P DOWN DR	OF STEPS AT BENE 1USWAY VAY
13. 14. 15.	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENE 1USWAY VAY
13	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENE 1USWAY VAY
13. 14. 15. 16. 17.	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENE 1USWAY VAY
13. 14. 15. 16. 17.	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. ————————————————————————————————————	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. ————————————————————————————————————	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 120. — 12.	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 20. — 21. — 22. — 3. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 19. — 19. — 12. — 12. — 3. — 4.	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 12. — 12. — 13. — 15. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 12. — 12. — 13. — 15. — 15. — 16. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 19. — 19. — 12. — 12. — 15. — 16. — 17. — 16. — 17. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 12. — 13. — 15. — 17. — 16. — 17. — 17. — 18. — 17. — 18. — 17. — 18. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 12. — 13. — 15. — 17. — 16. — 17. — 17. — 18. — 17. — 18. — 17. — 18. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 16. — 17. — 18. — 19. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 19. — 19. — 12. — 19. — 12. — 15. — 19. — 15. — 16. — 17. — 16. — 17. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 19. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 17. — 18. — 19. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 1USWAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 120. — 13. — 16. — 17. — 18. — 19. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY
13. — 14. — 15. — 16. — 17. — 18. — 19. — 12. — 16. — 17. — 18. — 19. —	PROXIMITY OF SPRINKLERS CLOSE-UP OF SPRINKLERS PARKINE AREA AT ROTTON	HOTO FROM FURTHE ON RIGHT SIDE HEAD	P DOWN DR	OF STEPS AT BENG 105WAY VAY

TI

Confidential


Vehicle Investigation Report CAID DEE #6571572

YEAR MODEL	the same of the sa	ENTIFICATION NUMBER	DOMETER DOMETER	M.O.H. DELIVERY DATE
99 JEEP WRA	NGLER ALC	WHOM 9 S X X P	10,4,2,9,1	0,60,212,0 7/3/89
ary	C 2 3	9 1999		
BLUE JAY	SPECIAL INVE	STIGATIONS	THE INTERIOR OF THE INTERIOR O	HOME OF OTHER
DON -A - VEE		ZONE DLR CODE	BELLFLOWER	CA
CHRYSLER REPRESENTATIVE -P	PINT	ZONE	PHONE	MINOR REPAIR ESTIMATE
EARL LI	20	E.A.A.	760 947-780 5	MAJOR \$ 7/8.57
INTERVIEW W		INTERVI		OF INCIDENT INSPECTION DATE
OTHER		1,21,619	91214199 9	1.20 PM 1,2/1,6/9,9
COLD - N	O NOISTURE	ASPHALT DA	CIVENAY VERY S	STEEP
Oriver's and/or occupant's description	"I GOT INTO	CAR, PUMPED BRAK	ES, LOOKED BACK AN	D STARTED TO SLOWLY
of incident What? When? Where?				TED TO SLIDE. I PRESSED
How? Exact order of events	BRAKES AS H	ARD AS I COULD, A	CEPT SLIDING, HIT S	TEPS ON SIDE OF DRIVE-
Did this happen before?	The Property of the Control of the C		, OFF STEPS BUT JEE	
NO Personal	Injury: Were the	re Personal Injuries?	☐ Yes Mo If yes, co	mplete section "L."
			& DRAW NO CONCLUSIO	
DIRECT		TUPPER PART OF FOR		
СОММЕ	• FOLLOW • FOLLOW • ATTACH :NTS: • NOTE AN	INSTRUCTIONS FOR S ANY ADDENDUMS TO F NY MISSING COMPONEI	ECTION "A" ON ALL VEHIC PECIFIC ALLEGATIONS FO REPORT AND STATE SECTION WITS AND WHO REMOVED TO IPMENT INSTALLED AND B	OR THIS VEHICLE. ON IT PERTAINS TO. THEM.
ALLEG. PHOTOGR	APH REQUIRED		MATION	EVALUATION
every 45 de	grees (8 total) maged — perspective (comer of vehicle down I lateral sight lines.	Police report NONE Nehicle service file Any reports/photos by others Location of inspection AVE'S VIKING A	How? How? WExact order of events	Complete exterior damage diagram and measurements on last page.
□ Send neg. 8		26343 APACHE RIM FOREST, CA	TRAIL Solid this happen before?	NO INT HAS VIDEO OF TAME DAY AS INCIDENT
	ers body contact areas dings using DRB II	☐ Record: ☐ Was Airbag deployed? ☐ Driver ☐ Yes ☐ No ☐ Passenger ☐ Yes ☐ No ☐ Type of Steering Wheel ☐ Tilt ☐ Std ☐ Condition of Steering Wheel	Use DRB II Record Existing Readings 1 Record Stored Readings	☐ Evidence of tampering or disassembly? ☐ Yes ☐ No
		Condition of Steering Wheel Medning (measure column collapse)	Important DO NOT ERASE DRB II READINGS.	005 Rept. Charles 10705

ALLEG.	PHOTOGRAPH REQUIRED	INFORMATION	EVALUATION
Sudden Acceleratio or Throttle Hold	O Accelerator Pedal On O Throttle Cable ' O Return Springs O Floor Mats	Describe any Accelerator Pedal Interference with Carpet/Met	DRB II Tests Disconnect Cable at Throttle Body/Carburetor lever; operate:
0			Any restricted motion?
0			Yes No
			 If safe and permitted to drive - attempt to duplicate and check Service Brakes at reported speed.
Brakes	☐ items in Information Block.	Check and record Brake Fluid Level.	
		Check and record if Vacuum Hose is connected. Q Yes Q No.	With Engine off: Apply Brake fully 3 or 4 times.
D		☐ Check and record for Brake Line Leaks. ☐ Yes ☐ No ☐ Pull Wheels, check Linings and record condition.	With light force held to Pedal, start the Engine.
		☐ Check Brake Pedal, does it set firm? ☐ Yes ☐ No	Note reaction of Pedal and record:
		Check operation of Parking Brake.	
		Check operation of ABS System.	☐ ABS System DRB II test readouts
Steering	Downley Orada Salar		
Glock May	Complete Steering System Including as required: • Rack & Pinion	☐ Record If: ☐ Manual Steering ☐ Power Steering ☐ Check Fluid Level	Unlock key and turn Wheels fully right and left.
	Linkage	☐ Record If Drive Belt is tight ☐ Yes ☐ No	If safe, start Engine and turn Wheels fully right and left.
E	C/V & Universal Joints	☐ Check for Hose/System leaks ☐ Yes ☐ No Leaks	☐ Record Steering function.
Andrew Marine	Column Belts & Bulleye	Check condition of Steering Linkage from Wheels to Steering Column, record deformation or loose connections.	
	Beits & Pulleys	Column, record deformation of loose connections.	
Trans- mission	Entire Transmission with	□ Record:	a train and a second second second
Masion	pictures and closeup of leaks, if any.	Type of Transmission?	If safe and permitted to drive vehicle:
		Auto Std.	Drive Vehicle and record feel of
		How many Speeds?	Gear during each Gear Shift
		Record Gast Shift location at time of inner at	The second second second
	/	Record Gear Shift location at time of inspection	
	/		
-		☐ Run Shift Lever thru all shift positions and record "Feel of Gating"	_
	/	The same of the sa	Does Parking Pawl engage?
		And the second financial and a second	Yes No
		Dy D	or I ransmission in all Gears.
		☐ Yes ☐ No	Check starting ability in park and neutral. Check to see that start does
			not occur in other selector positions.
Sanina [200	1234 7.1	
Engine C Stall/	Including as required:	☐ Record type of Spark Plugs (location of unique plugs).	If safe and permitted to:
Orivability	Underhood/Emissions Label	V alence V	Try to duplicate Allegation Off Hiway
	Engine Wiking/Connections		DAB II or I/P Fault Code Test
•	Vacuury Hoses		
G	• Fuel Lines		
•	Exhaust System		
	Spark Plugs		
	 Connections 		
			(
		EA49.0	05 5 011- 10700

ALLEG.	PHOTOGRAPH REQUIRED	INFORMATION		EVALUATION			
Seet/ Shoulder Belts	Overall of seat belts I/B and O/B. Close ups of any irregularities on belts. Shoulder Belt Pendulum	labels are sewn to	bels and record ALL i webbing, other labels abels are near floor.)	information (Some are on retractor frame,	If allowed, function belts to insuriney FUNCTION PROPERLY, insurins: Do they latch? Yes Do they release? Yes Do they retract? Yes Do they retract? Yes Yes Yes Yes Yes Yes Yes Ye		
П	☐ Latchplate wear ☐ Close up of D-ring to show belt loading.	Record ALL Inform	nation stamped on late	chplate.			
Seet	Overall of seat Close ups of damage	Aeer m lest edde o	r Pawi (crayon mark i	eeth from rear of sector ocation).	If allowed, adjust and return to or	st all functions of sea	
•	¥	Existing location of restraint).	head restraint imeasu	re gap under heed	☐ Note any Irregul	ar orientations	
Tiree	Each Tire with visible location label, insuring all Tire	Record:	Front Left	Front Right	Rear Left	Rear Right	
	identification and Tread wear is documented.	☐Brand	/		-		
J	All damaged Wheel and Rim area including impacted foreign	□Ratings				- 165	
	material.	DOT No.(VB Side)					
		☐Rim Size					
K		Trans. Axie - rotate V	Wheels				
ontact (See Seat Belt/Seats Occupant contact de					
	cloth Exterior and interior damage						
			-				
			NAL COMMENT				
emcle	HAD ALPEADY BEE	N REPAIRE	ON DAY	OF INSPECTI	ON, SO T	HE GAS	
tuk H	AD ALREADY BEEN	REMOVED.	THE TANK	WAS THORE	SUGHLY E	KANINEN	
ER E	uery square inc	h of surfa	ICE. THE E	BOTTOM RIGHT	T REAR CO	RNER	
MS PU	nctured from im	PACT DAMAG	E. NO O	THER DAMAG	E WAS SE		
L SEA		TIONS/FIT	TINGS AN	ID SURFACE	S HAD NO	VISIRIE	
FECT.	NOTED. THE MI	etal shiel	D ENCASING	6- THE GAS 7	MASK WAS	DAMAGEN	
PECIA	LLY THE SIDE SHIE	TA AT PICH	TONE AE	TALIL AT -		1	
	OSE AND BENT, S	THE PLICA	1 3/00 01	IMNE M EXT	HAUST PIPE	. IT was	

Exterior Damage Diagram and Measurements



NO EXTERIOR DAMAGE TO VEHICLE

Sketch damage on all views. Include dimensions to describe and locate each damaged area and maximum depth of penetration for each impact. Annotate observations which might be useful in reconstructing the accident (e.g., direction of scrapes, markings on tires and wheels, etc.). Take photographs.

EA12-005 Peer - Chrysler - 10708

		•						
i hereby authorice the repair work insted hereon, including aublet work. To be done along with necessary materials. You and your employees may operate the described vehicle for purposes of testing, inspection or delivery at my risk. An express tien is exhonwedged on said vehicle to secure the amount of repairs thereto. You will not be head responsible for loss or demand to vehicle or articles left in vehicle in case office, theft, excisent or any other cause beyon default is made in any payment due to the property of the secure of the payment due to the paym			Rim	Ve's Vik 28343 Aper Forest, CA (909) 337 PA CAL SO BAR # AB	the Trail 92378-000 -8534 18684 19			
MAME ADDRESS CITY STATE ZIP CODE	YEARIM	AKE		4.55.3%	100	E 174		
		7.75		MILEAGE	1201	PU	TICHASE O	ADEA
HALE APROWHEAD. GA	LICENSE	NUMBER		MOTO	XR SIZE	AC	COOE	WIRE
HOME PROME				+	40	WR	ITTENBY	
VENCLE PRESLEM STATEMEN	FCAT RATE	MEO!	1	BLACK WRA	NGLER			
	PATE	MECH.	-	LABORO	PERATIONS	1.		PRICE
OR PUEL LEAK; PUEL TANK & SHIELD FOUND	4	AA	TEST FU	EL SYSTEM;	RER TANK		1	\$224.00
MECONHIGHED SERVICE								
STIMATE OF REPAIRS: Includes all peris, labor, heroling and diagnosis. If on closer anama necessary, you will be contacted for authorization.	yars it is lourd	that addition	ons' repeirs	TOTAL LABOR				22/ 22
STIMATE OF REPAIRS Includes all parts and parts		that addition		Parts consider and	not wall and beyon	nd Wall given by		224.00
STIMATE OF REPAIRS: Includes all perts, lebor, hendling and diagnosis. If on closer energy necessary, you will be contacted for euthorization OTY. PART NUMBER PART PROPRETION A	\$7			Parts cretation are No other watering	not wattended beyon the flede encopy i PART DESCRIM	se need ou this is	respective n	
STIMATE OF REPAIRS: Includes all parts, labor, handling and diagnosis. If on closer anaman necessary, you will be contacted for authorization	\$7	50.00		Parts cretation are No other watering	PART DESCAN	se need ou this is	respective n	anutacturera

· · · · · · · · ·

REPORT SUMMARY

The vehicle was inspected at Dave's Viking Auto, 26343 Apache Trail, Rim Forest, CA., prior to visiting the incident scene. An interview with David Nelson, owner of the shop, revealed the following: The Jeep Wrangler was brought into the shop on a flat-bed truck. The gas tank was completely empty. The gas tank/exhaust pipe shield was bent back and under the gas tank. Welds were broken from this shield and it was torn loose from the main shield.

The vehicle had already been repaired prior to my inspection. The original gas tank had been removed from the vehicle and saved for my inspection. Upon inspection, it was immediately obvious that there was impact damage to the tank. The lower right-hand corner was scraped and a hole was torn in the plastic tank. The metal shield on the right side of the tank was broken loose from the main shield and bent. (see photos # 13 & 14). There was a reddish colored scrape mark on the exhaust pipe next to the shield on the right side of the vehicle. (See photo number 7). The underbody of the Jeep was inspected for any more evidence of impact – a scrape mark with paint removed was noted on the right side of the rear axle directly in line with the scrape mark on the exhaust pipe. (see photo # 10). No other damage was found on the vehicle. The gas tank was photographed on top and bottom. (See photos # 11, 12,15,16, & 17). When the inspection was completed, a short phone interview was conducted with the driver, at her place of business. She gave me directions to her home, which is the scene of the incident. However, she was not able to be present at the scene, therefore I inspected the incident scene without the benefit of her presence to ask questions as I proceeded. (See description of incident scene).

After inspecting the gas tank, I had a pre-conceived idea of what I would see at the scene. I expected to see evidence of gasoline spillage only at the point of impact where the hole was torn in the gas tank. Instead, the following is what I observed: Black tire marks showing a skidding pattern start at the top of the steep driveway and continue all the way down to the bottom of the driveway. The skid marks turn to the left and go off the edge of the driveway at the stairway at approximately the mid-point of the driveway. Impact marks were observed on the brick stairway and the corner of one of the brick steps had chips and scrapes and black marks the same color as the gas tank. There was also a tire mark on top of the steps at this point. The skid marks on the asphalt then change direction and pattern at this point, showing a pattern consistent with wheels spinning as though the vehicle tried to pull away from the impact area. Then the marks continue down to the bottom of the driveway, again, in a sliding pattern.

There was a dark stain in the middle of the driveway starting at the top and continuing all the way down to the bottom and out into the street. It was NOT predominate at the point of impact at the stairway, however the stain became larger and more evident of a fluid spill in the middle of the driveway and as it continued down to the bottom. The stain goes out into the street, then branches off down the right-hand side of the street and continues in a dripping pattern (heavy drip) down the street.

The tire marks at the top of the driveway, in the leveled-off parking area, begin 77 inches from a block wall on the right tire mark and 120 inches from the wall on the left tire mark. The wall is at an angle from the front of the vehicle. This indicates that the tire marks are from the front tires at this point because the vehicle is much longer than 77 inches long and the rear tires could not have been that close to the wall. The vehicle tread width from right to left tires was measured at 65 inches at the outside edges of the tire marks. These marks also indicate that the vehicle started to slide down the driveway right from the initial parking spot. In view of all the evidence at the

scene, I had many more questions to ask the claimant. I also decided to go back to the auto shop, to re-examine the gas tank to see if I had missed anything on my first inspection

When I got back to the auto shop I re-inspected the gas tank thoroughly over every square inch of the surface to determine if I had missed seeing a defect in the seam or around the hose connections or anywhere else on the surface for cracks or pin holes or anything. No other defects could be found. Only the impact damage was there. I could not determine what caused the dark stains in the claimant's driveway starting above the impact point, nor why the vehicle started to slide down the driveway all the way from it's parking location at the very top.

DESCRIPTION OF SCENE

The residence is situated on top of a hill with an asphalt driveway going from a level parking area at the top of the driveway, down a very steep grade to the street. There is another level parking area adjacent to the driveway at street level. On the left side of the driveway, looking up from the street, is a brick stairway consisting of 33 steps with each step having a rise of seven and one-half inches. The right side is dirt with some foliage, but no grass. The dirt was dry and the foliage is sparse. The driveway is 13 feet wide and approximately 59 feet long from the crest where it levels off at the top, to the bottom of the brick steps. The "drop" in the driveway in that distance is approximately 21 feet as measured by the rise of the steps. It is approximately another 30 more feet to the edge of the street. The surface of the asphalt is very smooth due to a slurry coat which has been applied over the asphalt. It does not have the porous surface normally seen on asphalt. There is a 2-inch diameter water drainage pipe at the top of the driveway on the left side, next to the stairway, with a shallow gutter running down along the side of the driveway next to the stairway. Off to the right of the driveway, in the dirt area, are "mini-sprayer" sprinklers, starting at the top of the hill and spaced several feet apart along the hill going towards the street.

CONTINUATION OF INTERVIEW WITH CLAIMANT

Because of the findings at the incident scene compared to the findings at the vehicle inspection, many questions arose in my mind. I telephoned the claimant, Mrs. again. The following is the question and answer session:

- Q. "When did you first notice gasoline in the driveway?"
- A. "I didn't see anything in the driveway before I started the Jeep."
- Q. "Did you smell anything like a gasoline smell?"
- A. "No, I didn't smell anything."
- O. "How much gas was in the gas tank?"
- A. "I had just filled it up a day or so ago. I would say it was about half full or a little more."
- Q. "Have you ever had problems getting up or down the driveway before?"
- A. "No."
- Q. "Do you need to use the 4-wheel drive to get up the driveway?"
- A. "Yes, I always use 4-wheel drive, but my husband can drive his Bronco up in 2-wheel drive."

- Q. "When was the slurry put on the driveway? Was it applied over rough asphalt?"
- R. "It was already there when we purchased the house 4 or 5 months ago."
- Q. "How did this incident begin to happen?"
- A. "As soon as I started to back up, the Jeep began to slide. I pressed on the brakes as hard as I could, but it just kept on going down the driveway."
- Q. "What was the weather like?"
- A. "It was cold about 40 degrees, but it wasn't damp."
- Q. "There were a lot of tire marks, in a strange pattern. How did that happen?"
- A. "I just slid down, then hit the steps. I tried to get off the steps, but then the Jeep went sideways. I thought I was going to tip over. It slid sideways all the way down to the bottom."
- Q. "How did you get the Jeep out of the driveway?"
- A. "When I got to the bottom and didn't tip over, I regained my composure. Then I just drove away down the street. I didn't know I was leaking gas at that time. I got about 2 blocks away and the car died. It was out of gas. Then I saw the trail of gas I left in the street.
- Q. "I saw a lot of black stains in the middle of the driveway. Were they there before the incident?"
- A. "No, they weren't there. The stains are from the gas spilling on the driveway."
- Q. "Did you notice any gas leakage at any other time before the incident?"
- A. "No, never."
- Q. "I noticed sprinklers alongside the driveway. Are they on timers?"
- A. "No. They are manual. We haven't used them in three months."
- Q. "When they do come on, does the water spray on the driveway?"
- A. "No."
- Q. "Could there have been any frost on your driveway that day?"
- A. "No. I always check the weather the night before. If it is going to be below freezing during the night, I park at the bottom of the driveway instead of the top. It wasn't that cold."
- Q. "Can you think of any other reason that your Jeep could have slid down the hill?"
- A. "No. My husband thinks the gas leaked on the tires and made the driveway slippery, so I didn't have any traction. He made a video tape of the driveway on the night of the accident."

END OF INTERVIEW

Gare Lino

Earl Lind, EAA

PRELIMINARY PAR INSPECTION FIELD PHOTOGRAPHIC NOTES

(page 1 of 1)

_	ed By: EARL LIND
	Organization: L.A.A.
	Inspection Date: 12, 16, 99 Mileage at Inspection: 004
g.#	Description
0	
1.	LEFT FRUNT 3/4 VIEW (SHOWING CAIR T)
2.	RIGHT FRONT 3/4 VIEW ("
3.	RILLET DEAD 31
4.	LEGT DEAD 3/4 WOLL
5.	VIN PLATE
3.	SCORDS MAN GAS TANK + SHIELD INSTALLED
7.	SCRAPE MARK ON EXHAUST PIPE
3.	CLOSE UP OF SCRAPE MADE ALL STATES
).	THE NEW DAYS FALLY A COLLEGE
0.	- MARKE ON RT DEAD AVIE 118 VE CILORE LOCALINE
1.	TOP VIEW OF REMOVED GAS TANK FRONT SIDE OF
2.	TOP VIEW OF REMOVED FAS TANK SCHOOL SIDE
3.	DISTORTED EXHAUST PIPE SHIELD
1.	BOTTOM OF REMOVED SHELD SHOWING INDACT DANAGE
5.	COUNTY OF TEMOUED FOR THIS
i	CORNER OF GAS TANK CHUSING IMPART 3414
	COULD OF PAPAGE DAMAGE
	OVERALL VIEW OF INCIDENT SCENE
	VIEW OF STEBP DRIVEWAY + POTINGUE AND
	TIRE MARKS STARTING AT TOP OF DOWNIAN
	VIEW LOOKING DOWN DRIVEWAY
- 2	VIEW WHERE VEHICLE BACKED WITH THE CHARLES
_	TOTAL DE IMPIECI POINT ON BOILE COM
_	VIEW FROM MIDDLE OF DRIVEWAY (SHOWING DARK STAIN FROM F
_	THE STAIN LEAK
-	
-	
7	
_	
-	
-	
-	
-	
-	
_	

PRELIMINARY PAR INSPECTION FIELD PHOTOGRAPHIC NOTES

	TEHRYSLER REIN CAIR 6571572 VIN: 174FY495XXP
	d By: <u>EARL LIND</u> Organization:
Phone:	(760) 947-7865x Inspection Date: 12 16 99 Mileage at Inspection: 00429
	3
Roll No	mber 2
Neg.#	Description
0	
1.	GAS STAIN IN STREET AND AT END OF DRIVEWAY
2.	GAS STAIN (LOOKING UP DRIVEWAY)
3.	TIRE MARKS AT BOTTOM OF STAIRWIAG
4.	TIRE MARKS IN MIDDLE OF DRIVEWAY (ADJACENT TO INDACT ANTES IN
5. 6.	OUS STAINS :) IN DRIVEWAY PRIOR TO IMPACT POUT
7.	DRAINAGE PIPE AT TOP OF DRIVEWAY WEST TO STAID !! AL
8.	SPRINKLERS IN YARD TO RIGHT SIDE OF DRIVEWAY
9.	SPRINKLERS AT TOP OF DRIVEWAY
10.	TOP OF DELITEMENT SHOWING TYPE OF SPEINKLERS
11.	TOP OF DRIVEWAY SHOWING TIRE MARKS AND "DARK SPOT" BETWEEN TRACKS
12.	MIDDLE OF DRIVEWAY (IMPACT POINT, OTHER SIDE, CORNER OF STEPS AT BENCE PHOTO FROM FURTHER DOWN DRIVEWAY
13.	PROXIMITY OF SPRINKLERS ON RIGHT SIDE OF DRIVEWAY
14.	CLOSE-UP OF SPRINKIER HEAD
15.	PARKING AREA AT BOTTOM OF DRIVEWAY AND SHOWS STEEPNESS OF DRIVE
16.	ANOTHER VIEW OF IMPACT POINT
17.	
18.	
19.	
20. 21.	
22.	
23.	
24.	
24. 25.	
24. 25. 26.	
24. 25. 26. 27,	
24. 25. 26. 27, 28.	
24. 25. 26. 27, 28. 29.	
24. 25. 26. 27, 28. 29. 30.	
24. 25. 26. 27, 28. 29. 30. 31.	
24. 25. 26. 27, 28. 29. 30. 31. 32.	
24. 25. 26. 27, 28. 29. 30. 31.	

PHOTO.DOC









\$3,20



HOW TO USE:



 COMPLETE ADDRESS LABEL AREA Type or print required return address and addressee information in customer block (white area) or on label (if provided).



PAYMENT METHOD
 Affix postage or meter strip to area indicated in upper right hand corner.



 ATTACH LABEL (If provided)
 Fiernove label backing and adhere over customer address block area (white area). DAIMLER-CHRYSLER MOTORS ATTN: DENNIS MUCCI P.O. BOX 21-8004 AUBURN HILLS, MI 48321

The efficient FLAT RATE ENVELOPE.

You don't have to weigh the envelope... Just pack all your correspondence and documents inside and pay only the 2 lb. Priority Mail postage rate.

The second secon

We Deliver For You.

MATTER # 6571572

FILE TYPE Customer Complaint

FILE NAME

6571572 CAIR #

DATE OF 12/14/1999 INCIDENT

12/15/1999 DATE OF NOTICE

MODEL/MODEL 1999 Jeep Wrangler (TJ) YEAR

1J4FY49SXXI VIN

MILEAGE 4,291

OWNER

Blue Jay, CA

COURT

DOCKET #

FIRE ALLEGED Leak Only, No Fire

DESCRIPTION On December 14, 1999, a 1999 Jeep Wrangler (TJ), operated by

was involved in a single-vehicle accident in the owner's Blue Jay, California. Investigation conducted by DaimlerChrysler Corporation revealed that the driveway was very steep asphalt with a 21-foot elevation drop over a 59-foot distance. The asphalt was very smooth with a "slurry" or sealant coat on the asphalt. At the time of the accident, the temperature was about 40 degrees. The driver of the Jeep Wrangler (TJ) stated that as she began to back down the driveway she felt the vehicle start to slide and that she braked but the vehicle moved sideways and the rear of the vehicle contacted and travelled over brick steps adjacent to the driveway. She stated that as she tried to get off of the steps, the vehicle slid down the driveway coming to a stop at the bottom. Fuel leakage from the fuel tank occurred. The driver stated that she did not see or smell evidence of leaking gasoline before starting the vehicle and only become aware that the fuel tank was leaking when she ran out of gas after driving for about two blocks.

PROPERTY DAMAGE ALLEGED

No

INJURIES **FATALITIES** 0

0

ANALYSIS

Based on an inspection of the 1999 Jeep Wrangler (TJ) and other available evidence, including an investigation report and photographs prepared at the request of DaimlerChrysler Corporation, Chrysler Group concludes that this was essentially a single-vehicle parking lot accident where the Jeep Wrangler (TJ) backed over brick steps at a low speed, probably in the range of 5-10 mph, resulting in contact of the steps with the rear undercarriage of the vehicle. Inspection of the vehicle by DaimlerChrysler Corporation revealed that the bottom rightrear corner of the fuel tank was punctured and the right side of the fuel tank skid plate was loose and bent. There were reddish colored scrape marks on the exhaust pipe adjacent to the right side of the skid plate, likely from contact with the brick steps. One of the bricks had chips and scrapes on it and black marks were present consistent with the color of the fuel tank. The fuel tank was likely punctured and the skid plate damaged as the rear undercarriage of the vehicle interacted with the brick steps as the Jeep Wrangler (TJ) slid over the steps or as the driver was attempting to move the vehicle off the steps. The damage to the fuel tank of the Jeep Wrangler (TJ) and the scrape marks on the brick steps are depicted in the photographs in Enclosure 3 - Claims - Lawsuits/Peer Vehicles 1997-2006 Wrangler (TJ)/Consumer Complaints, Bates Nos. EA12-005 Peer - Chrysler -10677 and 10681.

EA12-005 CHRYSLER 2/18/2013 **ENCLOSURE 3 CLAIMS-LAWSUITS** PEER VEHICLES – 1997 – 2006 WRANGLER (TJ) LAWSUITS AND CLAIMS

		PLD-PI-001
	ATTORNEY OF PARTY WITHOUT ATTORNEY (Home, S. Januarde, and redevest): Jonathan Gary Netzer, CSBH 157481 SAWL & NETZER 2150 Tulare Street Fresno, California 93721	
	SUPERIOR COURT OF CALIFORNIA, GOUNTY OF Fresho street Address: 2317 Tuolumne Street	ILED
	GRYAND ZIP CODE: Fresno, California 93721	FEB - 4 2009
	By_	SINO COUNTY SUPERIOR COURT
	DEFENDANT: CHRYSLER, LLC: AIRTEX PRODUCTS, LP;	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
	DOES 1 TO	
	COMPLAINT—Personal Injury, Property Damage, Wrongful Death AMENDED (Number): Type (check all that apply): X MOTOR VEHICLE X Property Damage Wrongful Death X Personal Injury Other Damages (specify):	
	Jurisdiction (check all that apply): ACTION IS A LIMITED CIVIL CASE	CASE HUMBER
	Amount domanded describe to the control of the cont	09 CE CG 003 6 2
	1 Pialntiff (name or names)	HTEX PRODUCTS. LP:
	alleges causes of action against defendant (name or names): CHRYSLER, LLC; Al 2. This pleasing, including attachments and exhibits, consists of the following number of page 3. Each plaintiff named above is a competent adult a except plaintiff (name): (i) a corporation qualified to do business in California (2) an unincorporated entity (describe): (3) a public entity (describe): (4) a minor an adult (a) for whom a guardian or conservator of the estate or a guardian ad filter (b) other (specify):	
÷.	bexcept plaintiff (name): (1)a corporation qualified to do business in Galifornia (2)an unincorporated entity (describe): (3)a public entity (describe): (4)a minoran adult (a)for whom a guardian or conservator of the estate-or a guardian ad litem (b) other (apoctly):	
	Information about additional plaintiffs who are not competent adults is shown in At	achment 3. Page 1 of 3 Tentral Code of Chil Procedure, § 425,12
	Form Approved for Optional Use COMPLAINT—Personal Injury, Property Action Countries Confernia Damage, Wrongful Death	Solutions Code of Civil Proceedure, § 425.12

-1	SHORT TITLE	CASE NUMBER:	
	4. Plaintiff (name): le doing business under the fictilious name (specify):		
	and has compiled with the fictitious business name laws.		
	Each defondant named above is a natural person a. X except defendant (name); CHRYSLER, LLC	c. except defendant (neme):	
1	(1) a business organization, form unknown (2) a corporation	(1) a businuss organization, form unknown (2) a corporation	-
	(3) an unincorporated entity (describe):	(3) an unincorporated entity (describe):	
	(4) a public entity (describe):	(4) a public entity (describs):	
	(5) other (specify):	(5) other (specify):	
	b. X except defendant (name): AIRTEX PRODUCTS, IP	d. except defendant (name):	
	(1) X a business organization, form unknown	(1) a business organization, form unknown	
	(2) a corporation (3) an unincorporated entity (describe):	(2) a corporation (3) an unincorporated entity (describe);	
	(4) a public onlity (describe):	(4) a public entity (describo):	
	(5) other (epacify):	(5) Other (spacify):	
	Information about additional defendants who are not natu	ral porsons is contained in Allachment 5.	
	6. The true names of defendants sued as Does are unknown to pl		
	a. Doe defendants (specify Doe numbers): named defendants and acted within the scope of that a	were the agents or employees of other	
	b. Doe defendants (specify Doe numbers):	are persons whose capacities are unknown to	
	plaintiff. 7. Defendants who are joined under Gode of Civil Procedure	section 382 are (names):	
	This court is the proper court because at losst one defendant new resides in its junisdictional	area.	
	b the principal place of business of a defandant corpora c injury to person or damage to personal property occur d other (specify):	tion or unincorporated association is in its jurisdictional area.	
	D. Plaintiff is required to comply with a claims statute, and a. has complied with applicable clothes statutes, or b. Is excused from complying because (specify):	100 Mary 1	11 (8 - 1)
	PLD-P1401 [Rev. January 1, 2007] COMPLAINT—Porsoi Damago, Wro	nal Injury, Property ngful Doath	

		PLD-PI-007	
	SHORTTITLE V. CHRYSLER	CASE NUMBER:	
	10. The following causes of action are attached and the statements above apply to eacauses of action attached): u. X Motor Vehicla o. Ganeral Regligence c. Intentional Tort d. X Products Llabbity e. Premises Liability f. X Other (specify): Exemplary	ich (each compleint must have one ar mora	
	11. Plaintiff has suffered a. X wage loss b. X loss of use of property c. X hospital and medical expenses d. X general damage e. X property damage f. X loss of saming capacity g. other damage (specify):		- *-
	The damages delimed for wrongful death and the relationships of plaintiff a. Ilsted in Attachment 12. b. ns follows:	(O NIN Dacsepen alo	
	13. The relief sought in this compleint is within the jurisdiction of this court.		
· · · · · · · · · · · · · · · · · · ·	to the state of th		5 1 Not 144
	14. Plaintiff prays for judgment for costs of suit; for such relief as is fair, just, and eco. 15. (1) 16. (2) 17. (2) 18. (3) 19. (4) 19. (5) 19. (6) 19. (7) 19. (8) 19. (9) 19. (1) 19. (1) 19. (2) 19. (1) 19. (1) 19. (1) 19. (1) 19. (1) 19. (2) 19. (1)		
	15. X The paragraphs of this complaint alleged on information and belief are as	follows (specify paragraph numbers):	
	ALL.		
		1	
- m	Date: V7 JAL OF	D	**************************************
	JONATHAN GARY NETZER (TYPE ORIVEN HAME)	(SIGNATURE OF PLANTIFF OR ATTORNEY)	
i	PLOTHONING, JANUARY 1, 2007] COMPLAINT—Personal Injury, Prop Damago, Wrongful Doath	erty Page 2 of 5	

FIRST CAUSE OF ACTION—Motor Vehicle
(number)
ATTACHMENT TO X Complaint Cross - Complaint
(Use a separate cause of action form for each cause of action.)
Plaintilf (nante):
MV-1. Plaintiff alleges the acts of defendants were negligent; the acts were the legal (proximate) cause of injuries
and damages to plainliff; the acts occurred
on (deleg): 9/15/08
al (place): SR 41 N/B, Fresno County, California
 Company Company
MV-2. DEFENDANTS
a. X The defendants who operated a motor vehicle are (names): CARRIE ANN STROUD
The defendance who operated a motor varieties are (numes); CARRIE ANN STROUD
X Does 1 to 50
b. X The defendants who employed the persons who operated a metor vehicle in the course of their employment are (names);
are (names).
C. X The defendants who owned the motor vehicle which was operated with their permission are (names):
The deficients who dwise up involvemed which was operated with their permission are (names):
· ·
 [V] 01
 d. X The defendants who entrusted the motor vehicle are (names):
C. E. The detailed in Symbol and Indier Venicle are (names):
X Does 1 to 50
e. X The defendants who were the agents and employees of the other defendants and acted within the scope
of the amenculare (names): CHRYSLER, LLC; AIRTEX PRODUCTS, LP AND
X Does 1 to 50
f. X The defendants who are liable to plaintiffs for other reasons and the reasons for the liability are
☐ listed in Attachment MV-2f 图 as follows:
CHRYSLER, LLC; AIRTEX PRODUCTS, LP and Does 1 to 50, who negligently and/or wrongfully managed, manufactured, sold and/or maintained a
motor vehicle.
X Doos 1 to 50

F.		PLD-PI-001(6)	
*	SHORT TITLE: V. CHRYSLER	CYGE HUNGEN	
	Exemplary Damages Attachment ATTACHMENT TO X Complaint Cross-Complaint EX-1. As additional damages against defendant (name):	Paga <u>5</u>	
_	Plaintiff alleges defendant was guility of X mailice I fraud X opprocessor as defined in Civil Code section 3294, and plaintiff should recover, in addition to	o actual damages, domages	—
	intoxicated; Defendant knew that when she became is going to be required to drive a car after she was was aware of the probable consequences; and Defend deliberately failed to avoid these consequences and dispensed for the safety or rights of others.	intoxicated. Defendant dant willfully and not acted with conscious cifically Plaintiffs, xicated, operated a motor	
and the Common way of the			
	EX-3. The amount of examplary damages sought is	44	
	a. not shown, pursuant to Code of Civil Procedure section 425.10.		

EXEMPLARY DAMAGES ATTACHMENT

		PLD-PI-001(5)	
Y ()	SHORT TITLE: V. CHRYSLER	C/SE INVIOERE	
	THIRD GAUSE OF ACTION—Products Liability (number) ATTACHMENT TO X Compleint Cross-Compleint (Use a separate cause of eallon form for each cause of eallon.) Pleintiff (name): Prod. L-1. On or about (date): 9/15/08 plaintiff was injured 2004 Jeep Wrangler and Airtex Electric Fuel Pu	Page <u>6</u> by the following product:	
		roduct at the time of injury	
	PLAINTIFF'S INJURY WAS THE LEGAL (PROXIMATE) RESULT OF THE FOrmation of the following defendants who a. X manufactured or essembled the product (normas): CHRYSL LP X Does 1 to 50 b. X designed and manufactured component parts supplied to the CHRYSLER, LLC, AIRTEX PRODUCTS, LP	ER, LLC, AIRTEX PRODUCTS,	
(ex-selves () (4e))	a, X cold the product to the public (names):CHRYSLER, LLC,	AIRTEX PRODUCTS, LP	
	Prod. L-5. X Count Two-Negligence of the following defendants who ewed a duty CHRYSLER, LLC, AIRTEX PRODUCTS, LP X Does 1 to 50 Prod. L-5. X Count Three-Breach of warranty by the following defendants (name PRODUCTS, LP X Does 1 to 50 a. X who breached an implied warranty b. X who breached an express warranty which was X written oral Prod. L-7. The defendants who are liable to plainliffs for other reasons and the residue.	os): CHRYSLER, LLC, AIRTEX	
	Illeted in Attachment-Prod. L-7 as follows:	Page 1 of 4	
	Form Appetition for Optional Use Judged Council of Circletonia B. D. Ellow (Circletonia B. D. Ellow) (Circletonia B. D. El	and the second s	

ATTERNEY OR PARTY VARIABLE ATTORNEY (Name -Bar minber, and address):	CM-010	
Jonathan Gary Netzer, Cod 157481 SAWL & NETZER 2150 Tulare Street Fresno, California 93721 Fresno, California 93721 Fresno, California 93721 FRENDORENO (559) 256-9800 ATTORNEY FOR PLAND PL	FILED	
STREET ADDRESS 2317 Tuolumne Street MANING ADDRESS 627 West 21st Street GRYAND SIPCODE Fresho, California 93721 BRAICHNAME Central Division GASE NAME: v. CHRYSLER	FEB - 4 2009 RESNO COUNTY SUPERIOR COURT	
 GIVIL-GASE-GOVER-SHEET Complex-Case-Designation— X	O 9 CE CG 0 0 3 6 2	
exceeds \$25,000 \$25,000 or loss) (Gal, Rules of Gourt, rule 3,402)	DEFI	
X Auto (22)	ovisionally Complex Civil Litigation sil. Rules of Count, rules 3.400-3.403) Antitust/trade regulation (03) Construction defact (10) Mass ton (40) Securites litigation (28) EnVironmento/Toxis ton (30) Insurance coverage dalma mising from the	
Other PIPDAWD (23) Condemnation (14) Non-PIPDAWD (Other) Tort Wrongful eviction (33)	aboue listed provisionally complex ease types (41)	
Civil rights (08) Unlawful Detainer Defemblion (13) Commercial (31) Mil Fraud (16) Residential (32) Intellectual property (19) Drugs (30)	Inforcement of Judgment Enforcement of Judgment (20) accillancem Civil Complaint RICO (27) Dibar complaint (not specified above) (42) scaliancems Civil Patition Fortnership and corporate governance (21) Other patition (not specified above) (43)	
seuce that will be time-consuming to resolve In other counties, to	filnosses elated actions pending in one or more courts states, or countries, or in a federal court dyment judicial supervision ratory or injunctive relief c. punilive	
	USB FORTY ORATIONHEY FOR PARTY)	
- Plaintif must file this cover sheet with the first paper filed in the ection or proceeding (examples the Probate Code, Family Code, or Welfare and institutions Code). (Gal. Rules of this accions. - File this cover sheet in addition to any cover sheet required by local court rule. - If this case is complex under rule 3,400 et seq. of the California Rules of Court, you must other parties to this action or proceeding. - Unless this is a collections case under rule 3,740 or a complex case, this cover sheet we	Court, rule 3.220.) Feiture to file may result at serve a copy of this cover sheet on all lil be used for stallatical purposes only.	
From Abopted for Monatohry Uses Autical Gourant of Carifornia CASE COVER SHEET Solution CASTO (Inc. Asy 1, 2007)	Fego 1 of 2] Col. Rules of Court, nation 2.30, 1220, 3.450–3.400, 3.740; Col. Standards of Judicki Administration, etc. 3.10 113	

FOR COURT USE ONLY SUPERIOR COURT OF CALIFORNIA . COUNTY OF FRESNO CIVIL DEPARTMENT, CENTRAL DIVISION 2317 Tuolumne Street Fresno, California 93721 Filed (559) 497-4100 Fresno County FEBRUARY 04, 2009 TITLE OF CASE: By System s Chrysler, LLC NOTICE OF CASE MANAGEMENT CONFERENCE AND CASE NUMBER ASSIGNMENT OF JUDGE FOR ALL PURPOSES -09CECG00362AMS To All Parties and their Attorneys of Record:

This case has been assigned to Judge Alan Simpson for all purposes.

All future hearings will be scheduled before this assigned judge.

You are required to appear at a Case Management Conference on JUNE 08, 2009 at 01:30 PM in Dept 97E, 2317 Tuolumns located at, Fresno, California.

0

You must comply with the requirements set forth in Fresno Superior Court Local Rule 2.1.

Failure to appear at the conference may result in imposition of sanctions, waiver of jury Irial, or other adverse consequences.

Defendants: Appearance at the Case Management Conference does not excuse you from having to file your response in proper legal form within 30 days after the Summons is served on you. You could lose the case if you do not file your response on time. If you do not know an attorney, and do not have one, you may call an attorney referral service or a legal aide office (listed in the phone book).

IMPORTANT: This hearing is no) a trial. It is for the court to inquire as to the status of the case and to determine what future hearings, including a trial date, need to be set.

DECLARATION

I declare under penalty of perjury under the laws of the State of California that I gave a copy of the Notice of Case Management Conference and Assignment of Judge for All Purposes to the person who presented this case for filling.

Date: February 4, 2009

Clark, by

L. Esparza

, Deputy

BCV-40C E04-00

NOTICE OF CASE MANAGEMENT CONFERENCE AND ASSIGNMENT OF JUDGE FOR ALL PURPOSES Local Fluie 2.1

	- UNLESS YOU ARE APPLYING FOR A DEFAULT JUDGMENT UNDER	CODE OF CIVIL PROCEDURE 6 505 -
	ATTORNEY OR PARTY WITHOUT ATTORNEY (Memo and Address): Jonathan Gary Netzer, CSB# 157481 SAWL & NETZER 2150 Tulare Street Fresno, California 93721 ATTORNEY FOR (sound: Plaintiffs	FOR COURT USE ONLY
(V	SUPERIOR COURT OF CALIFORNIA, COUNTY OF Fresho STREETADDNESS: 2317 Tuolumne Street MAUNIGADDRESS: CHYAND ZIP CODE: Fresho, California 93721 GIVANDELAWARE: CENTRAL DIVISION	
	DEFENDANT: CHRYSLER, LLC, AIRTEX PRODUCTS, LP, CA STATEMENT OF DAMAGES (Personal Injury or Wrongful Death)	CASE NUMBER:
	To (name of one defendant only): Plaintiff (name of one plaintiff only): seeks damages in the above-onlitied action, as follows: 1. General damages a. X Pain, suffering, and inconvenience b. Emotional distress c. Loss of consortium	\$
	d. Loss of society and companionship (wronglul death actions only)	\$
	e. Other (specify) f. Other (specify) g. Continued on Attachment 1.g. Special damages a. X Medical expenses (to date) b. X Future medical expenses (present value)	\$\$
	c. X Loss of earnings (to date)	
	d. X Lose of future earning capacity (present value). e. Property damage f. Funeral expenses (wrongful death actions only). g. Future contributions (present value) (wrongful death actions only). h. Value of personal service, advice, or training (wrongful death actions only). Cher (specify) j. Other (specify) k. Continued on Attachment 2.k. 3. Punitive damagos: Plaintiff reserves the right to seek punitive damages in when pursuing a judgment in the suit filed against you.	\$
de S	Jonathan Gary Netzer. CSB4 157481	OF PLANMIFF ON ATTORNEY FOR PLANMIFF) Page 1 of 2 Legal Code of Code Pricadus; 55 425.11, 425 115 Solutions Cal Plus

- DO NOT FILE WITH THE COURT -

CIV-050

- DO NOT FILE WITH THE COURT -R A DEFAULT JUDGMENT UNDER CODE OF CIVIL PROCEDURE \$ 585 -

	ATTORNEY OR PARTY WITHOUT ATTORNEY (Name and Address). TELEPHONE NO:	FOR COURT USE ONLY	
*	Jonathan Gary Netzer, CSB# 157481 SAWL & NETZER 2150 Tulare Street Fresno, California 93721 Fresno, California 93721 Fresno, California 93721 ATTORING FORMATT Plaintiffs		
	SUPERIOR COURT OF CALIFORNIA, COUNTY OF Fresho street address: 2317 Tuolumne Street MALLIG ADDRESS: TURNING ADDRESS: Tresho, California 93721		
100	PLAINTIFF: DEFENDANT: CHRYSLER, LLC, AIRTEX PRODUCTS, LP, CA		
	STATEMENT OF DAMAGES (Personal Injury or Wrongful Death)	CASE HUNDER:	
	To (name of one defendant only): AIRTEX PRODUCTS, LP Plaintill (name of one plaintill only): SHERI CABALLERO seeks damages in the above-entitled action, as follows: 1. General damages a. X Pain, suffering, and inconvenience b. Emotional distress c. Loss of consortium	\$	
	d. Loss of society and companionship (wrongful death actions only)		
	e. Other (specify) f. Other (specify) g. Continued on Attachment 1.g. 2. Special damages a. X Medical expenses (to date).	s	
	b. X Future medical expenses (present value) c. X Lass of earnings (to date)	\$ 1,000,000	
	d. X Loss of future earning capacity (prosent value). e. Property damage f. Funoral expenses (wrongful doath actions only). g. Future contributions (present value) (wrongful death actions only). h. Value of personal service, advice, or training (wrongful death actions only).	\$ _5,000,000 \$	Section Section 11 s language
	Other (specify) Other (specify) k, Continued on Allachment 2.k.	\$ \$	
	Punitive damages: Pleintiff reserves the right to seek punitive damages in whon purpuling a judgment in the suit filed against you.	the amount of (specify). \$	40-24-2-2-
	Jonathan Gary Netzer, CSB# 157481 Jonathan Gary Netzer, CSB# 157481 [Pred on Willett MANE] (Proof of service on reverse) STATEMENT OF DAMAGES (Personal Injury or Wrongful Death)	COS PLAINTEFF ON ATTOUNEYFOR PLAINTEFF) Page 1 oi 2 Legal Code of CMI Procedure, 59 125.11. 425 115 Solutions G Plus	

ATTORNEY OR PARTY WITHOUT ATTORNEY (Name, State JOHNATHAN NETZER SAWL & NETZER 2150 TULARE STREET FRESNO, CA 93721 TELEPHONE NO.: (559) 266-9800 FAX NO.(Optional): (559) 266-3421 E-MAIL ADDRESS (Optional): ATTORNEY FOR (Name): Plaintiff SUPERIOR COURT OF CALIFORNIA, COUNTY OF FRESNO	FOR COURT USE ONLY FOR COURT USE ONLY MAR - 5 2000
STREET ADDRESS: 2317 TUOLUMNE STREET MAILING ADDRESS: CITY AND ZIP CODE: FRESNO, CA 93721 BRANCH NAME: UNLIMITED	THE TOWN COUNTY SUPERIOR COUNTY
PLAINTIFF/PETITIONER: ET AL	CASE NUMBER:
DEFENDANT/RESPONDENT: CHRYSLER, LLC, ET AL	09CECG00362
PROOF OF SERVICE OF SUMMONS	Ref. No. or File No.:
(Separate proof of service is required for each party se	erved.)
 At the time of service I was at least 18 years of age and not a party to this action. I served copies of: 	7
a. X summons b. X complaint c. Alternative Dispute Resolution (ADR) package d. X Civil Case Cover Sheet (served in complex cases only) e. cross-complaint f. X other (specify documents): Notice of Case Management Conference as purposes; Statement of Damages	nd assignment of Judge for all
3. a. Party served (specify name of party as shown on documents served): CHRYSLER, LLC	
 b. Person served:	the party named in item 3a): ROCESS
4. Address where the party was served: 2730 GATEWAY OAKS DRIVE SACRAMENTO, CA	
 I served the party (check proper box) a. X by personal service. I personally delivered the documents listed in item 2 to the receive service of process for the party (1) on (date): 02/11/2009 (2) at (time): 	ne party or person authorized to 11:30 am
b. by substituted service. On (date): at (time): I left the documents listed in ite in the presence of (name and title or relationship to person indicated in item 3b):	m 2 with or
(1) (business) a person at least 18 years of age apparently in charge at the person to be served. I informed him or her of the general nature of the p	office or usual place of business of the apers.
(2) (home) a competent member of the household (at least 18 years of age) abode of the party. I informed him or her of the general nature of the party.	at the dwelling house or usual place of pers.
(3) (physical address unknown) a person at least 18 years of age apparer of the person to be served, other than a United States Postal Service po- general nature of the papers.	atly in charge at the usual mailing address st office box. I informed him or her of the
(4) thereafter mailed (by first-class, postage prepaid) copies of the docume place where the copies were left (Code Civ. Proc., §415.20). I mailed the (date): from (city): or	nts to the person to be served at the documents on a declaration of mailing is attached.
(5) I attach a declaration of diligence stating actions taken first to attempt	에 보고 있다. 그렇게 되었다면 하는데 하는데 보고 있다면 하는데 되었다면 되었다면 보고 있다면 보고

PLAINTIFF/PETITIONER:	CASE NUMBER:
DEFENDANT/RESPONDENT: CHRYSLER, LLC, ET AL	09CECG00362
c. by mail and acknowledgment of receipt of service shown in item 4, by first-class mail, postage prepaid	ce. I mailed the documents listed in item 2 to the party, to the address
(1) on (date):	(2) from (city):
(Attach completed Notice and Acknowledge (4) to an address outside California with return	
d. L by other means (specify means of service and auth	horizing code section):
Additional page describing service is attached. 6. The "Notice to the Person Served" (on the summons) was	completed as follows:
 a. as an individual defendant. b. as the person sued under the fictitious name of (special as occupant.) 	necify);
 d. X On behalf of (specify): CHRYSLER, LLC under the following Code of Civil Procedure section: 	c c
416.10 (corporation) 416.20 (defunct corporation)	415.95 (business organization, form unknown) 416.60 (minor)
416.30 (joint stock company/associa 416.40 (association or partnership) 416.50 (public entity)	ation) 416.70 (ward or conservatee) 416.90 (authorized person) 415.46 (occupant)
	other: LLC
7. Person who served papers a. Name: TERRY ROOT	
 b. Address: 1099 East Champlain Ave., Suite A-102 c. Telephone number: (559) 222-2274 	2 Fresno, CA 93720
d. The fee for service was: \$ 77.50 e. lam:	
 (1) not a registered California process server. (2) exempt from registration under Business and Process 	rofessions Code section 22350/b).
(3) X registered California process server: (i) owner X employee (ii) Registration No.: 2006-72 (iii) County: SACRAMENTO	independent contractor.
B. X I declare under penalty of perjury under the laws of the	e State of California that the foregoing is true and correct.
9. I am a California sheriff or marshal and I certify that	the foregoing is true and correct.
Date: 02/12/2009	
Eddings Attorney Support Services, Inc. 1099 East Champlain Ave., Suite A-102 Fresno, CA 93720 (559) 222-2274	
	1
TERRY ROOT (NAME OF PERSON WHO SERVED PAPERS/SHERIFF OR MARSHAL)	(SIGNATURE)

MATTER # 1203422

FILE TYPE Legal Claim

FILE NAME
CAIR #

DATE OF 09/15/2008 INCIDENT

DATE OF NOTICE 07/06/2009

MODEL/MODEL 2004 Jeep Wrangler (TJ)
YEAR

VIN 1J4FA29154F

MILEAGE

OWNER

Fairfield, CA

DOCKET #

FIRE ALLEGED Yes

On September 15, 2008, a 2004 Jeep Wrangler (TJ), operated by was travelling on Interstate 41 in Fresno County, California.

Based on the Complaint and discovery motions filed in subsequent

litigation related to the accident, a 2007 Audi 4, operated by struck the left-rear of the Jeep Wrangler (TJ). A fire ensued in the area of both vehicles. It was alleged in the litigation that the driver of the Audi 4 was intoxicated at the time of the accident.

PROPERTY No DAMAGE ALLEGED

INJURIES 2

FATALITIES 0

ANALYSIS The 2004 Jeep Wrangler (TJ) was not inspected. Chrysler Group has

also been unable to obtain a police accident report. Because Chrysler Group has limited information regarding the accident, it is unable to determine a likely relative impact velocity of the Audi 4 that struck the rear of the Jeep Wrangler (TJ), but notes that the accident occurred on an interstate highway with a high speed limit. Because it has not inspected the Jeep Wrangler (TJ), Chrysler Group is unable to confirm that, as a result of the impact, the fuel tank ruptured or that the origin

of the fire was at the fuel tank.

EA12-005 CHRYSLER 2/18/2013 **ENCLOSURE 3 CLAIMS-LAWSUITS** PEER VEHICLES – 1997 – 2006 WRANGLER (TJ) LAWSUITS AND CLAIMS

Customer A	ssistance	Inquiry Re	cord (CAIR)#				20372373
VIN	1J4FA49S9	Y	Open Date	01/31/2011	Built Date	05/24/2000	
Model Year	2000	Body	TJJH77	JEEP WRANGLER SPORT 4X4 SPORT UTILITY 2-DR			
In Service Dt	12/29/2000	Mileage	138,000	Dealer Zone	63	DALLAS	
Plant	P	TOLEDO ASS	EMBLY PLANT II (STICKNEY)	Market	U	US	
Color	PBT	PATRIOT BLUE PEARL COAT					
Engine	ERH	4.0L I6 POWER TECH ENGINE					
Transmission	DDD	5-SPEED HD	5-SPEED HD MANUAL TRANSMISSION				
Dealer	26057	DENNIS EAKIN CHRYSLER JEEP					
Dealer Address	4301 STAN						
Dealer City	KILLEEN	GILLEEN Dealer State TX			TX	Dealer Zip	76543
Owner						Contact Type	TELEPHONE
Address						Home Phone	
	FORT HOOD TX				Country	UNITED STATES	
Product - Unknow	wn - Unknown	- Accident - De	fault		rear end	ed, caught fire.	
Corporate - Prop			ult - Default				
Dealer - By-Pass Product - Fuel Sy							

1 Who is calling and what is their contact information?

Product - Unknown - Unknown - Fire - Unknown

2. What happened? Sitting at a stop light. Vehicles rear ended and pushed into the intersection. Rear of the jeep and front of the other vehicle were on fire. Customer states from what he saw it looked like the vehicle got under the jeep and the fuel tank was sheared open, providing fuel for the fire. All the doors were stuck locked and customer could not get them to unlock or open. Customer was trapped in the vehicle until someone came and removed the passenger side window and let him out.

 What is the current location of the vehicle? Goody towing and recovery, 5209 South Fort Hood Road, Killeen, TX, 76542. Contact Number: 800-654-2419/254-526-2774

Reassigned to 88S

02.01.11

>> case is being forwarded to Chrysler Legal (CCRG) (2-5 days contact).
VEHICLE LOCATED AT:

Goode Towing & Recovery 5209 South Fort Hood Street

Killeen, TX 76542-4810

(254) 526-2774

Per OGC Matrix, reassigned to 82T. MG17

2.1.11 One Open Recall;

_B06 INTAKE MANIFOLD DEBRIS SHIELD SAFETY 05/09/2002 INCOMPLETE

2.1.11 Assigned to RLG92. MJK

CAIR NUMBER 20372373 REQUEST EAA INSPECTION 02-01-2011 12:20

CAIR NUMBER 20372373 E-MAIL SENT TO EAA 02-01-2011 12:20

CCRG Open Date: 02/01/2011 10:05:28

Letter Sent: Acknowledgement 02/02/2011 14:07:27

PHOTOGRAPHIC IMAGES POSTED TO THIS CAIR ON 02/07/11 AT 19:45:56 20372373

Letter Sent: Denial 02/11/2011

















































Ci

CAR 20372373 All-147 10/3

OBSERVERS ATEMENT REGARDING TRAFFIC ACCIDENT

Y		DATE 97 JAN 2011
NAME _		behave no 12,
ADDRESS	Kilken City	Tems
Street Addres		State
My location when accident has bound on their cleek & Florida.	ppenel was Stopped for	t car at light towely to
14 14	your own words just w	you saw Page lof
while stooped at the least within a private of private by	appear duls fising	and let witnessed (4 per seden)
the vehicles were	ing S. When the	ran into the back
	+ burst into flames	the sound front left of
	it with such force	the back lifted off
	d approximately 5-10	into the intersection
and the sedan continue	n the road nitting	e mail buy at
	ntrol into the right	older gammakely body
5 of the intersection . A	fite witnessing the	ident I immediately
ran to Vehicle ##	ture off the right	surger side Plastic winder
and pulled to the	e burning vehicle. =	emoved his assault
pack and consolidate in	and his apar at	parement leading into
, I s	a nearly onlocker	yelled to call 911.
I then ron to a	iccord white and	ned the door so the
sedan. [continent kt	Pye SIGNATURE	
Information Copy Only value of property or damage not verified	FOR OFFICE USE ONLY	
		11100
County Sell	Highway & Location	POR CROCK D ZIMS
Date of Accident / 1	20 Day of Week	ms Hour 6/5 PM

UPM PALII	ase 10 A11-800147	TALKO: Crash 'D		Page : 2
	7.	laver By	Arts of Deep MODULANCE	i manta
1 1 DARNELL AR	MY HOSPITAL	KILLEEN EMS 5	Di	
GIRWELL AR	MY HOSPITAL	KILLEEN EMS 5		
2				- 1
*			2000年17 ニー	
			置 選/ _	
Lot Ran				
2 .		Depe		Clation Reference reur
	FAIL TO CO	NTROL SPEED		433
Denegati Protein Gran Pan Veno	6)	Owners Name	Owner	Address
	NSPORTING T	. 25 ver 29 Came		
Centra Cor	ARDOUS MATERIAL FAMOUS	City Oper (0.1)0e		
No Remy 31 ROVW	Personne Harwa Pers	news negation		erus:
Type Street	ROW NO S	Sata Num Churm		NA
Social State Traces No.	DAWR	Type trans-3 N	VR VR	34 fee Type
ChiEvens 15 Sec. 15 Sec.		16 Seq 4		Total Num. Tres
26 Controuting Factors Investigators Unit Num Community Way II	Operation Control Control of	(Investigator's Opinion) May Have Compo	ental and Ro.	toway Conditions
1 2 22		173	ng Rusumuy = Type	Rosdway Surface Trail Algorithms Condition Con
			1	1 2 5
Knee Justin's Namables Claim (Apach Appropria Shar	FO T NECESSARY)	Indicate 🛕	- Not to Se	cále
LIGHT IN THE 3300 BLOCK OF CLE		North 🕇	11.5	
COMING UP BEHIND UNIT 1. UNIT		4	1	Y
HIS SPEED AND STRUCK UNIT 1 D	UE TO UNIT 2 STRIKING		3 1	
THE GAS TANK ON UNIT 1. BOTH FLAMES, BOTH DRIVERS WERE TR		2350 Bix closed Com		
ARMY HOSPITAL WITH UNKNOWN	NINJURIES UNIT 1	3,00	2	STACKIE SIMS
RECEIVED VB-1 DAMAGE UNIT 2 : DAMAGE	RECEIVED BY-7 AND LF-3	×		
	日臺	Q		
	1	8		
	1 2	6		
	-	F(+	di di	
	B	المُعْلِدُ ا	等!	
	11 4	1		
	計 臺		12	1
	1		11-	
WANTE DISP	ATCHED	DE S	M 0 2	0 3 2 0 1 1
No No New Printer MICHAEL A	WATTS		E No	79
- TX3 14 0 4 0 0 **	SES KILL	EEN POLICE DEPAR	Details	
W	-		E 1	
	. 4		85	
	i. I		EA12-005 Pe	eer - Chrysler - 10769
				The second secon

0372373. PACE KILLEEN POLICE DEPARTME OBSERVERS STATEMENT REGARDING TRAF CCIDENT DATE 27 Jan 2011 Appear OUIS NAME Middle Last ADDRESS treet Address City State My location when accident happened was Page sof 5 (Please tell in your own words just you saw) we on Until arrived Ident to nas his jured he Traps appeared and complain COMSOID OFT Dennis HHL 0748 KILLEEN PO E DEPARTMEN Inform Copy On value of prope damage not v SIGNATURE 30+3 FOR DFFICE USE ONLY

Highway & Locat

20 _ Day of Weel

County

Date of

dent

Hour

AM

PM

CAIA: 20372373 PACE

11.147 20/3

CESERVERS STATEMENT REGALDING TRAFFI CCIDENT

NAM				27 Jan 2011
111	4 #		Las	IDATAWAY =
ADDRESS		City		State
My location when acc	ident happened	es see pas-	4 (104	
(Please	tel in your or	w Words just w	that who save	Page 2.f
		1	Ė	
air 1 Jepl		dazed wi	*	
of vept	to and his	and was		to the help
we mr.	from	the burning i		moved him
10 McDona		area. As w	The state of the s	Mr
the officer		J grove	and stop	ped traffic
he as sed from	Le Sorth.	I Stepped	with 1	nim and inform
him be star		s injured pe	ence 1 and	informed him
that hould	e and in	two at -		ius were
wer	N. P. I.	9	the	I can
we prov	by me infe	i .	he police.	
per man w	1 we provi	•	ic from m	
and to form	s riked out	to Keep		naim and
mtn-us	bale	SIGNATURE		-
	FOR OF 1	CE USE ONLY		
Count	Hibb	way & Location	*	
eate dent	20	Day of Week		Hour PM
.P.D1				
			EA1 005 Peer - Ch	nrysler - 10771

MATTER #

FILE TYPE Legal Claim

FILE NAME

CAIR # 20372373

DATE OF 01/27/2011 INCIDENT

DATE OF NOTICE 01/31/2011

MODEL/MODEL

DEL 2000 Jeep Wrangler (TJ)

1219129

YEAR

VIN 1J4FA49S9Y

MILEAGE 138,000

OWNER

Fort Hood, TX

COURT

DOCKET #

FIRE ALLEGED Yes

On January 27, 2011, a 2000 Jeep Wrangler (TJ) was being operated by southbound on Clear Creek Road near the intersection

of Elms Rd. in Killeen, Texas. The posted speed limit at the site of the accident was 55 mph. According to the police accident report, the Jeep Wrangler (TJ) was stopped for a red light at the intersection with Elms Rd. when a 2002 Buick LeSabre, operated by also southbound on Clear Creek Road approaching the Elms Rd. intersection and failed to control its speed causing the left-front of the Buick to strike the right-rear of the Jeep Wrangler (TJ). The impact caused the Jeep Wrangler (TJ) to move approximately 5-10 feet into the intersection and the Buick travelled through the intersection and off the road onto the right shoulder where it struck a mail box. A fire

ensued in the area of the Jeep Wrangler (TJ).

PROPERTY DAMAGE ALLEGED

No

INJURIES 2

FATALITIES 0

ANALYSIS Chrysler Group does not have sufficient information about the accident

to determine a likely relative impact velocity between the Jeep Wrangler (TJ) and the Buick LeSabre, but notes that the speed limit at the site of the accident was 55 mph and the Jeep Wrangler (TJ) was stopped at the time of the accident. Based on an inspection of the 2000 Jeep Wrangler (TJ) and other available information, including the police accident report, Chrysler Group concludes that during the impact, the front end of the Buick travelled under the right-rear bumper of the Jeep Wrangler (TJ) contacting the right side of the skid

plate resulting in an approximate 8-inch fold in the skid plate and the

subsequent fire.¹ The impact also resulted in damage to the rear of the Jeep Wrangler (TJ) including deformation of the spare tire carrier. The damage to the rear of the Jeep Wrangler (TJ), including abrasion damage on the fuel tank skid plate, is depicted in the photographs in Enclosure 3 – Claims – Lawsuits/Peer Vehicles – 1997-2006 Wrangler (TJ)/Lawsuits and Claims, Bates Nos. EA12-005 Peer – Chrysler – 10765-10766. Chrysler Group notes that, according to records from the CarFax vehicle database, the Jeep Wrangler (TJ) had been involved in a severe accident two years earlier resulting in the vehicle being sold for salvage and rebuilt.

¹ A vehicle inspection was conducted at the request of counsel in anticipation of litigation and the report is being withheld under a claim of attorney work product privilege.

EA12-005 CHRYSLER 2/18/2013 **ENCLOSURE 3 CLAIMS-LAWSUITS** PEER VEHICLES - 1997 -2006 WRANGLER (TJ) Reports of Accidents

[3	AW Enfor	cemen []C			Jse Only OOL BUS	RAILE	OAD [МАВ		SUPPLE	EMENT	□ ACTIV	Æ OOL ZONE	Total Num Units L	3 Total Num Prsn	. 1	TxDOT Crash ID	1 55411
Γ	*Crash (MM/DD/		,0,5	1	_3_/_2	, 0 , 1 ,	0 * Cra	ash Tim RMM)	e	1,7,	1,7,	Case ID				Local Use		
NO	*County Name	E	Bastro	p							* City Name	ed is no		(record [14] and 14		-1-	···	Outside City Limi
DLOCATI		to any o	ne person	's prop		st \$1,000	47.5	itude cimal di	egree	s) _3	3,0.	1,6	9,6	Longitude (decimal de	grees)	_0,9,7	1,9,	5, 2, 4
ON AN	*1 Rdwy.		14.00	My.	21	2 Rdwy Part	1	Block Num.			3 Stre	et	* Stree	1	10 T 1 T 10 T 10 T 10 T 10 T 10 T 10 T		4 Street	
A7	Cr. Cr.	ash Occording	curred on ate Prope	a Priva rty/Pari	te Drive or king Lot	Toll L		eed nit	70	Const. Zone	☐Yes ☑No	Workers Present	Yes No	Street Desc.	+ 11912	j.	TOURING TO SERVICE OF THE SERVICE OF	
DENTIFIC	INTERSE	ECTING	ROAD, C	RIFC	RASH NOT	AT INTERS	ECTION, I	VEARE	STR	DAD OR	REFEREN	ICE MARK			- Comme		(m) (1 (m) (m) (m) (m)	/)
IDE	At V	Yes			Hwy, Num.	139	2 Rdwy. Part	1	Blo	ck		3 Stree Prefix		Street TRA	VIS		4 Street Suffix	RD
L	Distance Ref. Mark		. or		FT	3 Dir. From or Ref. Ma		Refe	erence ker	9	Stre			×\$	Policina (management)	RRX Num.		1 1

TEXAS HIGHWAY PATROL DIVISION



MAJOR CRASH INVESTIGATION

Investigated by:	R. Bradshaw #12059	
Approved by:	77.7	Date: 09-20-10
REVISION (IS/16 SCRT	TONY D. THOMPSON, SGT	-HP

	V	ehicle IN1	# 1 ERIOR	Page	e 1 of 6	3				
LICENSE PLATE OR VEHICLE DESCRIP	PTION:	200	2 Silver, Ch	evrole	t Prizm	4DR, TX LF				
SPEEDOMETER LOCKED ON SPEED:	YES			NO	X	SPEED				
HEADLAMP SWITCH:	ÓN			OFF	X	OPERATIVE	E: YES	X	NO	
TURN INDICATOR:	UP		1	DOWN		OFF X				
HORN:	OPERABLE	X		NOT		NO F	OWER			
HIGH BEAM INDICATOR LIGHT:	HIGH BEAM		LOW	BEAM	X	NO F	OWER			
HIGH BEAM SELECTOR SWITCH:	OPERABLE	X		NOT		NO P	OWER			
MILEAGE:			UNK			NO P	OWER		(DIGIT	AL)
POSITION OF GEAR SHIFT:			DRIV	E						
WINDSHIELD WIPER:	ON		OFF	X	OPE	RATIVE: YE	s X	NO		
RADIO OR STEREO SYSTEM:	ON		OFF	X	V	OLUME:				
C.B. RADIO: N/A	X ON		OFF		V	OLUME:				
REAR VIEW MIRROR:	INTACT	X	GONE:		0	THER:				
POSITION OF TEMPERATURE CONTRO	OL: OFF HEAT	В	A/C VENT	X		DEFROST X	1999	AX HER]	
ASH TRAY:	FULL		EMPTY	X	LOCA	ATION/CONTE	ENTS			
RADAR DETECTOR:	YES		NO	X						
SEAT BELTS: (DRIVER) FRONT SEAT MIDDLE: SEAT BELT ANCHORS I PASSENGER: SEAT BELT ANCHORS I BELTS CUT, BROKEN, O	BROKEN:	OPE	RABLE: RABLE: RABLE:	YES YES YES YES YES YES	X	NO	NO FR	ONT/M	DDLE	S/B
CONDITION OF BRAKE AND GAS PEDAI NOTE ANY PROBLEMS WITH REAR SEA LOCATION OF TINTED GLASS: LOCATION OF BLOOD: LOCATION OF BODY TISSUE: LOCATION OF HAIR: LOCATION OF OTHER: NOTE AND DESCRIBE ANY ODORS:			0	NONE NONE NONE NONE NONE NONE NONE						

Vehicle # 1 Page 2 of 6

FRONT LEFT	
SIZE: 185/65R14 WEAR PATTE	RN:EVENTREAD DEPTH:6/32 LUGS:4
MANUFACTURER: TRAZANO	TREAD CONDITION: X GOOD WORN
AIR PRESSURE: 28PSI DAMAGE T	O TIRE OR WHEEL: NONE
BLOW OUT: LOST AIR: C	OTHER:
D.O.T. SERIAL NUMBER:	The state of the s
FRONT RIGHT	
SIZE: 185/65R14 WEAR PATTE	RN:EVENTREAD DEPTH:5/32LUGS:4
MANUFACTURER: TRAZANO	TREAD CONDITION: X GOOD WORN
AIR PRESSURE:28PSI DAMAGE T	O TIRE OR WHEEL: NONE
BLOW OUT: LOST AIR: C	THER:
	UNK.
BACK LEFT SIZE: 185/65R14 WEAR PATTER	RN: <u>EVEN</u> TREAD DEPTH: 7/32 LUGS: 4
MANUFACTURER: STARFIRE	TREAD CONDITION: X GOOD WORN
AIR PRESSURE: 0 PSI DAMAGE TO	O TIRE OR WHEEL: WHEEL RIM BENT
BLOW OUT: LOST AIR: X 0	THER:
D.O.T. SERIAL NUMBER:	. UNK.
BACK RIGHT	
SIZE:185/65R14 WEAR PATTER	RN:EVENTREAD DEPTH:7/32 LUGS:4
MANUFACTURER: STARFIRE	TREAD CONDITION: X GOOD WORN
AIR PRESSURE: 26PSI DAMAGE TO	O TIRE OR WHEEL: NONE
BLOW OUT: LOST AIR: 0	THER:
D.O.T. SERIAL NUMBER:	UNK.

Vehicle # 1 Page 3 of 6 LEFT SIDE


FRONT			REAR					
DOOR:			IS THERE A REAR DOOR ?	X YES	□ NO			
FORCED OPEN BY COLLISION:	YES	X NO	FORCED OPEN BY COLLISION:	YES	X NO			
LOCKED INSIDE:	YES	X NO	LOCKED INSIDE:	X YES	□ NO			
JAMMED SHUT:	X YES	☐ NO	JAMMED SHUT:	X YES	☐ NO			
OPERATE NORMALLY:	YES	X NO	OPERATE NORMALLY:	YES	X NO			
WAS THE WINDOW UP?	X YES	☐ NO	IS THERE A REAR WINDOW?	X YES	☐ NO			
WINDOW BROKEN:	YES	X NO	WAS THE WINDOW UP?	X YES	□ NO			
BROKEN GLASS: INSIDE	□ ot	JTSIDE	WINDOW BROKEN:	YES	X NO			
OUTSIDE MIRROR C	ONDITION:		BROKEN GLASS: INSIDI		UTSIDE			
BROKEN BEFORE ACCIDENT:	YES	X NO	REAR WINDSHI	ELD				
BROKEN DURING ACCIDENT:	YES	X NO	DAMAGED X INTACT	OBSTRU	CTED/FOGGED			
			WHEEL, DAMAGED IN COLLISION.					
		FRONT C	DF VEHICLE					
LEFT HEADLAMP BROKEN:	YES	X NO	RIGHT HEADLAMP BROKEN:	YES	S X NO			
AMOUNT OF DIRT ON HEADLAM	P:NC	NE	AMOUNT OF DIRT ON HEADLAM	P:N	ONE			
DESCRIBE FILAMENT:	INT	ACT	DESCRIBE FILAMENT:	INT	TACT			
LEFT TURN INDICATOR BROKEN	: YES	X NO	RIGHT TURN INDICATOR BROKE	N: YES	S X NO			
DESCRIBE FILAMENT:	INT	ACT	DESCRIBE FILAMENT:	INT	TACT			
NOTE ANY AUXILIARY LIGHTING, NOTE LOCATION OF ANY PHYSIC NOTE WEATHER CONDITION: ON NOTE ROAD CONDITION: MEANTS:	CAL EVIDENCE LEAR / HOT	E: NONE						

Vehicle # 1 Page 4 of 6 RIGHT SIDE

FRONT			REAR		
DOOR:			IS THERE A REAR DOOR ?	X YES	□ NO
FORCED OPEN BY COLLISION:	YES	X NO	FORCED OPEN BY COLLISION:	YES	X NO
LOCKED INSIDE:	YES	X NO	LOCKED INSIDE:	YES	X NO
JAMMED SHUT:	YES	X NO	JAMMED SHUT:	YES	X NO
OPERATE NORMALLY:	X YES	☐ NO	OPERATE NORMALLY:	X YES	☐ NO
WAS WINDOW UP ?:	X YES	☐ NO	IS THERE A REAR WINDOW?	X YES	□ NO
WINDOW BROKEN:	YES	X NO	WAS THE WINDOW UP?	X YES	☐ NO
BROKEN GLASS: INSIDE	ou	JTSIDE	WINDOW BROKEN:	YES	X NO
OUTSIDE MIRROR C	ONDITION:		BROKEN GLASS: INSIDI		UTSIDE
BROKEN BEFORE ACCIDENT:	YES	X NO			
BROKEN AFTER ACCIDENT:	YES	X NO			
	TOTTLERO		F THE RIGHT SIDE OF THE VEHICLE		
1		REAR OF	VEHICLE		
LEFT TAIL LAMP BROKEN:	XYES	□ NO	RIGHT TAIL LAMP BROKEN:	YES	X NO
AMOUNT OF DIRT ON LENS:	NC	DNE	AMOUNT OF DIRT ON LENS:	No	ONE
DESCRIBE FILAMENT:	INT.	ACT	DESCRIBE FILAMENT:	INT	ACT
LEFT TURN INDICATOR BROKEN:	XYES	□ NO	RIGHT TURN INDICATOR BROKE	N: YES	X NO
DESCRIBE FILAMENT:	INT	ACT	DESCRIBE FILAMENT:	INT	ACT
BACK UP LIGHTS CONDITION:	BRO	KEN	REAR LENSES REFLECTIVE:	XYES	NO
REAR EXHAUST CONDITION:	X	GOOD	OTHER: L/R TAIL, BRAKE, TURN	SIGNAL-OP	ERATIVE

	Vel	hicle #1	Page 5 of 6	1	
	TOWING A	AND UNDERC	ARRIAGE		
TOWING ?	YES	X NO	WHAT?		
HITCH TYPE:	NONE				
HITCH BROKEN?	YES	□ NO	WHERE ?	*	
TYPE OF LIGHTING ON TRAILER.					
BRAKES OF TRAILER:	YES	☐ NO	TYPE ?	4-	
BREAK AWAY DEVICE:	YES	□ NO	TYPE ?		
	NOTE ANY	Y OTHER CON	DITIONS		
	UN	DERCARRIAG	E		
CONDITION OF DRIVE SHAFT:	GOOD	OTHER: F	RONT WHEEL DRIVI	Barran	
CONDITION OF SHOCKS:	X GOOD	OTHER: _			W
CONDITION OF EXHAUST:	X GOOD	OTHER: _			

Vehicle # 1 Page 6 of 6 SKETCH DAMAGE PROFILES



		V	ehicle INT	# 2 ERIOR	Page	1 of 6	3				
LICENSE PLAT	E OR VEHICLE DESCR	RIPTION:	2003	3 Jeep Wra	ngler T	×	(Burne	d-No ot	her info	. avail.)	
SPEEDOMETE	R LOCKED ON SPEED	: YES			NO	X	SPEED				
HEADLAMP SV	VITCH: NOT PRESE	ON			OFF		OPERATIVE:	YES		NO	Х
TURN INDICAT	OR: NOT PRESENT	UP			NWOC		OFF				
HORN:		OPERABLE			NOT		NO PO	WER	X		
HIGH BEAM INI	DICATOR LIGHT:	HIGH BEAM		LOW	BEAM		NO PO	WER	X		
HIGH BEAM SE	ELECTOR SWITCH:	OPERABLE			NOT		NO PO	WER	X		
MILEAGE:							NO PO	WER	X	(DIGITA	AL)
POSITION OF	GEAR SHIFT:	- Y		UNKNO	WN						
WINDSHIELD V	WIPER:UNKNOU	ON ON		OFF		OPE	RATIVE: YES		NO	X	
RADIO OR STE	EREO SYSTEM: _UN	KNOMY ON		OFF		V	OLUME:				
C.B. RADIO;	MUKHOMY N	A ON		OFF		V	OLUME:				
REAR VIEW MII	RROR:	INTACT		GONE:	Х	0	THER:				
POSITION OF T	TEMPERATURE CONTR		Jown						, , _	-	
		OFF HEAT	H	A/C VENT	H		NORMAL		HER _		
ASH TRAY:	NOT PRESENT	FULL		EMPTY		LOC	ATION/CONTEN	TS _			
RADAR DETEC	TOR: _UNKHOWN	YES		NO							
SEAT BELTS:	(DRIVER) FRONT SEAT MIDDLE SEAT BELT ANCHORS PASSENGER: SEAT BELT ANCHORS BELTS CUT, BROKEN	S BROKEN: S BROKEN:	OPE	RABLE: RABLE:	YES YES YES YES YES YES	X	NO X NO X NO X NO X	ONE	BURN	ED	
NOTE ANY PRO LOCATION OF LOCATION OF LOCATION OF LOCATION OF LOCATION OF	BODY TISSUE: HAIR:			Veh	Unk. Unk. None None None						

Vehicle # 2 Page 2 of 6 TIRES

FRONT LEFT	
SIZE: Unknown	WEAR PATTERN: Unk TREAD DEPTH: Unk LUGS: 5
MANUFACTURER: Unk	TREAD CONDITION: GOOD WORN
AIR PRESSURE: 0	DAMAGE TO TIRE OR WHEEL: Vehicle burned, no tires present
AND THE RESERVE OF THE PARTY OF	AIR: OTHER:
FRONT RIGHT	
SIZE: Unknown	WEAR PATTERN: Unk TREAD DEPTH: Unk LUGS: 5
MANUFACTURER: Unk	TREAD CONDITION: GOOD WORN
AIR PRESSURE: 0	DAMAGE TO TIRE OR WHEEL: Vehicle burned, no tires present
BLOW OUT: LOST	AIR: OTHER:
D.O.T. SERIAL NUMBER:	
BACK LEFT SIZE: Unknown MANUFACTURER:	WEAR PATTERN: Unk TREAD DEPTH: Unk LUGS: 5 TREAD CONDITION: GOOD WORN
AIR PRESSURE:	DAMAGE TO TIRE OR WHEEL:
BLOW OUT: LOST D.O.T. SERIAL NUMBER:	AIR: OTHER: Vehicle burned, no tires present
BACK RIGHT	
SIZE: Unknown	WEAR PATTERN:UnkTREAD DEPTH:UnkLUGS:5
MANUFACTURER:	TREAD CONDITION: GOOD WORN
AIR PRESSURE:	DAMAGE TO TIRE OR WHEEL:
BLOW OUT: LOST	AIR: OTHER: Vehicle burned, no tires present
D.O.T. SERIAL NUMBER:	1000°417 W

Vehicle # Page 3 of 6 LEFT SIDE

FRONT		1	REAR		
DOOR:			IS THERE A REAR DOOR ?	YES	X NO
FORCED OPEN BY COLLISION:	YES X] NO	FORCED OPEN BY COLLISION:	YES	□ NO
LOCKED INSIDE:	YES] NO	LOCKED INSIDE:	YES	☐ NO
JAMMED SHUT:	YES] NO	JAMMED SHUT:	YES	□ NO
OPERATE NORMALLY:	YES] NO	OPERATE NORMALLY:	YES	□ NO
WAS THE WINDOW UP?	YES	NO [IS THERE A REAR WINDOW ?	YES	NO
WINDOW BROKEN:	YES] NO	WAS THE WINDOW UP ?	YES	□ NO
BROKEN GLASS: INSIDE	OUTSID	DE	WINDOW BROKEN:	YES	☐ NO
OUTSIDE MIRROR CO	NDITION:		BROKEN GLASS: INSIDE	: 	UTSIDE
BROKEN BEFORE ACCIDENT;	YES X	NO	REAR WINDSHIE	ELD	
BROKEN DURING ACCIDENT:	X YES	NO	X DAMAGED INTACT	OBSTRI	JCTED/FOGGED
	ed over, and caug		vehicle burned completely and no oth	er informatio	n could
	F	FRONT OF	VEHICLE		
LEFT HEADLAMP BROKEN:	X YES	NO	RIGHT HEADLAMP BROKEN:	XYE	s No
AMOUNT OF DIRT ON HEADLAMP:	NONE		AMOUNT OF DIRT ON HEADLAME	: <u>N</u>	ONE
DESCRIBE FILAMENT:	BURNT		DESCRIBE FILAMENT:	BL	JRNT
LEFT TURN INDICATOR BROKEN:	X YES	NO	RIGHT TURN INDICATOR BROKE	N: XYES	s No
DESCRIBE FILAMENT:	BURNT	_	DESCRIBE FILAMENT:	BL	JRNT
NOTE ANY AUXILIARY LIGHTING, TO NOTE LOCATION OF ANY PHYSICAL NOTE WEATHER CONDITION: NOTE ROAD CONDITION: COMMENTS:	AL EVIDENCE:		N USE:		


Vehicle # 2 Page 4 of 6 RIGHT SIDE

FRONT			REAR		
DOOR:			IS THERE A REAR DOOR ?	YES	X NO
FORCED OPEN BY COLLISION:	YES	X NO	FORCED OPEN BY COLLISION:	YES	□ NO
LOCKED INSIDE:	YES	□ NO	LOCKED INSIDE:	YES	□ NO
JAMMED SHUT:	YES	□ NO	JAMMED SHUT:	YES	☐ NO
OPERATE NORMALLY:	YES	□ NO	OPERATE NORMALLY:	YES	□ NO
WAS WINDOW UP ?:	YES	□ NO	IS THERE A REAR WINDOW ?	YES	☐ NO
WINDOW BROKEN:	YES	☐ NO	WAS THE WINDOW UP ?	YES	□ NO
BROKEN GLASS: INSIDE	□ ou	ITSIDE	WINDOW BROKEN:	YES	□ NO
OUTSIDE MIRROR CO	ONDITION:		BROKEN GLASS: INSIDE	☐ OI	UTSIDE
BROKEN BEFORE ACCIDENT:	YES	X NO	(4)		
BROKEN AFTER ACCIDENT:	X YES	□ NO			
Vehicle was struck from the rear, roll			e vehicle burned completely.	50.	
		REAR OF	VÉHICLE		
LEFT TAIL LAMP BROKEN:	X YES	NO	RIGHT TAIL LAMP BROKEN:	X YES	S NO
AMOUNT OF DIRT ON LENS:	NO	NE	AMOUNT OF DIRT ON LENS:	N	ONE
DESCRIBE FILAMENT:	BUF	RNT	DESCRIBE FILAMENT:	BU	IRNT
LEFT TURN INDICATOR BROKEN:	XYES	□ NO	RIGHT TURN INDICATOR BROKEN	I: XYES	S NO
DESCRIBE FILAMENT:	BUF	RNT	DESCRIBE FILAMENT:	BU	IRNT
BACK UP LIGHTS CONDITION:	BUF	RNT	REAR LENSES REFLECTIVE:	YES	S X NO
REAR EXHAUST CONDITION:	☐ G	OOD	OTHER:		

Vehicle # 2 Page 5 of 6

	TOWING	AND UNDER	CARRIAGE
FOWING ?	YES	X NO	WHAT?
HITCH TYPE:	-		
HITCH BROKEN ?	☐ YES	□ NO	WHERE ?
YPE OF LIGHTING ON TRAILER:		*	
RAKES OF TRAILER:	YES	☐ NO	TYPE ?
REAK AWAY DEVICE:	☐ YES	☐ NO	TYPE ?
3	NOTE AN	Y OTHER CO	ONDITIONS
	UN	NDERCARRIA	AGE -
ONDITION OF DRIVE SHAFT:	GOOD	OTHER:	Vehicle frame was buckled along with the drive shaft.
ONDITION OF DRIVE SHAFT:	GOOD GOOD		Vehicle frame was buckled along with the drive shaft. Burned, broken

Vehicle # 2 Page 6 of 6 SKETCH DAMAGE PROFILES



Vehicle #__3_ Page 1 of 6 INTERIOR

LICENSE PLAT	TE OR VEHICLE DESCRIP	PTION:	1999	9 Gold, Nissan Pa	thfinde	r, TX				_
SPEEDOMETE	ER LOCKED ON SPEED:	YES		NO	X	SPEED				
HEADLAMP SI	WITCH:	ON		OFF	X	OPERATIVE:	YES		NO	X
TURN INDICA	TOR:	UP		DOWN	X	OFF				
HORN:		OPERABLE		NOT	X	NO POW	/ER	X		
HIGH BEAM IN	IDICATOR LIGHT:	HIGH BEAM		LOW BEAM		NO POW	/ER	X		
HIGH BEAM SI	ELECTOR SWITCH:	OPERABLE		NOT	X	NO POW	/ER	X		
MILEAGE:			_	UNK.		NO POW	ER	Х	(DIGIT	AL)
POSITION OF	GEAR SHIFT:			NEUTRAL						
WINDSHIELD	WIPER:	ON		OFF X	OPE	RATIVE: YES		NO	X	
RADIO OR STI	EREO SYSTEM:	ON		OFF X	V	OLUME:				
C.B. RADIO:	N/A	X ON		OFF	V	OLUME:				
REAR VIEW M	IRROR:	INTACT	X	GONE:	0	THER: ON	DASH	_		
POSITION OF	TEMPERATURE CONTRO			46 E				_	_	
	v .	OFF HEAT	Н	VENT X		NORMAL X	OTHE	G65,000	1	
ASH TRAY:		FULL		EMPTY X	LOC	ATION/CONTENT:	s _			
RADAR DETEC	CTOR:	YES		NO X						
SEAT BELTS:	(DRIVER) FRONT SEAT MIDDLE: SEAT BELT ANCHORS PASSENGER: SEAT BELT ANCHORS BELTS CUT, BROKEN, G	BROKEN:	OPE	RABLE: YES RABLE: YES YES RABLE: YES YES YES YES	X	NO	O FRO	NT/M	IDDLE	S/B
NOTE ANY PROLOCATION OF LOCATION OF LOCATION OF LOCATION OF	BODY TISSUE: HAIR:			OPERAB NONE SIDE & REAR V DRIVER AII NONE NONE NONE	WINDO R BAG					

Vehicle # 3 Page 2 of 6

FRONT LEFT		*	
SIZE:P235/75R15	WEAR PATTERN: _	EVENTREAD DEPTH:	9/32 LUGS:6
MANUFACTURER: ARIZONIA	AN	TREAD CONDITION: X	GOOD WORN
AIR PRESSURE: 56	DAMAGE TO TIRE	OR WHEEL: NONE	
BLOW OUT: LOST	AIR: OTHER		
D.O.T. SERIAL NUMBER:		UNK.	
RONT RIGHT			¥.
SIZE: P235/75R15	WEAR PATTERN:	EVEN TREAD DEPTH:	7/32 LUGS:6
MANUFACTURER: ARIZONIA	N	TREAD CONDITION: X	GOOD WORN
No. of the last of		OR WHEEL: BROKE SEAL	
LOW OUT: LOST			
D.O.T. SERIAL NUMBER:			
		×.	
ACK LEFT			-
IZE: P235/75R15	WEAR PATTERN:	EVEN TREAD DEPTH:	8/32 LUGS: 6
ANUFACTURER: ARIZONIA	N	TREAD CONDITION: X	GOOD WORN
IR PRESSURE: 0 PSI	DAMAGE TO TIRE	OR WHEEL: TIRE OFF RIM	
LOW OUT: LOST			w
D.O.T. SERIAL NUMBER:	-	UNK.	
ACK RIGHT			
ZE: P235/75R15	WEAR PATTERN:	EVEN TREAD DEPTH:	8/32 LUGS:6
ANUFACTURER: ARIZONIA	Ν -	TREAD CONDITION: X	GOOD WORN
R PRESSURE:38	DAMAGE TO TIRE	OR WHEEL: NONE	
LOW OUT: LOST	AIR: OTHER:		
D.O.T. SERIAL NUMBER:		UNK.	
The state of the s		PUBLIC SAFETY - CONFIDENTIA	000000

Vehicle # 3 Page 3 of 6 LEFT SIDE

FRONT			R	EAR	
DOOR:			IS THERE A REAR DOOR ?	X	YES NO
FORCED OPEN BY COLLISION:	YES	X NO	FORCED OPEN BY COLLIS	ION:	YES X NO
LOCKED INSIDE:	YES	X NO	LOCKED INSIDE:		YES X NO
JAMMED SHUT:	YES	X NO	JAMMED SHUT:		YES X NO
OPERATE NORMALLY:	X YES	☐ NO	OPERATE NORMALLY:	XY	ES NO
WAS THE WINDOW UP?	X YES	□ NO	IS THERE A REAR WINDOV	V? X Y	res No
WINDOW BROKEN:	YES	X NO	WAS THE WINDOW UP?	XY	ES NO
BROKEN GLASS: INSIDE	OL	ITSIDE	WINDOW BROKEN:	□ Y	ES X NO
OUTSIDE MIRROR C	ONDITION:		BROKEN GLASS:	NSIDE _	OUTSIDE
BROKEN BEFORE ACCIDENT:	YES	X NO	REAR WIN	DSHIELD	
BROKEN DURING ACCIDENT:	YES	X NO	DAMAGED X INTA	CT OE	SSTRUCTED/FOGGED
×		EDON'T (
		FRONT	OF VEHICLE		
LEFT HEADLAMP BROKEN:	X YES	NO	RIGHT HEADLAMP BROKEN	1: X	YES NO
AMOUNT OF DIRT ON HEADLAME	: <u>NO</u>	NE	AMOUNT OF DIRT ON HEAD	DLAMP:	NONE
DESCRIBE FILAMENT:	BRO	KEN	DESCRIBE FILAMENT:	_	BROKEN
LEFT TURN INDICATOR BROKEN	XYES	□ NO	RIGHT TURN INDICATOR BE	ROKEN: X	YES NO
DESCRIBE FILAMENT:	BRO	KEN	DESCRIBE FILAMENT:		BROKEN
NOTE ANY AUXILIARY LIGHTING, NOTE LOCATION OF ANY PHYSIC NOTE WEATHER CONDITION: CI NOTE ROAD CONDITION: M COMMENTS:	AL EVIDENC	E: BLOOD	ON DRIVER AIR BAG	WERE ON, B	ULBS BROKEN

Vehicle # 3 Page 4 of 6 RIGHT SIDE

FRONT			REAR		
DOOR:			IS THERE A REAR DOOR ?	X YES	☐ NO
FORCED OPEN BY COLLISION:	YES	X NO	FORCED OPEN BY COLLISION:	YES	X NO
LOCKED INSIDE:	YES	X NO	LOCKED INSIDE:	YES	X NO
JAMMED SHUT:	X YES	□ NO	JAMMED SHUT:	YES	X NO
OPERATE NORMALLY:	YES	X NO	OPERATE NORMALLY:	X YES	☐ NO
WAS WINDOW UP ?:	X YES	□ NO	IS THERE A REAR WINDOW?	X YES	☐ NO
WINDOW BROKEN:	X YES	□ NO	WAS THE WINDOW UP ?	X YES	□ NO
BROKEN GLASS: X INSIDE	□ ot	JTSIDE	WINDOW BROKEN:	YES	X NO
OUTSIDE MIRROR C	ONDITION:		BROKEN GLASS: INSIDE	_ o	UTSIDE
BROKEN BEFORE ACCIDENT:	YES	X NO			
BROKEN AFTER ACCIDENT:	X YES	□ NO			
		REAR OF	VEHICLE		
LEFT TAIL LAMP BROKEN:	YES	X NO	RIGHT TAIL LAMP BROKEN:	YES	X NO
AMOUNT OF DIRT ON LENS:	. NO	NE	AMOUNT OF DIRT ON LENS:	N	ONE
DESCRIBE FILAMENT:	INT	ACT	DESCRIBE FILAMENT:	INT	ACT
LEFT TURN INDICATOR BROKEN	: YES	X NO	RIGHT TURN INDICATOR BROKEN	I: YES	NO X
DESCRIBE FILAMENT:	INT	ACT	DESCRIBE FILAMENT:	INT	ACT
BACK UP LIGHTS CONDITION:	INT	ACT	REAR LENSES REFLECTIVE:	XYES	NO
REAR EXHAUST CONDITION:	X G	GOOD	OTHER:		

Page 5 of 6

Vehicle # 3

TOWING AND UNDERCARRIAGE TOWING? YES X NO WHAT? HITCH TYPE: NONE HITCH BROKEN? YES NO WHERE? TYPE OF LIGHTING ON TRAILER: BRAKES OF TRAILER: YES NO TYPE? **BREAK AWAY DEVICE:** YES TYPE? NOTE ANY OTHER CONDITIONS UNDERCARRIAGE

CONDITION OF DRIVE SHAFT:

CONDITION OF SHOCKS:

CONDITION OF EXHAUST:

X

X

GOOD


GOOD

GOOD

OTHER:

OTHER:

Vehicle # 3 Page 6 of 6 SKETCH DAMAGE PROFILES



DRIVER EXAMINATION REPORT

DRIVER UNIT #

PHYSICAL CONDITION MISSING LIMBS - VISION PROBLEM - HEART CONDITION MISSING LIMBS - VISION PROBLEM - HEART CONDITION - FAINTING SPELLS, DIABETES, DEAF, ETC. - FAINTING SPELLS, DIABETES, DEAF, ETC. No medical issues. No medical issues. MENTAL CONDITION ANGRY, FAMILY FIGHT-GRIEF-HURT FEELINGS-ANGRY, FAMILY FIGHT-GRIEF-HURT FEELINGS-ELATION-ANTICIPATION-FEAR, ETC. ELATION-ANTICIPATION-FEAR, ETC. None. None. Driver and passenger had just came from an outing at a river, somewhere near San Marcos, TX. TRIP INFORMATION LEFT FROM, TIME, DESTINATION, ELASPED TIME, LEFT FROM, TIME, DESTINATION, ELASPED TIME, TRIP DISTANCE, IS THIS MOST DIRECT ROUTE TRIP DISTANCE, IS THIS MOST DIRECT ROUTE Left from work traveling home. Driver had been on the Left from area of San Marcos, TX and was traveling to road for approximately 45 minutes. This is the most College Station, TX. direct route to the driver's residence on Travis Road. ANY OTHER

THE DRIVER LAST SLEPT, TYPE OF JOB, LAST WORKED, LAST LAST SLEPT, TYPE OF JOB, LAST WORKED, LAST STOPPED (THIS TRIP).

CONCERNING

Last slept a full night the night prior. Driver is a laborer and was enroute home from working that day.

STOPPED (THIS TRIP).

DRIVER UNIT # 1

Unknown amount of sleep. Driver was a college student at Texas A & M University.

Page 1 of 3

DRIVER EXAMINATION REPORT Page 2 of 3 DRIVER UNIT# DRIVER UNIT# PHYSICAL CONDITION MISSING LIMBS - VISION PROBLEM - HEART CONDITION MISSING LIMBS - VISION PROBLEM - HEART CONDITION - FAINTING SPELLS, DIABETES, DEAF, ETC. - FAINTING SPELLS, DIABETES, DEAF, ETC. Mr. Hawkins had no pre-existing medical conditions and was in excellent health prior to the crash. MENTAL CONDITION ANGRY, FAMILY FIGHT-GRIEF-HURT FEELINGS-ANGRY, FAMILY FIGHT-GRIEF-HURT FEELINGS-ELATION-ANTICIPATION-FEAR, ETC. ELATION-ANTICIPATION-FEAR, ETC. was excited that his daughter, was coming home from college for the summer. TRIP INFORMATION LEFT FROM, TIME, DESTINATION, ELASPED TIME, LEFT FROM, TIME, DESTINATION, ELASPED TIME, TRIP DISTANCE, IS THIS MOST DIRECT ROUTE TRIP DISTANCE, IS THIS MOST DIRECT ROUTE Left from Texas A & M University, College Station, Tx at approximately 4PM was enroute to his home in San Antonio, Tx. The crash occurred at 5:17 PM. The one way trip distance is approximately 150 miles but, had only traveled approximately 70 miles when the crash occurred. This is the most direct route. ANY OTHER CONCERNING THE DRIVER LAST SLEPT, TYPE OF JOB, LAST WORKED, LAST LAST SLEPT, TYPE OF JOB, LAST WORKED, LAST STOPPED (THIS TRIP). STOPPED (THIS TRIP). had slept the night prior for 8-9 hours. Mr. works for Johnson Brothers Bakery as a Bakery Distributor. The job is mainly clerical in nature. had worked a full day on Wednesday, the

day prior to the crash, and had left work at around 5PM. made no stops prior to the crash.

NOTIFICA	TION OF NEXT OF KIN
NAME OF PERSON NOTIFIED: ADRESS: CITY, STATE & ZIP TELEPHONE NUMBER: RELATIONSHIP TO DECEASED: TIME NOTIFIED: HOW NOTIFIED: NAME OF DECEASED: ADRESS: CITY, STATE & ZIP NAME OF PERSON THAT MADE NOTIFICATION:	Page 3 of 3 Vidor, TX Father 7:50 PM via Telephone Vidor, TX Trp. Keith Montgomery, #12608, THP-Bastrop
LOCATION OF DECEASED: Travis County Medi DECEASED PERSONAL EFFECTS LOCATION:	with body
NAME OF PERSON NOTIFIED: ADRESS: CITY, STATE & ZIP TELEPHONE NUMBER: RELATIONSHIP TO DECEASED: TIME NOTIFIED: HOW NOTIFIED: NAME OF DECEASED: ADRESS: CITY, STATE & ZIP	San Antonio, TX Mother 10:42 PM In Person San Antonio, TX
NAME OF PERSON THAT MADE NOTIFICATION:	Trp. Larry Wilson, #10241, THP
LOCATION OF DECEASED: Travis County Medic	cal Examiner
DECEASED DEDCOMAL EFFECTS LOCATIONS	with hadu

TEXAS DEPARTMENT OF PUBLIC SAFETY

WITNESS CONTACT LOG

#	NAME	ADDRESS	TELEPHONE
			HOME:
1			BUS.:
		Tennessee Colony, TX	CELL:
			HOME:
2			BUS.:
		TX	CELL:
			HOME:
3			BUS.:
		Kyle, TX	CELL:
			HOME:
4			BUS.:
	Control of the control of		CELL:
			HOME:
5			BUS.:
	* = No statement taken.		CELL:
			HOME:
6			BUS.:
			CELL:
1			HOME:
7	14		BUS.:
1			CELL:
			HOME:
8			BUS.:
٩l			
-			CELL:
9			HOME:
9			BUS.:
-	Number 1		CELL:
			HOME:
10			BUS.:
-		the state of the s	CELL:
			HOME:
11			BUS.:
-			CELL:
			HOME:
12		The state of the s	BUS.:
	1		CELL:
			HOME:
13			BUS.:
			CELL:
			HOME:
14			BUS.:
	the second second		CELL:
			HOME:
15			BUS.:
			CELL:
			HOME:
16			BUS.:
			CELL:
			HOME:
17			BUS.:
			CELL:
			HOME:
18			BUS.:
-			CELL:

Bastrop County Sheriff's Office AFFIDAVIT OF FACT CASE NUMBER:

	who has identified his/her self as a
I am giving this statement to Deputy Deputy Sheriff (Peace Officer) with	, who has identified his/her self as a
Deputy Sherii (Feace Officer) with	the Bastrop County Sucriti s Office.
My name is	. My date of birth is
My residence is located at	KULE TX
My social security number i	my driver's license number is
My Home/Cell telephone number is	The Present of the Pr
My work telephone number is	
TRAVELENCE SB .	N ZI HWY APPROXIMATELY Z CAL
LENGTHS AWAY SAW	JEEP HEATENS NB ON ZI
TRY AND PASS GEO	
MAKE IT PITEPED	RIGHT REAR OF UEHICLE WHICH
	INING OUT OF CONTROL HAD \$INT
THE FRONT OF TH	& TRUNNER WHICH IN TURN
MADE THE JEEP FLI	P SEVERAL TIMES AND LAND ON
	JEEP CAUGHT FIRE TWO PEOPLE
INSTAGE COULD NOT	JEEP CAUGHT FIRE TWO PEOPLE BE RESOURD AT THE TIME OF
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOUED AT THE TIME OF
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE AMERICANT EXPLOSE	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ADDITION TEXALOST	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE AMERICANT EXPLOSE	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE AMERICANT EXPLOSE	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
INSTAL COULD NOT THE ACCEDENT EXPLOSE TO PLANT THE VICTIM	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
INSIDE COULD NOT THE ACCIDENT EXPLOSE TO HOLD THE VICITION 5-13-2010	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AND TRUE
THE ACCIDENT EXPLOSE TO NOLL THE VICTIM 5-13-2010 DATE	JEEP CAUGHT FIRE TWO PEOPLE BE RESOVED AT THE TIME OF ON BY PEOPLE ASSISTING AOND TRUE

PHOTOGRAPH LOG

NAME OF PHOTOGRAPHER:

CONTRACTOR SANS	MANUL OF PHOTOGRAPHER.
Photo #	Description of Photograph
1	SH 21 facing west
2	SH 21 facing east
3	SH 21 facing NE, view of crash scene
4	Closer view of crash scene, skids, debris, etc.
5	Travis Rd. facing south, looking towards SH 21
6	View of crash scene facing SW
7	Front view of Unit 3
8	Close up, front view of Unit 3
9	Unit 3, front and right side
10	Close up, Unit 3 front and right side
11	Unit 3 rear view
12	Unit 3 left side
13	Unit 3 interior
14	Unit 3 dash / speedometer
15	Unit 3 driver seat & safety belt
16	Unit 1 rear and left side, depicting area of contact
17	Unit 1 rear view
18	TX LI license plate from Unit 2
19	Unit 2 front view
20	Unit 2 undercarriage
21	Unit 2 rear & undercarriage
22	Unit 2 rear axle, fuel tank, suspension, etc.
23	Unit 2 showing final resting position of occupants
24	Body of (foreground) and packground)
25	Unit 2 safety belt buckle still engaged
26	Close up
27	Unit 2 from different angle, body of
28	Arm of

PHOTOGRAPH LOG

NAME OF PHOTOGRAPHER:

STO CONTROL BOOK SHOWS AND REPORT	RAPH LOG NAME OF PHOTOGRAPHER:
Photo #	Description of Photograph
29	Unit 2 from rear
30	rom front of Unit 2
31	Unit 2 right side windshield showing
32	Close up of above (#31)
33	Crash scene facing SW
34	Crash scene facing S-SW
35	Crash scene facing N-NE



1. SH 21 facing west




2. SH 21 facing east



3. SH 21 facing NE, view of crash scene



4. Closer view of crash scene, skids, debris, etc.




5. Travis Road facing south, looking towards SH 21



6. View of crash scene facing SW.



7. Front view of Unit 3




8. Close up, front view of Unit 3

9. Unit 3, front and right side




10. Close up, Unit 3 front and right side



11. Unit 3 rear view



12. Unit 3 left side



13. Unit 3 interior




14. Unit 3 dash / speedometer




15. Unit 3 driver seat & safety belt



16. Unit 1 rear and left side, depicting area of contact.



17. Unit 1 rear view




EA12-005 Peer - Chrysler - 10808




19. Unit 2 front view





20. Unit 2 undercarriage




21. Unit 2 rear & undercarriage




















29. Unit 2 from rear



EA12-005 Peer - Chrysler - 10814








33. Crash scene facing SW



34. Crash scene facing S-SW



35. Crash scene facing N-NE

Point	X	Υ	Elevation	Description	Audio	History
1	0.000	0.000	0.000	EP1		
2	140.000	0.000	0.000	EP1	1	1
2 3	0.000	2.300	0.000	FL1	1	İ
4	140.000	2.300	0.000	FL1		
5	0.000	26.900	0.000			1
6	91.000	26.900	0.000		1	
7	121.000	26.900	0.000	DY2	1	1
8	140.000	26.900	0.000		1	1
9	0.000	27.300	0.000	DY3	1	1
10	91.000	27.300	0.000	DY3	1	Ì
11	121.000	27.300	0.000		1	1
12	140.000	27.300	0,000	64444444444444444444444444444444444444	1	
13	0.000	50.700	0.000	france , reserves and , and recognition and action and action and	1	
14	140.000	50.700	0.000	6	1	
15	0.000	53.800	0.000		1	
16	140.000	53.800	0.000		†	Ì
17	34,000	15.000	0.000		-	****************
18	44.000	15.000	0.000		†	
19	74.000	15.000	0.000		1	
20	84.000	15.000	0.000	******************************	†	
21	114.000	15.000	0.000		†	
22	124.000	15.000	0.000	Annesia e regardo conservado en como de la la decida de la compansa	· • • • • • • • • • • • • • • • • • • •	
23	30.600	39.000	0.000			
24	40.600	39.000	0.000			
25	70.600	39.000	0.000			
26	80.600	39.000	0.000		ļ	
27	110.600	39.000	0.000		1	
28	120.600	39.000	0.000		 	
29	126.600	29.800	0.000		ļ	
30	121.200	26.900	CAPPERSON AND AND ADDRESS OF THE PARTY OF TH	GOUGE1	·	*********************
31	117,700	25.700	a harmonia a named Philip Paris of Printing States	GOUGE1	!	
32	88.600	18.900	0.000	******************	ļ	
33	78.700	18.500	0.000		ł	
34	63.700	17.500	0.000		·	
35	48.800	14.800	0.000		}	
36	24.400	19.300	turnfalentet enter falle to take natheral statut &	V3 R/R		***************************************
37	28.300	14.800		V3 L/R	ļ	·
38	18.700	14.500		V3 R/F	ļ	
39	54.400	9.600		GOUGE2		
40	69.100	10.700	***********************	GOUGE2	•	
41	63.800	8.300		GOUGE3	Į	
42		7.800		GOUGE3	ļ	************
43	57.000 20.000	-22.500		V2 REAR	•	
44	10.700			V2 FRONT	ļ.,	
		-21.600				
45	76.500	-2.200		TRAVIS		
46	85.600	-8.300		TRAVIS		
47	90,900	-14,400	enertereintere transferent ten relationet &	TRAVIS	ļ	
48	120,300	-31.200		TRAVIS	ļ	
49	125,200	-14.800		TRAVIS		
50	140.000	0.000		TRAVIS		
51	128.600	-30,900	0.000	STOP SIGN	l	

5/14/2010 11:46 AM >>>
Fire fatalities of two 18-year olds in a 2003 Jeep Wrangler, from The Austin American Statesman web site.

Home > The Blotter > Archives > 2010 > May > 13 > Entry

Two Texas A&M students killed in Texas 21 crash
By Claudia Grisales Thursday, May 13, 2010, 08:31 PM
A three-vehicle accident late Thursday left two Texas A&M University freshman students
dead and another man injured, police officials and friends of the students said today.
and both died when their 2003 Jeep
Wrangler struck another vehicle stopped on Texas 21, a Texas Department of Public
Safety dispatcher said.
The wreck happened at at 5:19 p.m., said
operator who was driving, was going east when his Jeep struck a 2002 Chevrolet
four-door vehicle that had stopped to turn onto Travis Road, about seven miles east of
said.
The Jeep then swerved across the traffic lanes and was struck from behind by a third
vehicle, a 1999 Nissan Pathfinder, which was going west on Texas 21, Letscher said.
The Jeep then caught on fire, he said.
The driver of the Nissan Pathfinder, see suffered facial lacerations and a
broken leg said. was taken to University Medical Center Brackenridge
in Austin Basid.
Friends of posted messages on Facebook today, describing the two as
members of the Aggie Corps of Cadets and band.
"They were both some of my closest friends. We all played in the same section," said
with all my heart it didn't."
The two were headed back from a yearly river trip following the end of exams,
said
profile showed he graduated high school in San Antonio and was a member of
the A&M Corps of Cadets. His profile said he was pursuing an engineering degree.
"He was a lhoughtful loving guy who would do anything to make you feel better,"
added. "When I was with we would always be smiling,"
last public post on Facebook was Wednesday. It said he was "done with exams."
and I sat next to each other in our first psychology class and he helped me pass
it,"[added.
ACA PERSONAL STATE OF THE PERSONAL PROPERTY OF

Road/Private Property/Parking Lot	Street Desc. St	in in
In your opinion, did this cresh result in at least \$1,000 \(\) Yes Latitude carriage to any one person's property? **ROAD ON WHICH CRASH OCCURRED** **I Ridwy.** SH. **Nhum.** 21 Part.** 1 Part.** 2 Part.** 1 Part.** 2 Part.** 1 Part.** 1 Part.** 2 Part.** 2 Part.** 1 Pa	Street Suffix Street Desc. Street Desc. Street Suffix Suffix Street Suffix Suffix Street Suffix	nin in
#1 Rdwy. SH *Hwy. 21 2 Rdwy. 1 Block Num. 3 Street Name Creat Occurred on a Private Drive or Toll Road/ Num. Toll Road/ Speed 70 Const. Yes Workers Yes Workers Yes Workers Yes Workers Yes Speed 70 Const. Yes Workers Yes Worke	Street Desc. Street St	nin in
Crash Occurred on a Private Drive or Road/ Private Property/Parking Lot. Toll Road/ Limit 70 Const. Yes X No Present X No D No	Street Desc.	nin in
INTERSECTING ROAD, OR IF CRASH NOT AT INTERSECTION, NEAREST ROAD OR REFERENCE MARKER ALL X Yes I Rdwy. CR Plwy. Num. 2 Rdwy. 1 Block Num. 3 Street Prefix Num. Part 1 Num. Prefix Num. Distance from Int. or Ref. Marker Re	RRX Num.	nin in
Int. No Sys. CR Num. Part Num. Prefx N. Distance from Int. or Ref. Markor Int. or Ref. or Int. or	RRX Num.	nin in
Ref. Marker	Num.	ain in
Num. Desc. 1 Vehicle Run State Num. Veh. And AD State Num. Veh. AD State Num. Veh. Address (Street, JP). Paige, TX. See See See See See See See See See Se	7 Body Syle P4 Pol., Fire, EMS on Emergency (Explain Syle P4 DOB (MM/DD/YYYY) 5 DOB (MM/DD/YYYY) 5 Pol. 1 1 1 1 1 97 N 96 98 97 Not Applicable - Alcohol	ain in
Marke 2 0 0 2 Color SIL Make Chaverolet Model 40	5 DOB (MM/DD/ YYYY) First State P4 Emeration (Explain P4 Emeration (Explain P4 Emeration (Explain P4 P4 P4 P4 P4 P4 P4 P	ain in
Nemo; Last. First, Middle Paige, TX Nemo; Last. First, Middle Finar Driver or Primary Person for this Unit on first line Nemo; Last. First, Middle Finar Driver or Primary Person for this Unit on first line NH NH NH NH NH NH NH NH NH N	CHWDDI CHWDI CHWDDI CHWDI CHWDDI CHWDDI CHWDDI CHWDDI CHWDDI CHWDDI CHW	25 Drug
Nemo; Last. First, Middle Enlar Oriver or Primary Person for this Unit on first line N N H N N H N N H N N N N	1 1 1 1 97 N 98 98 97 Not Applicable - Alcohol	25 Drug
N H X Owner Owner/Leace Leace Name & Address Neef of X Yes Expired 26 Fin. 2 Fin. Resp. N. Resp. No Exempt Resp. Type 2 Name Farmers TX Co. Mutual Num.	1 1 1 1 97 N 98 98 97 Not Applicable - Alcohol	255
X) Owner Owner/Leasee Leasee Name & Address reef of X) Yos Expired 26 Fin. 2 Fin. Resp. In. Resp. No Exempt Resp. Type 2 Name Farmers TX Co. Mutual Num.	Not Applicable - Alcohol	A STATE OF
Tessoe Nemic & Address Paige, TX rest of XYos Expired 26 Fin. 2 Fin. Resp. Name Farmers TX Co. Mutual Num.	Not Applicable - Alcohol	
Teesoe Nemic & Address Paige, TX recf of X Yos Expired 26 Fin. 2 Fin. Resp. Name Farmers TX Co. Mutual Num.	for Driver/Primary Perso	behog
reef of XYos Expired 26 Fin. 2 Fin. Resp. Name Farmers TX Co. Mutual Num.		16
Tarmers 1X Co. Mateur		
	Vehicle Damago Vehicle X	You
Towed Towed	71 West Bastrop, TX. 78502	No.
nt - 51mt - Parent - Hit and I.P - I.P	J. 4, F. A, 3, 9, S, 5, 3, P,	
en. 2 0 0,3 Color 99 Von. Jeep Von. Mete Jeep Woodel Wrangler	7 Body P2 Pol. Fire, EMS on Emergency (Explain Namelive II checked)	ı in
DLAD 1 DLAD TX DLAD Num. 9DL Class C End. 96 Fest 96	DOB DOB	
dress (Street, b), Strie, ZIP) Vidor, TX		
Namo: Lost, First, Middle 수도 1993년 Enter Driver or Primary Parson for this Unit on first line 1993년 또 중 1993년 보다 1993년	17 Elect. 18 Restr. 19 Asbag 20 Helmet 21 Sol. 22 Ac. Spoc. 72 Bong 950-6.	5 Drug
1 1 1 K W	1 1 1 1 97 N 96 98 97	97
2 2 3 K B	1 1 1 1 97 N Not Applicable - Alcondia	orted
	Drug Renults are only repo for Driver/Primery Person	
Owner Owner/Lessen Vidor, TX	Drug Renulls are only repo	_

10.7	2	Pran. Num.	Travis		kan Ta			Tal	ken By			D	nto of Deat	m	-	of Dogs
Uni		-	Travis	25.753						-		(M	M/DD/YYY	Y	192	HRMM
Uni		2		Co. Me	edical Exa	miner	1	farrs, Jo	nes, Nev	vby	0			0,1,0	1 9 1 9 1 9 1 1 9 1 1 9 1 1 9 1 1 9 1 1 9 1 1 1 9 1	4
Uni			Travis	Co. Me	dical Exa	miner	N	Marrs, Jo	nes, Nev	/by	-			,0 ,1 ,0 ,		
Uni	_								THE TOTAL			./,	1	1 ())		
Uni				-	leld Cox							7.	1,		-	
	47.7					TONO	1 Fran			(Astronomy)	1	1/1	1			
	1						10177.6	Ustog	le le			1/.	1.			
744		Pren. Num.					. Chi		1110	9				Citatio	n/Reference	e Num
	-	Come .	-							-						-
	1						19/48				_			-	-	- 1
	T				7						-				-	
-		Damagno	Property Other	Than Vehi	cles		O	vnor's Namo					Owne	l'a Address		
		44.4				VIII.		1								
Unit Vum.		I 1	0,001+ LBS.		ANSPORTING		9+ Capacity	28 Veh. Oper.		Certier Type		anter ID		""		
Carrier	's Cor	p,		- /2			Carrier's Pirmary Addr.				403					
to Rav		31 Veh.	RGW			HazMat	Yes 32 H	InzMat	HazMat			32 HaxMi		HazMat		
CORSE		Туре	GWF	-	RGW	Released		trir.	ID Num.	Unit		Class		D Num.	34 7dt	
ody S			rellar t Unit Nitm.		GWR			pa	Trailer 2	Num.		GW				
A Eve	nts	35 Seq. 1		35 Soq		- Contract (1)	95 Seq, 3		35 Seq. 4		N	m, Axins		Total Num, Tir		
Uni	38 C H Num		ng Factors (Inv	May I	Opinion) levo Contrib.		icle Defects (in	May Hav	e Contrib.	3â	39	40	41	42	43	44
The state of the s	1	41	98	20						Weather cond.	Light Cond.	Entering Roads	Rondwny Type			Cont
	2									1	1	2	1	1	1	11
		ir	(Affacts Add	rative Opin	ion of What Ha	rppened (y)		Indic	ate	Fie	eld Dia	gram -	Not to S	cale		
ane. he v struc skido ight rom caug	left Dri wron ik U ded I lane beh ht fil cons	onto Ti ver of ig side init 1 into the b. Unit : ind. Ur re. Driv cle and sumed way.	on SH 21 ravis Road. Unit 2 used in a no pai in its left is opposite is 2 skidded in it 2 continuer of Unit 2 were unab by fire, Un	Unit 2 i faulty ssing zo ear. Unit of the placed off the placed of	was EB o evasive a one. Unit 2 rotal nit 3 was v oath of Un he roadwa e passen extricated	on SH 21 ction and with its fed clock VB on SI it 3 and it ay, overtinger were before t	in the left i drove on front right kwise and I 21 in the was struck urned, and pinned in the vehicle		<u></u>			SH2	71/2	Travis_E	(2	
nn No MRM vest, i mp.	tified M)	nvest	2 1 How Notified (Printed) Ray	0	O Dispato	h nGÝ		Time Am (24HRM)		7, 2, 5	Pepti (MM/			/ <u>1.4./</u>	2,0,	1, 0

	į.	0	1	-		M	all to	: Tax	nn D	epartr	ment	of Tra	nebotte	tion, Cr	Altho	Recon	ds. P.O	Box for	49349 Numb	CR-3 1 Austin Gred Fle X.: addit	TX 7	10) 6714 (Unit	no? C	all (61	21486	5780 4			12.19	Png	3	of_
			sh D) _	0,	5,/	1,	3	1.2	0	1	0	Crash 24HFMI			7,	1,7		Case ID	Ī		Th.	20				Local Usa					
74		Cou	inty		Ва	stro	p								-			* City										4				X	Outsi City Lir
200						this c				at les	st 51		Yes	Lofflud (decim		grees) _							ngitud ealmai		es)	-						
AMM	1	Ra	wy.	-	SH	CRAS	wy.	CCU	-	1		2 Fichw	у.		ock		_		Street			Street				_	_				4 31		
THE TOWN	Sy					Nu ed on Prope	a Pr		Driv	e or	1	-	Road/	Speed	im.	70	Const.	_		Workers			Stree		-						Suffi		
1	DV At	- 2.	SE	_	-	AD,	OR I	FCR	ASH	-	1	-	-	ON, NE	ARES	STRO	AD OF	***	7	E MAR	KER		Street			_			_		4 Str		
4	int.	-		No	Sys		C		lwy.	FT	lan	fr. Fro	Part		1 Date	Nun	1.		Street	Prefix	_		Name		avis	_		RRX			Suff		RD
		if, M	arke	r	i Uni		_	_	Park	M	or F	Ret. Me			Mark				Desc.			_						Nam	_	1	1	1_1	_1
	Nur Voi	m.	3	,	losc	_	1 8 V	ah.	Vehi		R	Veh.	State	SAN		Num.	Н			Veh.	-	J. THE	-	_	R,	1	7 Body	**	K,W	Pol.	Fie,	MS o	in lain in
	8 D	11.7	1	1 5	9 Sta	9	-	or DLa	_	1		Make	F	JAN	90		C 10	COL		Model	51	DL ,	4	LIN	po	_	Style	Ī	V -	Nerr	dua P	Exp	cad)
	Add	dres	rs (S		Citi			Mair			an /	Anto	nio, T	X	uia		101	_			11/10	211			· (m)	1001	1111	_					
& PERSONS	Person	Num	Two	13 Seut	Position				Ente	Drive				irst, Mic on for th		ilt on 1	îmi line	ie.		14 Juliary	Ace	N	16 Sex	17 Elect.	18 Rastr.	19 Airbag	20 Heimst	21 Sol.	22 Ac. Spec.	Atc. Result	23 Divg	Spec.	Result 25 Drug
	1		1	1	I	_														A		V	/ 1	1	1	1	97	N	96		9	6 9	Carl Carl
		1			ľ	_	-	_	-		_							_		İ	L		-						Drug	Driver/	te are	only n	eponed son for
	X	Ow	mer	10	mer/	Losse	10	_	-	_	-	_	_	-	_	-		-	_			_	L	_	_	_		_	_		BOT U	nc.	
	Proc	of of		N	n [Add		123	Fin.	Deta		2	Fin. R			0	alasti.	al Ca		an An	toni	Fin.	Sp.			-					-	_	
1	Fin.	Res	- 1		-					353	5		27	Vehicle nage Re	etina		. 1 .	2	-	F, D	5	27 V	oblete	Deme	90	-	-	9-			ohicle		X Yos
1	Towe		-				-			Auto					OWEC						-	10.5	1.6	95 Ba	astro	p. T.	× 76	602			T WITH SE		live
1	Joli Jum Jeh.	-			Unit	_	[V	enici		Ru	n	LP State		N	um.				v	N L	_				- 1		_	-	Pol., F			
1	ear OL	L	_	-	יועום	-1	Cotor		_		100	ah. Iske		-	9 04		710.0	ni.		/eh. Aodal	11 1	v .			DOB	St.	Body yie			Emerg	ency	Expla	in in
A	ypo	R4S	(Str	eet.	State			um.	-	_	-	_			Class		End		_		Res		=			DD/ Y	m		_/		1		
		T	te, Z	Posifica T				6	ter I	Orlver				st, Midd for this		on fin	t line			14 Injury Severity	Age	15 Ethnicity	16 Sex	I7 Eject.	(B Rosh.	9 Altheg	20 Hefmet	21.504.	22 Alc. Sper.	Ma. Result	3 Grup	Dung	25 Drug Category
				-			_													- 41							7	N	C4 65	_ <_	N. G	ME	20
								_							_	_						Drug Res						Resulta iven/Pi	silcebie - Alcohol and sults are only reported enPrimary Person for				
Ē]0	YVIDO	ar	Own	90/140	issee		-	-	_	-		_	-	_	_	-	_											_	90	oh Un	1.	
	DOF I		en .		. S. a.	Expli Exan	ed	20 F	īn. p. Ty	pe	-		in Res	ρ,	_							Fin. Re	išp.		_		_		-	-		-	-
-	n. Re	_	-		_		-					-	27 V	hicia		-	-	-	-	200	-	7 Vet	icle D	emage				-		Vel	nicte	ed =	Yes

-	CR-3 1	/1/2010 Pren.	DOT USE ONLY		ase ID					XDOT CM	ih ID					Page L	4 01
	Num.	Num.		Take	n To				Tak	en By				M/DDYYY			of Den IRMM)
	3	1	Bra	ckenrid	ge Hospit	al			Guardi	an EMS			_/_			سال	
SHEE												1	1	1	1 1-1		
REDA						16	do						1	1			
MUNRREDIKKLED							10/	1/ - 1	ý.	-		1.	./.	1.	-		
73									9/5/0				./.	1.			-
				-	-					A CUO	6.	-	1	1		1	
	Int	Pran.						Chan	10	-	Option !	3		اسا الس	Pleas	on/Reference	- Alum
-	um.	Num.								TO CUS		100			-	a. a. r. o.	
-	-	-		-	-	-	-										
-	-	-				-					-	_		-	-		_
-	_	Damaged	Property Other T	han Vehicle	05	-	-	Own	er's Name	_	-	_		Owner	a Address	-	_
		-	1 2 3		W-100									311/0			_
									_	_							-
Unit		10.	001+ L9S.		NSPORTING ARDOUS MA	TERIAL	9+ C#	pacity	28 Von.		Carrier		artier ID				
Con	ler's Co	-	111	- HAVA	ALUUUS MA	LINAL	Comfora		Oper.	Jiu	Гуре	N	um.	-			+
	dwy.	Voh.	RGW		-	HazMat	Pinnsiy	32 Ha		HazMat			32 HazMo		nzMet	-	-
Acc		Тура	GWR		RGVW	Release	No	Class		ID Num.	الم	111	Cleas	II.	Num.		1 1
	argo Stylo	To	Mer 1 Unit Num.		GWR L	لسا	1 1	34 T		Treller 2	Num.		GW			34 Trr. Type	
	ence vente	35 Seq. 1		35 Seq. 2	2		35 Seq. 3			35 Seq. 4			itel .m. Axfes		Total Num. T	Ires	
2	Joil Num		Factors (Inves	May Ha	pinion) vo Contrib.		nicia Defe	cts (lnve	May Have		38	39	40	al and Ros	dway Condi	Hone 43	44
COMPATIONS	3										Weather cond.	Light Cond.	Entering Roads	Roadway Type	Rondway	Surface Condition	Contr
5																	
		inv	enligator's Name (Attach Addill	tive Opinio	n of What Ha	ppennd y)			Indica	ita	Fie	eld Dia	gram - I	Not to S	cale		
Se	e pag	e 2.							North	1							
	77								-								
									=								
											_		-				
											S	ee Pag	je 2				
								10									
									Time Anti-	Rd .	7.0	Repor	t Date	0.5	11.41	2.0.4	. 0
mo / 4+15	lottled MM0	1.7			Dispatch				Time Anti-		7, 2, 5	Report	t Date		<u> </u>	- C-	10
ime i AHR	MM)	as Investige	thr Daym	BCSO		part -					7, 2, 5	Report (MM/C	t Date	ID Num.		2,0,1 12059	, 0,

MATTER # 1213402 FILE TYPE Notice

FILE NAME

CAIR #

DATE OF INCIDENT 05/13/2010

DATE OF NOTICE 05/14/2010

MODEL/MODEL

2003 Jeep Wrangler (TJ)

YEAR

VIN 1J4FA39S53

MILEAGE

OWNER

Vidor, T

COURT

DOCKET #

FIRE ALLEGED Yes

DESCRIPTION

Chrysler Group learned from a media report that on May 13, 2010, a 2003 Jeep Wrangler (TJ), operated by was travelling eastbound on Texas S.H. 21 near the intersection with Travis Road in Bastrop County, Texas. The posted speed limit at the site of the accident is 70 mph. According to the police accident report, a 2002 Chevrolet passenger car had stopped on S.H. 21 at the intersection with Travis Road waiting to make a left turn when the Jeep Wrangler (TJ) attempted to avoid the Chevrolet by passing it on the left side in the oncoming lane of travel. The right-front of the Jeep Wrangler (TJ) struck the left-rear of the Chevrolet, causing the Jeep Wrangler (TJ) to yaw in a clockwise direction in the oncoming lane of travel. After rotating 180 degrees in the oncoming lane, the Jeep Wrangler (TJ) was struck in the rear by a 1999 Nissan Pathfinder that was travelling westbound on S.H. 21 at an unknown rate of speed. As a result of the impact with the Pathfinder, the Jeep Wrangler (TJ) travelled off the north side of S.H. 21 and overturned. A fire ensued at some point after the impact with the Nissan Pathfinder.

PROPERTY DAMAGE ALLEGED No

INJURIES 1
FATALITIES 2

ANALYSIS

The 2003 Jeep Wrangler (TJ) has not been inspected. Chrysler Group does not have sufficient information about the accident to determine a likely relative impact velocity between the Jeep Wrangler (TJ) and the Nissan Pathfinder but notes that the speed limit at the site of the accident was 70 mph and the Nissan Pathfinder was moving in the opposite direction as the Jeep Wrangler (TJ) at impact. Based on this,

Chrysler Group concludes that this was likely an extremely high energy impact at a high closing speed that was made more severe by the vehicles moving in opposite directions at impact. This is consistent with severe damage to the front end of the Nissan Pathfinder and the rear end of the Jeep Wrangler (TJ), including a deformed frame rail and significant undercarriage damage, depicted in the police accident scene photographs. Because it has not inspected the Jeep Wrangler (TJ), Chrysler Group is unable to confirm that, as a result of the impact, the fuel tank ruptured or that the origin of the fire was at the fuel tank. The damage to the vehicles is depicted in the photographs in Enclosure 3 – Claims –Lawsuits/Peer Vehicles – 1997-2006 Wrangler (TJ)/Reports of Accident, Bates Nos. EA12-005 Peer – Chrysler – 10824, 10850, and 10854.