

GCQIS Report Entry/Maintenance

GCQIS Technical Service Detail

[Close](#)[Print](#)[Help](#)

ArticleType : ISM **ArticleNumber :** 11-08-019 **Entered Date :** 08/29/2011 **Times Recommended :** 104

Date is displayed in **MM/DD/CCYY** format

LOSS OF POWER STEERING ASSIST WITH C200D IN PSCM :

SOME 2011-2012 EXPLORER VEHICLES MAY EXHIBIT A LOSS OF POWER STEERING ASSISTANCE WITH DTC C200D SETTING IN THE POWER STEERING CONTROL MODULE (PSCM). ENGINEERING HAS ISOLATED THE ROOT CAUSE AND HAS DETERMINED THAT EPAS STEERING RACK REPLACEMENT IS NECESSARY TO RESOLVE THIS ISSUE.

AUTHOR: TFUMEROL (313) 317-9383

Requester:

Technical Service Detail

Server: FCWS686**Ford Proprietary, Private**

10-Jul-2012

Retention: None