

CERTAIN 2009 THROUGH 2013 MODEL YEAR FUSION, MILAN, ESCAPE AND MARINER VEHICLES — THROTTLE BODY REPLACEMENT

OVERVIEW

Affected vehicles may develop contamination on the internal motor contacts of the Throttle Body, resulting in intermittent electrical connectivity. If this condition is present, the Malfunction Indicator Lamp (MIL) or Wrench light will illuminate and the vehicle may enter a Failure Mode Effects Management (FMEM) of default throttle position with fixed RPM. In this mode, engine power and vehicle speed are reduced, while full function of the power steering, power braking, lighting, and climate control systems are maintained. If dealer diagnosis of an engine warning lamp on an affected vehicle identifies the Throttle Body as the causal component, dealers are authorized to replace the Throttle Body under this program

SERVICE PROCEDURE

1. If normal diagnosis leads to Throttle Body Replacement, refer to Workshop Manual (WSM) Section 303-04.

