EA14-002 KIA 11/26/2014 TAB A Field Reports 2011-2013MY



Kia Motors America Field Product Quality Report

	Case Number:	Page 1 of 2
Distributor: KMA		
Region/District: SO10	Report No.: SO2013MP02148	
Dealer Code: AR017	Issue Date: 11/12/2013 8:11	
Dealer City: Bentonville	Dealer Name: Frank Fletcher Kia	
Name: Melkowski, Paul FTR	Dealer State: AR	
Component Group:		
Component Code:		
TREAD Code:		
Subject/Title: Sunroof Glass Shattered		
Vehicle Data		
Model Code: 74282	Model Desc: SORENTO SX FWI	Year: 2012
VIN: 5XYKW4A28CG	Mileage: 52,288	
Engine No: G6DCBS639788	Trans No: BBBECA398785	Trans Type: Automatic
Prod Date: 4/27/2011 12:00	Delivery Date: 7/2/2011 12	Repair Date: 11/12/2013 8
Part Information		
Part Number:81610 2P000	Part Name: PNL ASSY-PANORAMARO	O(
Condition:N59BROKEN / CRACKED	Cause: C07CRACKED	
Part ID/Lot:	Other Part No:81620 2P000	Other Part No:81646 1U000J7
Case History		
CUSTOMER COMPLAINT		
Sunroof shattered while driving on the highway		
ACTUAL CONDITION		
Sunroof shattered while driving on the highwayApp PMApproximate speed, 52 MPHThe sunroof and a	proximate temperature outside; 62 deg FApproximate	e time; 12:15
INVESTIGATION RESULTS		
Innonalizativa		

Unknown

POSSIBLE CAUSE

CORRECTIVE A	ACTION
--------------	--------

Sunroof assembly and related parts need to be replaced

RECOMMENDATIONS













