HONDA


1/23/2015

Q8

Epoxy splatter

Q8-8 -

5P_Bourns_Silver_Epoxy_Torq ue Sensor REDACTED



HONDA


1/23/2015

Q8

ASIC analysis

Q8-1 -

5P_Bourns_ASIC_Failure_RE DACTED





PE14-033 HONDA 1/23/2015

Q8

ASIC analysis

Q8-1 - Q8-2 - ASIC Improvements 6in vs

8in_REDACTED

HONDA

1/23/2015

Q8

Q8-0 - Gearbox DTC 53 MQ update to AHM_REDACTED



1.0 Subject Overview (ENTIPE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION



1.1 Subject Overview (PATRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION






















HONDA


1/23/2015

Q8

Capacitor

Q8-3 -

5P_Bourns_Capacitor_Internal_ Crack_REDACTED









HONDA


1/23/2015

Q8

Capacitor


Q8-4 -

5P_Bourns_Capacitor_Torque_ Sensor_REDACTED











PE14-033

HONDA

1/23/2015

Q8

Capacitor

Q8-5 - Johanson Visit Report Capacitor August
2013_REDACTED







PE14-033

HONDA

1/23/2015

Q8

Clock spring

Q8-6 - 5P_Bourns_Lifted Wire_REDACTED










PE14-033
HONDA


1/23/2015


Q8


Clock spring


Q8-7 - DTC-148 SHOWA
Customer Return_Jul-232014_Final FA
Report_REDACTED



































PE14-033
HONDA
1/23/2015
Q8
QIS sheets


HONDA QIC REPORT	No 4AHE2013036-01

22	HONDA QIC F	REPORT	No 4AHE2014019-00	


HONDA QIC REPORT	No 4HDM2014048-00


HONDA QIC REPORT	No 40MC2014009-00


HONDA QIC REPORT	No 4UAE2014006-00















































PE14-033


HONDA


1/23/2015


Q8


Smashed bond wire


Q8-13 - Feed Forward Process or Look Across REDACTED


































































PE14-033


HONDA


1/23/2015


Q8


Q8-14 - Layout move delivery plan first sensor 1st cm sensor_REDACTED

















PE14-033


HONDA


1/23/2015


Q8


Loose bond wire


Q8-10 - Showa Quality Issues
Report Loose Bond
Wire REDACTED







































































ENTIRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION

(hit

W


Inc shi


VIS

Cro eve

lnv

equ





PE14-033

HONDA

1/23/2015

Q8

Loose bond wire

Q8-9 -

5P_Bourns_Loose_Bond_Wire __REDACTED



































ENTIRE PAGE CONTAINS BUSINESS CONFIDENTIAL INFORMATION

PE14-033

HONDA


1/23/2015

Q8

MR analysis

Q8-11 -

5P_Bourns_MR_Torque_Senso r REDACTED



Record #



PE14-033

HONDA

1/23/2015

Q8

MR analysis

Q8-12 - Showa Quality Issues
Report_Template for MR
Issue 20130617 REDACTED

