



May 22, 2014

US Department of Transportation
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE
Washington DC, 20590

RE: Information regarding General Motors Recall Campaign 13136

Gentlemen:

Enclosed you will find information provided to Sands Chevrolet LLC in regards to Campaign 13136. Attached to the original correspondence from General Motors announcing the recall to the respective dealerships is the pdf. Acrobat bulletin with the specifics of the campaign along with an attachment in excel format of all the vehicles identified by the vehicle identification number and BAC code of the dealerships with vehicles involved. The BAC code is a code generated by General Motors which specifically identifies each dealership.

Sands Chevrolet LLC's BAC code is 256053. As you can see from the attached VIN and BAC listing, Sands Chevrolet LLC had no vehicles involved in Campaign 13136.



Should you need further assistance, please feel free to contact the undersigned at any time. Thank you in advance for your consideration in this matter.

Sincerely,

A handwritten signature in black ink, appearing to read "Jerry Moore". The signature is written in a cursive style and is positioned above the printed name.

Jerry Moore
Dealer Operator
Sands Chevrolet LLC

Message View

: Help  : Print 

View and read message below or use the links in the task bar below to perform various actions.
Using the Web Browser back button may not work as expected.

[▶Back](#)
[▶Previous](#)
[▶Usage Metrics](#)
[▶Remove from Saved Messages](#)
[▶Next](#)

[+ Product Safety](#)
Archived
Message Due to Expire

Date: 5/23/2013

Ref. number: Service / Field Action / G_0000166497

Subject: **13136 - Safety Recall - Loss of Battery Charge - Inspect Generator Control Module**

GM CUSTOMER CARE AND AFTERSALES
DCS2972
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 23, 2013

Subject: 13136 - Safety Recall
Loss of Battery Charge – Inspect Generator Control Module

Models: 2012-13 Buick LaCrosse and Regal; 2013 Chevrolet Malibu Eco
Equipped with eAssist

To: All Buick and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Safety Recall 13136 today. The total number of U.S. vehicles involved is approximately 21,000. Please see the attached bulletin for details.

Customer Letter Mailing

The customer letter mailing will begin in early June 2013.

Global Connect (GWM)

The "Investigate Vehicle History" (IVH) screen will be updated May 24, 2013. A list of involve vehicles in dealer inventory is attached to this message.


Campaign Initiation Detail Report (CIDR)

The CIDR will be available June 29, 2013.


END OF MESSAGE

GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 13136 bulletin.pdf Acrobat PDF (249.2KB)

13136 bulletin

 13136 Inventory VNs.xlsx MS Excel Workbook 2007 (142.0KB)

13136 Inventory VINs

Contact name: Loren Rusk

E-Mail: loren.rusk@gm.com

Department: Service - Brand Quality

Phone:

Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Used Vehicle Sales Manager, Warranty Administrator

Archives: 6/23/2013

Expires: 5/23/2014

BAC	VIN
111118	1G11D5RR6DF
111137	1G11D5RR9DF
111193	1G11D5SR7DF
111197	1G11D5RR3DF
111221	1G11F5SR5DF
111223	1G11D5RR5DF
111242	1G11D5RR3DF
111242	1G11D5RR3DF
111266	1G11D5RRXDF
111287	1G11D5RR2DF
111287	1G11D5SR4DF
111287	1G11F5SR5DF
111289	1G4GA5ERXDF
111303	1G11D5SR5DF
111311	1G11F5SR6DF
111311	1G11F5SR4DF
111349	1G11D5SR0DF
111349	1G11F5SR8DF
111383	1G11D5RR5DF
111385	1G11D5SR2DF
111385	1G11D5SR1DF
111385	1G11D5SR3DF
111394	1G11D5SR1DF
111411	1G11F5RR7DF
111411	1G4GC5ER1DF
111437	1G11F5SR8DF
111503	1G11D5SR3DF
111503	1G11D5SR9DF
111553	1G11D5SR2DF
111568	1G4GC5ER7DF
111568	1G4GC5ER7DF
111590	1G11D5RR9DF
111590	1G11D5SR7DF
111634	1G11D5SR9DF
111636	1G11F5SR6DF
111637	1G4GA5ER1DF
111648	1G11D5SR3DF
111684	1G11F5RR1DF
111703	1G11D5SR3DF
111707	2G4GR5ER3D9
111732	1G11D5SR1DF
111744	1G11D5SR5DF
111744	1G11D5SR2DF
111752	1G11F5SR0DF
111769	1G4GC5GRXD
111792	1G11F5SR5DF

111806	1G4GC5ER3DF		
111811	1G11D5SR4DF		
111820	1G4GA5GR2DF		
111858	1G11D5RR1DF		
111875	1G11D5SR3DF		
111927	1G11F5SR4DF		
111928	1G11D5RR8DF		
111963	1G4GC5ER3DF		
111996	1G11D5SR8DF		
111996	1G11D5SR6DF		
112008	1G11F5SR4DF		
112016	1G11F5SR6DF		
112016	1G11F5SR8DF		
112016	1G11F5SRXDF		
112024	1G11D5SR7DF		
112119	1G11F5SR3DF		
112173	1G4GC5GR5DF		
112189	1G11D5SR5DF		
112193	1G11D5SR0DF		
112238	1G4GC5GRXD		
112248	1G11F5RR2DF		
112263	1G11F5RR6DF		
112263	1G11F5SR5DF		
112282	1G4GC5ER3DF		
112295	1G11F5RR6DF		
112295	1G11F5RR5DF		
112304	1G11F5SR5DF		
112318	1G11F5SR0DF		
112329	1G11D5SR9DF		
112329	1G4GA5ER1DF		
112329	1G4GC5ER4DF		
112358	1G11F5SR2DF		
112396	1G11D5SR4DF		
112396	1G11D5SR3DF		
112465	1G11F5SR6DF		
112529	1G4GC5ERXDF		
112563	1G11F5SR9DF		
112619	1G11D5SR8DF		
112629	1G11D5SR0DF		
112629	1G11D5SR6DF		
112636	1G4GB5ER8CF		
112659	1G11F5SR1DF		
112660	1G4GC5ER5DF		
112700	1G11D5SR1DF		
112700	1G11D5SR8DF		
112791	1G11D5RR6DF		
112791	1G11D5SR8DF		

112791	1G11F5SR0DF		
112796	1G11D5SR4DF		
112796	1G11D5SR8DF		
112811	1G11F5SR9DF		
112832	1G11D5SRXDF		
112840	1G11F5SR2DF		
112884	1G11D5RR4DF		
112885	1G4GC5ER9D		
112923	1G11D5RR5DF		
112925	1G11D5RR7DF		
112925	1G11D5RR8DF		
112926	1G11F5RR4DF		
112949	1G11F5SR7DF		
112967	1G11D5SRXDF		
112969	1G11D5SR2DF		
113043	1G11F5SR8DF		
113083	1G11D5SR7DF		
113094	2G4GS5ERXC		
113112	1G4GC5GR8D		
113114	1G11D5SR8DF		
113114	1G11D5SR9DF		
113116	1G11D5SR6DF		
113116	1G11D5SR2DF		
113122	1G11D5SRXDF		
113144	1G11D5RR0DF		
113145	1G11F5SR7DF		
113150	1G11D5RR1DF		
113159	2G4GT5GR7D		
113164	1G11F5SR7DF		
113182	1G11F5RR4DF		
113183	1G11D5RR9DF		
113190	1G11D5RR3DF		
113194	1G11F5RR6DF		
113215	1G11D5SR3DF		
113215	1G11D5SR7DF		
113215	1G11D5SR3DF		
113217	1G11D5SR8DF		
113217	1G11D5SR4DF		
113217	1G11D5SR4DF		
113217	1G11F5RR3DF		
113217	1G11F5RR8DF		
113217	1G11F5RR4DF		
113243	1G11F5SR9DF		
113252	1G11D5SRXDF		
113252	1G11F5SR5DF		
113272	1G11D5SR8DF		
113326	1G11F5SR6DF		

113328	1G4GC5ER4D		
113344	1G11D5RR1DF		
113404	1G11D5SR8DF		
113413	1G11D5SR5DF		
113413	1G11D5SR6DF		
113483	1G11D5SR0DF		
113488	1G11D5RR2DF		
113509	1G11D5RR1DF		
113536	1G4GA5ER8DI		
113550	1G11D5SR8DF		
113550	1G11D5SR8DF		
113557	1G4GA5ER5DI		
113639	1G4GA5ER5DI		
113643	1G11F5SR6DF		
113659	1G11F5SR6DF		
113659	1G11F5SR8DF		
113659	1G11F5SR5DF		
113667	1G11D5SR8DF		
113673	1G11D5SR5DF		
113686	1G11F5SR0DF		
113705	1G11F5RR9DF		
113707	1G4GC5GR6D		
113712	1G11D5SR7DF		
113712	1G11D5SRXDF		
113713	1G11D5SR0DF		
113751	1G11F5RR4DF		
113776	1G11D5SR6DF		
113777	1G4GC5ER6DI		
113814	1G11F5SR2DF		
113822	1G11F5SR0DF		
113823	1G11D5RR6DF		
113823	1G11F5RR0DF		
113844	1G11F5RR0DF		
113866	1G11F5SR1DF		
113879	1G11D5RR1DF		
113926	1G11D5SR8DF		
113926	1G11D5SR7DF		
113926	1G11F5RRXDF		
113947	1G11D5RR4DF		
113986	1G11F5SR5DF		
114023	1G11D5RR4DF		
114031	1G11F5SR8DF		
114146	1G11D5SR1DF		
114146	1G11D5SR6DF		
114150	1G4GC5ER0DI		
114156	1G11D5SR3DF		
114156	1G11D5SR1DF		

114171	1G4GA5ER0DF		
114181	1G11D5SR9DF		
114181	1G11D5SR4DF		
114181	1G11D5SR3DF		
114181	1G11F5SR9DF		
114181	1G11F5SR7DF		
114181	1G11F5SR4DF		
114230	1G11D5SR5DF		
114249	1G11D5RR8DF		
114266	1G11F5SR1DF		
114295	1G11D5SRXDF		
114392	1G11D5SR6DF		
114397	1G11F5SR1DF		
114398	1G4GC5ER7DF		
114486	1G11F5SR5DF		
114562	1G11F5SR9DF		
114592	1G11F5SR1DF		
114592	1G11F5SR6DF		
114619	1G11D5SR1DF		
114620	1G11F5RR3DF		
114647	1G4GA5ER2DF		
114649	1G11D5RR3DF		
114786	1G11D5RRXDF		
114788	1G11F5SR8DF		
114794	1G11D5RR2DF		
114795	1G11F5SR8DF		
114878	1G11D5SR4DF		
114914	1G11F5SR4DF		
114920	1G11D5RR5DF		
114932	1G4GC5ER7DF		
114932	1G4GC5ER7DF		
114942	1G11D5RR7DF		
114946	1G11D5RRXDF		
114954	1G11F5SR1DF		
114957	1G11D5RR5DF		
114957	1G11D5RR7DF		
114958	1G11D5SRXDF		
115002	1G11D5SRXDF		
115016	1G11D5SR2DF		
115023	1G11D5SR8DF		
115037	1G11D5RR6DF		
115037	1G11D5SRXDF		
115048	1G11D5SR7DF		
115048	1G11D5SR6DF		
115084	1G11D5SR1DF		
115084	1G11D5SR9DF		
115084	1G11D5SR2DF		

115084	1G11D5SRXDF		
115084	1G11F5RR8DF		
115084	1G11F5RR6DF		
115084	1G11F5RR7DF		
115084	1G11F5RR5DF		
115084	1G11F5SR8DF		
115085	1G11F5SR3DF		
115088	1G11D5RR6DF		
115088	1G11F5RR2DF		
115093	1G11D5RR6DF		
115093	1G11D5RR8DF		
115096	1G11D5SR4DF		
115096	1G11D5SR2DF		
115096	1G11D5SR6DF		
115096	1G11F5SR0DF		
115097	1G11D5RR7DF		
115097	1G11D5SR3DF		
115097	1G11F5SR4DF		
115101	1G11D5SRXDF		
115105	2G4GR5ER2C9		
115114	1G11D5RR9DF		
115122	1G11D5SR5DF		
115136	1G11D5SR3DF		
115141	1G4GC5ERXD		
115161	1G11D5RR7DF		
115184	1G11D5SR5DF		
115187	1G11D5RR5DF		
115187	1G11D5SR5DF		
115193	1G4GC5ER0DF		
115195	1G11F5RR6DF		
115217	1G11D5SR0DF		
115229	1G11D5SR7DF		
115229	1G11D5SR4DF		
115229	1G11D5SR9DF		
115229	1G11D5SR5DF		
115233	1G11D5SRXDF		
115233	1G11D5SR7DF		
115233	1G11D5SR5DF		
115233	1G11D5SR2DF		
115263	1G11D5RR5DF		
115269	1G11D5SR2DF		
115325	1G11D5SRXDF		
115328	1G11D5SR6DF		
115350	1G11F5RR0DF		
115357	1G11D5RRXDF		
115360	1G11D5RR4DF		
115360	1G11D5RR7DF		

115360	1G11D5RR5DF		
115360	1G11D5SR0DF		
115361	1G11D5RR8DF		
115373	1G11D5SR6DF		
115385	1G11D5RR2DF		
115385	1G11D5RR8DF		
115385	1G11D5RR7DF		
115385	1G11F5RRXDF		
115400	1G11D5SR9DF		
115414	1G4GA5ER0DF		
115414	1G4GA5ER7DF		
115414	1G4GA5ER3DF		
115417	1G4GC5GR0DF		
115538	1G4GC5ER9DF		
115575	1G4GC5ER6DF		
115589	1G4GA5ER2DF		
115589	1G4GA5ER4DF		
115589	1G4GA5ER7DF		
115589	2G4GR5ERXD9		
115592	1G4GA5ERXDF		
115607	1G4GC5ER0DF		
115614	1G4GC5ERXDF		
115618	1G4GC5ER1DF		
115618	1G4GC5ER6DF		
115618	2G4GR5ER7D9		
115655	1G4GB5GR7CF		
115660	1G4GA5ER5DF		
115698	1G4GA5GR8DF		
115731	1G11D5SR3DF		
115735	1G4GA5ER3DF		
115783	2G4GR5ER5D9		
115795	1G4GA5ER1DF		
115795	1G4GA5ERXDF		
115795	1G4GC5ER9DF		
115815	1G4GA5ER2DF		
115867	1G4GA5ER2DF		
115880	1G4GA5ER4DF		
115880	1G4GC5ER5DF		
115897	1G4GA5ER8DF		
115897	1G4GA5ER7DF		
115920	1G4GA5ER6CF		
115929	2G4GR5ER2D9		
115942	2G4GR5ER2D9		
115970	1G4GA5ER8DF		
115970	1G4GC5ERXDF		
115970	1G4GC5ER6DF		
116064	2G4GR5ER6D9		

116079	1G4GA5ERXD	
116079	1G4GA5ER7D	
116079	1G4GC5ER1D	
116079	1G4GC5ER8D	
116079	1G4GC5ER3D	
116079	1G4GC5ER4D	
116096	1G4GA5ER9D	
116149	1G4GC5ER1D	
116241	1G11D5SR3D	
116259	2G4GS5ERXD	
116299	1G4GC5ER4D	
116322	1G4GC5ER4C	
116333	2G4GR5ER3D	
116377	1G4GD5GR9C	
116385	1G4GA5ER1D	
116434	1G4GC5ER4D	
116438	1G4GA5ER0D	
116438	1G4GC5ER0D	
116446	1G4GC5ER5D	
116446	2G4GS5ER8D	
116462	1G11F5SR7D	
116504	1G11D5SR5D	
116519	2G4GR5ER2D	
116543	1G4GD5GR1C	
116543	1G4GC5ER0D	
116563	1G4GC5ER0D	
116568	2G4GR5ERXD	
116592	2G4GR5ER6D	
116592	2G4GR5ER0D	
116604	2G4GR5ER0D	
116606	1G4GC5ER6D	
116620	1G11D5RR3D	
116620	1G11D5SR4D	
116620	1G11D5SR0D	
116622	1G4GA5ER0C	
116654	1G4GA5ER1D	
116677	1G4GC5ER0D	
116729	1G4GA5GR1D	
116817	2G4GR5ER7D	
117067	2G4GR5ER8D	
117097	1G4GA5ER5D	
117097	1G4GC5ER5D	
117174	1G4GC5ER9D	
117194	1G4GA5ER1D	
117194	1G4GA5ER3D	
117194	1G4GA5ER0D	
117196	1G11D5SR5D	

117196	1G11D5SR8DF	
117196	1G11D5SR7DF	
117196	1G11D5SR9DF	
117196	1G4GC5ER4DF	
117234	1G11F5SR0DF2	
117271	1G4GC5ER1DF	
117314	2G4GR5ER3D9	
117314	2G4GR5ER5D9	
117394	1G4GA5GR6DF	
117399	1G11D5SR2DF	
117452	2G4GR5ER0D9	
117452	2G4GR5ER3D9	
117529	1G11D5SR2DF2	
117552	2G4GR5ER0D9	
117712	2G4GR5ERXD9	
117811	1G4GC5ERXDF	
117825	1G4GC5GR5DF	
117825	1G4GC5GR9DF	
117874	2G4GS5ER6C9	
117920	1G4GA5ER4DF	
117922	2G4GS5ER7D9	
117945	1G4GC5ER4DF	
117945	1G4GC5ER3DF	
117951	1G4GC5ER5DF	
117953	1G4GC5ER1CF	
117953	1G4GC5ER4DF	
117954	1G4GA5ER5DF	
117959	1G4GC5ER2CF	
117959	1G4GA5ER2DF	
117960	1G11D5RR8DF	
117960	1G4GB5ER3CF	
117960	1G4GA5ER6DF	
117960	1G4GC5ER6DF	
117960	1G4GC5ER9DF	
117960	1G4GC5ER6DF	
117960	1G4GC5ERXDF	
117982	1G4GA5ER1DF	
117984	1G4GC5ER1DF	
118026	1G4GA5ER5DF	
118034	1G4GA5ER7DF	
118034	1G4GA5ER5DF	
118059	2G4GR5ER5D9	
118062	1G4GC5ER2DF	
118062	1G4GC5ER8DF	
118072	2G4GR5ER0C9	
118072	1G4GC5ER9DF	
118086	1G4GC5ER2DF	

118088	1G4GA5ER4DF		
118108	1G4GC5ER5DF		
118109	2G4GR5ER6D9		
118134	1G4GC5ER8DF		
118171	1G11D5RRXDF		
118171	2G4GR5ER1C9		
118225	1G4GC5ER3DF		
118228	1G4GC5ER5CF		
118304	2G4GR5ER0D9		
118306	2G4GS5ER3D9		
118318	1G4GC5ERXDF		
118318	1G4GC5ER8DF		
118351	1G4GC5ER0DF		
118375	2G4GR5ER8D9		
118440	1G4GA5ER8DF		
118445	1G4GC5ER4DF		
118465	1G4GC5ER5DF		
118480	1G4GA5ERXDF		
118483	1G4GA5ER7DF		
118484	1G4GC5ER5DF		
118484	1G4GC5ER8DF		
118496	1G4GA5ER2DF		
118496	1G4GA5ER5DF		
118522	1G4GC5ER9DF		
118522	1G4GC5ER8DF		
118522	1G4GC5ER6DF		
118522	1G4GC5ER3DF		
118522	1G4GC5ER4DF		
118538	1G11D5SR8DF		
118542	1G4GA5ER1DF		
118579	2G4GR5ER3D9		
118579	2G4GS5ER8D9		
118587	1G4GC5ERXDF		
118594	1G4GC5ER4DF		
118595	1G4GA5ER9DF		
118595	1G4GA5ER1DF		
118602	1G4GC5ER8DF		
118602	1G4GC5ER6DF		
118631	1G4GA5ER7DF		
118631	1G4GC5ER2DF		
118639	2G4GS5ER4D9		
118653	1G4GC5ERXDF		
118653	1G4GC5ER6DF		
118659	2G4GT5GR9D9		
118659	2G4GT5GR7D9		
118680	1G4GA5ER2DF		
118696	1G4GA5ER9DF		

118696	1G4GC5ER0DF	
118697	1G4GC5GR9DF	
118734	1G4GA5ER8DF	
118737	1G4GA5ER2CF	
118813	1G4GC5ER1DF	
118815	1G4GB5ER4CF	
118815	1G4GA5ER0DF	
118861	1G4GC5ER2DF	
118862	1G4GC5ER2DF	
118895	1G4GC5ER4DF	
118899	1G4GC5ER0DF	
118900	1G11D5SR9DF	
118903	1G4GC5ER9DF	
118910	1G4GC5ERXDF	
118914	1G4GC5ER9DF	
118958	1G4GB5ER4CF	
118981	1G4GA5ER9DF	
118994	1G4GC5ERXDF	
119048	2G4GS5ER6C9	
119048	2G4GS5ERXC9	
119086	1G11F5SR4DF	
119086	2G4GT5GR6D9	
119150	1G4GC5ER8DF	
119157	2G4GT5GRXD9	
119162	1G4GB5ER7CF	
119165	1G4GC5ERXCF	
119290	1G11D5SR0DF	
119293	1G4GA5ER7DF	
119293	1G4GA5ER9DF	
119293	1G4GA5ER6DF	
119293	1G4GC5ER8DF	
119356	1G4GC5ER3DF	
119442	1G4GA5ER4DF	
119446	1G4GA5ER1DF	
119595	2G4GR5ER0D9	
119649	2G4GR5ER2D9	
119649	2G4GR5ER2D9	
131062	1G11F5SR2DF	
132475	1G4GC5ER0DF	
132637	1G4GC5ER1DF	
132659	1G11F5SR5DF	
132692	1G4GA5ERXDF	
132742	1G4GC5ER6DF	
132792	2G4GT5GRXC9	
132830	1G4GD5ER6CF	
132834	2G4GT5GR3C9	
132843	1G4GC5ER3DF	

132850	1G4GC5ER6DI	
132864	1G4GC5ER1DI	
132870	1G4GC5ER5DI	
134967	1G4GA5ER7CF	
135543	1G11F5RR8DF	
135543	1G11F5RR5DF	
137382	1G11F5RR9DF	
137382	1G11F5RR6DF	
137382	1G4GD5GR8C	
139090	1G4GA5GR5CI	
144945	1G11F5SR0DF	
148606	2G4GS5ER6DS	
149952	2G4GT5GR5CS	
152011	1G4GC5ERXD	
157596	1G11D5RR6DF	
157596	1G11D5RRXDF	
157596	1G11D5RR5DF	
157858	1G11D5SR4DF	
158544	1G4GA5GR8DI	
158544	1G4GC5ER7DI	
158632	1G11D5RRXDF	
158644	1G11D5RR3DF	
158644	1G11F5SR6DF	
159198	1G11F5RR1DF	
159291	2G4GT5GR9CS	
159603	1G4GA5ERXD	
159929	1G11F5SRXDF	
159967	1G11F5SR6DF	
160034	1G4GC5ER2DI	
160075	1G11F5RRXDF	
160075	2G4GR5ER9DS	
160846	2G4GS5ER3CS	
161177	1G11F5SR3DF	
161392	1G11D5RR0DF	
161584	1G11D5SR2DF	
162254	1G11F5SR8DF	
162341	1G11D5SR5DF	
163294	1G11D5SR2DF	
163499	1G11D5RR2DF	
163891	1G11F5SR0DF	
163979	1G11D5SR4DF	
164427	1G11D5RR5DF	
164494	1G11F5RR6DF	
164494	1G11F5RR0DF	
164494	1G11F5RR6DF	
164494	1G11F5RR2DF	
164761	1G11D5SR2DF	

164761	1G11F5RR6DF1	
164830	1G11D5RR0DF1	
165012	1G4GC5ERXDF1	
165568	1G11D5SR9DF1	
165681	1G11D5RR6DF1	
165940	1G11F5RR4DF1	
165940	1G11F5SR5DF1	
165940	1G11F5SR3DF1	
165940	1G11F5SR5DF1	
165940	1G11F5SRXDF1	
165940	1G11F5SR9DF1	
165940	1G11F5SR2DF1	
165940	1G11F5SR5DF1	
165940	1G11F5SR3DF1	
165940	1G11F5SR5DF1	
165940	1G11F5SR0DF1	
165940	1G11F5SR6DF2	
165940	1G11F5SR8DF2	
165940	1G11F5SR7DF2	
165940	1G11F5SR1DF2	
165940	1G11F5SR9DF2	
165940	1G11F5SR3DF1	
165940	1G1GA5RR2DF1	
165940	1G1GA5RR0DF1	
165940	1G1GA5RR7DF1	
165940	1G1GA5RR7DF1	
165940	1G1GA5RR0DF1	
165940	1G1GA5RR6DF1	
165940	1G1GA5RR8DF1	
165940	1G1GA5RR1DF1	
165940	1G1GA5RR4DF1	
165940	1G1GA5RR1DF1	
165940	1G1GA5RRXDF1	
165940	1G1GA5RR2DF1	
165940	1G1GA5RR5DF1	
165940	1G1GA5RR9DF1	
165940	1G1GA5RR1DF1	
165940	1G1GA5RR0DF1	
165940	1G4GA5ER0CF1	
165940	1G4GA5GR1CF1	
165940	1G4GA5GR6CF1	
165940	1G4GB5ER6CF1	
165940	1G4GD5GR4CF1	
165940	1G4GD5GR9CF1	
165940	2G4GP5ERXC9	
165940	2G4GT5GR1C9	
165940	1G4GC5ER6DF1	

165940	1G4GC5GR5DF	
165940	1G4GC5GR3DF	
165940	2G4GR5ER3D9	
165940	1G4GC5ER1DF	
166341	1G11D5RR9DF	
166392	1G11D5RR7DF	
166751	1G11F5RR8DF	
166751	1G11F5RR8DF	
166751	1G11F5RR5DF	
166751	1G1GA5RR9DF	
166751	1G1GA5RR6DF	
166751	1G1GA5RR9DF	
166751	1G1GA5RR2DF	
166751	1G1GA5RR6DF	
166751	1G1GA5RR6DF	
166751	1G1GA5RR7DF	
166751	1G4GD5GR2C	
166751	2G4GS5ERXC9	
166751	2G4GT5GR8C9	
166751	2G4GS5GR0D9	
166763	1G4GD5ER5CF	
166784	1G11D5SR5DF	
166784	1G11F5SR7DF	
167112	1G4GC5ER0DF	
167170	1G4GC5ERXD	
167326	1G4GC5ER9DF	
167890	1G11D5RR9DF	
167890	1G11F5RR8DF	
168006	1G4GC5ER3DF	
168594	1G11F5SR9DF	
168594	1G4GC5ER8DF	
168594	1G4GC5ER1DF	
168594	2G4GS5ER2D9	
168598	2G4GS5ER7D9	
168620	2G4GR5ER5D9	
168833	1G11D5RR7DF	
168833	1G11D5SRXDF	
168837	1G4GD5GR7C	
169192	1G11F5SR9DF	
169516	2G4GR5ER0D9	
169666	1G4GA5ER0DF	
169884	1G4GC5ER7CF	
170745	1G4GC5GR7D	
170745	1G4GC5GR0D	
171436	1G11D5SR5DF	
171599	1G11F5RR5DF	
171599	1G11F5RR9DF	

171599	1G11F5RR2DF		
171599	1G11F5RR6DF		
171599	1G11F5RRXDF		
171599	1G11F5RR3DF		
171599	1G11F5RR3DF		
171599	1G11F5RR6DF		
171599	1G11F5RR7DF		
171599	1G11F5RR4DF		
171599	1G1GA5RR3DF		
171599	2G4GT5GR0C9		
171750	1G4GC5ER6DF		
172181	1G11D5RR9DF		
172181	1G11D5RR0DF		
172181	1G11D5RR4DF		
172181	1G11D5RR3DF		
172181	1G11D5RR0DF		
172181	1G11D5RR1DF		
172181	1G11D5RR2DF		
172181	1G11F5RRXDF		
172181	1G11F5RR1DF		
172181	1G11F5RR4DF		
172181	1G11F5RRXDF		
172181	1G11F5RR8DF		
172181	1G11F5RR3DF		
172181	1G11F5RR1DF		
172181	1G11F5RR7DF		
172181	1G1GA5RR1DF		
172181	1G4GA5ER1CF		
172181	1G4GB5ER6CF		
172181	1G4GB5GR8CF		
172181	1G4GC5GR1CF		
172181	1G4GD5GR4CF		
172181	1G4GD5GR8CF		
172181	1G4GD5GR5CF		
172181	1G4GD5GR2CF		
172181	1G4GD5GR3CF		
172181	1G4GD5GR7CF		
172181	1G4GD5GR6CF		
172181	1G4GD5GR6CF		
172181	1G4GD5GR7CF		
172181	1G4GD5GR0CF		
172181	2G4GR5ER0C9		
172181	2G4GS5GR4C9		
172215	1G11F5RR9DF		
172758	1G11D5SR1DF		
172786	1G4GA5ER3DF		
173280	1G11D5SR3DF		

173280	1G11F5SR3DF		
173478	2G4GS5ER5D9		
173478	2G4GS5ER0D9		
173478	2G4GS5ERXD9		
177073	1G11D5RR2DF		
178568	1G11D5SR6DF		
181417	1G11D5SR9DF		
183136	2G4GS5ER8C9		
183998	1G4GC5ER9DF		
184042	1G11D5SR8DF		
184221	1G11D5SR9DF		
184234	1G4GA5ER9DF		
184306	1G4GC5ER3DF		
184564	2G4GR5ER8D9		
185162	1G11F5SR8DF		
185170	1G4GC5ER3DF		
185170	2G4GR5ER4D9		
185238	1G11F5RR7DF		
185536	1G4GB5ER5CF		
186891	1G11F5SR6DF		
186891	1G11F5SR4DF		
187128	1G11F5SR1DF		
187318	1G4GC5GR7DF		
187516	1G1GA5RRXDF		
187553	1G4GC5ER6DF		
188691	1G11D5RR4DF		
189360	1G11F5RRXDF		
189360	1G11F5RR4DF		
190151	1G11F5RR3DF		
191496	1G11D5RR8DF		
191555	1G11D5SR6DF		
191653	1G11D5RR0DF		
192724	1G11D5SR5DF		
195241	1G11D5SR2DF		
195266	1G11D5RRXDF		
195266	1G11D5RR7DF		
195266	1G11D5RR0DF		
195266	1G11D5RR8DF		
195266	1G11F5RR9DF		
195266	1G11F5RR6DF		
195266	1G1GA5RR5DF		
195266	1G1GA5RR4DF		
195266	1G1GA5RR6DF		
195266	1G4GD5GRXC		
195266	2G4GP5ER9C9		
196453	1G11F5RR3DF		
196674	1G11F5RR7DF		

197031	1G11D5RR2DF		
198128	1G4GC5ER9DF		
198943	1G4GC5ER2DF		
199364	1G4GD5ER6CF		
201507	1G11D5SR5DF		
202287	1G4GA5ER4CF		
202468	1G4GB5ER4CF		
202468	1G4GA5ER3DF		
204195	1G11D5SR6DF		
205140	1G11D5RR9DF		
205586	1G11F5SR1DF		
205747	1G4GA5GR7DF		
205747	1G4GA5GR4DF		
205808	1G4GA5ER5DF		
206632	2G4GR5ER3D9		
207393	1G11D5SR0DF		
208998	1G4GC5ERXDF		
210275	1G4GA5ER7DF		
210683	1G11F5SR8DF		
212287	1G11F5RR8DF		
213519	2G4GS5ER1D9		
213670	1G11D5SR0DF		
214085	1G11F5RR4DF		
215125	1G11D5RRXDF		
215723	1G4GA5ER3DF		
216129	1G4GC5ER3DF		
216645	1G11F5RR1DF		
216822	1G11F5SRXDF		
217160	1G11D5SR6DF		
218363	1G11F5SR0DF		
218781	1G11D5SR0DF		
221254	1G4GA5ER9DF		
221407	1G11F5SRXDF		
221437	1G11F5SR4DF		
221765	1G4GA5ER1DF		
222191	2G4GS5ER6D9		
222235	1G4GA5ER7DF		
222340	1G4GC5ER2DF		
223429	2G4GS5ER3D9		
224441	1G11F5RRXDF		
224502	1G4GC5ERXDF		
224502	1G4GC5GR9DF		
226078	1G4GC5ER8DF		
226395	1G11D5RR7DF		
226429	2G4GS5ER5C9		
226429	1G4GA5ER1DF		
226728	1G4GA5ER3DF		

227227	1G11F5RR1DF	
229994	1G11D5SR3DF	
231012	1G4GC5ERXDF	
232372	2G4GS5ER0D9	
233037	1G11D5SR7DF	
234885	1G4GC5GR6DF	
235184	1G4GC5ER3DF	
235818	1G11D5RR3DF	
235818	1G11D5SR8DF	
236250	1G4GC5ER3DF	
240963	1G11F5SR4DF	
241284	1G11D5SR8DF	
242774	1G11D5SR2DF	
242774	1G11D5SR7DF	
245235	1G4GD5ER7CF	
245235	1G4GC5ER2DF	
245411	1G11D5RR5DF	
246121	1G4GD5GR0CF	
246150	1G4GC5ER2DF	
246814	1G11D5SR3DF	
255106	1G4GC5ER8DF	
255769	1G11F5RR3DF	
257856	1G11D5RRXDF	
259000	1G11D5SR9DF	
259000	1G11D5SR2DF	
259000	1G11D5SR3DF	
259182	1G4GA5ER6DF	
259332	1G11F5RR0DF	
259332	1G11F5SR9DF	
259332	1G11F5SR1DF	
259332	1G4GD5ER8CF	
259332	2G4GT5GR0D9	
259449	1G11D5SR7DF	
259469	1G11F5SR3DF	
259504	1G4GA5ER4DF	
259550	1G11F5RR9DF	
259830	1G11F5SR6DF	
260495	2G4GR5ER5C9	
260798	1G4GC5ER8DF	
260808	2G4GT5GR9C9	
261289	2G4GS5ER1C9	
261507	1G11F5SR7DF	
262748	1G11D5RR3DF	
262847	1G11D5RR9DF	
263297	1G11F5SR4DF	
263302	1G11D5RR4DF	
263719	1G4GC5ER6DF	

264241	1G11D5SR8DF	
265150	1G4GD5GR6CF	
265151	1G11D5RR7DF	
265151	1G11D5RR8DF	
265151	1G11F5RR9DF	
265151	1G1GA5RR5DF	
265151	1G4GC5ER3DF	
265179	1G4GA5ER7CF	
265179	1G4GA5ERXCF	
265179	1G4GA5ER1CF	
265198	1G4GA5ER5DF	
265413	1G11D5RR6DF	
265434	1G11D5SR3DF	
265448	1G4GC5ER9DF	
265471	1G4GC5ER0DF	
266521	1G11D5SR2DF	
266996	1G4GC5ER7DF	
267093	1G11D5SR0DF	
267093	1G11F5SR2DF	
267093	1G11F5SR2DF	
267093	1G11F5SR4DF	
267283	1G4GA5ER6DF	
267456	1G11F5SR4DF	
267456	1G11F5SR7DF	
268456	1G11D5RR2DF	
269155	1G11D5SR2DF	
272029	1G11D5SR8DF	
272115	1G4GA5ER1DF	
272115	1G4GA5ERXDF	
272115	1G4GC5ER7DF	
272503	1G11F5SR8DF	
272665	2G4GS5ER3D9	
272795	1G11D5RR4DF	
272795	1G11F5RR5DF	
272811	1G11F5RR0DF	
273167	1G11F5SR0DF	
273944	1G4GC5ER9DF	
273944	1G4GC5ER5DF	
274559	1G4GC5ER1DF	
274648	1G11D5SR5DF	
274861	1G4GA5ER3DF	
275012	1G4GA5ER9DF	
275012	1G4GA5ER1DF	
275536	1G11F5SR6DF	
278138	1G4GA5ERXDF	
278143	1G11F5SR3DF	
278146	2G4GR5ER6D9	

279478	1G4GC5ER4DF		
--------	-------------	--	--



Bulletin No.: 13136
Date: May 2013

Recall Bulletin



PRODUCT SAFETY RECALL

SUBJECT: Loss of Battery Charge – Inspect Generator Control Module

MODELS: 2012-2013 Buick LaCrosse, Regal
2013 Chevrolet Malibu Eco
Equipped with eAssist

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

Vehicles that were involved in Service Update 12238 but have not yet had the repair performed have been transferred to this recall. Vehicles that had parts replaced under Service Update 12238 prior to Nov 15, 2012, have also been transferred to this recall.

CONDITION

General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 2012-2013 model year Buick LaCrosse and Regal, and 2013 model year Chevrolet Malibu Eco vehicles, equipped with eAssist. Some of these vehicles have a condition in which the Generator Control Module (GCM) may not function properly. This could cause a gradual loss of battery charge and the illumination of the malfunction indicator light. If these warnings are ignored, eventually, the engine will stall and/or the vehicle will not start. In addition, there may be a burning or melting odor, smoke, and possibly a fire in the trunk.

CORRECTION

Dealers are to inspect and, if necessary, replace the GCM.

VEHICLES INVOLVED

All involved vehicles are identified by Vehicle Identification Number on the Investigate Vehicle History screen in GM Global Warranty Management system. Dealership service personnel should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared

and will be provided to dealers through the GM GlobalConnect Recall Reports. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

PART INFORMATION

Parts required to complete this recall are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts.

Only a small number of vehicles are expected to require replacement of the generator control module. Parts can only be ordered from the Product Quality Center (PQC) when the service procedure determines that it is necessary to replace the generator control module. Orders placed without PQC approval will automatically cancel.

Note: Approximately 1% of vehicles will require replacement of the Generator Control Module.

Part Number	Description	Quantity/Vehicle
24267940	MODULE, GEN CONT (all 2012 MY & 2013 Malibu)	1 (If Req'd)
24267941	MODULE, GEN CONT (2013 LaCrosse, Regal)	1 (If Req'd)

SERVICE PROCEDURE

Caution: *This service procedure is intended to fully stress the generator control module beyond normal customer use. This stress, in rare cases, may result in smoke and thermal damage to the generator control module. For the extended idle portion of the service procedure (Steps 8 and 12), the vehicle should be located outdoors, with the right rear seat back down, and with the location of the power pack in view of an observer in the left rear seat during the complete idle portion. Do not remove any trim panels. If smoke is observed or smelled, even a trace level, or a popping or unusual noise is heard from the power pack, immediately turn off the engine and exit the vehicle. Continue to observe vehicle for 10 minutes, making sure event has subsided. Connect GDS2 tool, key on to RUN, and acquire freeze frame data from ECM and HPCM. Turn the key to the off position and disconnect 12V battery while vehicle waits for repair.*

Note: Install GDS2 to vehicle. Enter current vehicle make model. Perform a Vehicle Wide DTC check and record any Freeze Frame records. Select Module Diagnostics / HPCM / Data Display / 14V Power Module menu. Leave GDS2 connected and on this menu throughout the drive cycle. If any one of the following DTCs P0CA2, P1AF0 P1B0B P1E0C P1E12 is set, replace the Generator Control Module (GCM). Refer to *Generator Control Module Replacement* in SI.

Note: Perform the Generator Control Module inspection to determine if the Generator Control Module requires replacement. The inspection will take about 3 hours to complete.

- If the generator control module is replaced, it will **not** be necessary to repeat a 3 hour drive cycle. However, a charging system voltage output test must be performed. Complete one of the following tests:
 - Option A: Perform a DC Power Conversion Test. Refer to *DC Power Conversion Test* in SI.
 - Option B: Using the DIC and a voltmeter at the 12V battery, monitor the charging system voltage while a load is applied by turning on the vehicle accessories listed in Step 7 of this bulletin.

Note: Verify the 175 amp fuse torque and APM cable crimp at the UBEC stud end of the cable prior to performing the inspection below.

1. Install GDS2 to vehicle. Start engine and confirm the vehicle has enough fuel for the drive cycle and 2 hour idle test. A quarter-tank of fuel is required to complete the test. Add fuel as required.
2. If the Service Hybrid System DIC message is displayed at any time, follow service instructions in SI for the particular DTC or tell tale that is set.
3. Change the driver information center to show Power Flow Display or use center console display.
4. Set parking brake and place shifter in Neutral position. Increase engine speed to 2,000 RPM.
5. Run in this mode until battery shown in Power Flow Display is completely filled.
6. Shift back to Park and release parking brake.
7. Turn on 12V loads.
 - Head lamps on with high beams
 - Air conditioning set to 78°F (25°C), Eco mode (green snowflake LED), recirc., BiLevel (foot / floor -- do not want Defrost enabled)
 - Cabin blower to high speed
 - Radio on, with sound muted.
 - Heated seats, if equipped
 - Rear defog, it will time out, no need to reinitiate
8. Allow vehicle to idle for approximately 15 minutes.
9. Perform drive cycle maintaining high 12V loads and air conditioning settings specified in Step 7.


10. The drive cycle should contain the following maneuvers.
 - Perform at least 10 moderate to heavy accelerations followed by, brake regen events, with 15% brake apply (light to moderate). Perform these tasks from a vehicle speed of greater than 30 mph (50 km/h) down to at least 5 mph (8 km/h).
 - Perform at least 3 key off / key on cycles with a 2 minute off time, spread out throughout drive cycle. Note: you will need to turn high beams and heated seats back on after each key cycle.
11. Return vehicle to dealership (testing continues outside). Set parking brake and place shifter in Neutral and operate engine at 2,000 RPM until hybrid battery display shows full.
12. Place shifter in Park, release parking brake, and allow vehicle to idle for 2 hours with the following 12V loads on:
 - Head lamps with high beams
 - Cabin blower on highest setting
 - Air conditioning set to 78 deg. F (25 deg. C), Eco mode (green snowflake LED), recirc., Bi Level (foot / floor -- do not want Defrost enabled)
 - Heated seats on high
 - Windows up
 - Radio on, with sound muted
 - 4 way flashers on
 - Dome lights on
13. Turn off engine and all 12 V loads, headlamps, dome lamps, and hazard lamps. Wait 2 minutes, then restart engine.
14. If the Service Hybrid System DIC message is displayed at any time, follow service instructions in SI for the particular DTC or tell tale that is set.
15. **FOR CALIFORNIA VEHICLES ONLY:** Install a Recall Identification Label and complete a "Proof of Correction" certificate upon recall completion.

RECALL IDENTIFICATION LABEL – California Vehicles Only

Place a Recall Identification Label on each vehicle corrected in accordance with the instructions outlined in this Product Recall Bulletin. Each label provides a space to include the recall number and the five-digit dealer code of the dealer performing the recall service. This information may be inserted with a ballpoint pen.

Put the Recall Identification Label on a clean and dry surface of the radiator core support in an area that will be visible to people servicing the vehicle.

When installing the Recall Identification Label, be sure to pull the tab to allow adhesion of the clear protective covering. Additional Recall Identification Labels for US dealers can be obtained from Dealer Support Materials by ordering on the web from DWD Store, www.gmglobalconnect.com, and then click on the DWD Store link. Request Item Number S-1015 when ordering.

**COURTESY TRANSPORTATION** – For US and Canada

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time	Net Item
9100017	Inspect GCM – No Further Action Req'd	3.0	*
9100018	Inspect & Replace GCM (inc testing of new module)		*
	- Malibu, Regal	5.5	
	- LaCrosse	6.0	

* Submit the cost of ¼ tank (15 litres) of gasoline required to perform the test in the Net Item field, not to exceed \$16.00 USD, \$24.00 CAD.

CUSTOMER NOTIFICATION – For US and Canada

General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

CUSTOMER NOTIFICATION – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

DEALER RECALL RESPONSIBILITY – For US and Export (US States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

DEALER RECALL RESPONSIBILITY – All

All unsold new vehicles in dealers' possession and subject to this recall must be held and inspected/repaired per the service procedure of this recall bulletin before customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.



Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2012-2013 model year Buick LaCrosse and Regal, and 2013 model year Chevrolet Malibu Eco vehicles, equipped with eAssist. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in safety recall 13136.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

Your vehicle may have a condition in which the Generator Control Module (GCM) may not function properly. This could cause a gradual loss of battery charge and the illumination of the malfunction indicator light. If you continue to drive the vehicle, the loss of battery charge will cause the engine to stall and/or the vehicle will not start. In addition, there may be a burning or melting odor, smoke, and possibly a fire in the trunk.

What will we do?

Your GM dealer will inspect and, if necessary, replace the GCM. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual inspection time of 3 hours. If the GCM requires replacement, an additional 2 hours and 30 minutes up to 3 hours will be needed.

If your vehicle is within the New Vehicle Limited Warranty, your dealer may provide you with shuttle service or some other form of courtesy transportation while your vehicle is at the dealership for this repair. Please refer to your Owner Manual and your dealer for details on courtesy transportation.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible.

California Residents: The state of California requires the completion of recalls on emission related parts prior to vehicle registration renewal. In addition, the state requires that every vehicle must pass an emission test (SMOG Check) every two years and before it is sold. Without the completion of this no-charge recall, your vehicle may be more likely to fail this test. At the time of the recall completion, your dealer will issue you a "Proof of Correction Certificate". Keep this certificate and, if required, present it to the Department of Motor Vehicles when renewing your registration as

proof of recall completion.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Buick	1-800-521-7300	1-800-832-8425
Chevrolet	1-800-222-1020	1-800-833-2438
Guam	65-6267-1752	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 13V173.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jim Moloney
General Director,
Customer and Relationship Services

GM Recall #13136