

EXHIBIT I TO SPECIAL ORDER RESPONSE

RECALLS ONLY: Provide the following information for each recall remedy repair kit part number purchased or sourced from Takata. See comments in cells for further info on each field. Leave no cells blanks.

Date: 11/10/2015
 Number of Rows: 359

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered
1	04785-55A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
2	04785-59A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
3	04785-59A-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
4	04785-5AA-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
5	04785-57A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
6	04785-55A-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
7	04785-SOX-307	PSPI	AB	PSPI	2477000	LS	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
8	04785-55A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
9	04785-59A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
10	04785-5AA-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
11	04785-57A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
12	04000-44112	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
13	04003-1130D	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
14	04003-11105	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
15	04003-11205	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
16	04000-44212	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
17	04003-1140D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
18	04000-44244	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
19	04003-11144	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
20	04003-11124	PSPI	AB	PSPI	2477000	LS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
21	04003-11102	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
22	04003-1110C	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
23	04003-11144	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
24	04770-SEL-407	PSPI	AB	PSPI	2477000	LS	Passenger	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
25	KH561-799CD	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	NISSAN	Takata	EU	UNKNOWN	See Response No. 3(d)	
26	GJYA-57K80	SPI	AA/AJ	SPI	2406388/2477298	YE/LV	Passenger	MAZDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
27	04785-5EA-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
28	04785-SOX-308	PSPI-L	FD	PSPI-L	2477002	LU	Passenger	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
29	04785-5DA-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
30	04785-S9V-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
31	04770-TQA-305	SDI-X	FY	SDI-X	2435513	UT	Driver	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
32	04770-SAA-405	PSDI	JB/JG	ADP	-	-	Driver	HONDA	Autoliv	EU	UNKNOWN	See Response No. 3(d)	
33	04770-S6D-315	SDI-X	FY	SDI-X	2435513	UT	Driver	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
34	K856M-7991D	SDI-X	SF	TBD	TBD	TBD	Driver	NISSAN	Takata	EU	UNKNOWN	See Response No. 3(d)	
35	04770-SEL-4072	SDI	JA	EHS	-	-	Driver	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	
36	04004-76152	SDI	FB	SDI	2401281	FB	Driver	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
37	04770-55A-305	PSDI	JB/JG	PSDI-4	2497539	GE	Driver	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
38	04770-5DA-305	PSDI	JB/JG	PSDI-4	2497539	GE	Driver	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
39	04770-S9A-306	PSDI	JD	PSDI-4	2496479	GB	Driver	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
40	04004-76152	SDI	FB	SDI	2401281	FB	Driver	TOYOTA	Takata	EU	UNKNOWN	See Response No. 3(d)	
41	KH561-799CD	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	NISSAN	Takata	EU	UNKNOWN	See Response No. 3(d)	
42	K8561-799CD	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	NISSAN	Takata	EU	UNKNOWN	See Response No. 3(d)	
43	04770-SJC-306	PSDI	JB/JG	PSDI-X	2496479	GB	Driver	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
44	04770-SVC-306	PSDI	JB/JG	PSDI-X	2496479	GB	Driver	HONDA	Takata	EU	UNKNOWN	See Response No. 3(d)	
45	04770-TR2-305	SDI-X	UT	SDI-X	2435513	UT	Driver	Honda	Takata	China	UNKNOWN	See Response No. 3(d)	
46	04770-T0A-305	SDI-X	PH	SDI-X	2435513	UT	Driver	Honda	Takata	China	UNKNOWN	See Response No. 3(d)	
47	04770SDA306	PSDI	JB/JG	PSDI-4	2496479	GB	Driver	Honda	Takata	China	UNKNOWN	See Response No. 3(d)	

EXHIBIT I TO SPECIAL ORDER RESPONSE

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered	
48	04785SEL308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	China	UNKNOWN	See Response No. 3(d)		
49	04785SA308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	China	UNKNOWN	See Response No. 3(d)		
50	047705AA406	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	China	UNKNOWN	See Response No. 3(d)		
51	047705EL405	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	China	UNKNOWN	See Response No. 3(d)		
52	0479059A405	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	China	UNKNOWN	See Response No. 3(d)		
53	047905AA405	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	China	UNKNOWN	See Response No. 3(d)		
54	047905EL405	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	China	UNKNOWN	See Response No. 3(d)		
55	04790TF0406	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	China	UNKNOWN	See Response No. 3(d)		
56	73960-0D300	SPI	AA/AJ	FM	-	-	Passenger	Toyota	Daicel	China	UNKNOWN	See Response No. 3(d)		
57	73960-0D280	SPI	AA/AJ	FM	-	-	Passenger	Toyota	Daicel	China	UNKNOWN	See Response No. 3(d)		
58	73960-0D290	SPI	AA/AJ	FM	-	-	Passenger	Toyota	Daicel	China	UNKNOWN	See Response No. 3(d)		
59	K8E6M7991D	SDI-X	SF	TBD	TBD	TBD	Driver	Nissan	Takata	China	UNKNOWN	See Response No. 3(d)		
60	K856A 7993K	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	China	UNKNOWN	See Response No. 3(d)		
61	K8561 8E90A	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	China	UNKNOWN	See Response No. 3(d)		
62	GJY57K80	PSPI	HE	PSPI	2477299	LW	Passenger	Mazda	Takata	China	UNKNOWN	See Response No. 3(d)		
63	04004-071B2	SDI-X	ED	SDI-X	2506289	ED	Driver	Daihatsu	Takata	Japan	UNKNOWN	See Response No. 3(d)		
64	04005-031B2	SDI-X	ED	SDI-X	2506289	ED	Driver	Daihatsu	Takata	Japan	UNKNOWN	See Response No. 3(d)		
65	047705AA405	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)		
66	047705AA406	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)		
67	047705CK405	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)		
68	047705CK405	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)		
69	047705EL405	SDI	JA	ADP1.3A	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)		
70	047705NB405	PSDI	JB/JG	JD	ADP1.3A	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)		
71	047705EL407	SDI	JA	EHS-180	-	-	Driver	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
72	0479055A4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
73	0479057A4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
74	0479059A4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
75	047905AA4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
76	047905CC4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
77	047905CK4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
78	047905CK4051	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
79	047905CV4051	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
80	047905EA4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
81	047905EL4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
82	047905NB4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
83	047905WA4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
84	04790TF04050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
85	04790TF04060	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
86	04790TJ04050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
87	04790TL04050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
88	04790TM04050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
89	04790TM84050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)		
90	047705SA305	PSDI	JB/JG	JD	PSDI-5	2497539	GE	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
91	047705DA305	PSDI	JB/JG	JD	PSDI-4K	2497539	GE	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
92	0477059A306	PSDI	JB/JG	JD	PSDI-X	2496479	GB	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
93	047705DA305	PSDI	JB/JG	JD	PSDI-4K	2497539	GE	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
94	047705DA306	PSDI	JB/JG	JD	PSDI-X	2496479	GB	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
95	047850X3070	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
96	0478553V3080	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
97	0478555A3070	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
98	0478559V3070	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
99	047855DA3070	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
100	04770TOA305	SDI-X	PH	SDI-X	2435513	UT	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
101	04770TR2305	SDI-X	UT	SDI-X	2435513	UT	Driver	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		
102	0478555A3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)		

EXHIBIT I TO SPECIAL ORDER RESPONSE

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered
103	0478557A3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
104	0478559A3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
105	047855AA3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
106	047855CC3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
107	047855CK3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
108	047855EA3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
109	047855EL3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
110	047855SA3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
111	0478557A3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
112	0478557A3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
113	0478559A3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
114	0478559A3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
115	047855AA3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
116	047855AA3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
117	047855CC3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
118	047855CC3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
119	047855CK3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
120	047855CV3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
121	047855EA3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
122	047855EA3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
123	047855EL3080	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
124	047855EL3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
125	GKYA57K80	PSDI-4	HC	PSDI-4	2400019	HC	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
126	F1Y157K80	PSPI	HE	PSPI	2477299	LW	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
127	FEY157K80A	PSPI	HE	PSPI	2477299	LW	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
128	GJYA57K80	PSPI	HE	PSPI	2477299	LW	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
129	D6Y157K80	SDI	XD	SDI	2402786	ZF	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
130	GRYA57K80	SDI	ZF	SDI	2402786	ZF	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
131	GRYD57K80	SPI	AA/AJ	SPI	2406388/2477298	YE/LV	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
132	EZY57K80	SPI	AA/AJ	SPI	2406388/2477298	YE/LV	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
133	GSY57K80	SPI	AA/AJ	SPI	2406388/2477298	YE/LV	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
134	7030A696	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Mitsubishi	Takata	Japan	UNKNOWN	See Response No. 3(d)	
135	7030A697	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Mitsubishi	Takata	Japan	UNKNOWN	See Response No. 3(d)	
136	K85607991D	SDI-X	SF	TBD	TBD	TBD	Driver	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
137	985617993J	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
138	985617993K	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
139	K85617993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
140	K85617993J	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
141	K856A7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
142	K85F17993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
143	K85FA7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
144	K85G17993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
145	K85GA7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
146	K8E617993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
147	K8E617993J	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
148	K8E617993K	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
149	K8E6A7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
150	K8EFA7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
151	KH5617993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
152	KH56A7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
153	KH5F17993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
154	KHE617993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
155	KHE61799CD	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
156	KHE6A7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
157	KHEF17993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
158	98279A6000	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Subaru	Takata	Japan	UNKNOWN	See Response No. 3(d)	
159	98279FE000	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Saab	Takata	Japan	UNKNOWN	See Response No. 3(d)	
160	04005-08142(45166-42060)	SDI	FB	EK-210	-	-	Driver	Toyota	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
161	04005-08242(45166-42070)	SDI	FB	EK-210	-	-	Driver	Toyota	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
162	04005-08342(45166-42080)	SDI	FB	EK-210	-	-	Driver	Toyota	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
163	04004-76152(45166-52130)	SDI	KW	SDI	2401281	FB	Driver	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
164	04004-78142(45166-42050)	SDI	KW	SDI	2401281	FB	Driver	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
165	04000-44112(K73980-12150-A)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	

EXHIBIT I TO SPECIAL ORDER RESPONSE

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered
166	04000-44122(K73980-22060-A)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
167	04000-44144(K73980-44090-A)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
168	04000-44151(K73980-51040-A)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
169	04000-44212(K73980-12160)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
170	04000-44244(K73980-44080-A)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
171	04003-11112(K73980-12170)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
172	04003-11128(K73980-28100)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
173	04003-11144(K73980-44100)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
174	04003-11158(K73980-58020)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
175	04003-11200(K73980-0D110)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
176	04005-13112(L73980-12150)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
177	04005-13222(L73980-22060)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
178	04005-13344(L73980-44100)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
179	04005-13451(L73980-51040)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
180	04005-13544(L73980-44080)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
181	04005-13658(L73980-58020)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
182	04005-13744(L73980-44090)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
183	04005-13828(L73980-28100)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
184	04005-13912(L73980-12170)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
185	73960-0D260	SPI	AA/AJ	FM	-	-	Passenger	Toyota	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
186	CBZP403AA	SPI	AJ	SPI	2400988	AJ	Passenger	Chrysler	Takata	NA	UNKNOWN	See Response No. 3(d)	
187	CBZP405AA	PSPI	MK	PSPI	2401982	MK	Passenger	Chrysler	Takata	NA	UNKNOWN	See Response No. 3(d)	
188	CBEZP404AA	PSPI	MK	PSPI	2401982	MK	Passenger	Chrysler	Takata	NA	UNKNOWN	See Response No. 3(d)	
189	CBZP402AA	PSDI-4	ZH	PSDI-4	2400138	ZH	Driver	Chrysler	Takata	NA	UNKNOWN	See Response No. 3(d)	
190	CBZP401AA	PSDI-4	ME	PSDI-4	2402833	ZH	Driver	Chrysler	Takata	NA	UNKNOWN	See Response No. 3(d)	
191	CBXZP811AA	PSDI-4	ME	TRW	-	-	Driver	Chrysler	TRW	NA	UNKNOWN	See Response No. 3(d)	
192	CBXZP812AA	PSDI-4	ZH	TRW	-	-	Driver	Chrysler	TRW	NA	UNKNOWN	See Response No. 3(d)	
193	8LSZ 10044A74 A	SPI	DH	SPI	2400096	MG	Passenger	Ford	Takata	NA	UNKNOWN	See Response No. 3(d)	
194	5R3Z 63043B13 A	PSDI-4	DH	PSDI-4	2400367	DH	Driver	Ford	Takata	NA	UNKNOWN	See Response No. 3(d)	
195	5G7Z 63044A74 A	PSPI	DL	PSPI	2400920	DL	Passenger	Ford	Takata	NA	UNKNOWN	See Response No. 3(d)	
196	4LSZ 63043B13 A	SDI	DC	SDI	2400150	DC	Driver	Ford	Takata	NA	UNKNOWN	See Response No. 3(d)	
197	19205568	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	GM	Takata	NA	UNKNOWN	See Response No. 3(d)	
198	23398587	PSPI-L	JD	PSPI-L	2477001	LT	Passenger	GM	Takata	NA	UNKNOWN	See Response No. 3(d)	
199	04785-55A-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
200	04785-5DA-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
201	04785-50X-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
202	04785-50X-306	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
203	04785-53V-306	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
204	04785-59V-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
205	04785-5CV-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
206	04785-55A-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
207	04785-59A-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
208	04770-5CV-306	PSDI PSDI-4	JB/JG JD	PSDI-X	2496479	GB	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
209	04770-55A-305	PSDI PSDI-4	JB/JG JD	PSDI-5	2497539	GE	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
210	04770-5DA-305	PSDI PSDI-4 PSDI-4K	JB/JG JD YG	PSDI-5	2497539	GE	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
211	04770-5JC-306	PSDI	JB/JG	PSDI-X	2496479	GB	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
212	04770-59A-306	PSDI PSDI-4	JB/JG JD	PSDI-X	2496479	GB	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
213	04785-5DA-306	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
214	04785-5JA-306	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
215	04785-59V-306	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
216	04785-59A-306	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
217	04785-5JC-307	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
218	04770-5DA-306	PSDI PSDI-4 PSDI-4K	JB/JG JD YG	PSDI-X	2496479	GB	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
219	04770-TR2-305	SDI-X	UT	SDI-X	2435513	UT	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
220	04770-TOA-305	SDI-X	PH	SDI-X	2435513	UT	Driver	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	

EXHIBIT I TO SPECIAL ORDER RESPONSE

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered
221	04770-SCV-405	PSDI	JB/JG	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	[
222	04770-SJC-406	PSDI	JB/JG	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
223	04770-SSA-408	PSDI	JB/JG	TRW	-	-	Driver	Honda	TRW	NA	UNKNOWN	See Response No. 3(d)	
224	04770-S9A-409	PSDI-4	JD	TRW	-	-	Driver	Honda	TRW	NA	UNKNOWN	See Response No. 3(d)	
225	04790-SSA-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
226	04790-S9A-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
227	04770-S9A-405	PSDI	JB/JG	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
228	04770-SAA-406	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
229	04770-SNB-405	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
230	04790-S9A-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
231	04790-SAA-405	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
232	04790-SWA-405	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
233	FEY157K80A	PSPI	HE	PSPI	2477299	LW	Passenger	Mazda	Takata	NA	UNKNOWN	See Response No. 3(d)	
234	GJYA57K80	PSPI	HE	PSPI	2477299	LW	Passenger	Mazda	Takata	NA	UNKNOWN	See Response No. 3(d)	
235	GKYA57K80	PSDI-4	HC	PSDI-4	2400019	HC	Driver	Mazda	Takata	NA	UNKNOWN	See Response No. 3(d)	
236	7030A696	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Mitsubishi	Takata	NA	UNKNOWN	See Response No. 3(d)	
237	K8561 7994D	PSPI	AB	PSPI	2477000	LS	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
238	K85FA7994D	PSPI	AB	PSPI	2477000	LS	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
239	985614260A	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
240	K8E617994D	PSPI	AB	PSPI	2477000	LS	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
241	K85617994D	PSPI	AB	PSPI	2477000	LS	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
242	KH5FA7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
243	KH5FA 7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
244	KH5FA 7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
245	BRPR7-70222	SDI-X	SF	SDI-X	2457522	SF	Driver	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
246	M85607991D	SDI-X	SF	SDI-X	2457522	SF	Driver	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
247	M85607991D	SDI-X	SF	SDI-X	2457522	SF	Driver	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
248	98279FE000	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Saab	Takata	NA	UNKNOWN	See Response No. 3(d)	
249	98279AF00A	PSPI	AB	PSPI	2477000	LS	Passenger	Subaru	Takata	NA	UNKNOWN	See Response No. 3(d)	
250	98279FE000	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Saab	Takata	NA	UNKNOWN	See Response No. 3(d)	
251	98279AG00A	PSPI-L	JD	PSPI-L	2477002	LU	Passenger	Subaru	Takata	NA	UNKNOWN	See Response No. 3(d)	
252	400311124	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
253	400311102	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
254	400311101	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
255	040031110C	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
256	400328102	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
257	400328101	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
258	040032810C	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
259	400328124	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
260	040047510C	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
261	040047520C	PSPI-L	FD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
262	400475101	PSPI-L	WQ	PSPI-L	2477001	EH	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
263	400475201	PSPI-L	WQ	PSPI-L	2477001	EH	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
264	400475102	PSPI-L	WQ	PSPI-L	2477001	EH	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
265	400475202	PSPI-L	WQ	PSPI-L	2477001	EH	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
266	040031130D	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
267	04770SDA3060	PSDI	JB/JG	PSDI-X	2496479	GB	Driver	Honda	Takata	China	UNKNOWN	See Response No. 3(d)	
268	KHE61 7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	China	UNKNOWN	See Response No. 3(d)	
269	0478555A3081	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
270	F1Y257K80	PSDI-4	HC	PSDI-X	2512370	DF	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
271	S4YP57K80	SDI	ZF	SDI-X	2512751	DJ	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
272	GRYD57K80A	SPI	AA/AJ	SPI	2406388/2477298	YE/LV	Passenger	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
273	7030A793	SDI	DC	SDI	2400150	DC	Driver	Mitsubishi	Takata	Japan	UNKNOWN	See Response No. 3(d)	
274	7030A750	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Mitsubishi	Takata	Japan	UNKNOWN	See Response No. 3(d)	
275	Under Investigation	SDI	KW	SDI	2401281	FB	Driver	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
276	04005-09152(L73980-52200)	SPI	AA/AJ	SPI	2511424	DP	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
277	04003-1110D(K73980-0D100)	SPI	AA/AJ	SPI	2476999/2502790	LR/FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
278	73960-0D220	PSPI	AB	ADPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
279	73960-44080	PSPI	AB	ADPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)]

EXHIBIT I TO SPECIAL ORDER RESPONSE

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered
280	73960-52260	PSPI	AB	ADPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
281	23341975	SPI	AA/AJ	SPI	2407292	YP	Passenger	GM	Takata	NA	UNKNOWN	See Response No. 3(d)	
282	04770-55A-405	PSDI PSDI-4	JB/JG JD	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
283	04770-5DA-406	PSDI PSDI-4	JB/JG JD	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
284	04790-5DA-305	PSPI-L	JD	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
285	K8E1 7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	NA	UNKNOWN	See Response No. 3(d)	
286	04005-08342	PSDI-5	ZA	Daicel	-	-	Driver	Toyota	Daicel	NA	UNKNOWN	See Response No. 3(d)	
287	04005-08442	PSDI-5	ZA	Daicel	-	-	Driver	Toyota	Daicel	NA	UNKNOWN	See Response No. 3(d)	
288	04785SEL3081(FIT)	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
289	73960-44100	SPI	AA/AJ	FM	-	-	Passenger	Toyota	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
290	73960-01010	PSPI-L	FD	APPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
291	73960-01040	PSPI-L	FD	APPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
292	73960-01030	PSPI-L	FD	APPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
293	73960-01060	PSPI-L	FD	APPS	-	-	Passenger	Toyota	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
294	KHE61 79930	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
295	04785S9A3070	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
296	04785SCV3070	PSPI	AB	PSPI	2477000	LS	Passenger	Honda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
297	04790SCV4050	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
298	04790TM84060	SPI	AA/AJ	FE-M	-	-	Passenger	Honda	Daicel	Japan	UNKNOWN	See Response No. 3(d)	
299	K8561799CD	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
300	KHEFA7993D	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
301	K85617993K	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Nissan	Takata	Japan	UNKNOWN	See Response No. 3(d)	
302	04770SNB305	PSDI PSDI-4	JB/JG JD	ADP1.3A	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
303	04785-SEL-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	HONDA	Takata	Japan	UNKNOWN	See Response No. 3(d)	
304	04005-08142	PSDI-5	ZA	Daicel	-	-	Driver	Toyota	Daicel	NA	UNKNOWN	See Response No. 3(d)	
305	04785-SWA-309	PSPI-6	YB	PSPI-6	2514943	DT	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
306	04003-11205	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
307	04003-11124	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
308	04005-09424	PSPI-L	EH	PSPI-L	2477001	LT	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
309	04003-11105	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
310	04005-09712	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
311	04770SAA407	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	China	UNKNOWN	See Response No. 3(d)	
312	04770SNB405	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	China	UNKNOWN	See Response No. 3(d)	
313	04790TM04050	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	China	UNKNOWN	See Response No. 3(d)	
314	04785-SEL-308	SPI	AA/AJ	SPI	2476998/2477361	LQ/LX	Passenger	Honda	Takata	EU	UNKNOWN	See Response No. 3(d)	
315	04005-32252	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	EU	UNKNOWN	See Response No. 3(d)	
316	04005-32152	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	EU	UNKNOWN	See Response No. 3(d)	
317	TBD	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	EU	UNKNOWN	See Response No. 3(d)	
318	TBD	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	EU	UNKNOWN	See Response No. 3(d)	
319	TBD	PSPI	AB	PSPI	2477000	LS	Passenger	Toyota	Takata	EU	UNKNOWN	See Response No. 3(d)	
320	04770SNB415	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
321	GPYA57K80	PSDI-4	HC	PSDI-X (DF)	2512370	DF	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
322	GRYC57K80	PSDI-4	HC	PSDI-X (DF)	2512370	DF	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
323	D6Y157K80A	SDI	XD	SDI (XD)	2418061	XD	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
324	GRYB57K80	SDI	TBD	SDI-X (DJ)	2512751	DJ	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
325	7030A763	SPI	AA/AJ	SPI (LQ)	2476998/2477361	LQ/LX	Passenger	Mitsubishi	Takata	Japan	UNKNOWN	See Response No. 3(d)	
326	04005-09252	PSPI-6	TBD	PSPI-6	TBD	TBD	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
327	04770SNB415	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	China	UNKNOWN	See Response No. 3(d)	
328	04790-TJ0-405	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
329	04790-TF0-406	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
330	04790-TM0-405	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
331	0400509524	PSPI-L	TBD	PSPI-L	2477001	LT	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
332	F1Y257K80	PSDI-4	HC	PSDI-X (DF)	2512370	DF	Driver	Mazda	Takata	NA	UNKNOWN	See Response No. 3(d)	
333	04770-SNB-415	SDI	JA	Autoliv	-	-	Driver	Honda	Autoliv	NA	UNKNOWN	See Response No. 3(d)	
334	04790-57A-405	SPI	AA/AJ	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
335	04770-SAA-407	SDI	JA	ADP1.3A	-	-	Driver	HONDA	Autoliv	EU	UNKNOWN	See Response No. 3(d)	
336	04770-SEL-405	SDI	JA	ADP1.3A	-	-	Driver	HONDA	Autoliv	EU	UNKNOWN	See Response No. 3(d)	
337	04770-SNB-405	SDI	JA	ADP1.3A	-	-	Driver	HONDA	Autoliv	EU	UNKNOWN	See Response No. 3(d)	
338	04790-SEL-G000	SPI	AA/AJ	FE-M-450	-	-	Passenger	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	
339	04790-SNB-G000	SPI	AA/AJ	FE-M-450	-	-	Passenger	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	

EXHIBIT I TO SPECIAL ORDER RESPONSE

	Remedy Kit Part No.	Original Inflator Type	Original Inflator Prefix	Replacement Inflator Type	Replacement Inflator PN	Replacement Inflator Prefix	Driver/Passenger	Customer	Replacement Inflator Supplier	TK Kit Manufacturer Region	US/Foreign Market	Number Purchased/Ordered	Number Produced/Delivered
340	04790-SWA-G000	SPI	AA/AJ	FE-M-450	-	-	Passenger	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	
341	04790-TFO-G000	SPI	AA/AJ	FE-M-450	-	-	Passenger	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	
342	04790-TFO-G100	SPI	AA/AJ	FE-M-450	-	-	Passenger	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	
343	04790-TLO-G000	SPI	AA/AJ	FE-M-450	-	-	Passenger	HONDA	Daicel	EU	UNKNOWN	See Response No. 3(d)	
344	GPYA57K80	PSDI-4	HC	PSDI-X	2512370	DF	Driver	Mazda	Takata	NA	UNKNOWN	See Response No. 3(d)	
345	0400509424	PSPI-L	EH	PSPI-L	2507292	EH	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
346	04785-SCV-308	SPI	AA/AJ	SPI	2476998	LQ	Passenger	Honda	Takata	NA	UNKNOWN	See Response No. 3(d)	
347	04790-S0X-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
348	04790-S9V-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
349	04790-SCV-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
350	04790-SDA-308	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
351	04790-S9V-305	PSPI	AB	Daicel	-	-	Passenger	Honda	Daicel	NA	UNKNOWN	See Response No. 3(d)	
352	CBXZR261AA	SPI	AA/AJ	SPI-D	2508088	DG	Passenger	Chrysler	Takata	NA	UNKNOWN	See Response No. 3(d)	
353	0400509524	PSPI-L	EH	PSPI-L	2507292	EH	Passenger	Toyota	Takata	NA	UNKNOWN	See Response No. 3(d)	
354	FEY557K80	PSDI-4	HC	PSDI-X	2512370	DF	Driver	Mazda	Takata	Japan	UNKNOWN	See Response No. 3(d)	
355	7030A817	SDI	TBD	Autoliv	-	-	Driver	Mitsubishi	Autoliv	Japan	UNKNOWN	See Response No. 3(d)	
356	04005-13912	SPI	AA/AJ	SPI	2502790	FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
357	04005-09152	SPI	AA/AJ	SPI	2403680	ZM	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
358	04003-1110D	SPI	AA/AJ	SPI	2502790	FS	Passenger	Toyota	Takata	Japan	UNKNOWN	See Response No. 3(d)	
359	7030A825	TBD	TBD	Autoliv	-	-	Driver	Mitsubishi	Autoliv	China	UNKNOWN	See Response No. 3(d)	