

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F150 BCM Change
Log

Parts Change Log

NHTSA Inquiry PE18-011

Part A Part Changes								Serv		
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change
1	2015	FL3T-15604-AH FL3T-15604-CG FL3T-15604-DG	8/11/2014	11/10/2014	One press of liftgate Release button on the RKE fob followed by an UNLOCK_DRV Disables the exterior liftgate switch ** Change was introduced with MY15 R05 SW release	When the liftgate release button on the RKE fob is pressed once; this must Enable the exterior liftgate switch for 45 secs.but if the unlock button is pressed on the RKE fob before the 45 secs; the vehicle is UNLOCKDRV (Two stage Unlocking) this disables the exterior switch.				
2	2015	FL3T-15604-AK FL3T-15604-CJ FL3T-15604-DJ	11/10/2014	10/5/2015	C/O changes from previous SW release					
3	2016	GL3T-15604-AB GL3T-15604-CB GL3T-15604-DB	10/5/2015	1/4/2016	P552 Tailgate; Decklid for other vehicle lines is disabled after a sequence of locking events ** Change was introduced with MY16 R07 SW release	To allow the customer to open the tailgate in the case of exterior switch failure				
4	2016	GL3T-15604-AC GL3T-15604-CC GL3T-15604-DC	1/4/2016	9/2/2016	C/O changes from previous SW release					
5	2017	HU5T-15604-JAJ HU5T-15604-LAJ HU5T-15604-MAJ	9/2/2016	12/2/2016	1) Transit Vehicles Locking Feature Modifications Design Implementation ** Change introduced with MY17 FDJ1 SW release 2) Transit Locking Changes New Requirements - MY17 only ** Change introduced with MY17 FDJ2 SW release	New locking features add only for commercial vans. Does not affect other vehicle types: Ex- Car, pick-up, SUV				
					Allow the manual liftgate; manual Decklid and Liftgate Glass to be released in the FACTORY mode. ** Change introduced with MY17 R07.2 SW release	ONLY used during vehicle assembly				
					Decouple the vehicle speed Slow/Fast for locking and change the Threshold type from a Constant to a configurable value ** Change introduced with MY17 R07.3 SW release	Allows the vehicle speed threshold to be different for locking versus other features.				
6	2017	HU5T-15604-JAP HU5T-15604-LAP HU5T-15604-MAP	12/2/2016	7/7/2017	C/O changes from previous SW release					
7	2018	JU5T-15604-JAG JU5T-15604-LAG JU5T-15604-MAG	7/17/2017	10/16/2017	Liftgate Glass not opening after pressing the Liftglass switch with PK in range ** Change introduced with MY18 R05 SW release	New requirements were needed for the BCM to send signal to priotitize liftglass release when commanded from keyfob.				
8	2018	JU5T-15604-JAL JU5T-15604-LAL JU5T-15604-MAL	10/16/2017	10/22/2018	C/O changes from previous SW release					
9	2018	JU5T-15604-JAR JU5T-15604-LAR JU5T-15604-MAR	10/22/2018	PRESENT	C/O changes from previous SW release					

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F150 Tailgate Handle
Change Log

P552 PEPS Tailgate Handle Parts Change Log

NHTSA Inquiry MA17-XXX / :NEF-120mjl

FL34-99431B82-E*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	15MY	FL34-99431B82-EAW	VP BUILD	3/11/2013	INITIAL RELEASE		N				
2		FL34-99431B82-EBW	3/11/2013	3/11/2013	RELOCATE ANTENNA	UPDATE PEPS TG HANDLE SURFACE TO IMPROVE CLEARANCE TO THE PEPS ANTENNA.	N				
3		FL34-99431B82-ECW	3/11/2013	3/11/2013	MODIFY TG HANDLE BEZEL TO RESOLVE STAMPING FEAS ISSUE.	P552 TAILGATE OUTER FEASIBILITY FIX REQUIRES TOOLING MODIFICATIONS ON BASE & STEPGATE TAILGATE MOLDINGS	N				
4		FL34-99431B82-EDW	3/11/2013	3/11/2013	RIB ADDED TO HOUSING OF THE TAILGATE HANDLE LIGHT	RIB ADDED TO HOUSING OF THE TAILGATE HANDLE LIGHT RIB ON LIGHT WILL PREVENT THE CLIP FROM BREAKING OFF THE LIGHT THAT HOLDS IT IN POSITION.	N				
5		FL34-99431B82-EEW	3/11/2013	8/11/2014	ADD 2-SHOT LENS AND GASKET TO THE TBA LIGHT	TWO SHOT MOLD TBA LIGHT & MODIFY ASSEMBLY TO MINIMIZE THE APPARENT GAP BETWEEN THE LIGHT AND THE TAILGATE HANDLE.	N				
6		FL34-99431B82-EFW	8/11/2014	8/11/2014	MODIFY THE PEPS TG HANDLE STUDS AND HOUSING TO IMPROVE ROBUSTNESS.	MODIFY THE PEPS TG HANDLE STUDS AND HOUSING TO IMPROVE ROBUSTNESS.	N				
7		FL34-99431B82-EGW	8/11/2014	8/11/2014	REVISE TBA LIGHT TO IMPROVE SEALING	ADD SEALING ROBUSTNESS ACTIONS TO THE TBA LIGHT IN THE TG HANDLE TO PREVENT CONDENSATION. O-N	N	FL34-9943800-EAW	8/11/2014		8/11/2014
8		FL34-99431B82-EHW	8/11/2014	8/11/2014	REVISE TAILGATE HANDLE AS NECESSARY TO ACHIEVE AAR APPROVAL	REVISE TAILGATE HANDLES TO IMPROVE CLASS A APPEARANCE CHANGE WILL BE REQUIRED TO ACHIEVE AAR APPROVAL.	N	FL34-9943800-EBW	8/11/2014		1/4/2016
9		FL34-99431B82-EJW	8/11/2014	8/11/2014	UPDATE REAR VISION CAMERA SOFTWARE TO REV. 5.5	UPDATE HIGHLINE AND TAD ECU AND CAMERAS FOR R5.5 SOFTWARE LEVEL CHANGES.	N				
10		FL34-99431B82-EKW	8/11/2014	8/11/2014	REVISE TBA LAMP INTENSITY	REVISE THE TBA LAMP TO LOWER THE LIGHT OUTPUT	N				
11		FL34-99431B82-ELW	8/11/2014	11/10/2014	UPDATE ASSEMBLY FOR NEW CAMERA SOFTWARE VERSION 6.0	UPDATE HIGHLINE ECU AND CAMERAS FOR R6.0 SOFTWARE LEVEL CHANGES.	N				
12		FL34-99431B82-ELW	11/10/2014	10/5/2015	CAD UPDATE - NO PHYSICAL CHANGES	UPDATE DRAWINGS/CAD TO PRODUCTION INTENT; NO PHYSICAL CHANGE TO THE PARTS; PART NUMBERS/SUFFIXES, NOT CHANGING;	N				
13		FL34-99431B82-EMW	10/5/2015	10/5/2015	RELEASE LOW GLARE TBA LIGHT	RELEASE LOW GLARE BACKUP ASSIST LIGHT TO REPLACE CURRENT LIGHT ON P552.	N				

14		FL34-99431B82-ENW	10/5/2015	1/4/2016	REVISE TAILGATE HANDLE ASSEMBLY FOR UPDATED CAMERA SOFTWARE	REAR VIDEO CAMERA AND FRONT VIDEO CAMERA SOFTWARE UPDATE MODIFY CAMERA SOFTWARE TO ADD RETRY IF INITIAL CHECKSUM MEASUREMENT IS INCORRECT.	N				
15		FL34-99431B82-EPW	1/4/2016	1/4/2016	ROBUSTNESS IMPROVEMENT ON CAMERA LOACTION RIBS - ADD SUPPORT GUSSETS	ROBUSTNESS IMPROVEMENT ON CAMERA LOCATING RIBS. ADD SUPPORT GUSSETS TO PREVENT HANDLING DAMAGE.	N	FL34-9943800-ECW	1/4/2016	17/07/2017	
16		FL34-99431B82-ERW	1/4/2016	7/17/2017	REPLACE CURRENT LED IN TBA	TBA LAMP LED SUPPLIER CHANGE FOR VA/VE COST REDUCTION	N				
17		FL34-99431B82-ESW	7/17/2017		MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	FL34-9943800-EDW	7/17/2017		

FL34-99431B82-G*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	15MY	FL34-99431B82-GAW	VP BUILD	3/11/2013	INITIAL RELEASE		N				
2		FL34-99431B82-GBW	3/11/2013	3/11/2013	RELOCATE ANTENNA	UPDATE PEPS TG HANDLE SURFACE TO IMPROVE CLEARANCE TO THE PEPS ANTENNA.	N				
3		FL34-99431B82-GCW	3/11/2013	3/11/2013	MODIFY TG HANDLE BEZEL TO RESOLVE STAMPING FEAS ISSUE.	P552 TAILGATE OUTER FEASIBILITY FIX REQUIRES TOOLING MODIFICATIONS ON BASE & STEPGATE TAILGATE MOLDINGS	N				
4		FL34-99431B82-GDW	3/11/2013	3/11/2013	RIB ADDED TO HOUSING OF THE TAILGATE HANDLE LIGHT	RIB ADDED TO HOUSING OF THE TAILGATE HANDLE LIGHT RIB ON LIGHT WILL PREVENT THE CLIP FROM BREAKING OFF THE LIGHT THAT HOLDS IT IN POSITION.	N				
5		FL34-99431B82-GEW	3/11/2013	8/11/2014	ADD 2-SHOT LENS AND GASKET TO THE TBA LIGHT	TWO SHOT MOLD TBA LIGHT & MODIFY ASSEMBLY TO MINIMIZE THE APPARENT GAP BETWEEN THE LIGHT AND THE TAILGATE HANDLE.	N				
6		FL34-99431B82-GFW	8/11/2014	8/11/2014	MODIFY THE PEPS TG HANDLE STUDS AND HOUSING TO IMPROVE ROBUSTNESS.	MODIFY THE PEPS TG HANDLE STUDS AND HOUSING TO IMPROVE ROBUSTNESS.	N				
7		FL34-99431B82-GGW	8/11/2014	8/11/2014	REVISE TBA LIGHT TO IMPROVE SEALING	ADD SEALING ROBUSTNESS ACTIONS TO THE TBA LIGHT IN THE TG HANDLE TO PREVENT CONDENSATION. 0-N	N	FL34-9943800-GAW	8/11/2014		8/11/2014
8		FL34-99431B82-GHW	8/11/2014	8/11/2014	REVISE TAILGATE HANDLE AS NECESSARY TO ACHIEVE AAR APPROVAL	REVISE TAILGATE HANDLES TO IMPROVE CLASS A APPEARANCE CHANGE WILL BE REQUIRED TO ACHIEVE AAR APPROVAL.	N	FL34-9943800-GBW	8/11/2014		1/4/2016
9		FL34-99431B82-GJW	8/11/2014	8/11/2014	UPDATE REAR VISION CAMERA SOFTWARE TO REV. 5.5	UPDATE HIGHLINE AND TAD ECU AND CAMERAS FOR R5.5 SOFTWARE LEVEL CHANGES.	N				

10		FL34-99431B82-GKW	8/11/2014	8/11/2014	REVISE TBA LAMP INTENSITY	REVISE THE TBA LAMP TO LOWER THE LIGHT OUTPUT	N				
11		FL34-99431B82-GLW	8/11/2014	11/10/2014	UPDATE ASSEMBLY FOR NEW CAMERA SOFTWARE VERSION 6.0	UPDATE HIGHLINE ECU AND CAMERAS FOR R6.0 SOFTWARE LEVEL CHANGES.	N				
12		FL34-99431B82-GLW	11/10/2014	10/5/2015	CAD UPDATE - NO PHYSICAL CHANGES	UPDATE DRAWINGS/CAD TO PRODUCTION INTENT; NO PHYSICAL CHANGE TO THE PARTS; PART NUMBERS/SUFFIXES, NOT CHANGING;	N				
13		FL34-99431B82-GMW	10/5/2015	10/5/2015	RELEASE LOW GLARE TBA LIGHT	RELEASE LOW GLARE BACKUP ASSIST LIGHT TO REPLACE CURRENT LIGHT ON P552.	N				
14		FL34-99431B82-GNW	10/5/2015	1/4/2016	REVISE TAILGATE HANDLE ASSEMBLY FOR UPDATED CAMERA SOFTWARE	REAR VIDEO CAMERA AND FRONT VIDEO CAMERA SOFTWARE UPDATE MODIFY CAMERA SOFTWARE TO ADD RETRY IF INITIAL CHECKSUM MEASUREMENT IS INCORRECT.	N				
15		FL34-99431B82-GPW	1/4/2016	1/4/2016	ROBUSTNESS IMPROVEMENT ON CAMERA LOACTION RIBS - ADD SUPPORT GUSSETS	ROBUSTNESS IMPROVEMENT ON CAMERA LOCATING RIBS. ADD SUPPORT GUSSETS TO PREVENT HANDLING DAMAGE.	N	FL34-9943800-GCW	1/4/2016	17/07/2017	
16		FL34-99431B82-GRW	1/4/2016	7/17/2017	REPLACE CURRENT LED IN TBA	TBA LAMP LED SUPPLIER CHANGE FOR VA/VE COST REDUCTION	N				
17		FL34-99431B82-GSW	7/17/2017	16/102017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	FL34-9943800-GDW	7/17/2017		
18		FL34-99431B82-GTW	10/16/2017		DELETE THE INTENT OF C13357998. USE THE OLD LEVEL PULL CUP WHICH FITS BETTER IN THE OLD OUTER USED BY LOBO.	DELETE THE INTENT OF C13357998 FOR LOBO TAILGATE HANDLE WITH PEPS.REPLACE THE CURRENT SPRINGS ON MECHANICAL HANDLES WITH ONE FOR COST SAVINGS	N				

+ Date part number removed from service.

FL34-99431B82-L *W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1		FL34-99431B82-LAW	10/5/2015		INITIAL RELEASE	RELEASE SATIN CHROME OUTSIDE HANDLES AND TAILGATE HANDLES	N	FL34-9943800-AAW	10/5/2015	1/4/2016	
2		FL34-99431B82-LBW	10/5/2015	10/5/2015	RELEASE LOW GLARE TBA LIGHT	RELEASE LOW GLARE BACKUP ASSIST LIGHT TO REPLACE CURRENT LIGHT ON P552.	N				
3		FL34-99431B82-LCW	10/5/2015	1/4/2016	REVISE TAILGATE HANDLE ASSEMBLY FOR UPDATED CAMERA SOFTWARE	REAR VIDEO CAMERA AND FRONT VIDEO CAMERA SOFTWARE UPDATE MODIFY CAMERA SOFTWARE TO ADD RETRY IF INITIAL CHECKSUM MEASUREMENT IS INCORRECT.	N				
		FL34-99431B82-LDW	1/4/2016	1/4/2016	ROBUSTNESS IMPROVEMENT ON CAMERA LOACTION RIBS - ADD SUPPORT GUSSETS	ROBUSTNESS IMPROVEMENT ON CAMERA LOCATING RIBS. ADD SUPPORT GUSSETS TO PREVENT HANDLING DAMAGE.	N	FL34-9943800-LBW	1/4/2016	17/07/2017	

		FL34-99431B82-LEW	1/4/2016	7/17/2017	REPLACE CURRENT LED IN TBA	TBA LAMP LED SUPPLIER CHANGE FOR VA/VE COST REDUCTION	N				
		FL34-99431B82-LFW	7/17/2017	16/10/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	FL34-9943800-LCW	7/17/2017		

+_____

HL3V-99431B82-C*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	17Y	HL3V-99431B82-CAW	10/31/2016		INITIAL RELEASE	17MY RAPTOR 360 CAMERA SYSTEM	N	FL34-9943800-GCW	10/31/2016	7/17/2017	
2		HL3V-99431B82-CBW	7/17/2017	16/10/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	FL34-9943800-GDW	7/17/2017		

JL34-99431B82-K*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18Y	JL34-99431B82-KAW	VP BUILD	2/17/2016	INITIAL RELEASE		N	JL34-9943800-KAW	2/17/2016	2/17/2016	
2		JL34-99431B82-KBW	2/17/2016	7/17/2017	ADD CAMERA SPACER; UPDATE TCE DATA FOR POST FDJ CHANGES	ADD PIA SPACER COMPONENT FOR CAMERA; UPDATE TCE FILE FOR DESIGN ENHANCEMENTS POST FDJ INCLUDING: CAMERA LOCATING, SUPPORT RIBBING, LOCATOR DESIGN, REINFORCEMENT CLEARANCE	N	JL34-9943800-KBW	2/17/2016	7/17/2017	
3		JL34-99431B82-KCW	7/17/2017	7/17/2017	UPDATE REAR VISION CAMERA	UPDATE TAILGATE HANDLE ASSEMBLIES TO REFLECT CAMERA PART	N				
4		JL34-99431B82-KDW	7/17/2017	7/17/2017	ADD RIBS TO CAMERA SPACER TO PREVENT EXCESS CAMERA ROTATION ISSUE	CAMERA SPACER DESIGN CHANGE TO RESOLVE CAMERA ISSUE	N				
5		JL34-99431B82-KEW	7/17/2017	7/17/2017	USE CAMERA WITH LATEST SOFTWARE UPDATE	UPDATE THE MIAMI3 REAR VIDEO CAMERA SOFTWARE TO CATER FOR THE CORRECT SERIAL PART NUMBERS.	N				
6		JL34-99431B82-KFW	7/17/2017	7/17/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	JL34-9943800-KCW	7/17/2017	16/10/2017	
7		JL34-99431B82-KGW	7/17/2017	10/16/2017	REVISE CAMERA RETAINER TO INCLUDE TWO WIRE CLIPS	REVISE TAILGATE HANDLE CAMERA RETAINER TO ADD AN ADDITIONAL WIRE HARNESS RETAINER CLIP	N				
8		JL34-99431B82-KHW	10/16/2017	10/16/2017	MODIFY RIB-LOCK RIB TO PREVERT WHITE CLIP FROM MOVING OR FALLING FROM TAILGATE HANDLE ASSEMBLY	ROBUSTNESS IMPROVEMENT- MODIFY RIB OF RIB-LOCK TO PREVENT ANY MOVEMENT OF THE RIB-LOCK WHITE CLIP ON THE OF THE TAILGATE HANDLE ASSEMBLY	N	JL34-9943800-KDW	10/16/2017	10/16/2017	
9		JL34-99431B82-KJW	10/16/2017		CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	N	JL34-9943800-KEW	10/16/2017		

JL34-99431B82-L*W Changes								Service Parts - Dis			
---------------------------	--	--	--	--	--	--	--	---------------------	--	--	--

Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18Y	JL34-99431B82-LAW	VP BUILD	2/17/2016	INITIAL RELEASE		N	JL34-9943800-KAW	2/17/2016	2/17/2016	
2		JL34-99431B82-LBW	2/17/2016	7/17/2017	ADD CAMERA SPACER; UPDATE TCE DATA FOR POST FDJ CHANGES	ADD PIA SPACER COMPONENT FOR CAMERA; UPDATE TCE FILE FOR DESIGN ENHANCEMENTS POST FDJ INCLUDING: CAMERA LOCATING, SUPPORT RIBBING, LOCATOR DESIGN, REINFORCEMENT CLEARANCE	N	JL34-9943800-KBW	2/17/2016	7/17/2017	
3		JL34-99431B82-LCW	7/17/2017	7/17/2017	UPDATE REAR VISION CAMERA	UPDATE TAILGATE HANDLE ASSEMBLIES TO REFLECT CAMERA PART	N				
4		JL34-99431B82-LDW	7/17/2017	7/17/2017	ADD RIBS TO CAMERA SPACER TO PREVENT EXCESS CAMERA ROTATION ISSUE	CAMERA SPACER DESIGN CHANGE TO RESOLVE CAMERA ISSUE	N				
5		JL34-99431B82-LEW	7/17/2017	7/17/2017	UPDATE WITH THE LATEST CAMERA LEVEL	MULTICAMERA FRONT AND REAR CAMERA SW UPDATED DUE TO BLACK SCREEN ISSUE.	N				
6		JL34-99431B82-LFW	7/17/2017	7/17/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	JL34-9943800-KCW	7/17/2017	16/10/2017	
		JL34-99431B82-LGW	7/17/2017	7/17/2017	REVISE CAMERA RETAINER TO INCLUDE TWO WIRE CLIPS	REVISE TAILGATE HANDLE CAMERA RETAINER TO ADD AN ADDITIONAL WIRE HARNESS RETAINER CLIP					
7		JL34-99431B82-LHW	10/16/2017	10/16/2017	MODIFY RIB-LOCK RIB TO PREVERNT WHITE CLIP FROM MOVING OR FALLING FROM TAILGATE HANDLE ASSEMBLY	ROBUSTNESS IMPROVEMENT- MODIFY RIB OF RIB-LOCK TO PREVENT ANY MOVEMENT OF THE RIB-LOCK WHITE CLIP ON THE OF THE TAILGA TE HANDLE ASSEMBLY	N	JL34-9943800-KDW	10/16/2017		
8		JL34-99431B82-LJW	10/16/2017		CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	N	JL34-9943800-KEW	10/16/2017		

JL34-99431B82-M*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18Y	JL34-99431B82-MAW	VP BUILD	2/17/2016	INITIAL RELEASE		N	JL34-9943800-MAW	2/17/2016	2/17/2016	
2		JL34-99431B82-MBW	2/17/2016	7/17/2017	ADD CAMERA SPACER; UPDATE TCE DATA FOR POST FDJ CHANGES	ADD PIA SPACER COMPONENT FOR CAMERA; UPDATE TCE FILE FOR DESIGN ENHANCEMENTS POST FDJ INCLUDING: CAMERA LOCATING, SUPPORT RIBBING, LOCATOR DESIGN, REINFORCEMENT CLEARANCE	N	JL34-9943800-MBW	2/17/2016	7/17/2017	
3		JL34-99431B82-MCW	7/17/2017	7/17/2017	UPDATE REAR VISION CAMERA	UPDATE TAILGATE HANDLE ASSEMBLIES TO REFLECT CAMERA PART	N				
4		JL34-99431B82-MDW	7/17/2017	7/17/2017	ADD RIBS TO CAMERA SPACER TO PREVENT EXCESS CAMERA ROTATION ISSUE	CAMERA SPACER DESIGN CHANGE TO RESOLVE CAMERA ISSUE	N				
5		JL34-99431B82-MEW	7/17/2017	7/17/2017	UPDATE WITH THE LATEST CAMERA LEVEL	MULTICAMERA FRONT AND REAR CAMERA SW UPDATED DUE TO BLACK SCREEN ISSUE.	N				
6		JL34-99431B82-MFW	7/17/2017	7/17/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	JL34-9943800-MCW	7/17/2017	16/10/2017	
		JL34-99431B82-MGW	7/17/2017	7/17/2017	REVISE CAMERA RETAINER TO INCLUDE TWO WIRE CLIPS	REVISE TAILGATE HANDLE CAMERA RETAINER TO ADD AN ADDITIONAL WIRE HARNESS RETAINER CLIP					

7		JL34-99431B82-MHW	10/16/2017	10/16/2017	MODIFY RIB-LOCK RIB TO PREVERNT WHITE CLIP FROM MOVING OR FALLING FROM TAILGATE HANDLE ASSEMBLY	ROBUSTNESS IMPROVEMENT- MODIFY RIB OF RIB-LOCK TO PREVENT ANY MOVEMENT OF THE RIB-LOCK WHITE CLIP ON THE OF THE TAILGATE HANDLE ASSEMBLY	N	JL34-9943800-MDW	10/16/2017		
8		JL34-99431B82-MJW	10/16/2017		CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	N	JL34-9943800-MEW	10/16/2017		

JL34-99431B82-N*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18Y	JL34-99431B82-NAW	VP BUILD	2/17/2016	INITIAL RELEASE		N	JL34-9943800-MAW	2/17/2016	2/17/2016	
2		JL34-99431B82-NBW	2/17/2016	7/17/2017	ADD CAMERA SPACER; UPDATE TCE DATA FOR POST FDJ CHANGES	ADD PIA SPACER COMPONENT FOR CAMERA; UPDATE TCE FILE FOR DESIGN ENHANCEMENTS POST FDJ INCLUDING: CAMERA LOCATING, SUPPORT RIBBING, LOCATOR DESIGN, REINFORCEMENT CLEARANCE	N	JL34-9943800-MBW	2/17/2016	7/17/2017	
3		JL34-99431B82-NCW	7/17/2017	7/17/2017	UPDATE REAR VISION CAMERA	UPDATE TAILGATE HANDLE ASSEMBLIES TO REFLECT CAMERA PART	N				
4		JL34-99431B82-NDW	7/17/2017	7/17/2017	ADD RIBS TO CAMERA SPACER TO PREVENT EXCESS CAMERA ROTATION ISSUE	CAMERA SPACER DESIGN CHANGE TO RESOLVE CAMERA ISSUE	N				
5		JL34-99431B82-NEW	7/17/2017	7/17/2017	UPDATE WITH THE LATEST CAMERA LEVEL	MULTICAMERA FRONT AND REAR CAMERA SW UPDATED DUE TO BLACK SCREEN ISSUE.	N				
6		JL34-99431B82-NFW	7/17/2017	7/17/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	JL34-9943800-MCW	7/17/2017	16/10/2017	
		JL34-99431B82-NGW	7/17/2017	7/17/2017	REVISE CAMERA RETAINER TO INCLUDE TWO WIRE CLIPS	REVISE TAILGATE HANDLE CAMERA RETAINER TO ADD AN ADDITIONAL WIRE HARNESS RETAINER CLIP					
7		JL34-99431B82-NHW	10/16/2017	10/16/2017	MODIFY RIB-LOCK RIB TO PREVERNT WHITE CLIP FROM MOVING OR FALLING FROM TAILGATE HANDLE ASSEMBLY	ROBUSTNESS IMPROVEMENT- MODIFY RIB OF RIB-LOCK TO PREVENT ANY MOVEMENT OF THE RIB-LOCK WHITE CLIP ON THE OF THE TAILGATE HANDLE ASSEMBLY	N	JL34-9943800-MDW	10/16/2017		
8		JL34-99431B82-NJW	10/16/2017		CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	N	JL34-9943800-MEW	10/16/2017		

JL34-99431B82-P*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18Y	JL34-99431B82-PAW	VP BUILD	2/17/2016	INITIAL RELEASE		N	JL34-9943800-PAW	2/17/2016	2/17/2016	
2		JL34-99431B82-PBW	2/17/2016	7/17/2017	ADD CAMERA SPACER; UPDATE TCE DATA FOR POST FDJ CHANGES	ADD PIA SPACER COMPONENT FOR CAMERA; UPDATE TCE FILE FOR DESIGN ENHANCEMENTS POST FDJ INCLUDING: CAMERA LOCATING, SUPPORT RIBBING, LOCATOR DESIGN, REINFORCEMENT CLEARANCE	N	JL34-9943800-PBW	2/17/2016	7/17/2017	
3		JL34-99431B82-PCW	7/17/2017	7/17/2017	UPDATE REAR VISION CAMERA	UPDATE TAILGATE HANDLE ASSEMBLIES TO REFLECT CAMERA PART	N				
4		JL34-99431B82-PDW	7/17/2017	7/17/2017	ADD RIBS TO CAMERA SPACER TO PREVENT EXCESS CAMERA ROTATION ISSUE	CAMERA SPACER DESIGN CHANGE TO RESOLVE CAMERA ISSUE	N				
5		JL34-99431B82-PEW	7/17/2017	7/17/2017	UPDATE WITH THE LATEST CAMERA LEVEL	MULTICAMERA FRONT AND REAR CAMERA SW UPDATED DUE TO BLACK SCREEN ISSUE.	N				

6		JL34-99431B82-PFW	7/17/2017	7/17/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	JL34-9943800-PCW	7/17/2017	16/10/2017	
		JL34-99431B82-PGW	7/17/2017	7/17/2017	REVISE CAMERA RETAINER TO INCLUDE TWO WIRE CLIPS	REVISE TAILGATE HANDLE CAMERA RETAINER TO ADD AN ADDITIONAL WIRE HARNESS RETAINER CLIP	N				
7		JL34-99431B82-PHW	10/16/2017	10/16/2017	MODIFY RIB-LOCK RIB TO PREVERNT WHITE CLIP FROM MOVING OR FALLING FROM TAILGATE HANDLE ASSEMBLY	ROBUSTNESS IMPROVEMENT- MODIFY RIB OF RIB-LOCK TO PREVENT ANY MOVEMENT OF THE RIB-LOCK WHITE CLIP ON THE OF THE TAILGATE HANDLE ASSEMBLY	N	JL34-9943800-PDW	10/16/2017		
8		JL34-99431B82-PJW	10/16/2017		CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	N	JL34-9943800-PEW	10/16/2017		

JL3V-99431B82-U*W Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18Y	JL34-99431B82-UAW	VP BUILD	2/17/2016	INITIAL RELEASE	RELEASE RAPTOR TAILGATE HANDLES FOR 201	N	JL34-9943800-KBW	2/17/2016	7/17/2017	
2		JL3V-99431B82-UBW	2/17/2016	7/17/2017	CAMERA UPDATE	R4 SOFTWARE RELEASE FOR MULTICAMERA IPMB MODULE	N				
3		JL3V-99431B82-UCW	7/17/2017	7/17/2017	ADD RIBS TO CAMERA SPACER TO PREVENT EXCESS CAMERA ROTATION ISSUE	CAMERA SPACER DESIGN CHANGE TO RESOLVE CAMERA ISSUE	N				
4		JL3V-99431B82-UDW	7/17/2017	7/17/2017	UPDATE WITH THE LATEST CAMERA LEVEL	MULTICAMERA FRONT AND REAR CAMERA SW UPDATED DUE TO BLACK SCREEN ISSUE.	N				
5		JL3V-99431B82-UEW	7/17/2017	7/17/2017	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT	MODIFY TG HANDLE SNAPS TO ALLOW MORE SHEETMETAL ENGAGEMENT AND BETTER RETENTION.MODIFY TGHANDLE/SPACER TO SHIFT CAMERA PITCH ANGLE HIGHER TO FIX TBA ISSUE	N	JL34-9943800-KCW	7/17/2017	16/10/2017	
6		JL3V-99431B82-UFW	7/17/2017	7/17/2017	REVISE CAMERA RETAINER TO INCLUDE TWO WIRE CLIPS	REVISE TAILGATE HANDLE CAMERA RETAINER TO ADD AN ADDITIONAL WIRE HARNESS RETAINER CLIP	N				
		JL3V-99431B82-UGW	10/16/2017	10/16/2017	MODIFY RIB-LOCK RIB TO PREVERNT WHITE CLIP FROM MOVING OR FALLING FROM TAILGATE HANDLE ASSEMBLY	ROBUSTNESS IMPROVEMENT- MODIFY RIB OF RIB-LOCK TO PREVENT ANY MOVEMENT OF THE RIB-LOCK WHITE CLIP ON THE OF THE TAILGATE HANDLE ASSEMBLY	N	JL34-9943800-KDW	10/16/2017		
7		JL3V-99431B82-UHW	10/16/2017		CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	CHANGE PULL CUP ON PEPS TG HANDLES FROM BC TO MIC	N	JL34-9943800-KEW	10/16/2017		

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

position

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F150 Wiring Change
Log

F150 Wiring Harness Parts Change Log

NHTSA Inquiry MA18-011 / :NEF-106rr

Part A Changes.- Wiring Assy - Tail Gate (14B562)								Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
8	2016	GL3T-14B562-FA GL3T-14B562-GA GL3T-14B562-HA GL3T-14B562-JA GL3T-14B562-KA	PP Build AE00-E-12988538-000	N/A	DCR 500 - ADD TAILGATE AJAR DCR 683 - TVM: UPDATE SLEEVE ON TG PASS-THRU DCR 684 - UPDATE R1 TO 9L3T-14A163-EA DCR 685 - BOM CORRECTION - TSP FOIL AND TAPE.	DCR 500 - Tailgate Ajar Switch required for vehicles with Remote Tailgate Release button on keyfob (CBFAN + CAQAB). DCR 683 - TVM. DCR 684 - Robustness Improvement - Tape tab has wings for better attachment. DCR 685 - Zuken tables automatically updated and calculated correct length required. Print was updated and BOM was updated.	N	GL3Z-14A412-E (for FA only)	5/19/2015			N		
9	2017	GL3T-14B562-GB GL3T-14B562-HB GL3T-14B562-JB GL3T-14B562-KB	Post Job 1 AE00-E-13203010-000	N/A	DCR 971 - UPDATE REAR CAMERA CONN DCR 1165-2 - ANTI-CAILLARY WIRE	DCR 971 - DFM - Yazaki - Difficulty inserting terminals into connector due to clearance to integrated strain relief grommet cap. DCR 1165-2 - Water Intrusion issues / Warranty Issues caused by improperly sealed 1-to-1 drain wire splices. Rear View Camera failures reported.	N	GL3Z-14A412-G GL3Z-14A412-H GL3Z-14A412-J GL3Z-14A412-K	12/2/2016			N		
10	2018	JL3T-14B562-FE JL3T-14B562-GD JL3T-14B562-HD JL3T-14B562-JD JL3T-14B562-KC JL3T-14B562-LE	VP Build AE00-E-13070292-070	N/A	REMOVED TG AJAR [REF: DCR 500] RELEASE NEW LEVEL "L"	INITIAL RELEASE	N	JL3Z-14A412-A JL3Z-14A412-B JL3Z-14A412-C JL3Z-14A412-D JL3Z-14A412-E JL3Z-14A412-F	5/18/2017			N		
11			TT Build AE00-E-13185580-000	N/A	DCR 1122: UPDATE TERM 8U5T-14474-BA TO BB [NYE LUBRICANT DISCONTINUED] DCR 1124: UPDATE REAR CAMERA CONNECTOR DCR 1138: RAPTOR BEAMING DAMPER ROUTING DCR 1165-2: ANTI-CAPILLARY WIRE FOR DRAIN SPLICES DCR 1174: ADDING TAILGATE AJAR DCR 1244: PRINT CLARIFICATIONS/DWG AUDIT	DCR 1122 - Discontinuation of Nye lubricant (561J), and change to a comparable alternative lubricant (568J). DCR 1124 - DFM - Yazaki - Difficulty inserting terminals into connector due to clearance to integrated strain relief grommet cap. [REFERENCE DCR 971 - 2016MY]. DCR 1138 - Raptor Beaming Damper. DCR 1165-2 - Water Intrusion issues / Warranty Issues caused by improperly sealed 1-to-1 drain wire splices. Rear View Camera failures reported. DCR 1174 - PDL update to add Tailgate Ajar for 2018MY. COORDINATED WITH NEW LATCH RELEASED VIA C13141556. DCR 1244 - Drawing/Print Audit Issues.	N					N		
14			PP Build AE00-E-13305927-000	N/A	DCR 1472: WHITE DOT ON TAILGATE AJAR CONN DCR 1473: RETAINER ON TAILGATE AJAR T/O	DCR 1472 - Manufacturing is requesting a white dot on the tailgate ajar latch connector to assist in quickly orienting the connector during assembly. The latch connection is somewhat hidden and in a darker area of the tailgate. DCR 1473 - The Tailgate Ajar Latch takeout can hover directly over the area of a fastener for the tailgate applique and can get trapped or damaged during the securing of that fastener.	N					N		
15			KCAP PP Build AE00-E-13313178-000	N/A	DCR 1485: DIMENSIONAL CHANGES FOR HANDLE T/O'S	DCR 1485 - 14B562 Wire for tailgate handle interfering with tailgate handle installation.	N					N		
16			KCAP MP1 AE00-E-13357725-000	N/A	DCR 1640: REMOVE CONVOLUTE AND REPLACE WITH ABRASION TAPE DCR 1644: ID LABEL CHANGES	DCR 1640 - THE TT BUILD EVENT SEEMED TO BE OKAY WITH REDUCING THE LENGTH BY 30mm (BOTH DTP AND KCAP) BUT FURTHER INVESTIGATION AT DTP PP BUILD EVENT REQUESTS A SMALLER BUNDLE DIAMETER IN THE CAVITY OF THE TAILGATE BEHIND THE HANDLE. DCR 1644 - AFFILIATE PRINT CLARIFICATIONS.	N					N		
17			DTP MP2 AE00-E-13377436-000	N/A	DCR 1660: ADD LOCATOR SPOT TAPE. DCR 1668: ADD 45 mm TO LOCK ACTUATOR T/O DCR 1670: REMOVE RAPTOR LEVELS	DCR 1660 - ASSURE CORRECT ROUTING FOR TAILGATE HANDLE. DCR 1668 - MODIFIED CAMERA RETAINER. DCR 1670 - PRINT CLEAN UP.	N					N		
18	2018.5		Post Job 1 AE00-E-13611032-001	N/A	Usage change only to effect-out Tail Gate Ajar level.	Remove Tail Gate Ajar.	N					N		

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F-Super Duty and
F150 Key Fobs RTM Change
Log

Parts Change Log

NHTSA Inquiry MA18-011 / :NEF-106rr

Part A Part Changes - Key Fobs								Service Parts - Disposition			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	17MY	HC3T-15K601-C* 868 MHz	J1	N/A	N/A	N/A	Yes	HC3Z-15K601-C*	J1	N/A	N/A
2	17MY	HC3T-15K601-B* 902 MHz	J1	N/A	N/A	N/A	Yes	HC3Z-15K601-B*	J1	N/A	N/A
3	18MY	HC3T-15K601-C* 868 MHz	J1	N/A	N/A	N/A	Yes	HC3Z-15K601-C*	J1	N/A	N/A
4	18MY	HC3T-15K601-B* 902 MHz	J1	N/A	N/A	N/A	Yes	HC3Z-15K601-B*	J1	N/A	N/A
5											

Part B Part Changes - RTM Assembly								Service Parts - Disposition			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	17MY	HC3T-18D816-DB 868 MHz	J1	N/A	N/A	N/A	F150	GD9Z-15607-F 868 MHz	J1	N/A	N/A
2	17MY	HC3T-18D816-CB 902 MHz	J1	N/A	N/A	N/A	F150	GD9Z-15607-J 902 MHz	J1	N/A	N/A
3	18MY	HC3T-18D816-DB 868 MHz	Carryover	N/A	N/A	N/A	F150	GD9Z-15607-F 868 MHz	Carryover	N/A	N/A
4	18MY	HC3T-18D816-CB 902 MHz	Carryover	N/A	N/A	N/A	F150	GD9Z-15607-J 902 MHz	Carryover	N/A	N/A
5											

+ Date part number removed from service.

--

Position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
N	N/A	N/A
N	N/A	N/A
Only with 17MY	N/A	N/A
Only with 17MY	N/A	N/A

Position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
N	N/A	N/A
N	N/A	N/A
Only with 17MY	N/A	N/A
Only with 17MY	N/A	N/A

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F-Super Duty BCM
Change Log

Parts Change Log

NHTSA Inquiry PE18-011

Part A Part Changes								Serv		
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change
1	2017	HU5T-15604-JAG HU5T-15604-LAG HU5T-15604-MAG HU5T-15604-NAG	5/31/2016	8/30/2016	1) Transit Vehicles Locking Feature Modifications Design Implementation ** Change introduced with MY17 FDJ1 SW release 2) Transit Locking Changes New Requirements - MY17 only ** Change introduced with MY17 FDJ2 SW release	New locking features add only for commercial vans. Does not affect other vehicle types: Ex- Car, pick-up, SUV				
					Allow the manual liftgate; manual Decklid and Liftgate Glass to be released in the FACTORY mode. ** Change introduced with MY17 R07.2 SW release	ONLY used during vehicle assembly				
					Decouple the vehicle speed Slow/Fast for locking and change the Threshold type from a Constant to a configurable value ** Change introduced with MY17 R07.3 SW release	Allows the vehicle speed threshold to be different for locking versus other features.				
2	2017	HU5T-15604-JAJ HU5T-15604-LAJ HU5T-15604-MAJ HU5T-15604-NAJ	8/30/2016	1/30/2017	C/O changes from previous SW release					
3	2017	HU5T-15604-JAN HU5T-15604-LAN HU5T-15604-MAN HU5T-15604-NAN	1/30/2017	5/1/2017	C/O changes from previous SW release					
4	2017	HU5T-15604-JAP HU5T-15604-LAP HU5T-15604-MAP HU5T-15604-NAP	5/1/2017	11/27/2017	C/O changes from previous SW release					
5	2018	JU5T-15604-JAJ JU5T-15604-LAJ JU5T-15604-MAJ JU5T-15604-NAJ	11/27/2017	2/26/2018	Liftgate Glass not opening after pressing the Liftglass switch with PK in range ** Change introduced with MY18 R05 SW release	New requirements needed for the BCM to send signal to priotitize liftglass release when commanded from keyfob.				
6	2018	JU5T-15604-JAL JU5T-15604-LAL JU5T-15604-MAL JU5T-15604-NAL	2/26/2018	9/3/2018	C/O changes from previous SW release					
7	2018	JU5T-15604-JAR JU5T-15604-LAR JU5T-15604-MAR JU5T-15604-NAR	9/3/2018	PRESENT	C/O changes from previous SW release					

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F-Super Duty EDS

Change Log

Parts Change Log

NHTSA Inquiry MA18-011 / :NEF-106rr

HC3T-14B562			Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2017	HC3T-14B562-AA/BA	HC3Z-14A412-A/B						
2	2017	HC3T-14B562-AB/BB	HC3Z-14A412-A/B						
3	2017	HC3T-14B562-AC/BC	HC3Z-14A412-A/B						
4	2017	HC3T-14B562-AD/BD	HC3Z-14A412-A/B						
5	2017	HC3T-14B562-AE/BE	HC3Z-14A412-A/B						
6	2018	JC3T-14B562-AA/BA	JC3Z-14A412-A/B						
7	2018	JC3T-14B562-AB/BB	JC3Z-14A412-A/B						

HC3T-14405			Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2017	HC3T-14405-ABC/ADC/AEC/AGC/ALC/BBC/BDC/BFC/BHC/CBC/CDC/CF	None Listed						
2	2017	HC3T-14405-ABD/ADD/AED/AGD/ALD/BBD/BDD/BFD/BHD/CBD/CDD/CF	None Listed						
3	2017	HC3T-14405-ABE/ADE/AEE/AGE/ALE/BBE/BDE/BFE/BHE/CBE/CDE/CF	None Listed						
4	2017	HC3T-14405-ABF/ADF/AEF/ALF/BBF/BDF/BHF/CBF/CDF/CHF/CJF/CMC/	None Listed						
5	2017	HC3T-14405-ABF/ADF/AEF/ALF/BBF/BDF/BHF/CBF/CDF/CHF/CJF/CMC/	None Listed						
6	2017	HC3T-14405-ABF/ADF/AEF/ALF/BBF/BDF/BHF/CBF/CDF/CHF/CJF/CMC/	None Listed						
7	2017	HC3T-14405-ABH/ADH/AEH/ALH/BBH/BDH/BHH/CBH/CDH/CHH/CJH/C	None Listed						
8	2017	HC3T-14405-ABJ/ADJ/AEJ/ALJ/BBJ/BDJ/BHJ/CBJ/CDJ/CHJ/CJJ/CMF/C	None Listed						
9	2017	HC3T-14405-ABK/ADK/AEK/ALK/BBK/BDK/BHK/CBK/CDK/CHK/CJK/CM	None Listed						
10	2018	JC3T-14405-AAA/ACA/AHA/AKA/BAA/BCA/BGA/CAA/CCA/CGA/CKA/CL	None Listed						
11	2018	JC3T-14405-AAB/ACB/AKBBAB/BCB/BGB/CAB/CCB/CKB/DAB/DCB/DG	None Listed						
12	2018	JC3T-14405-AAC/ACC/AKC/BAC/BCC/BGC/CAC/CCC/CKC/DAC/DCC/D	None Listed						
13	2018	JC3T-14405-AAD/ACD/AKD/BAD/BCD/BGD/CAD/CCD/CKD/DAD/DCD/D	None Listed						
14	2018	JC3T-14405-ABA/ADA/AEA/ALA/BBA/BDA/BHA/CBA/CDA/CHA/CMA/CN	None Listed						

15	2018	JC3T-14405- ABB/ADB/ALB/BBB/BDB/BHB/CBB/CDB/CHB/DBB//DDB/D	None Listed						
16	2018	JC3T-14405- ABC/ADCALCBBCBDCBHC/CBC/CDC/CHC/DBC/DDC/DHC	None Listed						
17	2018	JC3T-14405- ABD/ADD/ALD/BBB/BDD/BHD/CBD/CDD/CHD/DBD/DDD/D	None Listed						

+ Date part number removed from service.

HC3T-14401			Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2017	HC3T-14401-ALL LEVELS EXCEPT JBA/JFA/JHA	None Listed						
2	2017	HC3T-14401-ALL LEVELS EXCEPT JBB/JFB/JHB	None Listed						
3	2017	HC3T-14401-ALL LEVELS EXCEPT JBC/JFC/JHC	None Listed						
4	2017	HC3T-14401-ALL LEVELS EXCEPT JBD/JFD/JHD	None Listed						
5	2017	HC3T-14401-ALL LEVELS EXCEPT JBE/JFE/JHE	None Listed						
6	2017	HC3T-14401-ALL LEVELS EXCEPT JBE/JFE/JHE	None Listed						
7	2017	HC3T-14401-ALL LEVELS EXCEPT JBA/JFA/JHA	None Listed						
8	2017	HC3T-14401-ALL LEVELS EXCEPT JBF/JFF/JHF	None Listed						
9	2017	HC3T-14401-ALL LEVELS EXCEPT JBF/JFF/JHF	None Listed						
10	2017	HC3T-14401-ALL LEVELS EXCEPT MNA/MPA/MRA/MSA/PKA/RFA/RGA/RKA	None Listed						
11	2017	HC3T-14401-ALL LEVELS EXCEPT MNA/MPA/MRA/MSA/PKA/RFA/RGA/RKA	None Listed						
12	2017	HC3T-14401-ALL LEVELS EXCEPT MNB/MPB/MRB/MSB/PKB/RFB/RGB/RKB	None Listed						
13	2017	HC3T-14401-ALL LEVELS EXCEPT MNB/MPB/MRB/MSB/PKB/RFB/RGB/RKB	None Listed						
14	2018	JC3T-14401-ALL LEVELS EXCEPT ANA/APA/DJA/DNA	None Listed						
15	2018	JC3T-14401-ALL LEVELS EXCEPT ANA/APA/DJA/DNA	None Listed						
16	2018	JC3T-14401-ALL LEVELS EXCEPT ANB/APB/DJB/DNB	None Listed						
17	2018	JC3T-14401-ALL LEVELS EXCEPT ANB/APB/DJB/DNB	None Listed						
18	2018	JC3T-14401-ALL LEVELS EXCEPT APA/DJA/DNA	None Listed						
19	2018	JC3T-14401-ALL LEVELS EXCEPT APC/DJC/DNC	None Listed						
20	2018	JC3T-14401-ALL LEVELS EXCEPT APC/DJC/DNC	None Listed						

HC3T-14631			Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2017	HC3T-14631-AA/BA/CA/DA/E/AFA/GA/HA/KA/LA	None Listed						
2	2017	HC3T-14631- AB/BB/CB/DB/EB/FB/GB/HB/KB/LB/NA/PA/RA/SA	None Listed						

3	2017	HC3T-14631- AC/BC/CC/DC/ED/FC/GC/HC/JB/LC/NB/PB/RB/SB/TA/UA/V	None Listed						
4	2017	HC3T-14631- AD/BD/CD/DD/FD/HD/KC/LD/NC/PC/RC/SC/TB/UB/VB/XB	None Listed						
5	2017	HC3T-14631- AE/BE/CE/DE/FE/HE/KE/LE/ND/PD/RD/SD/TC/UC/VC/XC	None Listed						
6	2017	HC3T-14631- AF/BF/CF/DF/FF/HF/KF/LF/NE/PE/RE/SE/TD/UD/VD/XD	None Listed						
7	2017	HC3T-14631- AF/BF/CF/DF/FF/HF/KF/LF/NE/PE/RE/SE/TD/UD/VD/XD	None Listed						
8	2017	HC3T-14631- AF/BF/CF/DF/FF/HF/KF/LF/NE/PE/RE/SE/TD/UD/VD/XD	None Listed						
9	2017	HC3T-14631- AG/BG/CG/DG/FG/HG/KG/LG/NF/PF/RF/SF/TE/UE/VE/XE	None Listed						
10	2017	HC3T-14631- AH/BH/CH/DH/FH/HH/KH/LH/NG/PG/RG/SG/TF/UF/VF/XF	None Listed						
11	2017	HC3T-14631- AJ/BJ/CJ/DJ/FJ/HJ/KJ/HJ/NH/PH/RH/SH/TG/UG/VG/XG	None Listed						
12	2017	HC3T-14631- AJ/BJ/CJ/DJ/FJ/HJ/KJ/HJ/NH/PH/RH/SH/TG/UG/VG/XG	None Listed						
13	2018	JC3T-14631- AA/BA/CA/DA/FA/HA/KA/LA/NA/PA/RA/SA/TA/UA/VA/XA	JC3Z-14631-A/B/C/D/E/F/G/H/J/K/L/M/N/P/Q/R/						
14	2018	JC3T-14631- AA/BA/CA/DA/FB/HB/KB/LB/NA/PA/RA/SA/TB/UB/VB/XB	JC3Z-14631-A/B/C/D/E/F/G/H/J/K/L/M/N/P/Q/R/						
15	2018	JC3T-14631- AA/BA/CA/DA/FB/HB/KB/LB/NA/PA/RA/SA/TB/UB/VB/XB	JC3Z-14631-A/B/C/D/E/F/G/H/J/K/L/M/N/P/Q/R/						
16	2018	JC3T-14631- AA/BA/CA/DA/FB/HB/KB/LB/NA/PA/RA/SA/UB/XB	JC3Z-14631-A/B/C/D/E/F/G/H/J/K/L/M/N/P/Q/R/						

HC3T-14A005			Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2017	HC3T-14A005-ALL LEVELS	None Listed						
2	2017	HC3T-14A005-ALL LEVELS	None Listed						
3	2017	HC3T-14A005-ALL LEVELS	None Listed						
4	2017	HC3T-14A005-ALL LEVELS	None Listed						
5	2017	HC3T-14A005-ALL LEVELS	None Listed						
6	2017	HC3T-14A005-ALL LEVELS	None Listed						
7	2017	HC3T-14A005-ALL LEVELS	None Listed						
8	2017	HC3T-14A005-ALL LEVELS	None Listed						
9	2018	JC3T-14A005-ALL LEVELS	None Listed						
10	2018	JC3T-14A005-ALL LEVELS	None Listed						
11	2018	JC3T-14A005-ALL LEVELS	None Listed						
12	2018	JC3T-14A005-ALL LEVELS	None Listed						

HC3T-13A409			Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

1	2017	HC3T-13A409- AA/BA/CA/DA/EA/FA/GA/HA/JB/MA/NA/PA/RA/SA	HC3Z-13A409- A/B/C/D/E/F/G/H/J/K/L/M/MB/NB/RB						
2	2017	HC3T-13A409- AB/BB/CB/DB/EB/FB/GB/HB/JC/MB/NB/PB/RB	HC3Z-13A409- A/B/C/D/E/F/G/H/J/K/L/M/MB/NB/RB						
3	2017	HC3T-13A409- AC/BC/CC/DC/EC/FC/GC/HC/JD/MC/NC/PC/RC	HC3Z-13A409- A/B/C/D/E/F/G/H/J/K/L/M/MB/NB/RB						
4	2017	HC3T-13A409- AD/BD/CD/DD/ED/FD/GD/HD/JE/MD/ND/PD/RD	HC3Z-13A409- A/B/C/D/E/F/G/H/J/K/L/M/MB/NB/RB						
5	2017	HC3T-13A409- AE/BE/CD/DD/EE/FE/GD/HD/JF/ME/NE/PD/RD	HC3Z-13A409- A/B/C/D/E/F/G/H/J/K/L/M/MB/NB/RB						
6	2017	HC3T-13A409- AE/BF/CE/DE/EF/FF/GE/HE/JG/MF/NF/PE/RE	HC3Z-13A409- A/B/C/D/E/F/G/H/J/K/L/M/MB/NB/RB						
7	2018	JC3T-13A409- AA/BA/CA/DA/EA/FA/GA/HA/JA/MA/NA/PA/RA	JC3Z-13A409-A/B/C/D/E/F/G/H/J/K/L/M/N						
8	2018	JC3T-13A409- AA/BA/CA/DA/EB/FB/GB/HB/JA/MB/NB/PB/RB	JC3Z-13A409-A/B/C/D/E/F/G/H/J/K/L/M/N						
9	2018	JC3T-13A409- AA/BA/CA/DA/EC/FC/GC/HC/JA/MB/NB/PB/RB	JC3Z-13A409-A/B/C/D/E/F/G/H/J/K/L/M/N						
10	2018	JC3T-13A409- AB/BB/CB/DB/ED/GD/GD/HD/JB/MC/NC/PC/RC	JC3Z-13A409-A/B/C/D/E/F/G/H/J/K/L/M/N						

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F-Super Duty
External Keypad Change Log

Parts Change Log	
------------------	--

NHTSA Inquiry MA18-011 / :NEF-106rr

[illegible]

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F-Super Duty
R'Control Asy Change Log

F-Super Duty Tailgate R'Control Asy (Brain-Plate Release Actuator) Parts Change Log

NHTSA Inquiry MA18-011 / :NEF-106rr

Part A Part Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	2017	GC34-99431F94-AA	Feb-17	Unknown	C13019894 - Initial production release	Initial release of plastic brainplate	NO		Feb-17		Unknown
2	2017	GC34-99431F94-AB	Feb-17	Unknown	C13218061 - Rod clip change	Rattling noise issue	NO		Feb-17		Unknown
3	2017	GC34-99431F94-AC	Apr-17	Unknown	C13317419 - Released 2D drawing in TCE along with base plate changes and added stronger spring	Spring to self return	NO		Apr-17		Unknown
4	2017	GC34-99431F94-AD	Apr-18	Unknown	C13557923 - Added foam seal around actuator	Water intrusion issues (note was used to bring parts into Ford facilities in Feb 2018)	NO		Apr-18		Unknown
5	2018	GC34-99431F94-AE	Jun-18	Unknown	C13629988 - Rod clip change	Fixed rattling noise issues on original clips	NO		Jun-18		Unknown

Part B Part Changes								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	2014	FL34-99431F94-DC	NA	Unknown	C12709999 - Initial production release C12645380-176 - Drawing clean up C12645380-229 - Drawing notes update	Initial release of Steel brainplate	NO		NA		Unknown
2	2014	FL34-99431F94-DC	NA	Unknown		Drawing clean up	NO		NA		Unknown
3	2014	FL34-99431F94-DC	Sep-14	Unknown		Stall torque note updaes, added bar code, clip position	NO		Sep-14		Unknown
4	2015	FL34-99431F94-DC	Nov-14	Unknown	C12645380-335 - National clip changed to ITW	Changed Clip	NO		Nov-14		Unknown
5	2016	FL34-99431F94-DD	Mar-16	Unknown	C13088664 - Effort change	Revised output forces to 35N & 75N	NO		Mar-16		Unknown

+ Date part number removed from service.

--

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
NO		
NO		
NO		
NO		
NO		

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

PE18-011

FORD

12/20/2018

Appendix H

Change Logs

PE18-011 F-Super Duty
Tailgate Handle Change Log

Parts Change Log

NHTSA Inquiry MA18-011 / :NEF-106rr

HC3B-99431B82-N*W Changes -- PEPS tailgate handle								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	17MY	HC3B-99431B82-NAW	VP BUILD	12/31/2014		INITIAL RELEASE	N				
2		HC3B-99431B82-NBW	12/31/2014	12/31/2014	ADD SEALING PLUGS TO TAILGATE HANDLE PIGTAIL CONNECTOR UPDATE CAD FOR PART TO STRENGTHEN STUD BOSSES	ADD SEALING PINS TO ELECTRICAL CONNECTOR FOR TAILGATE HANDLE	N				
3		HC3B-99431B82-NCW	12/31/2014	5/31/2016	UPDATE UTT LIGHT FOR GLARE AND PACKAGE ROBUSTNESS; IMPROVE PADDLE COVER ATTACHMENT ROBUSTNESS	MODIFY UTT LIGHT FOR BETTER RETENTION AND LIGHT DISPERSION TO ADDRESS AIMS. MODIFY TAILGATE HANDLE COVER FOR BETTER RETENTION ON MECHANICAL HANDLES	N				
4	2017MY MP1	HC3B-99431B82-NDW	5/31/2016	5/31/2016	UPDATE REAR CAMERA IN TAILGATE HANDLE ASSEMBLY	MULTICAMERA IPMB SOFTWARE UPDATE TO R0 LEVEL	N				
5		HC3B-99431B82-NEW	5/31/2016	5/31/2016	ADD TAPE WRAP TO TAILGATE HANDLE HARNESS	TAILGATE HANDLES: ADD TAPE WRAP TO HANDLE WIRING HARNESS, LEVEL UP PRICE TO REFLECT ACTUAL WEIGHT, CORRECT TAKE RATES	N				
6		HC3B-99431B82-NFW	5/31/2016	5/31/2016	MULTICAMERA R4 LEVEL SOFTWARE UPDATES TO THE IPMB MODULE AND ANALOG RVC AND CHMSL CAMERAS.	UPDATE TAILGATE HANDLE TO CAPTURE CAMERA COMPONENT CHANGE	N				
7		HC3B-99431B82-NGW	5/31/2016	5/31/2016	RELEASE SERVICE ASSEMBLIES FOR TAILGATE HANDLE	RELEASE SERVICED COMPONENTS: HC3B-9943800-N	N	HC3B-9943800-NAW	5/31/2016		5/31/2016
8		HC3B-99431B82-NHW	5/31/2016	5/31/2016	REVISE EXTERIOR HANDLE TO INCLUDE CAMERA UPDATE	UPDATE CAMERA	N				
9		HC3B-99431B82-NJW	5/31/2016	5/31/2016	REVISE TG HANDLE BEZEL AND PEPS CUP TO RELOCATE TWO CENTER STUDS FORWARD IN DESIGN LOCATION. EXTEND BEZEL WIRE ROUTING TABS DOWNWARD AND ADD SHEET METAL ALIGNMENT FEATURES IN 2	REVISE BEZEL: RELOCATE STUDS; EXTEND WIRE ROUTING TABS; ADD SHEET METAL ALIGNMENT FEATURES	N	HC3B-9943800-NBW	5/31/2016		8/30/2016
10		HC3B-99431B82-NKW	5/31/2016	8/30/2016	IPMB MODULE AND CAMERAS UPDATE	UPDATE SOFTWARE FOR TAILGATE HANDLE DIGITAL CAMERA COMPONENT AND UPDATE BRANDING ON TAILGATE HANDLE FOR SUFFIX BUMP	N				
11		HC3B-99431B82-NLW	8/30/2016	8/30/2016	ADD NOTCHES TO TAILGATE HANDLE BEZEL TO ACCOMODATE NEW FASTENERS ON TAILGATE TOP MOLDING.	ADD NOTCHES TO TAILGATE HANDLE BEZEL TO ACCOMODATE ADDED FASTENERS IN TAILGATE TOP MOLDING	N	HC3B-9943800-NCW	8/30/2016		2/26/2018
12		HC3B-99431B82-NMW	8/30/2016	1/30/2017	UPDATE TO DIGITAL CAMERAS FOR FLICKER ISSUE AND SERIALIZER	UPDATE TO REVISED CAMERA	N				
13		HC3B-99431B82-NNW	1/30/2017	1/30/2017	UPDATE TAILGATE HANDLE ASSEMBLY TO LATEST CAMERA REVISION	UPDATE ASSEMBLY FOR LATEST REAR VISION CAMERA CHANGE	N				
14		HC3B-99431B82-NPW	1/30/2017	5/1/2017	REVERT BACK CAMERA UPDATE FOR LENS BARREL MATERIAL CHANGE ORIGINAL CHANGE WAS APPROVED UNDER C13215024.	DELETE CAMERA CHANGE FROM TAILGATE HANDLES	N				
15		HC3B-99431B82-NRW	5/1/2017	2/26/2018	UTT LAMP LED SUPPLIER CHANGE FOR VA/VE COST REDUCTION	REPLACE CURENRT LED IN TBA LAMP	N				

16		HC3B-99431B82-NSW	2/26/2018	2/26/2018	ROBUSTNESS IMPROVEMENT- MODIFY THICKNESS OF TPE SEAL OF UTT LIGHT ASSEMBLY OF THE TG HANDLE FOR EASE OF ASSEMBLY	MODIFY LAMP ASSEMBLY TPE SEAL. INCREASE THICKNESS TO 1.5 MM AND REMOVE SCREW HOLES	N				
17	18MY	HC3B-99431B82-NTW	2/26/2018		CARROT REVISION TO TAIL GATE EDGE MOLDING AND ADDED FEATURE ON TG HANDLE TO ADDRESS FIT CONCERN - CHANGE NEEDS TO BE COORDINATED	ADDED NOTCH STEP FOR EDGE MOLDING TO ADDRESS FIT CNCERN.DELTE ISOLATOR CHANGE NEEDS TO BE COORDINATED	N	HC3B-9943800-NDW	2/26/2018		

HC3B-99431B82-S*Wchanges -- PEPS tailgate handle with Chrome Insert								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	17MY	HC3B-99431B82-SAW	5/31/2016	5/31/2016	UPDATE MFALS FOR TAILGATE HANDLE RELEASES	UPDATE MFAL CODES FOR PEPS HANDLE WITH ANALOG CAMERA	N	HC3B-9943800-NAW	5/31/2016		5/31/2016
2		HC3B-99431B82-SBW	5/31/2016	8/30/2016	REVISE TG HANDLE BEZEL AND PEPS CUP TO RELOCATE TWO CENTER STUDS FORWARD IN DESIGN LOCATION. EXTEND BEZEL WIRE ROUTING TABS DOWNWARD AND ADD SHEET METAL ALIGNMENT FEATURES IN 2	REVISE BEZEL: RELOCATE STUDS; EXTEND WIRE ROUTING TABS; ADD SHEET METAL ALIGNMENT FEATURES	N	HC3B-9943800-NBW	5/31/2016		8/30/2016
3		HC3B-99431B82-SCW	8/30/2016	1/30/2017	ADD NOTCHES TO TAILGATE HANDLE BEZEL TO ACCOMODATE NEW FASTENERS ON TAILGATE TOP MOLDING.	ADD NOTCHES TO TAILGATE HANDLE BEZEL TO ACCOMODATE ADDED FASTENERS IN TAILGATE TOP MOLDING	N	HC3B-9943800-NCW	8/30/2016		2/26/2018
4		HC3B-99431B82-SDW	1/30/2017	1/30/2017	UPDATE TAILGATE HANDLE ASSEMBLY TO LATEST CAMERA REVISION	UPDATE ASSEMBLY FOR LATEST REAR VISION CAMERA CHANGE	N				
5		HC3B-99431B82-SEW	1/30/2017	5/1/2017	REVERT BACK CAMERA UPDATE FOR LENS BARREL MATERIAL CHANGE ORIGINAL CHANGE WAS APPROVED UNDER C13215024.	DELETE CAMERA CHANGE FROM TAILGATE HANDLES	N				
6		HC3B-99431B82-SFW	5/1/2017	11/27/2017	UTT LAMP LED SUPPLIER CHANGE FOR VA/VE COST REDUCTION	REPLACE CURENT LED IN TBA LAMP	N				
7		HC3B-99431B82-SGW	11/27/2017	2/26/2018	P558 MY18 ZURICH RVC TO 60% DEWARP SETTING	P558 USE CAMERA WITH LATEST UPDATE ZURICH RVC	N				
8		HC3B-99431B82-SHW	2/26/2018	2/26/2018	ROBUSTNESS IMPROVEMENT- MODIFY THICKNESS OF TPE SEAL OF UTT LIGHT ASSEMBLY OF THE TG HANDLE FOR EASE OF ASSEMBLY	MODIFY LAMP ASSEMBLY TPE SEAL. INCREASE THICKNESS TO 1.5 MM AND REMOVE SCREW HOLES	N				
9	18MY	HC3B-99431B82-SJW	2/26/2018		CARROT REVISION TO TAIL GATE EDGE MOLDING AND ADDED FEATURE	ADDED NOTCH STEP FOR EDGE MOLDING TO ADDRESS FIT CNCERN.DELTE ISOLATOR	N	HC3B-9943800-NDW	2/26/2018		

+ Date part number removed from service.

JC3B-99431B82-X*W Changes-- PEPS tailgate handle with Satin Insert								Service Parts - Dis			
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service
1	18MY	JC3B-99431B82-XAW	1/26/2016	5/1/2017	RELEASE SATIN FINISH FOR HANDLES			JC3B-9943800-XAW	1/26/2016		
2		JC3B-99431B82-XBW	5/1/2017	11/27/2017	UTT LAMP LED SUPPLIER CHANGE FOR VA/VE COST REDUCTION	REPLACE CURENT LED IN TBA LAMP	N				
3		JC3B-99431B82-XCW	2/26/2018	2/26/2018	ROBUSTNESS IMPROVEMENT- MODIFY THICKNESS OF TPE SEAL OF UTT	MODIFY LAMP ASSEMBLY TPE SEAL. INCREASE THICKNESS TO 1.5 MM AND REMOVE	N				
4		JC3B-99431B82-XDW	2/26/2018		CARROT REVISION TO TAIL GATE EDGE MOLDING AND ADDED FEATURE	ADDED NOTCH STEP FOR EDGE MOLDING TO ADDRESS FIT CNCERN.DELTE ISOLATOR	N				

[illegible]

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

position		
Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days

--	--	--