

Safety Recall V06: Drag Link, Rev 8, October 2023

Inspect Drag Link for Separation 19-V0-61-82
Replace Drag Link and Set Toe

Inspect Drag Link and Jam Nut Gap (Not OK) 19-V0-61-83
Measure Drag Link Assembly (Not OK)
Replace Drag Link and Set Toe

Inspect Drag Link and Jam Nut Gap (Not OK) 19-V0-61-84
Measure Drag Link Assembly (OK)
Set Toe and Weld Jam Nuts
(weld time not included, see related LOP)

Inspect Drag Link and Jam Nut Gap (OK) 19-V0-61-85
Jam Nut Torque (Achieved 20 N·m (15 ft./lbs.)
Weld Jam Nuts
(weld time not included, see related LOP)

Inspect Drag Link, Jam Nut Torque (20 N·m (15 ft./lbs.) Not Achieved) 19-V0-61-86
Measure Drag Link Assembly (OK)
Set Toe and Weld Jam Nuts
(weld time not included, see related LOP)

Inspect Drag Link, Jam Nut Torque (20 N·m (15 ft./lbs.) Not Achieved) 19-V0-61-87
Measure Drag Link Assembly (Not OK)
Replace Drag Link and Set Toe

Weld Jam Nuts 19-V0-61-50

Safety Recall V06: Drag Link (International) - Rev 1, May 2021

Replace Drag Link and Set Toe 19-V0-61-88

Stellantis Standard Service Repair LOPs

Steering ; Steering linkage ; Drag link ; Inner 196500501

Steering ; Steering linkage ; Drag link ; Outer 196500502