

INFORMATION REDACTED
 PURSUANT TO THE FREEDOM OF
 INFORMATION ACT (FOIA), 5 U.S.C.
 552(B)(6)

CUSTOMER #: [REDACTED]

WILLIS, TX
 HOME [REDACTED]
 BUS: [REDACTED]

COMP: [REDACTED]
 CELL: [REDACTED]

COLOR	YEAR	MAKE/MODEL
	18	RAM RAM2500

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PU NO.	RATE	PAYMENT	INV. DATE
18AUG20 IS							
18AUG20 DI			15:30 12MAY25		199.95	CASH	09MAY25

R.O. OPENED: [REDACTED] READY: [REDACTED] OPTIONS: DLR:44231 ENG:6.4_Liter

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
00							
1	68338342AD		DRAG LINK-STEERING		723.35	723.35	723.35

A QUICK SERVICE [DRAG LINKS ARE WELDED AND NEED DIAGNOSIS ON WETHER IT NEEDS REPLACE3D OR IF IT IS POSSIBLE TO ALIGN AS IS]
 CAUSE: INSPECTION FOUND THE STEERING DRAGLINK PERVIOUSLY WELDED UNDER THE V06 RECALL IN 2020. FURTHER INSPECTION FOUND THE WELDS HAVE BEEN CUT OFF TO ALLOW FOR ADJUSTMENT. ADVISED CUSTOMER THAT THIS IS NOT A STANDARD PRACTICE AND THE DRAGLINK WILL NEED TO BE REPLACED DUE TO DAMAGE FROM CUTTING THE WELDS OFF.

00 QUICK SERVICE

109	CP				209.95	209.95	
1	68338342AD	DRAG LINK-STEERING			723.35	723.35	723.35

GAVE ESTIMATE FOR DRAGLINK REPLACEMENT.

B Recall / CSN 1 [Safety Recall C4B - Hydraulic Control Unit (HCU) ABS

CHRYSLER

THANK YOU
 CUSTOMER COPY

\$121.99

Op Road
 Home - 7/18/2020

MSR
 15.0000

ST SALE
 ST CABO

05-09-2025

14:13:28

DEARBORN AUTO CENTER INC

8881 Promble 45 S
 COMERCIAL TR 17704
 281412300