

Quality Monitoring Report



QMR Id QMR1- [REDACTED]	Created By [REDACTED]	Report Date 10/26/2017	Last Updated 10/26/2017	Reg-Zn-Dst [REDACTED]	Dealer 040743
-----------------------------------	---------------------------------	----------------------------------	-----------------------------------	---------------------------------	-------------------------

Section Electrical	Sub Section SRS Airbag & Pretentioners
------------------------------	--

VIN [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 34559
--------------------------	-------------------------------	------------------------------	-------------------------

Failure Code [REDACTED]	Failure Date 10/26/2017	Failed Part # 64139sg002II	Technician Duplicated Condition? Y
-----------------------------------	-----------------------------------	--------------------------------------	--

R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N	Property Damage N
---------------------------------	----------------------	------------------	----------------------	--------------------	-------------------	-----------------------------

DTC Code(s)
B1650

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --
------------------------------------	-------------------------------------	------------------------------------

Customer's Description of Complaint

Customer states even after the drying attempt light and srs warning back on.

Technician's Findings and Repair

previously replaced ods, found new stain on seat, attempted drying process, codes had been clear. Verified codes have return believe to be caused liquid intrusion, not defect.

Attachments

[REDACTED]

VIN Remainder [REDACTED]	Warranty Start Date 05/24/2016	Production Date 04/04/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2016	Model Code GFF
Color JGM	Options 14	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

