

Quality Monitoring Report



QMR Id QMR1 [REDACTED]	Created By [REDACTED]	Report Date 10/27/2017	Last Updated 10/27/2017	Reg-Zn-Dst [REDACTED]	Dealer 090772
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 12		
Failure Code [REDACTED]	Failure Date 09/29/2017	Failed Part # --	Technician Duplicated Condition? N		
R/O Number --	Rollover N	Fire N	Accident N	Injury N	Death N
					Property Damage N
DTC Code(s) B1650					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	-------------------------------------	--

Customer's Description of Complaint

CS: Intermittent air bag light comes on when front passenger seat is occupied.

Technician's Findings and Repair

TS: Unable to duplicate, no indication of spilled beverage or after market accessories causing, but had stored DTC. DPSM authorized seat cushion replacement.

Attachments

[REDACTED]

VIN Remainder JF2SJAJC8HH [REDACTED]	Warranty Start Date 11/12/2016	Production Date 09/15/2016	Car Line Forester
Original Engine # 464385	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFI
Color CBS	Options 21	Emission Spec C	Turbo N
Engine Size	Original Trans # [REDACTED]		

2.5
