

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By jsha	Report Date 12/14/2017	Last Updated 12/14/2017	Reg- Zn-Dst [REDACTED]	Dealer 040731
Section --	Sub Section --				
VIN JF2SJATC5HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 11617		
Failure Code [REDACTED]	Failure Date 12/14/2017	Failed Part # 64139SG220VH	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	---	--

Customer's Description of Complaint

air bag light on

Technician's Findings and Repair

Technician verified concern and pulled code B1650. FSE noticed this seat bottom in warranty 10-Bin and asked technician if he followed the new bulletin 07-108-16R. Unfortunately the repair was completed on 12/5/17 and the bulletin was released on 12/6/17.

Attachments

No Attachments Found

VIN Remainder JF2SJATC5HH [REDACTED]	Warranty Start Date 02/04/2017	Production Date 12/17/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFJ
Color DG2	Options 32	Emission Spec C	Turbo N
Engine Size	Original Trans # [REDACTED]		

2.5
