

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By ostran	Report Date 12/23/2017	Last Updated 12/23/2017	Reg- Zn- Dst [REDACTED]	Dealer 400960
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJAEC1HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 23932		
Failure Code [REDACTED]	Failure Date 12/23/2017	Failed Part # 64139SG002VH	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

Customer states that the Air Bag Light came on again over the weekend.

Technician's Findings and Repair

Technician performed diagnostic TT for code B1650 on 10/23/17 and determined that it was necessary to replace part # 64139SG002VH. FSE contacted retailer and advise them to reperform diagnostics following directives from TSB 07-108-16R. Service manager informed FSE that diagnostics still leads to replacement of the seat bottom assembly. FSE will generate TR.

Attachments

[REDACTED]

VIN Remainder JF2SJAEC1HH [REDACTED]	Warranty Start Date 08/05/2016	Production Date 06/17/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color	Options	Emission Spec	Turbo

DGM

13

C

N

Engine Size

Original Trans #

2.5

