

## Quality Monitoring Report



<b>QMR Id</b> QMR1- [REDACTED]	<b>Created By</b> jcruz	<b>Report Date</b> 02/09/2018	<b>Last Updated</b> 02/09/2018	<b>Reg- Zn-Dst</b> [REDACTED]	<b>Dealer</b> 040635
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretensioners				
<b>VIN</b> JF2SJAEC0JH [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 6711		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 01/18/2018	<b>Failed Part #</b> 64139SG060LL	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
					<b>Property Damage</b> N

### DTC Code(s)

--

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> [REDACTED]
------------------------------------	-------------------------------------	--

### Customer's Description of Complaint

C/S airbag light is on.

### Technician's Findings and Repair

FSE found part in 10 bin inspection. Customer returned for SOP to be installed. Technician followed diagnostic procedure for B1650. Tech also performed visual inspection for seat cushion and found no trace of water or moisture. Replaced seat cushion. vehicle operates as designed.

### Attachments

No Attachments Found

<b>VIN Remainder</b> JF2SJAEC0JH [REDACTED]	<b>Warranty Start Date</b> 06/24/2017	<b>Production Date</b> 05/17/2017	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2018	<b>Model Code</b> JFF
<b>Color</b> JGM	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

2.5

---