

## Quality Monitoring Report



<b>QMR Id</b> QMR1- [REDACTED]	<b>Created By</b> ostran	<b>Report Date</b> 06/05/2018	<b>Last Updated</b> 06/05/2018	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 401898
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJGEC7J [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 6111		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 06/05/2018	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					

**DTC Code(s)**

--

<b>Reporter Name</b> Ole Strand	<b>Reporter Email</b> ostran@subaru.com	<b>Reporter Phone Number</b> --
------------------------------------	--	------------------------------------

**Customer's Description of Complaint**

Customer states that the passenger seat belt light and bell stay on and the airbag light is on.

**Technician's Findings and Repair**

FSE was present at retailer for routine visit in which he was queried about this vehicle when it arrived. FSE was informed that seat was dry and that no codes are currently present. FSE examined vehicle and found both seats to be wet between the seat back and seat bottom. FSE advised ensuring the seats are fully dried and then perform diagnosis using TSB 07-108-16R.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJGEC7JH [REDACTED]	<b>Warranty Start Date</b> 01/29/2018	<b>Production Date</b> 11/15/2017	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> [REDACTED] Variable Transmission	<b>Model Year</b> 2018	<b>Model Code</b> JFM
<b>Color</b> CBS	<b>Options</b> 11	<b>Emission Spec</b> C	<b>Turbo</b> Y
<b>Engine Size</b>	<b>Original Trans #</b>		

