

Quality Monitoring Report



| | | | | | |
|-------------------------------------|-------------------------------------|--|-----------------------------------|---|---------------------------------|
| QMR Id QMR1- [REDACTED] | Created By cman4750 | Report Date 07/24/2018 | Last Updated 07/24/2018 | Reg- Zn- Dst [REDACTED] | Dealer 010287 |
| Section Body | Sub Section Front Seat | | | | |
| VIN JF2SJAEC6H [REDACTED] | Engine # [REDACTED] | Trans # [REDACTED] | Mileage 18622 | | |
| Failure Code [REDACTED] | Failure Date 07/24/2018 | Failed Part # 64139SG060LL | Technician Y | Duplicated Condition? Y | |
| R/O Number [REDACTED] | Rollover N | Fire N | Accident N | Injury N | Death N |
| | | | | | Property Damage N |
| DTC Code(s) B1760 | | | | | |
| Reporter Name [REDACTED] | Reporter Email [REDACTED] | Reporter Phone Number -- | | | |

Customer's Description of Complaint

Customer states that when someone is in the passenger seat the red airbag light will come on

Technician's Findings and Repair

Following flow chart for b1760 I found that the occupant detection mat would erratically change from occupied to non occupied

Attachments

No Attachments Found

| | | | |
|---|---|--------------------------------------|-----------------------------|
| VIN Remainder JF2SJAEC6H [REDACTED] | Warranty Start Date 12/28/2016 | Production Date 10/24/2016 | Car Line Forester |
| Original Engine # [REDACTED] | Trans. Type Desc Continuously Variable Transmission | Model Year 2017 | Model Code HFF |
| Color JGM | Options 13 | Emission Spec C | Turbo N |
| Engine Size 2.5 | Original Trans # [REDACTED] | | |