

**Quality Monitoring Report**

<b>QMR Id</b> QMR1 [REDACTED]	<b>Created By</b> afil2042	<b>Report Date</b> 07/31/2018	<b>Last Updated</b> 07/31/2018	<b>Reg- Zn- Dst</b> [REDACTED]	<b>Dealer</b> 010270
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJAEC2H [REDACTED]	<b>Engine</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 14219		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 07/31/2018	<b>Failed Part #</b> 64139SG060LL	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650					
<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> [REDACTED]			

**Customer's Description of Complaint**

Customer states air bag light on

**Technician's Findings and Repair**

Tech scanned for codes, found B1650. Tech performed diagnostic, checked for moisture on seat, none found and no staining, customer confirmed no moisture spilled onto seat. Tech measured voltage between connector in test harness and ground, found over 10V, determined OCD passenger side cushion and frame assembly will need to be replaced, part is now on order.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAEC2 [REDACTED]	<b>Warranty Start Date</b> 01/28/2017	<b>Production Date</b> 11/22/2016	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2017	<b>Model Code</b> HFF
<b>Color</b> QBP	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

2.5

---