


INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

**Quality Monitoring Report**

<b>QMR Id</b> QMR1- [REDACTED]	<b>Created By</b> ahil5705	<b>Report Date</b> 09/28/2018	<b>Last Updated</b> 09/28/2018	<b>Reg- Zn-Dst</b> [REDACTED]	<b>Dealer</b> 020234
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJAEC7H [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 9961		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 09/28/2018	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	------------------------------------

**Customer's Description of Complaint**

Customer states Airbag light comes on.

**Technician's Findings and Repair**

As per TSB 07-108-16R, follow trouble Tree. Step 2 no poor contact. Step 3, Resistance is greater than 10. 6 Ohms measured. Step 4 Resistance is more than 1M. -1.8M measured. step 5 Voltage 10V or more. 12.5 measured. Step 6 B1650 is Detected.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAEC7H [REDACTED]	<b>Warranty Start Date</b> 05/31/2017	<b>Production Date</b> 04/07/2017	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2017	<b>Model Code</b> HFF
<b>Color</b> CBS	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

2.5

---