

## Quality Monitoring Report



<b>QMR Id</b> QMR1- [REDACTED]	<b>Created By</b> ewalke	<b>Report Date</b> 09/30/2018	<b>Last Updated</b> 09/30/2018	<b>Reg- Zn- Dst</b> [REDACTED]	<b>Dealer</b> 030149
<b>Section</b> Electrical	<b>Sub Section</b> SRS Airbag & Pretentioners				
<b>VIN</b> JF2SJALCXJH [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 7488		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 08/09/2018	<b>Failed Part #</b> 64139SG160LL	<b>Technician Duplicated Condition?</b> N		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650					
<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --			

**Customer's Description of Complaint**

Customer states that the SRS Light is on while driving.

**Technician's Findings and Repair**

While I was at the Retailer they asked me about this vehicle due to the parts delay. I told them inspect the seat and see if the DTC would clear, If it does then the seat could just have gotten wet. If it doesn't then replace the cushion. They told me the DTC would not clear so they did order a ODS Module.

**Attachments**

[REDACTED]

<b>VIN Remainder</b> JF2SJALCXJ [REDACTED]	<b>Warranty Start Date</b> 10/19/2017	<b>Production Date</b> 06/20/2017	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2018	<b>Model Code</b> JFI
<b>Color</b> VRP	<b>Options</b> 22	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

2.5

---