

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

**Quality Monitoring Report**

<b>QMR Id</b> QMR1 [REDACTED]	<b>Created By</b> jmarch	<b>Report Date</b> 10/11/2018	<b>Last Updated</b> 10/11/2018	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 401192
<b>Section</b> NDF - Specified Area	<b>Sub Section</b> Electrical				
<b>VIN</b> JF2SJAEC3JH [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 9653		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 10/11/2018	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> --	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident Injury</b> N	<b>Death</b> N	<b>Property Damage</b> N
<b>DTC Code(s)</b> B1650, B1760					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> [REDACTED]
------------------------------------	-------------------------------------	--

**Customer's Description of Complaint**

Customer states that the airbag light switches to odd after 2 hours of driving.

**Technician's Findings and Repair**

Technician was wondering if body sweat could cause issues with ODS system. Technician was advised by tech line that sweat could cause this problem. The technician remove d the seat cover to check for staining. Technician removed the seat cover and it was not wet and does not have any staining or contamination. Light is coming on after 3+ hours of driving, customer is a larger person. Technician will find out if they have the seat heater on. Technician will update FSE with any findings.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAEC3 [REDACTED]	<b>Warranty Start Date</b> 06/12/2018	<b>Production Date</b> 03/23/2018	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2018	<b>Model Code</b> JFF
<b>Color</b> QBP	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N

**Engine Size**

**Original Trans #**

2.5

