

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By dpag	Report Date 12/12/2018	Last Updated 12/12/2018	Reg-Zn-Dst [REDACTED]	Dealer 040459
Section Electrical	Sub Section Power Seat				
VIN JF2SJAECXH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 21180		
Failure Code ULI41	Failure Date 12/12/2018	Failed Part # --	Technician Duplicated Condition? N		
R/O Number --	Rollover N	Fire N	Accident Injury Death N N N	Property Damage N	
DTC Code(s) B1650					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --
------------------------------------	-------------------------------------	------------------------------------

Customer's Description of Complaint

CS: Air Bag light is on, check and advise.

Technician's Findings and Repair

Retailer found customer had spilled liquid on the seat. When the vehicle was presented the liquid had all dried, code was in history. Retailer explained to customer the issue was caused by the liquid spilled on the seat. Retailer has cleared the code and road tested vehicle to ensure proper operation with no further issues.

Attachments

No Attachments Found

VIN Remainder JF2SJAECXH [REDACTED]	Warranty Start Date 09/24/2016	Production Date 07/18/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color WHC	Options 13	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

