

**Quality Monitoring Report**

<b>QMR Id</b>	<b>Created By</b>	<b>Report Date</b>	<b>Last Updated</b>	<b>Reg- Zn-Dst Dealer</b>
QMR1- [REDACTED]	sdcjpyl	12/21/2018	12/21/2018	[REDACTED] 020151

<b>Section</b>	<b>Sub Section</b>
Electrical	SRS Airbag & Pretentioners

<b>VIN</b>	<b>Engine #</b>	<b>Trans #</b>	<b>Mileage</b>
JF2SJAEC2H [REDACTED]	[REDACTED]	[REDACTED]	35917

<b>Failure Code</b>	<b>Failure Date</b>	<b>Failed Part #</b>	<b>Technician Duplicated Condition?</b>
[REDACTED]	10/06/2018	64139SG060LL	Y

<b>R/O Number</b>	<b>Rollover</b>	<b>Fire</b>	<b>Accident Injury Death</b>	<b>Property Damage</b>
[REDACTED]	N	N	N N N	N

**DTC Code(s)**  
B1650

<b>Reporter Name</b>	<b>Reporter Email</b>	<b>Reporter Phone Number</b>
[REDACTED]	[REDACTED]	--

**Customer's Description of Complaint**

Customer states airbag light came back on.

**Technician's Findings and Repair**

Technician Perform diagnosis as per B1650 trouble tree, check poor contact of connectors all ok, seat bottom not wet, check rear harness with harness adapter resistance readings below 1 ohm ok, measure to ground ok 1M (OL), occupant harness ok replaced seat bottom, clear code test operation all ok. Technician supplied SSM4 attached, no other information is available

**Attachments**

[REDACTED]

<b>VIN Remainder</b>	<b>Warranty Start Date</b>	<b>Production Date</b>	<b>Car Line</b>
JF2SJAEC2H [REDACTED]	08/27/2016	07/05/2016	Forester
<b>Original Engine #</b>	<b>Trans. Type Desc</b>	<b>Model Year</b>	<b>Model Code</b>
[REDACTED]	Continuously Variable Transmission	2017	HFF
<b>Color</b>	<b>Options</b>	<b>Emission Spec</b>	<b>Turbo</b>
QBP	13	C	N

**Engine Size**

**Original Trans #**

2.5

