

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By kste4245	Report Date 01/19/2019	Last Updated 01/19/2019	Reg- Zn- Dst [REDACTED]	Dealer 010209
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJAEC3H [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 25070		
Failure Code [REDACTED]	Failure Date 01/19/2019	Failed Part # --	Technician Duplicated Condition? Y		
R/O Number --	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) --					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

Customer states passenger side airbag light keeps coming on and off

Technician's Findings and Repair

Tech pulled codes B1693 and B1650 for faulty passenger side seat bottom (occupancy detection system malfunction). Replaced passenger side load cell sensor cushion assembly.

Attachments

No Attachments Found

VIN Remainder JF2SJAEC3H [REDACTED]	Warranty Start Date 06/26/2017	Production Date 04/28/2017	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color DGM	Options 13	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

