

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By jsha	Report Date 01/17/2019	Last Updated 01/17/2019	Reg- Zn-Dst Dealer [REDACTED] 402444
Section Electrical	Sub Section SRS Airbag & Pretensioners			
VIN JF2SJGWC0JH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 15503	
Failure Code [REDACTED]	Failure Date 09/06/2018	Failed Part # 64139SG220VH	Technician Duplicated Condition? Y	
R/O Number [REDACTED]	Rollover N	Fire N	Accident Injury N	Death N
Property Damage N				
DTC Code(s) B1650				

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	---	--

Customer's Description of Complaint

During claims review, FSE found this claim.

Technician's Findings and Repair

FSE interviewed technician to verify if he was aware of TSB 07-108-16R and found that he was not. FSE then explained how to verify if the seat bottom needs to be replaced or dried out. Technician will review the TSB before another repair.

Attachments

No Attachments Found

VIN Remainder JF2SJGWC0J [REDACTED]	Warranty Start Date 10/11/2017	Production Date 06/09/2017	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2018	Model Code JFN
Color W1C	Options 32	Emission Spec C	Turbo Y
Engine Size	Original Trans # [REDACTED]		

