

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By kste4245	Report Date 04/23/2019	Last Updated 04/23/2019	Reg- Zn- Dst [REDACTED]	Dealer 010209
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJAJC2HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 17204		
Failure Code [REDACTED]	Failure Date 04/23/2019	Failed Part # INVALID	Technician Duplicated Condition? Y		
R/O Number --	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) --					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --			

Customer's Description of Complaint

Customer states check airbag system light came on

Technician's Findings and Repair

Tech found code B1650. Found passenger front load cell sensor cushion faulty. Replaced passenger front seat bottom.

Attachments

No Attachments Found

VIN Remainder JF2SJAJC2HH [REDACTED]	Warranty Start Date 01/25/2017	Production Date 11/17/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFI
Color VRP	Options 21	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

