

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report

QMR Id QMR1- [REDACTED]	Created By msan3827	Report Date 06/28/2019	Last Updated 06/28/2019	Reg-Zn-Dst [REDACTED]	Dealer 020165
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJAWC6HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 18994		
Failure Code [REDACTED]	Failure Date 06/28/2019	Failed Part # --	Technician Duplicated Condition? N		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1760					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	-------------------------------------	--

Customer's Description of Complaint

customer states airbag light is on again

Technician's Findings and Repair

scan for codes found b 1650 and b1760 stored in airbag and occupant detection module both as history.referanced bulletin 07-108-16r and followed diag chart for b1760.diag chart led to no repair,clear memory and return.contacted techline case number [REDACTED].was provided with a list of questions for customer before any further diagnosis

Attachments

No Attachments Found

VIN Remainder JF2SJAWC6HH806145	Warranty Start Date 06/14/2017	Production Date 04/19/2017	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFJ
Color SBM	Options 34	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

