

Quality Monitoring Report



QMR Id QMR1- [REDACTED]	Created By msan3827	Report Date 07/24/2019	Last Updated 07/24/2019	Reg- Zn- Dst [REDACTED]	Dealer 020165
Section Electrical	Sub Section SRS Airbag & Pretentioners				
VIN JF2SJGEC1H [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 12375		
Failure Code [REDACTED]	Failure Date 07/24/2019	Failed Part # INVALID	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1760					

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]
------------------------------------	-------------------------------------	--

Customer's Description of Complaint

airbag light is on intermittent

Technician's Findings and Repair

scanned for codes and found B1650, and B1760 stored as current codes. Referenced bulletin 07-108-16r, at step 2 where it states check for poor connection, before unplugging and inspecting connection I just moved the connector and the code went to history. I then unplugged the connector and saw no visible damage. unable to determine which side of the connector is causing the issue, will need to replace seat base and Rh side harness and re evaluate.

Attachments

No Attachments Found

VIN Remainder JF2SJGEC1H [REDACTED]	Warranty Start Date 07/18/2017	Production Date 03/31/2017	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFM
Color VRP	Options 16	Emission Spec C	Turbo Y

Engine Size

Original Trans #

2

