

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report



QMR Id QMR1- [REDACTED]	Created By sdcjcol	Report Date 08/09/2019	Last Updated 08/09/2019	Reg-Zn-Dst [REDACTED]	Dealer 020165
Section Electrical Location Grids		Sub Section Body Wiring - Wire Harness			
VIN JF2SJGEC1HH [REDACTED]	Engine # [REDACTED]	Trans # [REDACTED]	Mileage 12375		
Failure Code [REDACTED]	Failure Date 07/23/2019	Failed Part # --	Technician Duplicated Condition? Y		
R/O Number --	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1760					
Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number [REDACTED]			

Customer's Description of Complaint

Customer states airbag light on intermittently.

Technician's Findings and Repair

Part found during 10 bin inspection. Tech found DTC B1760 and B150 current. Tech suspects poor connection in AB59-AB53 See techs QMR1-[REDACTED] Tech replaced passenger seat bottom and rear harness. Both parts will be collected and shipped to PCC.

Attachments

No Attachments Found

VIN Remainder JF2SJGEC1HH [REDACTED]	Warranty Start Date 07/18/2017	Production Date 03/31/2017	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFM
Color VRP	Options 16	Emission Spec C	Turbo Y

Engine Size

Original Trans #

2

