

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By phay	Report Date 05/19/2017	Last Updated 05/19/2017	Reg- Zn-Dst Dealer [REDACTED] 040743
Section Electrical	Sub Section Air Bag			
VIN JF2SJAGC2H [REDACTED]	Engine # --	Trans # --	Mileage 7224	
Failure Code [REDACTED]	Failure Date 03/30/2017	Failed Part # 64139SG060LL	Technician Duplicated Condition? Y	
R/O Number [REDACTED]	Rollover N	Fire N	Accident Injury Death N N N	Property Damage N
DTC Code(s) B1650				

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --
------------------------------------	-------------------------------------	--

Customer's Description of Complaint

Customer states that passenger side airbag sensor only works certain times.

Technician's Findings and Repair

Technician confirmed B1650 code. Technician did not refer to TSB 07-108-16. Technician not able to send SSM4 data, however, attached is a photo of the DTC B1650. No FFD available. Technician condemned ODS module, no additional troubleshooting was performed. There are signs of multiple spill on the seat surface. Customer was not interviewed to determine if other items are placed on the seat cushion during vehicle operation. FSE will enter TR [REDACTED]. FSE will collect failed part and return to the PCC for further evaluation.

Attachments

[REDACTED]

VIN Remainder JF2SJAGC2H [REDACTED]	Warranty Start Date 09/24/2016	Production Date 07/05/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color	Options	Emission Spec	Turbo

DGM

14

C

N

Engine Size

Original Trans #

2.5

