

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report



| | | | | | |
|--------------------------------------|-------------------------------------|----------------------------------|--|---------------------------------|-------------------------|
| QMR Id QMR [REDACTED] | Created By apor | Report Date 05/25/2017 | Last Updated 05/25/2017 | Reg-Zn-Dst [REDACTED] | Dealer 040733 |
| Section Electrical | Sub Section Miscellaneous | | | | |
| VIN JF2SJAJC7HH [REDACTED] | Engine # -- | Trans # -- | Mileage 5339 | | |
| Failure Code [REDACTED] | Failure Date 05/24/2017 | Failed Part # -- | Technician Duplicated Condition? Y | | |
| R/O Number [REDACTED] | Rollover N | Fire N | Accident Injury Death N N N | Property Damage N | |
| DTC Code(s) B1650, B1760 | | | | | |

| | | |
|------------------------------------|-------------------------------------|------------------------------------|
| Reporter Name [REDACTED] | Reporter Email [REDACTED] | Reporter Phone Number -- |
|------------------------------------|-------------------------------------|------------------------------------|

Customer's Description of Complaint

SRS light came on while driving

Technician's Findings and Repair

Tech found a failed right side passenger seat sensor failed, ordered new part, part on back order. QMR due to FSE reviewed vehicle with tech by phone. Customer waiting for new part to arrive and is still driving vehicle.

Attachments

No Attachments Found

| | | | |
|--|---|--------------------------------------|-----------------------------|
| VIN Remainder JF2SJAJC7HH [REDACTED] | Warranty Start Date 08/03/2016 | Production Date 05/25/2016 | Car Line Forester |
| Original Engine # [REDACTED] | Trans. Type Desc Continuously Variable Transmission | Model Year 2017 | Model Code HFI |
| Color IS1 | Options 21 | Emission Spec C | Turbo N |
| Engine Size 2.5 | Original Trans # [REDACTED] | | |

