

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By tken	Report Date 05/25/2017	Last Updated 05/25/2017	Reg-Zn-Dst [REDACTED]	Dealer 090180
Section Electrical	Sub Section Air Bag				
VIN JF2SJAGC1HH [REDACTED]	Engine # --	Trans # --	Mileage 19969		
Failure Code [REDACTED]	Failure Date 03/28/2017	Failed Part # 64139SG002VH	Technician Duplicated Condition? Y		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650, B1760					

Reporter Name [REDACTED]	Reporter Email --	Reporter Phone Number --
------------------------------------	-----------------------------	------------------------------------

Customer's Description of Complaint

CUSTOMER STATES THE RED AIRBAG LIGHT IS ON ON THE DASH

Technician's Findings and Repair

PULLED FAULTS FOUND B1650 OCCUPANT DETECTION SYSTEM MALFUNCTION AND B1760 OCCUPANT DETECTION SENSOR MAT. CHECKED ALL CONNECTIONS ARE GOOD , NEEDS NEW SEAT BRACKET. Part found during 10 bin inspection and is being returned to pcc for additional inspection.

Attachments

[REDACTED]

VIN Remainder JF2SJAGC1HH [REDACTED]	Warranty Start Date 08/06/2016	Production Date 06/17/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color ISM	Options 15	Emission Spec C	Turbo N

Engine Size

Original Trans #

2.5

