

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By tken	Report Date 05/25/2017	Last Updated 05/25/2017	Reg-Zn-Dst [REDACTED]	Dealer 090180
Section Electrical	Sub Section Air Bag				
VIN JF2SJAFC5FH [REDACTED]	Engine # --	Trans # --	Mileage 21218		
Failure Code [REDACTED]	Failure Date 05/08/2017	Failed Part # 64139SG002LL	Technician Duplicated Condition? N		
R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N
Property Damage N					
DTC Code(s) B1650					
Reporter Name [REDACTED]	Reporter Email --	Reporter Phone Number --			

Customer's Description of Complaint

CUSTOMER STATES PASSENGER SIDE SEAT WAS DINGING AF IF THERE WAS SOMEONE SITTING IN SEAT WHEN THERE WASNT.

Technician's Findings and Repair

THE TECH PULLED CODE B1650 PASSENGER OCCUPANT DETECTION SYSTEM FAULT. DIAGNOSED TO R/F SEAT BOTTOM NEEDS TO BE REPLACED. Part found during 10 bin inspection and is being returned to pcc for additional inspection.

Attachments

No Attachments Found

VIN Remainder JF2SJAFC5FH [REDACTED]	Warranty Start Date 06/30/2015	Production Date 02/24/2015	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2015	Model Code FFF
Color DGM	Options 14	Emission Spec C	Turbo N
Engine Size	Original Trans # [REDACTED]		

2.5
