

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

## Quality Monitoring Report



<b>QMR Id</b> QMR [REDACTED]	<b>Created By</b> kco2	<b>Report Date</b> 05/30/2017	<b>Last Updated</b> 05/30/2017	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 070602
<b>Section</b> Electrical	<b>Sub Section</b> Air Bag				
<b>VIN</b> JF2SJAWC9HH [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 2607		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 05/02/2017	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident Injury Death</b> N    N    N	<b>Property Damage</b> N	

**DTC Code(s)**  
B1760

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	------------------------------------

**Customer's Description of Complaint**

Customer states that the SRS Air Bag Light is illuminated.

**Technician's Findings and Repair**

Technician performed system diagnosis and ordered a passenger side seat bottom. Part is currently on backorder. Per QA request FSE reviewed Service Bulletin 07-108-16 with technician for repair. Technician will perform bulletin and verify repair.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAWC9HH [REDACTED]	<b>Warranty Start Date</b> 12/23/2016	<b>Production Date</b> 11/04/2016	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2017	<b>Model Code</b> HFJ
<b>Color</b> VRP	<b>Options</b> 33	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

2.5

---