

## Quality Monitoring Report



<b>QMR Id</b> QMR [REDACTED]	<b>Created By</b> kco2	<b>Report Date</b> 05/30/2017	<b>Last Updated</b> 05/30/2017	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 070587
<b>Section</b> Electrical	<b>Sub Section</b> Air Bag				
<b>VIN</b> JF2SJADC8GH [REDACTED]	<b>Engine #</b> [REDACTED]	<b>Trans #</b> [REDACTED]	<b>Mileage</b> 38161		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 05/02/2017	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident Injury</b> N	<b>Death</b> N	<b>Property Damage</b> N
<b>DTC Code(s)</b> B1760					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	------------------------------------

**Customer's Description of Complaint**

Customer states that the SRS Air Bag light illuminates intermittently.

**Technician's Findings and Repair**

Technician performed system diagnosis and order passenger side seat bottom per diagnosis. Part is currently on backorder. FSE reviewed with technician bulletin 07-108-16 for diagnosis review and repair procedures. Technician will perform bulletin process for cleaning and drying seat and test drive to verify repair.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJADC8GH [REDACTED]	<b>Warranty Start Date</b> 08/18/2015	<b>Production Date</b> 06/26/2015	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2016	<b>Model Code</b> GFF
<b>Color</b> CBS	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N
<b>Engine Size</b>	<b>Original Trans #</b>		

2.5

