

## Quality Monitoring Report



<b>QMR Id</b> QMR [REDACTED]	<b>Created By</b> dmacdo	<b>Report Date</b> 06/02/2017	<b>Last Updated</b> 06/02/2017	<b>Reg- Zn-Dst</b> [REDACTED]	<b>Dealer</b> 040586
<b>Section</b> Body and Paint	<b>Sub Section</b> Seats				
<b>VIN</b> JF2SJGDC8FH [REDACTED]	<b>Engine #</b> --	<b>Trans #</b> --	<b>Mileage</b> 34363		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 04/27/2017	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> --	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
					<b>Property Damage</b> N
<b>DTC Code(s)</b> B1650					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	------------------------------------

**Customer's Description of Complaint**

Customer states srs light comes on intermittently

**Technician's Findings and Repair**

Tech followed trouble tree until step 5 advised to replace occupant detection harness, and ods system. Once this work was completed the system operated as designed. There was no external evidence of moisture on the ods components.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJGDC8FH [REDACTED]	<b>Warranty Start Date</b> 08/31/2015	<b>Production Date</b> 04/10/2015	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2015	<b>Model Code</b> FFM
<b>Color</b> DGM	<b>Options</b> 16	<b>Emission Spec</b> C	<b>Turbo</b> Y
<b>Engine Size</b>	<b>Original Trans #</b> [REDACTED]		

