

## Quality Monitoring Report



<b>QMR Id</b> QM [REDACTED]	<b>Created By</b> lgil4245	<b>Report Date</b> 06/17/2017	<b>Last Updated</b> 06/17/2017	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 020165
<b>Section</b> Electrical	<b>Sub Section</b> Air Bag				
<b>VIN</b> JF2SJADC0F [REDACTED]	<b>Engine #</b> --	<b>Trans #</b> --	<b>Mileage</b> 36183		
<b>Failure Code</b> URD43	<b>Failure Date</b> --	<b>Failed Part #</b> --	<b>Technician Duplicated Condition?</b> N		
<b>R/O Number</b> --	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
					<b>Property Damage</b> N
<b>DTC Code(s)</b> B1650					

<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --
------------------------------------	-------------------------------------	------------------------------------

**Customer's Description of Complaint**

Airbag warning lamp on in cluster

**Technician's Findings and Repair**

Airbag warning lamp off at time of service. Scanned Airbag module, past code B1650 Occupant Detection System Malfunction. No freeze frame data available. Scanned Occupant Detection module, which contained no DTC's. Occupant detection system is currently working as designed. This is one of three 2015 vehicles that I have encountered with these symptoms in the past two days, and we have just had extremely hot and extremely humid weather.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJADC0F [REDACTED]	<b>Warranty Start Date</b> 05/28/2015	<b>Production Date</b> 03/10/2015	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> 6-Speed Manual	<b>Model Year</b> 2015	<b>Model Code</b> FFE
<b>Color</b> WHI	<b>Options</b> 11	<b>Emission Spec</b> C	<b>Turbo</b> N

**Engine Size**

**Original Trans #**

2.5

