

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By tken	Report Date 07/05/2017	Last Updated 07/05/2017	Reg-Zn-Dst [REDACTED]	Dealer 090223
Section Electrical	Sub Section Miscellaneous				
VIN JF2SJARC8GH [REDACTED]	Engine # --	Trans # --	Mileage 11733		
Failure Code [REDACTED]	Failure Date 06/19/2017	Failed Part # 64139SG043VH	Technician Duplicated Condition? N		
R/O Number --	Rollover N	Fire N	Accident N	Injury N	Death N
					Property Damage N

DTC Code(s)

[REDACTED]

Reporter Name T Kenner	Reporter Email --	Reporter Phone Number --
----------------------------------	-----------------------------	------------------------------------

Customer's Description of Complaint

Intermittently airbag light is On

Technician's Findings and Repair

The technician could not duplicate the concern however code B1650 was in history, the customer has been multiple times for the concern FSE directed the tech to replace the ODS cushion. The part is being returned to PCC for additional inspection.

Attachments

[REDACTED]

VIN Remainder JF2SJARC8GH [REDACTED]	Warranty Start Date 05/14/2016	Production Date 02/09/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2016	Model Code GFI
Color BBM	Options 23	Emission Spec C	Turbo N
Engine Size	Original Trans #		

2.5

