

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

## Quality Monitoring Report



<b>QMR Id</b> QMR [REDACTED]	<b>Created By</b> ostran	<b>Report Date</b> 07/18/2017	<b>Last Updated</b> 07/18/2017	<b>Reg- Zn- Dst</b> [REDACTED]	<b>Dealer</b> 070594
<b>Section</b> Electrical	<b>Sub Section</b> Air Bag				
<b>VIN</b> JF2SJAEC6HH [REDACTED]	<b>Engine #</b> --	<b>Trans #</b> --	<b>Mileage</b> 20908		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 07/07/2017	<b>Failed Part #</b> 64139SG060LL	<b>Technician Duplicated Condition?</b> Y		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650, B1760					
<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> [REDACTED]	<b>Reporter Phone Number</b> --			

**Customer's Description of Complaint**

Customer states the air bag light is illuminated. Customer also noted when starting the vehicle, it states the SRS air bag system needs to be checked.

**Technician's Findings and Repair**

Technician found codes B1650 and B1760. Technician determined that ODS system is defective. Technician replaced passenger seat bottom assembly, air bag light is now off and working as designed. No FF data available, No TT data available. TR with part collection will be issued.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAEC6H [REDACTED]	<b>Warranty Start Date</b> 08/05/2016	<b>Production Date</b> 05/13/2016	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2017	<b>Model Code</b> HFF
<b>Color</b> JGM	<b>Options</b> 13	<b>Emission Spec</b> C	<b>Turbo</b> N

**Engine Size**

**Original Trans #**

2.5

